| -        | unded Projec           | •                |            |  |   | F        | unding    |   |          |                        |
|----------|------------------------|------------------|------------|--|---|----------|-----------|---|----------|------------------------|
|          | Priority               | Immediacy        | Agency     | Facility                                 | Project Title   | R        | equest    | Comments  | Ru       | nning Total            |
|          |                        |                  |            |  |   |          |           | The tunnel at ICIW is collapsing and unsafe. Numerous areas are<br>blocked off due to being unsafe to even walk on. Cannot be worked<br>on until current construction is complete, likely early FY2016. Some                            |          |                        |
| 4        |                        |                  | D00        |  | Demoliah Turnel   | ¢        | F00 000   | sections already demolished. Study underway to evaluate severity,   | ¢        | 500.000                |
| 1        | 1) L/H/S               | A) Now           | DOC        | ICIW<br>Iowa Veterans                    | Demolish Tunnel   | \$       | 500,000   | cost and scope before funding.<br>Replace sidewalks and concrete areas that are deteriorating and/or  | \$       | 500,000                |
| 2        | 1) L/H/S               | A) Now           | DVA        | Home                                     | Sidewalk and Concrete Repairs                                   | \$       | 200,000   | difficult for residents to navigate with wheel chairs.  | \$       | 700,000                |
| 3        | 2) Damage              | A) Now           | DOC        | Clarinda DOC                             | Plaster ceiling in Kitchen<br>replacement                       | \$       | 125,000   | Safety of staff, offenders, unsanitary, demo out plaster and install new metal ceiling.   | \$       | 825,000                |
| 4        | 2) Damage              | A) Now           | DAS        | Capitol<br>Complex                       | Ola Babcock Miller Basement<br>Waterproofing                    | \$       | 600,000   | Excavate and waterproof foundation at Ola Babcock Miller Building to<br>eliminate mold and interior wall damage.<br>Basement egress windows are not properly closed and sealed; need  | \$       | 1,425,000              |
| F        |                        |                  |            | Iowa Veterans                            | Loftus Basement & Foundation                                    | ¢        | 75 000    | to be removed, refilled, tiled, and area backfilled to prevent water penetration. DIA issued a comment during annual inspection,  | ¢        | 4 500 000              |
| 5        | 2) Damage              | A) Now           | DVA        | Home                                     | Work<br>Replace roof covering on the                            | \$       | 75,000    | indicating this work needs completed to avoid a citation.<br>Composite shingle failure with leaks into the building interior causing  | \$       | 1,500,000              |
| 6        | 2) Damage              | A) Now           | DHS        | Clarinda MHI                             | Engine room Main building                                       | \$       | 85 000    | damage. Facility requests metal replacement.  | \$       | 1,585,000              |
| U        | 2) Damage              |                  |            | Capitol                                  | Remove and Reseal Windows at                                    |          |           | To avoid exponential damage to facility, exterior windows will need to<br>be removed and resealed properly to avoid water damage. These<br>recommendations are part of the window study conducted by Elite                              | Ŷ        | 1,000,000              |
| 7        | 2) Damage              | A) Now           | DAS        | Complex                                  | Oran Pape Building  | \$       | 207,438   | Glass and Metal company.  | \$       | 1,792,438              |
| 8        | 2) Damage              | A) Now           | DAS        | Capitol<br>Complex                       | Painting Capitol Building North and South Face Windows          | \$       | 1,138,350 | Maintenance painting of windows at the Capitol Building that were last done early to mid 1990's. Some wood sills are completely exposed wood.   | \$       | 2,930,788              |
| 9        | 2) Damage              | A) Now           | DCA        | Matthew Edel<br>Blacksmith<br>Shop House | Building envelope repairs                                       | \$       | 200 000   | Study done in 2012. Glass now falling out of windows.   | \$       | 3,130,788              |
| 0        | 2) Damage              | A) 110W          | DOA        |  |   | Ψ        | 200,000   | Frames are rusting through. Leaking occurs. Single glass pane   | Ψ        | 5,150,700              |
| 10       | 2) Damage              | A) Now           | DOC        | Mt. Pleasant                             | Window Replacement - East & Gym                                 | \$       | 750,000   | windows with cracks. Contains lead paint.<br>Previous MM project installed a temporary fix to get the facility  | \$       | 3,880,788              |
|          |                        |                  |            |  | WHTC Roof Replacement and                                       |          |           | through the winter months and evaluated options to correct the issues. New funding is needed to correct the issues. As of 3/13 the temporary fix was holding and it was not currently leaking. 9/14                                     |          |                        |
| 11       | 2) Damage              | A) Now           | DCA        | WHTC                                     | interior repair   | \$       | 450,000   | started leaking again.  | \$       | 4,330,788              |
| 40       |                        |                  |            | Iowa Veterans                            | Cheeler Duilding Tuel: Deinting                                 | ¢        | 75 000    |   | ¢        | 4 405 700              |
| 12<br>13 | 2) Damage<br>2) Damage | A) Now<br>A) Now | DVA<br>DHS | Home<br>Glenwood                         | Sheeler Building Tuck Pointing<br>Tuckpointing in Lacey Complex | \$<br>\$ |           | Tuck pointing needed to protect against moisture damage<br>Bricks falling off the façade.   | \$<br>\$ | 4,405,788<br>4,775,788 |
| 15       | 2) Damage              |                  |            |  |   | Ŷ        | 370,000   | Leaking. Facility thinks rain water is getting behind the EPDM liner<br>where it is attached to the posts on the railing of the widows walk.<br>They used roof caulk a few years ago to reseal them, will plan to do                    | φ        | 4,773,788              |
| 14       | 2) Damage              | A) Now           | DCA        | Montauk                                  | Main House Roof Replacement                                     |          |           | that again this fall and hope that it helps.  | \$       | 4,775,788              |
| 15       | 2) Damage              | A) Now           | DHS        | CCUSO                                    | Bathroom repair/redesign South 9<br>and South 6                 | \$       | 400,000   | Poor design is resulting in decay and rot of walls and floor from<br>showers. Also, population trends at CCUSO require more ADA<br>facilities for patients.<br>Repoint or seal all mortar joints in the turrets, chimneys, parapets and | \$       | 5,175,788              |
|          |                        |                  |            |  |   |          |           | water tables. Inspect and flashing and sealants and make repairs as   |          |                        |
| 16       | 2) Damage              | A) Now           | DOC        | ASP                                      | Tuckpointing priorities 1                                       | \$       | 400,000   |   | \$       | 5,575,788              |
| 17       | 2) Damage              | A) Now           | DHS        | CCUSO                                    | Secure Doors for South 6 and South 9                            | \$       | 30,000    | Security concern that patients could compromise and enter secure  | \$       | 5,605,788              |
|          | ,                      |                  |            | Capitol                                  | Oran Pape exterior drainage                                     |          | -,        | Design is estimated at \$10,000. When it rains hard (3-5 times a year)  |          | -,,0                   |
| 18       | 2) Damage              | A) Now           | DAS        | Complex                                  | improvement   |          |           | water enters the building from the exterior ground level.   | \$       | 5,605,788              |

|    |           |           |              |                 | ,                                     | Fui      | nding   |   |    |             |
|----|-----------|-----------|--------------|-----------------|---------------------------------------|----------|---------|---|----|-------------|
|    | Priority  | Immediacy | Agency       | Facility        | Project Title                         | Re       | quest   | Comments  | Ru | nning Total |
|    |           |           |              | -               | -                                     |          | -       | Flooring is cracked in several areas and is creating a trip/fall and      | T  | -           |
| 19 | 2) Damage | A) Now    | DHS          | Cherokee        | Replace flooring on North 9 ward      | \$       |         | sanitation issue.   | \$ | 5,685,788   |
| 20 | 2) Damage | A) Now    | DOC          | IMCC            | Admin Bldg Roof Replacement           | \$       | 76,202  | Replace existing roofing on the admin building                            | \$ | 5,761,990   |
|    |           | ,         |              |                 | 5                                     |          |         | Building interior was remodeled recently, but several of the windows      | Ţ, | -, - ,      |
| 21 | 2) Damage | A) Now    | DOC          | ICIW            | Replace Pharmacy Windows              | \$       |         | leak severely in driving rains. 12 windows in total.                      | \$ | 5,781,990   |
|    |           | ,         |              | Capitol         |                                       |          |         |   | Ţ, | -, - ,      |
| 22 | 2) Damage | A) Now    | DAS          | Complex         | Capitol West Drive Repair             | \$       | 300.000 | Repair broken pavers on Capitol West Drive.                               | \$ | 6,081,990   |
|    | ,         | / -       | -            |                 | Tuckpointing in Building 120 Phase    | •        |         |   | Ť  | -,,         |
| 23 | 2) Damage | A) Now    | DHS          | Glenwood        | <br>                                  | \$       | 660,000 |   | \$ | 6,741,990   |
|    | ,         | / -       | _            |                 |                                       | •        |         | No current citation. However, both systems are not in compliance          | Ť  | -,,         |
|    |           |           |              |                 |                                       |          |         | with requirements of Chapter 69. Continued use of the systems             |    |             |
|    |           |           |              |                 |                                       |          |         | under current wastewater loads is not recommended because of the          |    |             |
|    |           |           |              |                 |                                       |          |         | uncertainty of their condition and treatment effectiveness. Fayette       |    |             |
|    |           |           |              |                 |                                       |          |         | County could require the upgrade of the systems if a notice of            |    |             |
|    |           |           |              |                 |                                       |          |         | violation is issued. If the wastewater contribution to the existing       |    |             |
|    |           |           |              |                 |                                       |          |         | system is increased it may cause the systems to fail and cause a          |    |             |
| 24 | 2) Damage | A) Now    | DCA          | Montauk         | Montauk Septic Replacement            | \$       |         | surface discharge or a backup into the structure.                         | \$ | 6,841,990   |
| 27 | 2) Damage | A) NOW    | DOA          | Montaux         |                                       | Ψ        |         | Does not meet city compliance. Significant fines may be effective in      | Ψ  | 0,041,000   |
|    |           |           |              |                 |                                       |          |         | year 2014. Will require engineering. High sewer bills due to storm        |    |             |
| 25 | 2) Damage | A) Now    | DOC          | Mt. Pleasant    | Storm Water Separation                | \$       |         | water going thru sewer meter.   | \$ | 7,191,990   |
| 25 | 2) Damaye | A) NOW    | DOC          | IVIL. FIEdSalit |                                       | φ        |         | Evaluate the number of expansion joints , anchors and pipe guides         | φ  | 7,191,990   |
|    |           |           |              |                 |                                       |          |         | required to update and replace the current expansion joints on the 6"     |    |             |
|    |           |           |              |                 |                                       |          |         |   |    |             |
|    |           |           |              |                 |                                       |          |         | and 10" lines in the utility tunnels. The current expansion joints are no |    |             |
|    |           |           |              |                 |                                       |          |         | longer supported and the proper packing is no longer available.           |    |             |
|    |           |           |              |                 |                                       |          |         | There needs to be additional expansion joints added to eliminate the      |    |             |
|    |           |           |              |                 |                                       |          |         | deflection of the current piping . These steam leaks affect the integrity |    |             |
| 00 | 0) D      | A) N      | DUIO         |                 | Add and Replace Steam Expansion       | ¢        |         | of the tunnel, increase energy cost in lost steam, and creates a safety   |    | 7 004 000   |
| 26 | 2) Damage | A) Now    | DHS          | Glenwood        | Joints in Tunnel                      | \$       | 200,000 | hazard for the staff working in the tunnel.                               | \$ | 7,391,990   |
| 07 |           |           | DU IO        |                 | Renovate HVAC & Building              | •        |         |   | •  | 7 054 000   |
| 27 | 2) Damage | A) Now    | DHS          | Glenwood        | Envelope for Cottage #36              | \$       |         | Currently vacated, budget includes mold remediation.                      | \$ | 7,651,990   |
|    |           |           |              |                 |                                       |          |         | Design is estimated at \$9,000. During heavy rains water enters the       |    |             |
|    |           |           | <b>D</b> 4 0 | Capitol         | Historical Building exterior drainage |          |         | building causing damage. During the winter the lack of drainage           | •  | 7 054 000   |
| 28 | 2) Damage | A) Now    | DAS          | Complex         | improvement                           |          |         | causes water pooling on the side walk leading to a build up of ice.       | \$ | 7,651,990   |
|    |           |           |              |                 |                                       |          |         | CMS is the regulatory agency. The gym is the only large area where        |    |             |
|    |           |           |              |                 |                                       |          |         | clients/patients can gather. Recreation is critical to treatment and the  |    |             |
|    |           |           |              |                 |                                       |          |         | gym is an key in recreation. This also is used for sharing state          |    |             |
| ~~ |           |           | -            |                 | Replacing Cooling units/AC for MHI    | <u>^</u> |         | changes/information with the community regarding the facility in Mt.      |    |             |
| 29 | 2) Damage | A) Now    | DHS          | Mt. Pleasant    | gym                                   | \$       |         | Pleasant.   | \$ | 7,901,990   |
|    |           |           |              |                 |                                       |          |         | The tunnels located on the west side of cellhouse row is in dire need     |    |             |
|    |           |           |              |                 |                                       |          |         | of repair. Repairs have been made to the topside, however, the            |    |             |
|    |           |           |              |                 |                                       |          |         | underside is crumbling. As the tunnel could collapse, this is a           |    |             |
|    |           |           |              |                 |                                       |          |         | life/safety issue. The water, electrical, sewer & steam lines all run     |    |             |
|    |           |           |              |                 |                                       |          |         | through these tunnels and if they collapse, it will cause damage to all   |    |             |
|    |           |           |              |                 |                                       |          |         | of these items. Shoring and/or bracing these areas would not be           |    |             |
|    |           |           |              |                 |                                       |          |         | adequate to prevent a collapse. Although we try to limit the traffic on   |    |             |
| 30 | 2) Damage | A) Now    | DOC          | ISP             | Tunnel Project                        | \$       | 250,000 | this tunnel, it is the main transportation route to the cellhouses.       | \$ | 8,151,990   |
|    |           |           |              |                 | Replace Water Softeners at            |          |         |   |    |             |
| 31 | 2) Damage | B) <1 yr  | DOC          | ASP             | Powerhouse                            | \$       |         | Facility can't get parts when they break.                                 | \$ | 8,251,990   |
|    |           |           |              |                 | Roof Replacement – North Addition     |          |         | Patched multiple times. Membrane is pulling away at corners. Leaks        |    |             |
| 32 | 2) Damage | B) <1 yr  | DOC          | IMCC            | Lower Level                           | \$       | 785,000 | currently.  | \$ | 9,036,990   |
|    |           |           |              |                 |                                       |          |         |   |    |             |

|     |            |                 |        |               |  |    | nding   |  | _        |              |
|-----|------------|-----------------|--------|---------------|--|----|---------|--|----------|--------------|
|     | Priority   | Immediacy       | Agency | Facility      | Project Title                              | Re | quest   | Comments   | Rι       | Inning Total |
|     |            |                 |        |               |  |    |         | Water softeners are approx. ten years old and becoming very<br>problematic because the inside of the cast iron regeneration controls<br>is rotting away. They experience malfunctions due to diaphragm<br>rupture from rust cutting them during re-generation. Also rust travels<br>thru the controls and hangs up the control shutting off the water flow<br>period. This issue is even more serious if this occurs during the night<br>when the power house is not staffed. Ultimately this cuts off the flow<br>of domestic hot water campus wide and boiler make-up water which<br>eventually shuts the boiler down on low water alarm. Then someone<br>has to be called in to repair or by-pass them until repairs can be |          |              |
| 33  | 2) Damage  | B) <1 yr        | DHS    | Cherokee      | Replace Water Softeners                    | \$ | 120,000 |  | \$       | 9,156,990    |
| ~ . |            |                 |        | American      |  | •  |         |  |          |              |
| 34  | 2) Damage  | B) <1 yr        | DCA    | Gothic/Eldon  | Additional building envelope repairs       | \$ | 100,000 |  | \$       | 9,256,990    |
| 25  |            | D)              | DOC    | IMCC          | Roof Replacement – North Addition          | ¢  | 705 000 | Databad multiple times. Manshrana is pulling away at asymptot  | ¢        | 10,041,990   |
| 35  | 2) Damage  | B) <1 yr        | DOC    |               | Upper Level                                | \$ | 765,000 | Patched multiple times. Membrane is pulling away at corners.<br>Based on recommendations from forced main sewer line study. Have   | \$       | 10,041,990   |
|     |            |                 |        |               |  |    |         | been putting bandaids on the problem but if it breaks down   |          |              |
| 36  | 2) Damage  | B) <1 yr        | DOC    | Newton CF     | Repair pump station                        | \$ | 505 800 | completely, it will be a big issue. Project # 8713.00  | \$       | 10,547,790   |
| 00  | L) Dunlage | <i>D</i> / (1 ) | 200    |               |  | Ψ  | 000,000 | Door tracking system is extremely worn. Has been retro fitted. Car is  | Ť        | 10,011,100   |
|     |            |                 |        |               |  |    |         | past life expectancy. Does not have phase one fire recall.   |          |              |
| 37  | 2) Damage  | B) <1 yr        | DOC    | Mt. Pleasant  | Elevator C                                 | \$ | 220,000 | Schumacher has said it is now critical.  | \$       | 10,767,790   |
|     |            |                 |        |               |  |    |         | Evidence of water infiltration, concrete deterioration in areas where rebar is exposed. Not critical yet (7/2014), but could deteriorate   |          |              |
| 00  |            |                 |        | Ohanalaa      | Repair Main Building to Voldeng            | ¢  | F70 000 | quickly and be much more expensive to replace than repair. Voldeng   | <b></b>  | 44 007 700   |
| 38  | 2) Damage  | B) <1 yr        | DHS    | Cherokee      | Tunnel                                     | \$ |         | tunnel in slightly worse shape.<br>Evidence of water infiltration, concrete deterioration in areas where   | Э        | 11,337,790   |
| 39  | 2) Damage  | B) <1 yr        | DHS    | Cherokee      | Repair Main Building to Ginzberg<br>Tunnel | \$ |         | rebar is exposed. Not critical yet (7/2014), but could deteriorate quickly and be much more expensive to replace than repair.  | \$       | 11,870,790   |
|     | ý J        | , ,             |        |               | CRC - Training Center Roof                 |    |         |  | ľ        |              |
| 40  | 2) Damage  | B) <1 yr        | DOC    | Newton CF     | Replacement                                | \$ | 87,000  | Patch a couple of times a year, 10 years past expected life.   | \$       | 11,957,790   |
| 41  | 2) Damage  | B) <1 yr        | DOC    | Mt. Pleasant  | Tunnel Tops                                | \$ |         | Tunnel tops are rapidly deteriorating. All utilities are located in the tunnels. Tunnel top failure could result in disruption of utilities. This would be an ongoing project as not all tunnels would need to be replaced at the same time.   | \$       | 12,007,790   |
|     | _/ _ amage |                 | 200    |               |  | ÷  | 00,000  | Zero ventilation of air for the living units. Institution is not air   | Ŷ        | 12,001,100   |
| 42  | 2) Damage  | B) <1 yr        | DOC    | Mt. Pleasant  | Ventilation for East & West Housing        | \$ | 250,000 | conditioned so there are periodic mold issues.   | \$       | 12,257,790   |
|     |            |                 |        | Iowa Veterans |  |    |         | The concrete tunnel tops are breaking down allowing water  | 1        |              |
| 43  | 2) Damage  | B) <1 yr        | DVA    | Home          | Tunnel top Replacement                     | \$ | 250,000 | infiltration. Needs additional evaluation to finalize budget.  | \$       | 12,507,790   |
| 44  | 2) Damage  | B) <1 yr        | DHS    | Mt. Pleasant  | Replacement of Building 20 roof            | \$ | 300,000 | The roof has been patched and it is a constant patch following a rain.<br>The roofing material is shrinking and pulling away from the parapet<br>walls.  | \$       | 12,807,790   |
|     | _/ge       |                 |        |               |  | +  |         | Pipes require extensive repair and patching. This is a high client use   | Ť        |              |
| 45  | 2) Damage  | B) <1 yr        | DHS    | Glenwood      | Replace plumbing in Meyer Bldg             | \$ | 300,000 | building as it houses all of the GRC's vocational services.  | \$       | 13,107,790   |
| 46  | 2) Damage  | B) <1 yr        | DHS    | Glenwood      | Evaluate Water Mains and Shut-offs         | \$ |         | Need to evaluate to determine current condition of underground<br>water service lines and identify reason for lack of adequate water<br>delivery/pressure between water tower and booster station to<br>residential houses.  | \$       | 13,157,790   |
|     | /          |                 |        |               |  | Ŧ  | ·       | The roof is leaking and damaging the stored contents. The current shingles are asbestos and would need to be abated to replace with shingles. We are proposing to add a metal roof on top of the current   | <b>*</b> | ,            |
| 47  | 2) Damage  | B) <1 yr        | DHS    | Glenwood      | Replace roof on mule barn                  | \$ |         | shingles which would alleviate the need to abate.  | \$       | 13,232,790   |
|     |            |                 | 2      |               | Replace MSU Northcore &                    | *  |         | Rubber is deteriorating and has to be patched constantly. In addition, the rubber is pulling away from the corners. As a result, leaks are   | Ť        | . 0,202,100  |
| 48  | 2) Damage  | B) <1 yr        | DOC    | Mt. Pleasant  | Southcore roof                             | \$ |         | occurring and water has gone into the elevator shaft.  | \$       | 13,682,790   |

|            |             |            |             |                  | - · · · · · · · · · · · · · · · · · · ·                | F        | unding    | ,   |    |               |
|------------|-------------|------------|-------------|------------------|--|----------|-----------|---|----|---------------|
|            | Priority    | Immediacy  | Agency      | Facility         | Project Title  | R        | lequest   | Comments  | Ru | nning Total   |
|            |             |            |             |                  |  |          | <u>.</u>  | Our current towers, intended to be temporary, must be replaced.   |    | U             |
|            |             |            |             |                  |  |          |           | Current structure is post frame construction. They are structurally   |    |               |
|            |             |            |             |                  |  |          |           | compromised and have become unsafe. We evacuate in storms due to the lack of acceptable sheltering. Should a fire occur, the situation      |    |               |
|            |             |            |             |                  |  |          |           | becomes more serious as the wood is so very dry. The pipes freeze   |    |               |
|            |             |            |             |                  |  |          |           | every year, which requires officers to haul water for flushing toilets.   |    |               |
|            |             |            |             |                  |  |          |           | We supply hand wipes and bottled water for drinking. With these new   |    |               |
|            |             |            |             |                  |  |          |           | towers are also asking to include stationary camera in strategic  |    |               |
| 49         | 2) Damage   | B) <1 yr   |             |                  | Replace Two Towers                                     | \$       | 700,000   | areas with split screen monitoring in these two towers.   | \$ | 14,382,790    |
| 50         | 0) <b>D</b> |            |             | 6450 Corporate   |  | •        | 05 000    | <b>-</b>  | •  | = =           |
| 50         | 2) Damage   | B) <1 yr   | IPTV        | Dr               | repair roof  | \$       | 65,000    | To prevent ice damming on a rubber membrane roof; four openings   | \$ | 14,447,790    |
| <b>F</b> 4 | 0) D        |            |             | la den en den es | Reynolds Masonry Repair Phase                          | ¢        | 000 000   |   | ¢  | 4 4 0 4 7 700 |
| 51         | 2) Damage   | B) <1 yr   | DHS         | Independence     | 3B   | \$       | 200,000   |   | \$ | 14,647,790    |
| 50         | 2) Damage   | B) <1 yr   | DOC         | IMCC             | Tuckpointing R/S Housing Unit -<br>North & South Walls | \$       | 25 000    | To fix worst areas. Majority of domage is around windows  | ¢  | 14 670 700    |
| 52         | 2) Damaye   | Б) < 1 уі  | DOC         | INICC            | Tuckpointing R/S Housing Unit -                        | φ        | 25,000    | To fix worst areas. Majority of damage is around windows.   | \$ | 14,672,790    |
| 53         | 2) Damage   | B) < 1 vr  | DOC         | ІМСС             | West Wall  | \$       | 25 000    | To fix worst areas. Majority of damage is around windows.   | \$ | 14,697,790    |
| 55         | z) Damage   | D) < 1 yi  | DOC         | INICO            |  | Ψ        | 23,000    | 16 yrs. old – rubber membrane is dried out and pulling away from the  | Ψ  | 14,037,730    |
|            |             |            |             |                  |  |          |           | leading edge of the roof creating leaks into the space below - ongoing  |    |               |
| 54         | 2) Damage   | B) <1 vr   | DOC         | Ft Dodge CF      | Replace Unit A Roof                                    | \$       | 128.000   | repairs as leaks develop. (12,205 sq.ft.)   |    | 14,825,790    |
| 0.         | _) _ aage   |            | 200         | i i Dougo oi     |  | Ŧ        | 0,000     | 16 yrs. old – rubber membrane is dried out and pulling away from the  | Ŧ  | ,0_0,. 00     |
|            |             |            |             |                  |  |          |           | leading edge of the roof creating leaks into the space below - ongoing  |    |               |
| 55         | 2) Damage   | B) <1 yr   | DOC         | Ft Dodge CF      | Replace Cedar Unit Roof                                | \$       | 300,000   | repairs as leaks develop. (29,296 sq.ft.)   |    | 15,125,790    |
|            |             | , ,        |             |                  |  |          |           | 16 yrs. old - rubber membrane is dried out and pulling away from the  |    |               |
|            |             |            |             |                  |  |          |           | leading edge of the roof creating leaks into the space below - ongoing  |    |               |
| 56         | 2) Damage   | B) <1 yr   |             | Ft Dodge CF      | Replace Boone Unit Roof                                | \$       |           | repairs as leaks develop. (29,296 sq. ft.)  | \$ | 15,425,790    |
| 57         | 2) Damage   | B) <1 yr   | DOC         | IMCC             | Roof Replacement – North Link                          | \$       | 125,000   |   | \$ | 15,550,790    |
|            |             |            |             |                  |  |          |           | 16 yrs. old – rubber membrane is dried out and pulling away from the  |    |               |
|            |             |            |             |                  |  | •        |           | leading edge of the roof creating leaks into the space below - ongoing  |    |               |
| 58         | 2) Damage   | B) <1 yr   | DOC         | Ft Dodge CF      | Replace Floyd Unit Roof                                | \$       | 310,000   | repairs as leaks develop. (30,563 sq.ft.)   | \$ | 15,860,790    |
| 50         | 0) D        |            |             | Ohanalaa         | Waterproof top of Voldeng &                            | ¢        | E47 E00   | Both are pedestrian walkways inside and Voldeng tunnel is also a fire   | ¢  | 40.070.000    |
| 59         | 2) Damage   | B) <1 yr   | DHS         | Cherokee         | Ginzberg tunnels                                       | \$       | 517,500   |   | \$ | 16,378,290    |
|            |             |            |             |                  |  |          |           | 16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing |    |               |
| 60         | 2) Damage   | B) <1 yr   | DOC         | Ft Dodge CF      | Replace Grove Unit Roof                                | \$       | 300.000   | repairs as leaks develop. (29.296 sq.ft.)   | \$ | 16,678,290    |
|            |             | B) <1 yr   |             | Ft Dodge CF      | Replace Emmet Unit Roof                                | \$       |           | 14 yrs. old (26,480 sq.ft.)   | \$ | 16,948,290    |
|            |             | B) <1 yr   |             | Ft Dodge CF      | Replace Dolliver Unit Roof                             | \$       |           | 14 yrs. old (26,480 sq.ft.)   | \$ | 17,218,290    |
|            |             | B) <1 yr   | DHS         | Clarinda MHI     | Tuck pointing main building                            | \$       | 2,669.450 | Can be done in stages as before. 1/4 completed 2009, 3/4 remains  | \$ | 19,887,740    |
|            | _, _ =      |            |             |                  | · · · · · · · · · · · · · · · · · · ·                  | Ŧ        | _,,       | There is quite a bit of damage over the years, but repair of side walls   | Ŧ  | ,             |
|            |             |            |             | North Central    |  |          |           | will reinforce the utility lines for the operations. There is also asbestos   |    |               |
| 64         | 2) Damage   | B) <1 yr   |             | CF               | Repair of Tunnel                                       | \$       | 600,000   | in on through out tunnel area.  | \$ | 20,487,740    |
|            | · · · · ·   | , <b>,</b> |             |                  |  |          |           | Car is past life expectancy. Tracks are worn. Does not have phase   |    |               |
| 65         | 2) Damage   | C) > 1 yr  | DOC         | Mt. Pleasant     | Elevator D   | \$       |           | one fire recall.  | \$ | 20,707,740    |
|            |             |            |             |                  |  |          |           | IVH has repaired two recent sewer line breaks. The lines are aged   |    |               |
|            |             |            |             |                  |  |          |           | and allow either ground water infiltration or collapse. This increases  |    |               |
|            |             |            |             |                  |  |          |           | the sewage flowing into the treatment plant from this facility due to   |    |               |
|            |             |            |             | Iowa Veterans    |  |          |           | ground water, or allows sewage to flow on the ground until an   |    |               |
| 66         | 2) Damage   | C) > 1 yr  | DVA         | Home             | Sanitary Sewer Line Replacement                        | \$       | 310,000   | emergency repair can be arranged.   | \$ | 21,017,740    |
|            |             |            |             |                  |  |          |           | 2. Reseal all mortar joints and cracks on the walkways on top of  |    |               |
|            |             |            |             |                  |  |          |           | stonewalls.\$50,000.  |    |               |
| <b>6</b> 7 | 0) D        |            | <b>DO</b> O |                  |  | <b>^</b> |           | 3. Repair stone masonry and install new coping to the top of  | ¢  |               |
| 67         | 2) Damage   | C) > 1 yr  | DOC         | ASP              | Tuckpointing priorities 2 & 3                          | \$       | 100,000   | stonewall on the southwest corner of the south wall. \$40,000.  | \$ | 21,117,740    |

|                |           |           |                   |  | DRAFT Unfunded Majo   |                | unding                                | oject Requests Printed .   | 2/19     | /2015                                  |
|----------------|-----------|-----------|-------------------|--|---|----------------|---------------------------------------|--|----------|--|
|                | Priority  | Immediacy | Agency            | Facility   | Project Title   |                | equest                                | Comments   | Ru       | Inning Total                           |
| 68             |           | , ,       | DHS               |  | Tunnel repairs and replacement -<br>sections A to D (HR Green study)                              | \$             | 1,120,800                             | Tunnel system provides major utilities (steam, water, fiber, telephone, fire alarms). Tunnel failure would cause catastrophic damage to these systems.   | \$       | 22,238,540                             |
| 69             | 2) Damage | C) > 1 yr | DHS               | Cherokee   | Tuck pointing Phase 2.2<br>Tuck pointing in Building 120 Phase                                    | \$             | 360,000                               | Finish north side of main building.  | \$       | 22,598,540                             |
| 70             | 2) Damage | C) > 1 yr | DHS               | Glenwood   | Il  | \$             | 330,000                               |  | \$       | 22,928,540                             |
| 71<br>72<br>73 | 2) Damage | C) > 1 yr | DHS<br>DHS<br>DHS | Glenwood<br>Glenwood<br>WRC                          | Tuck pointing in Buildings 102<br>Tuck pointing in Buildings 110<br>Tunnel cap at Supply Building | \$<br>\$       | 280,000<br>85,000                     | Bricks are falling off the façade. 9/10/14 - 29C20 submitted for roof<br>leak due to storm; needs complete replacement. Bricks are falling<br>onto current roof, so should address current tuckpointing at same<br>time.<br>Below existing truck service road  | \$ \$ \$ | 23,208,540<br>23,293,540<br>23,443,540 |
| 74<br>75<br>76 | 2) Damage | C) > 1 yr | DHS<br>DHS<br>DHS | State Training<br>School - Eldora<br>Cherokee<br>WRC | Tunnel Top Sealing<br>Tuck pointing Phase 2.3<br>Tuck Point various buildings                     | \$<br>\$<br>\$ | 25,000<br>360,000                     | Seal top of tunnel system to prevent water infiltration and further deterioration<br>Finish south side of main building.<br>Westwood and larches and other areas   | \$ \$ \$ | 23,468,540<br>23,828,540<br>23,908,540 |
|                |           |           |                   | ASP  | Tuckpointing priorities 4, 5 &6   | \$             | , , , , , , , , , , , , , , , , , , , | <ol> <li>Repoint the defective mortar joints on the Administration Building.</li> <li>\$90,000.</li> <li>Repoint all mortar joints on the top half of stonewalls, tuckpoint only the defective mortar joint on the bottom half of the stonewalls.</li> <li>\$900,000</li> <li>Repoint all mortar joints 100% on the west wall on the school / store room / living unit E. \$90,000.</li> </ol>   | \$       | 24,988,540                             |
| 78             | 2) Damage | C) > 1 yr | DOC               | ASP  | Tuckpointing priorities 7, 8 &9   | \$             |                                       | 7.Secure the bulging stone on west wall of the old kitchen-dinning hall<br>and repoint all mortar joints 100% on the entire building. \$220,000<br>8.Repoint defective mortar joints, thirty-two feet on the west wall, sixty<br>feet on the east wall and all mortar joints above the windows on the<br>south wall of the Clothing, R&D and Custom Wood Building. \$ 60,000<br>9. Repoint all mortar joints on the east wall of the Living Unit A, Living<br>Unit C and Living Unit E and replace some eroded stone Repoint only<br>the defective mortar joints on the west inside walls. \$520,000<br>10. Repoint defective mortar on the south wall of Living Unit B and D. | \$       | 25,788,540                             |
| 79             | 2) Damage | C) > 1 yr | DOC               | ASP  | Tuckpoint priorities 10 & 11  | \$             | 825,000                               | <ul> <li>10. Repoint defective mortar on the south war of Living Onit B and D.</li> <li>\$375,000</li> <li>11. Repoint the defective mortar joints as needed on the Sign Shop,<br/>Commissary, Gymnasium, Maintenance Shop and Deputy's<br/>Office.\$450,000</li> </ul>  | \$       | 26,613,540                             |
| 80             | 2) Damage |           | DOC               | Newton CF  | Tuckpoint Dorms 1&2 (CRC)   | \$             | 60,000                                |  | \$       | 26,673,540                             |
| 81             | 2) Damage | C) > 1 yr | DHS               | Clarinda MHI   | Tunnel repair/replace main bldg to<br>SW Wing   | \$             |                                       | Was noted that tunnel was deficient and a serious threat of collapsing<br>on mechanical systems in the tunnel. No pedestrian use inside the<br>tunnel but heavy ped use on top as a walkway. Utility only inside.<br>However, in 2014 the facility said tunnel was not in bad shape.   | \$       | 27,843,140                             |
| 00             |           | 0. 1. 1.  |                   |  | Repair Historical Building Exterior   | ¢              | 4 074 000                             | Denois the outerion menito stars for a de  | ۴        | 00 747 440                             |
| 82             |           |           |                   | 6450 Corporate                                       | Walls Re-caulk joints between concrete  | \$             |                                       | Repair the exterior granite stone façade.<br>Roofing contractor advised IPTV to re-caulk the joints because<br>cracks in the caulk may be the cause of water leaks. Upon visual<br>inspection the caulking looks like it needs to be replaced. Caulking  | \$       | 29,717,140                             |
| 83             | 2) Damage | C) > 1 yr |                   |  | panels for the entire building<br>East Porch Newel Post and Spindle                               | \$             | 40,000                                | was last done prior to 1999 (we think 1996)  | \$       | 29,757,140                             |
| 84             | 2) Damage | C) > 1 yr | Terrace<br>Hill   |  | Repair  | \$             | 42,000                                | Rotting out supports; new foundation for posts (heaving)   | \$       | 29,799,140                             |

|     |           |                        |        |                 |                                    | F  | unding    |   |     |              |
|-----|-----------|------------------------|--------|-----------------|------------------------------------|----|-----------|---|-----|--------------|
|     | Priority  | Immediacy              | Agency | Facility        | Project Title                      | R  | lequest   | Comments  | Ru  | Inning Total |
|     |           |                        |        |                 |                                    |    |           |   | ĺ   |              |
|     |           |                        |        | State Training  |                                    |    |           |   | l   |              |
| 85  | 2) Damage | C) > 1 yr              | DHS    | School - Eldora | Kitchen Tuck pointing              | \$ | 75,000    | Building exteriors is in critical need of tuck pointing repairs           | \$  | 29,874,140   |
|     |           |                        |        |                 |                                    |    |           | Leak has been repaired, but the material is breaking down and is not      | İ   |              |
|     |           |                        |        |                 | Replace Administration Building    |    |           | bonded in place. Drainage issues. New estimate Aug 2012. Estimate         | Ì   |              |
| 86  | 2) Damage | C) > 1 yr              | DHS    | Glenwood        | Roof                               | \$ | 175,000   | does not include A & E, PM or CM costs.                                   | \$  | 30,049,140   |
| 87  | 2) Damage | C) > 1 yr              | DHS    | Glenwood        | Tuck pointing in Building 116      | \$ | 40,000    |   | \$  | 30,089,140   |
|     |           |                        |        |                 |                                    |    |           | Tunnel system provides major utilities (steam, water, fiber, telephone,   | Í   |              |
|     |           |                        |        | State Training  | Tunnel repairs and replacement -   |    |           | fire alarms). Tunnel failure would cause catastrophic damage to           | Ì   |              |
| 88  | 2) Damage | C) > 1 yr              | DHS    | School - Eldora | sections E to J (HR Green study)   | \$ | 957,200   | these systems.  | \$  | 31,046,340   |
|     |           |                        |        |                 |                                    |    |           | Need to address water infiltration in one section but rest of bldg can    | Í   |              |
| 89  | 2) Damage | C) > 1 yr              | DHS    | Glenwood        | Tuck pointing in Building 119      | \$ | 180,000   |   | \$  | 31,226,340   |
|     |           |                        |        |                 |                                    |    |           | Tunnel system provides major utilities (steam, water, fiber, telephone,   | İ   |              |
|     |           |                        |        | State Training  | Tunnel repairs and replacement -   |    |           | fire alarms). Tunnel failure would cause catastrophic damage to           | i   |              |
| 90  | 2) Damage | C) > 1 yr              | DHS    | School - Eldora | sections K to N (HR Green study)   | \$ | 1,152,500 | these systems.  | \$  | 32,378,840   |
|     |           |                        |        |                 |                                    |    |           | MPCF requested this project be added back to the list. Frame are          | İ   |              |
|     |           |                        |        |                 |                                    |    |           | rusting through and leaking occurs. Single glass panes are cracked        | Ì   |              |
| 91  | 2) Damage | C) > 1 yr              | DOC    | Mt. Pleasant    | Window Replacement - West          | \$ | 700,000   | and paint contains lead.  | \$  | 33,078,840   |
|     |           |                        |        |                 |                                    |    |           | 16 yrs. old - rubber membrane is dried out and pulling away from the      | ĺ   |              |
|     |           |                        |        |                 |                                    |    |           | leading edge of the roof creating leaks into the space below - ongoing    | i   |              |
| 92  | 2) Damage | C) > 1 yr              | DOC    | Ft Dodge CF     | Replace Power Plant Roof           | \$ |           | repairs as leaks develop. (10,392 sq.ft.)                                 |     | 33,188,840   |
|     |           | , ,                    |        | Ŭ               |                                    |    |           | 16 yrs. old – rubber membrane is dried out and pulling away from the      | l İ | ,,           |
|     |           |                        |        |                 |                                    |    |           | leading edge of the roof creating leaks into the space below - ongoing    | i   |              |
| 93  | 2) Damage | C) > 1 yr              | DOC    | Ft Dodge CF     | Replace Warehouse Roof             | \$ |           | repairs as leaks develop. (8,756 sq. ft.)                                 |     | 33,278,840   |
| ••• |           | <i>cy</i> · · <i>y</i> |        |                 |                                    | Ŧ  | ,         | 16 yrs. old – rubber membrane is dried out and pulling away from the      | ÌŤ  | 00,210,010   |
|     |           |                        |        |                 |                                    |    |           | leading edge of the roof creating leaks into the space below - ongoing    | i   |              |
| 94  | 2) Damage | C) > 1 yr              | DOC    | Ft Dodge CF     | Replace Administration Roof        | \$ |           | repairs as leaks develop. (7,700 sq.ft.)                                  |     | 33,358,840   |
| 04  | 2) Damage | 0) × 1 yi              | 200    | T t Dougo of    |                                    | Ψ  | 00,000    | 14 yrs. old - skylight flashing continues to leak into building - ongoing | ΙΨ  | 33,330,040   |
| 95  | 2) Damage | C) > 1 yr              | DOC    | Ft Dodge CF     | Replace Education Roof             | \$ | 200.000   | repairs as leaks develop. (19,399 sq.ft.)                                 | \$  | 33,558,840   |
| 00  | 2) Damage | 0) > 1 yi              | 200    | T t Dougo of    |                                    | Ψ  | 200,000   |   | ſŤ  | 00,000,040   |
|     |           |                        |        |                 |                                    |    |           | System is partially functioning. Prone to refrigerant leaking.            | i   |              |
|     |           |                        |        |                 |                                    |    |           | Equipment is 20+ years old. A temporary fix was made in July 2014         | i   |              |
| 96  | 2) Damage | C) > 1 yr              | DOC    | Mt. Pleasant    | Northcore Air Conditioning Unit    | \$ |           | so the new equipment/repairs should last for a couple more years.         | ¢   | 33,708,840   |
| 90  | z) Damaye | C) > 1 yi              | DOC    | Capitol         | Repair Existing Pedestrian Tunnel  | ę  | 130,000   | To water proof the existing tunnel and to bring it up to all Building and | Ψ   | 55,700,040   |
| 97  |           | () > 1 vr              | DAS    |                 | between Lucas and the Capitol      | ¢  | 6 527 482 | Fire Codes.   | ¢   | 10 226 222   |
| 97  | 2) Damage | C) > 1 yr              | DAS    | Complex         | between Lucas and the Capitol      | \$ |           | Project funded, designed, and bid in 2010, but placed on "hold" since     | \$  | 40,236,322   |
| 00  |           | () $()$                | DOC    | ASP             | Loundry Doof Donlocomont           | ¢  |           |   | ¢   | 40 496 222   |
| 98  | 2) Damage | C) > 1 yr              | DOC    | ASP             | Laundry Roof Replacement           | \$ | 250,000   | bid was over budget . Laundry roof is now shot and leaking.               | Э   | 40,486,322   |
|     |           |                        |        |                 |                                    |    |           | Both roofs have been damaged from storms and winter weather               | i i |              |
|     |           |                        |        |                 |                                    |    |           | conditions, there are missing shingles and there has been leaks           | i i |              |
|     |           |                        |        |                 |                                    |    |           | periodically throughout the last four years. The gutters are in need of   | i i |              |
|     |           |                        |        |                 |                                    |    |           | replacement and fascia boards are damaged. We are requesting              | i i |              |
|     |           |                        |        |                 |                                    |    |           | funds to be approved while the other 7 roofs inside the secure            | i i |              |
|     |           |                        |        |                 |                                    |    |           | perimeter are being reroofed with current funds. We are hoping to         | i i |              |
|     |           |                        |        |                 |                                    |    |           | complete all buildings inside the perimeter to avoid any future request   | i i |              |
|     |           |                        |        | North Central   | Roof Project Replacement of        |    |           | for 20 years. Per CM in June 2014 the roofs could last another 5          | Ι.  |              |
| 99  | 2) Damage | C) > 1 yr              | DOC    | CF              | Treatment Bldg. and Control Center | \$ | 45,000    |   | \$  | 40,531,322   |
|     |           |                        |        |                 |                                    |    |           | High security glass in the control center is delaminating. This glass     | i   |              |
|     |           |                        |        |                 |                                    |    |           | and the bars on the windows is all that separates control center staff    | i   |              |
|     |           |                        |        |                 | Replace delaminated glass in       |    |           | from the main yard. Manufacturer feels that the integrity isn't           | i   |              |
| 100 | 2) Damage | C) > 1 yr              | DOC    | Ft Dodge CF     | Master Control Center              | \$ | 20,000    | compromised yet, but may be in a few years.                               | \$  | 40,551,322   |
|     |           |                        |        |                 |                                    |    |           |   | i   |              |
|     |           |                        |        | Centennial      |                                    |    |           | This elevator has had several engineering studies and was prioritized     | i   |              |
|     |           |                        |        | Building, Iowa  |                                    |    |           | under ADA funding. The elevator was recently cited by Workforce           | i   |              |
| 101 | 3) ADA    | A) Now                 | DCA    | City            | Elevator Replacement               | \$ | 300,000   | Development as being non-compliant and it skips one stop.                 | \$  | 40,851,322   |
|     |           |                        |        | -               |                                    |    |           |   |     |              |

|     |              |           |        |                |                                     |    | Funding   | <b>,</b>   |     |              |
|-----|--------------|-----------|--------|----------------|-------------------------------------|----|-----------|--|-----|--------------|
|     | Priority     | Immediacy | Agency | Facility       | Project Title                       | F  | Request   | Comments   | Rι  | Inning Total |
|     |              |           |        |                |                                     |    |           | Needed for elderly patients and med clinic. Currently non-ambulatory     | I   |              |
|     |              |           |        |                | ADA compliant restrooms for S1      |    |           | patients are taken through the food service area to use an ADA           |     |              |
| 102 | 3) ADA       | A) Now    | DHS    | CCUSO          | and S2 wards                        | \$ | 250,000   | compliant restroom on another ward.                                      | \$  | 41,101,322   |
|     |              |           |        |                | Voldeng Building Elevator and       |    |           |  | 1   |              |
| 103 | 3) ADA       | A) Now    | DHS    | Cherokee       | Lobby Area Remodel                  | \$ | 750,000   | Improvements to accommodate ADA  | \$  | 41,851,322   |
|     |              |           |        |                |                                     |    |           | Cannot achieve Correctional Education Accreditation until this is        | Ī   |              |
| 104 | 3) ADA       | A) Now    | DOC    | ASP            | Access to School and Library        | \$ | 98,000    | addressed, but can provide services through other means.                 | \$  | 41,949,322   |
|     |              |           |        |                |                                     |    |           | Lifts currently in place (main building and Ginzberg) fail regularly. At | Ī   |              |
|     |              |           |        |                |                                     |    |           | least three times in the last year we've had handicapped people stuck    |     |              |
| 105 | 3) ADA       | A) Now    | DHS    | Cherokee       | Redesign handicap entrances         |    |           | on the lifts. Would prefer a non-mechanical solution.                    | \$  | 41,949,322   |
|     |              |           |        |                |                                     |    |           | Interior ramp needs to be redesigned to comply with 2010 ADA             | T   |              |
|     |              |           |        |                |                                     |    |           | Standards for Accessible Design. Adjustments are required for            |     |              |
|     |              |           |        |                |                                     |    |           | slope, distance, and level to assure resident safety. Preliminary        |     |              |
|     |              |           |        |                |                                     |    |           | estimate in range of \$500,000. Ramp is very steep and the facility      |     |              |
|     |              |           |        |                |                                     |    |           | has installed bumpers at the bottom facing wall and assigned staff to    |     |              |
|     |              |           |        | Iowa Veterans  |                                     |    |           | watch the ramp. Governor recommended for FY17 Capitals.                  |     |              |
| 106 | 3) ADA       | A) Now    | DVA    | Home           | Loftus Resident Ramp                | \$ | 500,000   | Reconsider if not funded.  | \$  | 42,449,322   |
|     |              |           |        | North Central  | ·                                   |    |           |  | İ.  |              |
| 107 | 3) ADA       | B) <1 yr  | DOC    | CF             | Education Bldg. Ramp ADA            | \$ | 6,000     | Access to the Education bldg for disable persons / HS                    | \$  | 42,455,322   |
|     |              | · · ·     |        |                |                                     |    |           | Restrooms do not comply with ADA regulations. There is poor              | 1   |              |
|     |              |           |        |                | Remodel/Renovate restroom &         |    |           | exhaust resulting in mold issues. There are also safety concerns with    |     |              |
| 108 | 3) ADA       | C) > 1 yr | DHS    | Mt. Pleasant   | shower on living units of #20 bldg  | \$ | 1,645,360 | the slick flooring.  | \$  | 44,100,682   |
|     |              | , ,       |        | North Central  | <u> </u>                            |    |           | 5  | † Ť | , ,          |
| 109 | 3) ADA       | C) > 1 yr | DOC    | CF             | Replace Non-Standard Walks ADA      | \$ | 60.000    | Widening of current main sidewalk on inside perimeter                    | \$  | 44,160,682   |
|     | 0//12/1      | C/ F 1 J1 |        |                |                                     | Ť  | 00,000    |  | Ť   | ,            |
| 110 | 4) Scheduled | A) Now    | DOC    | Mt. Pleasant   | Parking lots NE and SE              | \$ | 95.000    | The lots are in very bad shape and the area is so large.                 | \$  | 44,255,682   |
|     | .,           | ,         |        |                |                                     | +  | ,         | Proper spill containment needed for 70,000 gallon diesel tank.           | Ť   | ,_00,00      |
| 111 | 4) Scheduled | A) Now    | DOC    | Mt. Pleasant   | Spill Containment for diesel tank   | \$ | 75,000    |  | \$  | 44,330,682   |
|     | .,           | ,         |        |                |                                     | Ť  | ,         | The fence is becoming wavy and we need cement under the fencing.         | Ť   | .,           |
| 112 | 4) Scheduled | A) Now    | DOC    | Mt. Pleasant   | Perimeter Fence                     | \$ | 1,000,000 |  | \$  | 45,330,682   |
|     | .,           | ,         |        |                |                                     | +  | .,,       | All of Elevator equipment is original equipment. The Lucas Building      | Ť   | .0,000,000   |
|     |              |           |        | Capitol        | Replace Lucas Building Elevators    |    |           | had 56 service calls for not being in operation with 4 entrapment        |     |              |
| 113 | 4) Scheduled | A) Now    | DAS    | Complex        | 1,2,3,4 & 5                         | \$ | 1,827,840 |  | \$  | 47,158,522   |
|     | .,           | ,         |        |                |                                     | +  | .,==.,=   | The penthouse roof is past its life expectancy, the membrane is          | Ť   | ,            |
|     |              |           |        |                |                                     |    |           | shrinking and the loose ballast has been eroded and is being blown       |     |              |
|     |              |           |        | Capitol        |                                     |    |           | off the roof. Underside of roof deck coated with a spray-on fire         |     |              |
| 114 | 4) Scheduled | A) Now    | DAS    | Complex        | Replace Grimes Penthouse Roof       | \$ | 128,000   | proofing that contains asbestos.   | \$  | 47,286,522   |
|     |              |           | 2/10   | Complex        |                                     | Ψ  | 120,000   | Equipment is at the limit of its usable lifetime, has never worked       | Ψ   | 47,200,022   |
| 115 | 4) Scheduled | A) Now    | DPS    | Post 12        | New HVAC & Controls                 | \$ | 250,000   |  | \$  | 47,536,522   |
|     | .) concatica | .,        |        |                |                                     | Ŷ  | 200,000   | The roofing membrane on all of these section has shrunk and has          | Ť   | 11,000,022   |
|     |              |           |        |                |                                     |    |           | pulled away from the parapet walls, and starting to pull the parapet     |     |              |
|     |              |           |        | Capitol        | Jessie Parker Building, Sections E, |    |           | walls in ward. Penthouses need tuck pointing and sealed, along with      |     |              |
| 116 | 4) Scheduled | A) Now    | DAS    |                | F, G, H Roof Replacement            | \$ | 565 000   | the exterior perimeter walls below the roof coping.                      | \$  | 48,101,522   |
| 110 |              | 7.91.000  | 0/10   |                |                                     | Ψ  | 000,000   | We have four roof top units at 6535. They are over 15 years old.         | Ψ   | 40,101,022   |
|     |              |           |        | 6535 Corporate |                                     |    |           | We need to start replacing them. This is a request to replace one of     |     |              |
| 117 | 4) Scheduled | A) Now    | IPTV   | Dr             | Replace roof top unit at 6535       | \$ | 60,000    | the four.  | \$  | 48,161,522   |
|     |              |           |        |                |                                     | Ψ  | 00,000    | The Lucas Building's roots are 14 years old. These roots are a Fully     | Ψ   | 40,101,522   |
|     |              |           |        |                |                                     |    |           | Adhered TPO Reinforced Membrane System. The Main section of              |     |              |
|     |              |           |        |                |                                     |    |           | this roof has had a lot of wind damage over the years, so they have      |     |              |
|     |              |           |        | Capitol        |                                     |    |           | installed 24" X 24" concrete pavers over the entire roof on 6 foot       |     |              |
| 118 | 4) Scheduled | A) Now    | DAS    | Complex        | Replace Lucas Building Roof         | \$ | 648,960   | ·  | \$  | 48,810,482   |
|     | ., concautou |           | 27.0   |                |                                     | Ť  | 0.000     | Replace AHU, connect cooling coils to the Central Energy Plant           | Ť   | .0,010,702   |
|     |              |           |        | Capitol        |                                     |    |           | chilled water loop, duct work, VAV and direct digital controls. All      |     |              |
| 110 | 4) Scheduled | A) Now    | DAS    | Complex        | Jessie Parker HVAC Renovations      | \$ | 8 331 802 | existing equipment is past its life expectancy.                          | \$  | 57,142,374   |
| 119 | T) Scheduled |           | 070    | Complex        |                                     | Ψ  | 0,001,092 | Johisting equipment is past its life expectation.                        | ĮΦ  | 51,142,514   |

| Priority         Immediate         Agency         Facility         Project Title         Request         Comments         Request difference         Comments         Resulting is the object of digital control.<br>All existing optimits pass the ife exocutancy. The equipment is<br>building with audion is the object of digital control.<br>All existing optimits pass the ife exocutancy. The equipment is<br>building with audion is the object of digital control.         S         65,189,894           120         4) Scheduled Al Now         DAS         Complex         Replace Condensate tanks in the turned at Walance and the Capital<br>applices this equipment.         S         65,538,620           121         4) Scheduled Al Now         DAS         control         S         80,202.000         For is long up and makes it slick to walk across.         S         65,538,620           123         4) Scheduled Al Now         DAC         colorer         Figure and the control of a sting up and makes it slick to walk across.         S         65,574,620           124         4) Scheduled Al Now         DAC         ICIW         Replace Condensate tanks in the turned in the turned at walance and the control on turned across and turned transmite and converts to 10 gauge boiler tubes.         S         65,774,620           124         4) Scheduled Al Now         DAC         ICIW         Replace Control Center         S         65,774,620           124         6) Scheduled Al Now </th <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th> </th> <th>Funding</th> <th></th> <th></th> <th></th>   |     |              |   |        |               |                                |    | Funding   |  |    |              |
|---|-----|--------------|---|--------|---------------|--------------------------------|----|-----------|--|----|--------------|
| No.         DAS         Complex         WD HVAC Renovations         S         8.021(s) g the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, which dud work ends to building is the original dud dut AH, MV, and AB.         \$ 65,986,629           12         4) Schedulet A) Now         DAS         towal Labs         Coder Mudification         \$ 00,000 floor is ion; and most as its building reasons the original dud dut AH, MV, and AB.         \$ 65,986,629           12         4) Schedulet A) Now         DAS         towal Labs         Coder Mudification         \$ 10,000         Replace codocter system         \$ 65,786,629           12         4) Schedulet A) Now         DAS         towal Labs         Coder Mudification         \$ 11,000         Replace chast purps in tomic controls         \$ 65,786,629           12         4) Schedulet A) Now         DAC         Toriginal mode state system         \$ 65,786,629         \$ 65,786,629           12         4) Schedulet A) Now         DAC         Toriginal mode state system         \$ 65,786,629         \$ 74,7629   |     | Priority     | Immediacy                               | Agency | Facility      | Project Title                  | l  | Request   | Comments   | R  | unning Total |
| 12         4) Scheduled         New         DAC         Capital<br>Capital         WD HVAC Renovations         5         6.027.00         Deligibior the square methan has a laid to work on or<br>Gapital         5         6.027.00         Complex         5         6.027.00         State  |     |              |   |        |               |                                |    |           | All existing equipment is past its life expectancy. The equipment in this building is the original dual duct AHU, with chilled water and hot   |    |              |
| 120 4) Scheduled A) New       DAS       Complex       WD FWAC Renovations       \$             8.027,800 Feplace tanks   |     |              |   |        | Capitol       |                                |    |           |  |    |              |
| 121       4) Scheduled A) New       DAS       Complex       Replace Condensate tanks       \$             368,665       Condensate tanks in the tunnel at Wallace and the Capital<br>Replace cooler flooring as it has buckled and relocate condensing<br>units to the exterior of the building to coller and makes it subt to wask access.       \$             66,538,629         122       4) Scheduled A) New       DAS       towe Labs       Cooler Modification       \$             60,000       for septer cooler flooring as it has buckled and relocate condensing<br>units to the exterior of the building to coller and makes it subt to wask access.       \$             66,538,629         123       4) Scheduled A) New       DOC       File Panel Upgrade       \$             15,000       Replace base pumps in both control centers       \$             66,748,629       \$             66,748,629       \$             66,774,629 <td< td=""><td>120</td><td>4) Scheduled</td><td>A) Now</td><td>DAS</td><td></td><td>IWD HVAC Renovations</td><td>\$</td><td>8,027,590</td><td></td><td>\$</td><td>65,169,964</td></td<>   | 120 | 4) Scheduled | A) Now                                  | DAS    |               | IWD HVAC Renovations           | \$ | 8,027,590 |  | \$ | 65,169,964   |
| 121       4) Scheduled A) Now       DAS       Complex       Replace Condensate tanks in the turnel at Wallace and the Capitol       \$       65.58.623         122       4) Scheduled A) Now       DAS       Lowa Labs       Cooler Modification       \$       60.000       floor is iscing up and makes islick to walk across.       \$       65.598.623         123       4) Scheduled A) Now       DOC       F1 bodge CF       Fire Panel Upgrade       \$       150.000       Replace coolers is table to building for easier maintenance. The metal       \$       65.598.623         124       4) Scheduled A) Now       DOC       F1 bodge CF       Fire Panel Upgrade       \$       150.000       Replace coolers is table to building for easier maintenance. The metal       \$       65.762.623         125       4) Scheduled A) Now       DOC       CIW       Reprovate Segregation Unit HVAC       Panding system meets to be building to replace tobes inside bolier #1 and #2, at an       North Central       North Central       North Central       North Central       North Central       S       65.832.623         126       4) Scheduled A) Now       DOC       Complex       Repace Linit & S       90.000       Rocklar to last #3 f50.000       S       65.832.623         127       4) Scheduled A) Now       DOC       C       Renovate 2 Boliers       \$   |     | ,            | ,                                       |        |               |                                |    |           |  | 1  |              |
| 122       4) Scheduled (A) Now       DAS       Iowa Labs       Coder Modification       \$  | 121 | 4) Scheduled | A) Now                                  | DAS    |               | Replace Condensate tanks       | \$ | 368,665   | Condensate tanks in the tunnel at Wallace and the Capitol  | \$ | 65,538,629   |
| 122       4) Scheduled Å) Now       DAS       Iowa Labs       Cooler Modification       \$       60.000       Robinson       \$       65,088,029         123       4) Scheduled Å) Now       DOC       Fit Dodge CF       Fire Panel Upgrade       \$       150,000       Replace obsolete system       \$       65,748,629         124       4) Scheduled Å) Now       DOC       ICIW       Replace Unit 9 Ontrol Centers       \$       140000       Replace heat pumps of not on toric otherers       \$       65,774,629         125       4) Scheduled Å) Now       DOC       ICIW       Reprised Difference       \$       12000       North Central       Replace heat pumps of not on centre is on othere it not control centers       \$       65,774,629         125       4) Scheduled Å) Now       DOC       CF       Repare parking lot       \$       90,000       Rocktar for last resurfaced in 1999       \$       65,832,629         126       4) Scheduled Å) Now       DPS       Pleasant       Repare parking lot       \$       90,000       Rocktar for last resurfaced in 1999       \$       65,832,629       \$       65,832,629       \$       66,832,629       \$       65,832,629       \$       65,832,629       \$       65,832,629       \$       65,832,629       \$       65,832,629       <  |     |              |   |        |               |                                |    |           |  | Ì  |              |
| 124       4) Scheduled A) Now       DOC       ILW       Replace Unit 9 Control Centers       \$ <ul> <li>14,000</li> <li>Replace Hat pumps in both control centers</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Second setting control centers</li> <li>Second setting control centrol centol control tend sexing cooting colis in thea</li></ul>   | 122 | 4) Scheduled | A) Now                                  | DAS    | Iowa Labs     | Cooler Modification            | \$ | 60,000    |  | \$ | 65,598,629   |
| 124       4) Scheduled A) Now       DOC       ILW       Replace Unit 9 Control Centers       \$ <ul> <li>14,000</li> <li>Replace Hat pumps in both control centers</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system needs to be balanced and the unit control center</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Alr handling system control centers. System condensates and dumps water</li> <li>Second setting control centers</li> <li>Second setting control centrol centol control tend sexing cooting colis in thea</li></ul>   | 123 | 4) Scheduled | A) Now                                  | DOC    | Et Dodge CE   | Fire Panel Upgrade             | \$ | 150 000   | Replace obsolete system  | \$ | 65 748 629   |
| 124       4) Scheduled A) New       DOC       ICIW       Heat Pumps       \$       14,000       Replace heat pumps in both control centers needs as separate heat pumps of inchemicals are discharged it dees not enter the control centers on the method start discharged it dees not enter the control centers. System condensates and dumps yater resets the control centers. System condensates and dumps yater resets the control centers. System condensates and dumps yater resets the control centers. System condensates and dumps yater resets to be balanced.       \$       6,774,629         126       4) Scheduled A) Now       DOC       CF       Renovate 2 Boilers       \$       5,0000       estimate on the control centers. System condensates and dumps yater reset for the control centers. System condensates and dumps yater reset for the control centers. System condensates and dumps yater reset for the control centers. System condensates and dumps yater reset for the control centers. System condensates and dumps yater reset for the control centers. System condensates and dumps yater reset for the condition of the leaking proting or the control. The condition of the leaking proting or the control tens to control. The condition of the leaking proting or the control tens to control. The condition of the leaking proting or the control tens condition of the leaking proting or the control tens to control. The control tens condition of the leaking proting or the control tens to control. The condition of the leaking proting or the control tens to control. The condition of the leaking proting or the control tens to control. The control tens control tens control tens control tens control tens control tens control tens control tens control tens control tens control tens control tens contresting costam tens the conthand tens to control. The c  | 120 | i) Conoduiod | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | 200    | r t Dougo or  |                                | Ψ  | 100,000   |  | Ψ  | 00,140,020   |
| Ar handling system needs to be balanced and the unit control center<br>needs as exparate heat pumps of rhemicals and discharged it does<br>not enter the control center. System condensates and dumps water<br>in the floor.         S         65,774,629           125         4) Scheduled A) Now         DOC         ICIW         system         S         120,000 on the floor.         Need tube replacement and convert to 10 gauge bolier fubes.<br>Annually, we continue to replace tubes inside bolier #1 and #2, at an<br>estimated cost of at least \$15,000.         \$         65,832,629           127         4) Scheduled A) Now         DPS         Pleasant         Renovate 2 Boliers         \$         90,000         Rechviter to tast resurfaced in 1999         \$         65,832,629         \$         5         65,922,629         \$         65,922,629         \$         5         65,922,629         \$         5         65,922,629         \$         5         65,922,629         \$         5         52,922,629         \$         7,33,95,626         \$         7,33,976,654         \$         7,33,976,654         \$         7,33,976,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$         7,38,76,654         \$  | 124 | 4) Scheduled | A) Now                                  | DOC    | ICIW          |                                | \$ | 14.000    | Replace heat pumps in both control centers   | \$ | 65.762.629   |
| 125         4)         Scheduled         A) Now         DCC         ICIW         System         S         12,000         mot enter the control center.         System condensates and dumps water         S         5,774,629           126         4)         Scheduled         A) Now         DCC         ICIW         System         North Central         North Central         North Central         North Central         North Central         North Central         Scheduled         A) Now         DPS         Pleasant         Repaye parking lot         S         90,000         Rock/tar tot last resurfaced in 1999         Scheduled         Scheduled         A) Now         DPS         Pleasant         Repaye parking lot         S         90,000         Rock/tar tot last resurfaced in 1999         Scheduled         Scheduled         A) Now         DPS         Capitol         Capitol <td< td=""><td></td><td>.,</td><td></td><td></td><td></td><td></td><td>Ŧ</td><td>- ,</td><td>Air handling system needs to be balanced and the unit control center</td><td></td><td>,,</td></td<>   |     | .,           |   |        |               |                                | Ŧ  | - ,       | Air handling system needs to be balanced and the unit control center   |    | ,,           |
| 125       4) Scheduled A) Now       DCC       ICIW       system       \$ 12,000       on the floor.       \$ 65,774,629         126       4) Scheduled A) Now       DCC       CF       Renovate 2 Boilers       \$ 58,000       estimated cost of at least \$15,000.       \$ 65,82,629         127       4) Scheduled A) Now       DPS       Pleasant       Repave parking lot       \$ 90,000       Rocktar lot last sufficience       \$ 65,922,629         128       4) Scheduled A) Now       DPS       Pleasant       Repave parking lot       \$ 90,000       Rocktar lot last resurfaced in 1999       \$ 65,922,629         128       4) Scheduled A) Now       DAS       Complex       Grimes Building HVAC Updates       \$ 7,7385,897       Pa capital request.       \$ 73,308,526         129       4) Scheduled A) Now       DAS       Complex       Grimes Building HVAC Updates       \$ 7,885,897       Pa capital request.       \$ 73,308,526         129       4) Scheduled A) Now       DAS       Complex       Replacement       \$ 568,328       Difficult to maintain cooling in summer heat.       \$ 73,308,526         130       4) Scheduled A) Now       DHS       CCLUC       karcha cupt start start sufface in 1999       \$ 74,266,854         131       4) Scheduled A) Now       DHS       CCLUCS       Karcha cu   |     |              |   |        |               | Renovate Segregation Unit HVAC |    |           |  |    |              |
| Image: state of the s | 125 | 4) Scheduled | A) Now                                  | DOC    | ICIW          |                                | \$ | 12,000    |  | \$ | 65,774,629   |
| 126       4) Scheduled A) Now       DC       CF       Renovate 2 Boilers       \$ 58,000       stimated cost of at least \$15,000.       \$ 65,832,629         127       4) Scheduled A) Now       DPS       Pletasant       Repave parking lot       \$ 90,000       Rock/tar lot last resurfaced in 1999       \$ 65,832,629         128       4) Scheduled A) Now       DPS       Pletasant       Repave parking lot       \$ 90,000       Rock/tar lot last resurfaced in 1999       \$ 65,922,629         128       4) Scheduled A) Now       DAS       Capitol       Capitol       Capitol       Capitol       Capitol       Capitol       This includes new cooling coils and removal of the eaking coils could lead to a health problem for the building coupants. Needs to be a capital request.       \$ 73,876,854         129       4) Scheduled A) Now       DAS       Complex       Replacement       \$ 568,226       2 ea - 80 ton & 65 ton       \$ 73,876,854         130       4) Scheduled A) Now       DHS       WRC       Larches chillers replacement       \$ 568,226       2 ea - 80 ton & 65 ton       \$ 74,266,854         131       4) Scheduled A) Now       DHS       CUSU       Security updates and installation of walk-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         132       4) Scheduled A) Now       DHS   |     |              |   |        | North Central |                                |    |           |  | Ì  |              |
| 127       4) Scheduled A) Now       DPS       Pleasant       Repave parking lot       \$ 90,000       Rock/tar lot last resurfaced in 1999       \$ 65,922,629         128       4) Scheduled A) Now       DAS       Capitol       Capitol       Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled Scheduled A) Now       DAS       Capitol       Capitol       Scheduled A) Now       DAS       Capitol       Capitol Scheduled Sch  | 126 | 4) Scheduled | A) Now                                  | DOC    |               | Renovate 2 Boilers             | \$ | 58.000    |  | \$ | 65,832,629   |
| 127       4) Scheduled A) Now       DPS       Pleasant       Repave parking lot       \$ 90,000       Rock/tar fot last resurfaced in 1999       \$ 65,922,629         128       4) Scheduled A) Now       DAS       Capitol       Capitol </td <td>120</td> <td></td> <td>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</td> <td>200</td> <td></td> <td></td> <td>Ŷ</td> <td>00,000</td> <td></td> <td>Ť</td> <td>00,002,020</td>  | 120 |              | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | 200    |               |                                | Ŷ  | 00,000    |  | Ť  | 00,002,020   |
| 128       4) Scheduled A) Now       DAS       Capitol<br>Complex       Grimes Building HVAC Updates       \$ 7,355,897       be a capital request.       Social dampers, drain pan liners in the both AHU, damper operators<br>and DDC Controls. Equipment tor the building occupants. Needs to<br>could ead to a health problem for the building occupants. Needs to<br>be a capital request.       \$ 7,3508,567       \$ 7,3676,564         129       4) Scheduled A) Now       DAS       Complex       Grimes Building Cooling Coil<br>Capitol       \$ 566,328       Difficult to maintain cooling in summer heat.       \$ 73,876,854         130       4) Scheduled A) Now       DHS       WRC       Larches chillers replacement       \$ 250,000       2 ea - 80 ton & 65 ton       \$ 74,126,854         131       4) Scheduled A) Now       DHS       CCUSO       waik-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         132       4) Scheduled A) Now       DHS       CCUSO       waik-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         133       4) Scheduled A) Now       DCA       Replacement       \$ 35,000       New controller       \$ 74,333,354         134       4) Scheduled A) Now       DCA       Replace Controls At The Historical<br>Scould Base Scould B  | 127 | 4) Scheduled | A) Now                                  | DPS    |               | Repave parking lot             | \$ | 90,000    | Rock/tar lot last resurfaced in 1999   | \$ | 65,922,629   |
| 128       4) Scheduled A) Now       DAS       Complex       Grimes Building HVAC Updates       \$         7,385,897       be a capital request.       \$         73,308,526         129       4) Scheduled A) Now       DAS       Complex       Replacement       \$         5       568,328       Difficult to maintain cooling is unmere heat.       \$         73,876,854         130       4) Scheduled A) Now       DAS       Complex       Replacement       \$         5       568,328       Difficult to maintain cooling in summer heat.       \$         74,126,854         131       4) Scheduled A) Now       DHS       WRC       Larches chillers replacement       \$         250,000       2 ea - 80 ton & 65 ton       \$         74,126,854         132       4) Scheduled A) Now       DHS       CCUSO       walk-through sally port gate       \$         140,000       Add pedestrian sally port.       \$         74,266,854         132       4) Scheduled A) Now       DHS       CCUSO       walk-through sally port gate       \$         33,500       New controller       \$         74,333,354         133       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$         31,500       \$         74,333,354       \$         74,345,354         134       4) Scheduled A) Now       DCA   |     |              |   |        | Capitol       |                                |    |           | coils, dampers, drain pan liners in the both AHU, damper operators<br>and DDC Controls. Equipment is original to building (1969),<br>temperatures are difficult to control. The condition of the leaking coils |    |              |
| 129       4) Scheduled       A) Now       DAS       Capitol<br>Complex       Lucas Building Cooling Coil<br>Replacement       \$ 568,328       Difficult to maintain cooling in summer heat.       \$ 73,876,854         130       4) Scheduled       A) Now       DHS       WRC       Larches chillers replacement       \$ 250,000       2 ea - 80 ton & 65 ton       \$ 74,126,854         131       4) Scheduled       A) Now       DHS       CCUSO       Security updates and installation of<br>walk-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         132       4) Scheduled       A) Now       DHS       CCUSO       walk-through sally port gate       \$ 35,000       New controller       \$ 74,301,854         133       4) Scheduled       A) Now       DCA       nt       Rof and Tuck Pointing       \$ 31,500       New controller       \$ 74,333,354         134       4) Scheduled       A) Now       DCA       nt       Rof and Tuck Pointing       \$ 31,500       New controller       \$ 74,363,354         135       4) Scheduled       A) Now       DCA       Nt       Replace Controls       \$ 276,800       \$ 74,363,354         136       4) Scheduled       A) Now       DCA       Replace Controls At the Historical<br>Building With Direct Digital Controls       \$ 1,727,680 <td>128</td> <td>4) Scheduled</td> <td>A) Now</td> <td>DAS</td> <td></td> <td>Grimes Building HVAC Updates</td> <td>\$</td> <td>7,385,897</td> <td></td> <td>\$</td> <td>73,308,526</td>   | 128 | 4) Scheduled | A) Now                                  | DAS    |               | Grimes Building HVAC Updates   | \$ | 7,385,897 |  | \$ | 73,308,526   |
| 131       4) Scheduled A) Now       DHS       CCUSO       Security updates and installation of walk-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         132       4) Scheduled A) Now       Hill       Terrace Hill       Elevator repair       \$ 35,000       New controller       \$ 74,301,854         133       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       New controller       \$ 74,333,354         134       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,365,354         134       4) Scheduled A) Now       DCA       Museum       Clermont Museum Repairs       \$ 32,000       \$ 74,365,354         135       4) Scheduled A) Now       DAS       Complex       sidewalks on the Complex       \$ 276,800       \$ 74,642,154         135       4) Scheduled A) Now       DAS       Capitol       Repair or replace streets, curbs, sidewalks on the Complex       \$ 276,800       \$ 74,642,154         136       4) Scheduled A) Now       DAS       Capitol       Replace Controls At The Historical Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,6369,834       \$ 76,6369,834         137       4) Scheduled A) Now       DAS       Complex  |     |              |   | DAS    |               | Lucas Building Cooling Coil    | \$ | 568,328   | This includes new cooling coils and removal of the existing steam reheat coils that were installed behind the existing cooling coils in both AHU 1 & 2. 2 coils are broken and 2 have questionable flow.       | \$ |              |
| 131       4) Scheduled A) Now       DHS       CCUSO       Security updates and installation of walk-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         132       4) Scheduled A) Now       Hill       Terrace Hill       Elevator repair       \$ 35,000       New controller       \$ 74,301,854         133       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       New controller       \$ 74,333,354         134       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,365,354         134       4) Scheduled A) Now       DCA       Museum       Clermont Museum Repairs       \$ 32,000       \$ 74,365,354         135       4) Scheduled A) Now       DAS       Complex       sidewalks on the Complex       \$ 276,800       \$ 74,642,154         135       4) Scheduled A) Now       DAS       Capitol       Repair or replace streets, curbs, sidewalks on the Complex       \$ 276,800       \$ 74,642,154         136       4) Scheduled A) Now       DAS       Capitol       Replace Controls At The Historical Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,6369,834       \$ 76,6369,834         137       4) Scheduled A) Now       DAS       Complex  |     |              |   |        |               |                                |    |           |  |    |              |
| 131       4) Scheduled       A) Now       DHS       CCUSO       walk-through sally port gate       \$ 140,000       Add pedestrian sally port.       \$ 74,266,854         132       4) Scheduled       A) Now       Hill       Terrace Hill       Elevator repair       \$ 35,000       New controller       \$ 74,301,854         133       4) Scheduled       A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       New controller       \$ 74,333,354         134       4) Scheduled       A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,365,354         134       4) Scheduled       A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,365,354         134       4) Scheduled       A) Now       DCA       Repair or replace streets, curbs, sidewalks on the Complex       \$ 276,800       \$ 74,642,154         135       4) Scheduled       A) Now       DAS       Complex       Sidewalks on the Complex       \$ 1,727,680       System is failing       \$ 76,369,834         136       4) Scheduled       A) Now       DAS       Complex       Sidiors Monument       \$ 260,000       \$ 76,629,834         137       4) Scheduled       A) Now       DAS       Complex       Sidior   | 130 | 4) Scheduled | A) Now                                  | DHS    | WRC           |                                | \$ | 250,000   | 2 ea - 80 ton & 65 ton   | \$ | 74,126,854   |
| 132       4) Scheduled A) Now       Hill       Terrace Hill       Elevator repair       \$ 35,000       New controller       \$ 74,301,854         133       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,333,354         134       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 32,000       \$ 74,365,354         134       4) Scheduled A) Now       DCA       Museum       Clermont Museum Repairs       \$ 32,000       \$ 74,365,354         135       4) Scheduled A) Now       DAS       Capitol Complex       Repair or replace streets, curbs, sidewalks on the Complex       \$ 276,800       \$ 74,642,154         136       4) Scheduled A) Now       DAS       Capitol Complex       Replace Controls At The Historical Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,369,834         137       4) Scheduled A) Now       DAS       Capitol Finish full restoration of Soldiers & 240,000       \$ 76,629,834       \$ 76,629,834         137       4) Scheduled A) Now       DAS       Complex       Sailors Monument       \$ 260,000       \$ 76,629,834   | 131 | 4) Scheduled | A) Now                                  |        | ccuso         |                                | \$ | 140,000   | Add pedestrian sally port.   | \$ | 74,266,854   |
| 133       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,333,354         134       4) Scheduled A) Now       DCA       nt       Roof and Tuck Pointing       \$ 31,500       \$ 74,333,354         134       4) Scheduled A) Now       DCA       Clermont       Scheduled Repairs       \$ 32,000       \$ 74,365,354         135       4) Scheduled A) Now       DCA       Repair or replace streets, curbs, sidewalks on the Complex       \$ 276,800       \$ 74,642,154         136       4) Scheduled A) Now       DAS       Capitol Complex       Replace Controls At The Historical Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,369,834         137       4) Scheduled A) Now       DAS       Capitol       Finish full restoration of Soldiers & Sailors Monument       \$ 260,000       \$ 76,629,834  | 400 |              |   |        | Tamaaa I Kil  |                                | ¢  | 25 000    | New centreller   | ¢  | 74 004 054   |
| 1334) Scheduled A) NowDCASchool/Clermo<br>ntRoof and Tuck Pointing\$ 31,500\$ 74,333,3541344) Scheduled A) NowDCAMuseumClermont Museum Repairs\$ 32,000\$ 74,365,3541344) Scheduled A) NowDCAMuseumClermont Museum Repairs\$ 32,000\$ 74,365,3541354) Scheduled A) NowDASCapitolRepair or replace streets, curbs, sidewalks on the Complex\$ 276,800\$ 74,642,1541364) Scheduled A) NowDASCapitolReplace Controls At The Historical Building With Direct Digital Controls\$ 1,727,680System is failing\$ 76,369,8341374) Scheduled A) NowDASCapitolFinish full restoration of Soldiers & Sailors Monument\$ 260,000\$ 76,629,8341374) Scheduled A) NowDASComplexSailors Monument\$ 260,000\$ 76,629,834   | 132 | 4) Scheduled | A) NOW                                  | HIII   |               |                                | Þ  | 35,000    |  | Э  | 74,301,854   |
| 1334) ScheduledA) NowDCAntRoof and Tuck Pointing\$ 31,500\$ 74,333,3541344) ScheduledA) NowDCAMuseumClermont Museum Repairs\$ 32,000\$ 74,365,3541354) ScheduledA) NowDASCapitolRepair or replace streets, curbs, sidewalks on the Complex\$ 276,800\$ 74,642,1541364) ScheduledA) NowDASCapitolReplace Controls At The Historical Building With Direct Digital Controls\$ 1,727,680System is failing\$ 76,369,8341374) ScheduledA) NowDASCapitolFinish full restoration of Soldiers & Sailors Monument\$ 260,000The water is very hard and continues to damage equipment.\$ 76,629,834   |     |              |   |        |               |                                |    |           |  |    |              |
| 1344) Scheduled A) NowDCAClermont<br>MuseumClermont Museum Repairs\$ 32,000\$ 74,365,3541354) Scheduled A) NowDASCapitol<br>ComplexRepair or replace streets, curbs,<br>sidewalks on the Complex\$ 276,800\$ 74,642,1541364) Scheduled A) NowDASCapitol<br>ComplexReplace Controls At The Historical<br>Building With Direct Digital Controls\$ 1,727,680System is failing\$ 76,369,8341374) Scheduled A) NowDASCapitol<br>ComplexFinish full restoration of Soldiers &<br>Sailors Monument\$ 260,000\$ 76,629,834  | 133 | 4) Scheduled | A) Now                                  |        |               | Roof and Tuck Pointing         | \$ | 31 500    |  | \$ | 74 333 354   |
| 1344) ScheduledA) NowDCAMuseumClermont Museum Repairs\$ 32,000\$ 74,365,3541354) ScheduledA) NowDASCapitol<br>ComplexRepair or replace streets, curbs,<br>sidewalks on the Complex\$ 276,800\$ 74,642,1541364) ScheduledA) NowDASCapitol<br>ComplexReplace Controls At The Historical<br>Building With Direct Digital Controls\$ 1,727,680System is failing\$ 76,369,8341374) ScheduledA) NowDASCapitol<br>ComplexFinish full restoration of Soldiers &<br>Sailors Monument\$ 260,000The water is very hard and continues to damage equipment.\$ 76,629,834   | 100 |              | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | 2011   |               |                                | Ŷ  | 01,000    |  | Ť  | 1 1,000,001  |
| 1354) Scheduled A) NowDASCapitol<br>ComplexRepair or replace streets, curbs,<br>sidewalks on the Complex\$ 276,800\$ 74,642,1541364) Scheduled A) NowDASCapitol<br>ComplexReplace Controls At The Historical<br>Building With Direct Digital Controls\$ 1,727,680System is failing\$ 76,369,8341374) Scheduled A) NowDASCapitol<br>ComplexFinish full restoration of Soldiers &<br>Sailors Monument\$ 260,000The water is very hard and continues to damage equipment.\$ 76,629,834   | 134 | 4) Scheduled | A) Now                                  | DCA    |               | Clermont Museum Repairs        | \$ | 32.000    |  | \$ | 74.365.354   |
| 135       4) Scheduled A) Now       DAS       Complex       sidewalks on the Complex       \$ 276,800       \$ 74,642,154         136       4) Scheduled A) Now       DAS       Capitol<br>Complex       Replace Controls At The Historical<br>Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,369,834         137       4) Scheduled A) Now       DAS       Capitol<br>Complex       Finish full restoration of Soldiers &<br>Sailors Monument       \$ 260,000       The water is very hard and continues to damage equipment.       \$ 76,629,834   | -   | ,            | , -                                     | _      |               |                                |    | - ,       |  | Ť  | .,           |
| 136       4) Scheduled       A) Now       DAS       Complex       Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,369,834         137       4) Scheduled       A) Now       DAS       Capitol<br>Complex       Finish full restoration of Soldiers &<br>Sailors Monument       \$ 260,000       * 76,629,834       \$ 76,629,834         137       4) Scheduled       A) Now       DAS       Complex       Sailors Monument       * 260,000       * 76,629,834   | 135 | 4) Scheduled | A) Now                                  | DAS    |               |                                | \$ | 276,800   |  | \$ | 74,642,154   |
| 136       4) Scheduled       A) Now       DAS       Complex       Building With Direct Digital Controls       \$ 1,727,680       System is failing       \$ 76,369,834         137       4) Scheduled       A) Now       DAS       Capitol<br>Complex       Finish full restoration of Soldiers &<br>Sailors Monument       \$ 260,000       * 76,629,834       \$ 76,629,834         137       4) Scheduled       A) Now       DAS       Complex       Sailors Monument       * 260,000       * 76,629,834   |     | ,<br>,       |   |        |               | ·                              |    |           |  | 1  |              |
| 137     4) Scheduled     A) Now     DAS     Capitol<br>Complex     Finish full restoration of Soldiers &<br>Sailors Monument     \$ 260,000       100     North Central     North Central     The water is very hard and continues to damage equipment.     \$ 76,629,834   |     |              |   |        |               |                                |    |           |  |    |              |
| 137       4) Scheduled       A) Now       DAS       Complex       Sailors Monument       \$ 260,000       \$ 76,629,834         137       4) Scheduled       Now       DAS       Complex       Sailors Monument       \$ 76,629,834         137       4) Scheduled       Now       DAS       Complex       The water is very hard and continues to damage equipment.       \$ 76,629,834  | 136 | 4) Scheduled | A) Now                                  | DAS    |               |                                | \$ | 1,727,680 | System is failing  | \$ | 76,369,834   |
| North Central         The water is very hard and continues to damage equipment.   |     |              |   |        |               |                                |    |           |  |    |              |
|   | 137 | 4) Scheduled | A) Now                                  | DAS    |               | Sailors Monument               | \$ | 260,000   |  | \$ | 76,629,834   |
|   | 138 | 4) Scheduled | A) Now                                  | DOC    |               | Replace Water Softeners        | \$ | 100,000   |  | \$ | 76,729,834   |

Printed 2/19/2015

|     |   |           |                |                         |  | F  | Funding                               | <i>,</i> ,  |    |                          |
|-----|---|-----------|----------------|-------------------------|--|----|---------------------------------------|---|----|--------------------------|
|     | Priority  | Immediacy | Agency         | Facility                | Project Title  | F  | Request                               | Comments  | Rı | unning Total             |
| 139 | 4) Scheduled  | A) Now    | DHS            | WRC                     | Grandwood chiller replacement  | \$ | 130,000                               | 1 ea - 120 ton  | \$ | 76,859,834               |
| 140 | 4) Scheduled  | A) Now    | DOC            | ASP                     | Replace Cell Locking System for<br>Living Unit B and D-3<br>Replace Central Energy Plant | \$ | 3,000,000                             | Will pursue a capital request.  | \$ | 79,859,834               |
| 141 | 4) Scheduled  | A) Now    | DAS            | Capitol<br>Complex      | deaerator tank   | \$ | 452,298                               |   | \$ | 80,312,132               |
| 142 | 4) Scheduled  | A) Now    | DHS            | Independence            | Reynolds Masonry Repair Phase 4  | \$ | 1,010,000                             |   | \$ | 81,322,132               |
| 143 | 4) Scheduled  | A) Now    | DHS            | Independence            | Infirmary Masonry Repair   | \$ | 405,000                               |   | \$ | 81,727,132               |
| 144 | 4) Scheduled  | A) Now    | DHS            | Independence            | Reynolds Masonry Repair Phase 5  | \$ | 300,000                               | Cost estimate lowered based on reassessment.<br>Obsolete, can't upgrade software. Have some spare parts in  | \$ | 82,027,132               |
| 145 | 4) Scheduled  | A) Now    | DOC            | Ft Dodge CF             | Replace Automation Panels<br>Repair Laundry Hot Water                                    | \$ | 280,000                               | inventory.<br>Hot water recovery system needed to keep up with hot water  | \$ | 82,307,132               |
| 146 | 4) Scheduled  | A) Now    | DOC            | Ft Dodge CF             | Recovery System Entry  | \$ | 10,000                                | demand, current pit very difficult to clean.<br>Lot 3 has buckled in several place, creating large pot holes. There   | \$ | 82,317,132               |
| 147 | 4) Scheduled  | A) Now    | DAS            | Capitol<br>Complex      | Replace parking lot 3, including new lighting  | \$ | 1,400,880                             | are lots of sunken in spots from heavy loading and wide joint and<br>settlement cracks. The over all condition of this parking lot is very<br>hazardous to drive or walk across.  | \$ | 83,718,012               |
|     |   |           |                |                         | Install backflow prevention or dry sprinkler system in residential                       |    |                                       |   |    |                          |
| 148 | 4) Scheduled  | A) Now    | DHS            | Glenwood                | houses   | \$ | 260,000                               | no citations, no contamination of drinking water<br>Project was funded 8/2013, but engineering review determined it did   | \$ | 83,978,012               |
| 149 | 4) Scheduled  | A) Now    | DHS<br>Terrace | Cherokee                | Replace Roof - Motor Pool<br>Replace wood shake roof on                                  | \$ | 150,000                               | not need to be replaced yet.<br>Inspection of roof to determine how much wood rot that is apparent if   | \$ | 84,128,012               |
| 150 | 4) Scheduled  | A) Now    | Hill           | Terrace Hill            | Carriage House   | \$ | 200,000                               | not 100%. No water issues inside.   | \$ | 84,328,012               |
| 151 | 4) Scheduled  | A) Now    | Hill           | Terrace Hill            | Timbers for Pool house   | \$ | 60,000                                | Timbers to be cured for one year and placed the following year<br>Electrical upgrade for the old part of the facility. Because of ever<br>changing needs in Corrections, existing cells and other areas do not<br>have enough power capabilities which are becoming necessary.<br>Wiring is becoming aged as well. Our electrician is telling us we   | \$ | 84,388,012               |
| 152 | 4) Scheduled  | A) Now    | DOC            | IMCC                    | Electrical Upgrade Study<br>Replace Condensate Return from                               | \$ | 100,000                               | simply do not have any more available power to simply add an outlet.<br>Current condensate lines are deteriorated and leak badly. Most of the   |    | 84,488,012               |
|     | 4) Scheduled  |           | DHS            | Cherokee                | Four Corners to Powerhouse   | \$ | · · · · · · · · · · · · · · · · · · · | design done under 8691.00<br>We need to complete the tuckpointing of CH17. This is needed as the<br>outer stone is starting to get major gaps in it. Water is then able to<br>get into the gaps and freeze/expand, crushing the limestone. These<br>caps also allow animals/birds/rodents, to build nests in some of the<br>larger areas. With the limestone crumbling, stone could fall out and<br>hurt someone. As this building is on the National Registry, we have | \$ | 84,838,012               |
|     | <ul><li>4) Scheduled</li><li>4) Scheduled</li></ul> | ,         | DOC            | ISP<br>Ft Dodge CF      | Tuckpoint of CH17<br>Replace rusted out door frame in<br>buildings DE&M                  | \$ |                                       | to keep it structurally sound<br>Existing steel frame doors were installed using an incompatible grout<br>material that is corrosive to the steel door frames. Rusted frames are<br>being replaced as required. Eventually all the frames will be in a<br>critical state that will require the replacement of 275 door frames for<br>security reasons.  | \$ | 84,938,012<br>85,238,012 |
|     |   | -         |                |                         | Ŭ  |    |                                       |   | Ι. |                          |
|     | 4) Scheduled  |           | DHS            | Mt. Pleasant<br>Capitol | Repair parking lot   | \$ |                                       | The lot is in very poor repair.<br>All of Elevator equipment is original equipment. The Hoover elevators<br>had 38 service calls for not being in operation in the last two years   |    | 85,303,012               |
| 157 | 4) Scheduled  | A) Now    | DAS            | Complex                 | Replace Hoover Building Elevators  | \$ | 2,031,430                             | and 12 service calls for people being entrapped.  | \$ | 87,334,442               |

|                  |                            |        |                                   |   | F        | Funding   |  |          |              |
|------------------|----------------------------|--------|-----------------------------------|---|----------|-----------|--|----------|--------------|
| Priority         | Immediacy                  | Agency | Facility                          | Project Title                           | I        | Request   | Comments   | Ru       | Inning Total |
| -                | -                          |        |                                   |   |          |           | Our facility has been in operation since approximately 1970. The old part of our facility has 15 existing air handling units which need replacement before failure occurs. These units are placed in |          |              |
|                  |                            |        |                                   |   |          |           | locations that make it very difficult to provide repairs to. They do   |          |              |
|                  |                            |        |                                   |   |          |           | provide heating and cooling to cell houses, offices, dietary and other   |          |              |
|                  |                            |        |                                   |   |          |           | activity areas at our facility. If removal and replacement is projected it   |          |              |
|                  |                            |        |                                   |   |          |           | will be necessary to remove some of the units through the roofs of   |          |              |
|                  |                            |        |                                   |   |          |           | our facility as there is no way of accessing the areas accept with foot  |          |              |
|                  |                            |        |                                   |   |          |           | traffic and walk through doorways. Roofing projects are already on   |          |              |
|                  |                            |        |                                   |   |          |           | the major maintenance list and it may be an opportune time to start<br>replacing some of these unit with a roof project. These units would   |          |              |
|                  |                            |        |                                   |   |          |           | also need to be tied into our Siemens building automation system.  |          |              |
|                  |                            |        |                                   |   |          |           | This estimate does not include engineering fees. It is based off   |          |              |
| 158 4) Scheduled |                            | DOC    | IMCC                              | Air Handler Replacement                 | \$       | 3 106 917 | \$150,000/air handler.   | \$       | 90,531,259   |
| 150 4) Scheduled | A) NOW                     | DOC    | Iowa Veterans                     |   | φ        | 3,190,017 | Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,  | φ        | 90,331,239   |
| 159 4) Scheduled |                            | DVA    | Home                              | Cast Iron Pipe Replacement              | \$       | 300 000   | and Loftus. Areas are brittle, with frequent breakages   | \$       | 90,831,259   |
| 159 4) Scheduled |                            | DVA    | Tiome                             | Replace taut wire sensor reporting      | Ψ        | 300,000   | Sensor reporting units are aged and beginning to give false alarms   | φ        | 90,031,239   |
| 160 4) Scheduled |                            | DOC    | Ft Dodge CF                       | units                                   |          |           | and fail at an unacceptable rate.  | \$       | 90,831,259   |
| 100 4) Scheduled |                            | DOC    | T t Douge Ci                      |   |          |           |  | Ψ        | 30,031,233   |
| 161 4) Scheduled | A) Now                     | DOC    | Newton CF                         | Replace siding on Bldg 14 (ILU)         | \$       | 25,000    |  | \$       | 90,856,259   |
|                  | / () / (0//                | 200    |                                   | NCF - Replace dishwasher in             | Ψ        | 20,000    | Original dishwasher; life expectancy exceeded; failing - become a  | Ψ        | 00,000,200   |
| 162 4) Scheduled | A) Now                     | DOC    | Newton CF                         | kitchen                                 | \$       | 130 000   | more dire issue  | \$       | 90,986,259   |
|                  | / () / (0//                | 200    |                                   |   | Ψ        | 100,000   | This is a backup to a backup generator. This generator is becoming   | Ψ        | 00,000,200   |
|                  |                            |        |                                   |   |          |           | antiguated and now repairs and replacements are costly. The  |          |              |
|                  |                            |        |                                   |   |          |           | generator is increasingly unreliable. If it should go down we lose the   |          |              |
| 163 4) Scheduled | A) Now                     | DOC    | Mt. Pleasant                      | North Core Generator                    | \$       | 40.000    | backups for the main security system.  | \$       | 91,026,259   |
| ,                | ,                          |        |                                   |   | +        |           | GRC previously submitted a request to evaluate the water mains (see  | Ť        | ,,           |
|                  |                            |        |                                   |   |          |           | #46 on earlier list). After speaking to a mechanical engineer they   |          |              |
|                  |                            |        |                                   |   |          |           | advised there is no good method to evaluate the water mains without  |          |              |
|                  |                            |        |                                   |   |          |           | extensive excavation. They recommended we consider replacement   |          |              |
|                  |                            |        |                                   |   |          |           | since the water mains are more than 100 years old and we are   |          |              |
|                  |                            |        |                                   |   |          |           | experiencing rust and contamination in the domestic water supply.  |          |              |
| 164 4) Scheduled | B) < 1 yr                  | DHS    | Glenwood                          | Replace water mains                     | \$       | 1,000,000 | The water mains are not lined and the service lines are galvanized.  | \$       | 92,026,259   |
|                  |                            | 500    | North Central                     | Air Handler Replacement and             | •        | 400.000   |  | •        |              |
| 165 4) Scheduled | B) < 1 yr                  | DOC    | CF                                | Condenser Coils                         | \$       | 130,000   | Unit A, B , C and Condenser Unit D.  | \$       | 92,156,259   |
|                  |                            |        | North Central                     |   | •        | 405 000   |  | <b>~</b> | 00 054 050   |
| 166 4) Scheduled | B) < 1 yr                  | DOC    | CF                                | Fire Alarm Upgrade                      | \$       | 195,000   | Addressing system upgrade by location and clean up fault issues.   | \$       | 92,351,259   |
|                  |                            |        |                                   |   |          |           | Panels are obsolete and malfunctioning often. These energy   |          |              |
|                  |                            |        | Otata Training                    | France Management Field Danal           |          |           | management panels controls all heating and cooling operations on   |          |              |
| 167 A Cohodulad  | $\mathbf{D}$ $(1)$         | DHS    | State Training<br>School - Eldora | Energy Management Field Panel           | \$       | 151 071   | the facility. Malfunction recently caused numerous boiler shutdowns during dead of winter.   | ¢        | 00 500 500   |
| 167 4) Scheduled | <i>b)</i> < 1 уі           | DHS    | School - Eldora                   | Replacements                            | ¢        | 151,271   | The two 1,000 gallon tanks have passed life cycle end and are  | \$       | 92,502,530   |
|                  |                            |        |                                   | Doplage Het Weter Topks and             |          |           |  |          |              |
| 168 4) Scheduled | $P \rightarrow 1 \gamma r$ | DHS    | Mt. Pleasant                      | Replace Hot Water Tanks and<br>Controls | \$       | 60.000    | showing signs of leakage and wear. They supply all the hot water for the 20 building   | ¢        | 92,562,530   |
| 100 4) Scheduleu | D) < T yi                  | DHS    |                                   | Controls                                | φ        | 00,000    |  | \$       | 92,502,550   |
| 169 4) Scheduled | $P \rightarrow 1 vr$       | DOC    | Newton CF                         | Update CCTV system                      | \$       | 250,000   |  | ¢        | 92,812,530   |
| 109 4) Scheduled | D) < T yi                  | DOC    | Newton Ci                         |   | φ        | 230,000   | Currently have to replace a \$7,000 pump about every 5 years. Will   | \$       | 92,012,550   |
| 170 4) Scheduled | B) < 1 vr                  | DOC    | ASP                               | Luster Heights – New Water Well         | \$       | 505 000   | pursue a capital request.  | \$       | 93,317,530   |
|                  |                            | 500    |                                   |   | Ψ        | 505,000   | Condensate Storage tanks have holes in them allowing steam to  | φ        | 55,517,550   |
|                  |                            |        |                                   |   |          |           | escape in the upper end. The lower end may rust through some day   |          |              |
|                  |                            |        |                                   | Replace steam condensate storage        |          |           | as well. If these tanks become unusable, boilers will not operate.   |          |              |
| 171 4) Scheduled | B) <1 vr                   | DOC    | ASP                               | system                                  | \$       | 200 000   | Engineering done.  | \$       | 93,517,530   |
|                  | -,,                        |        |                                   | Replace Water Conditioning              | <b>–</b> | _30,000   |  | Ψ        | 55,517,000   |
| 172 4) Scheduled | B) < 1 yr                  | DOC    | Et Dodge CE                       | System                                  | \$       | 70 000    | Undersized, regenerate 3 - 4 times/day   | \$       | 93,587,530   |
| 1/2 4) Scheduled | в) <1 yr                   | DOC    | Ft Dodge CF                       | System                                  | \$       | 70,000    | Undersized, regenerate 3 - 4 times/day   | \$       | 93,587,530   |

|                  |              |        |                    | DICAL T OFFICIAL MAJO  |          | unding    | ject Requests Fillited  | 2/10     | /2013        |
|------------------|--------------|--------|--------------------|--|----------|-----------|---|----------|--------------|
| Priority         | Immediacy    | Agency | Facility           | Project Title  |          | equest    | Comments  | Ru       | unning Total |
|                  |              |        |                    | Replace large 350 lb built in clothes                              |          |           | Laundry process approx. 5000lbs of laundry per day on average of  | Ī        |              |
| 173 4) Schedule  | d B) <1 yr   | DOC    | Clarinda DOC       | dryers in laundry  | \$       |           | offender clothing.  | \$       | 93,837,530   |
|                  |              |        |                    |  |          |           | Current phone system is end of life (replacement parts are not  |          |              |
| 174 4) Schedule  | d B) <1 yr   | DOC    | Clarinda DOC       | Replacement of IP Phone System                                     | \$       | 500,000   | manufactured anymore).  | \$       | 94,337,530   |
|                  |              |        |                    | NCF - Living Unit C Roof   | •        |           |   |          |              |
| 175 4) Schedule  | d B) <1 yr   | DOC    | Newton CF          | Replacement  | \$       | 350,000   | Patching on the roof has happened and nearing the end of life cycle   | \$       | 94,687,530   |
| 176 (1) Sobodulo |              | DOC    | Nouton CE          | NCF - Living Unit D Roof   | ¢        | 250.000   | Detaking on the reaf has been and and nearing the and of life surely  | ¢        | 05 027 520   |
| 176 4) Schedule  | а в) <1 yr   | DOC    | Newton CF          | Replacement  | \$       |           | Patching on the roof has happened and nearing the end of life cycle<br>Car is past life expectancy. Controller is in need of repair. Does not | \$       | 95,037,530   |
|                  |              |        |                    |  |          |           | have phase one fire recall. The facility is being vacated and has been  |          |              |
| 177 4) Schedule  | d(C) > 1 vr  | DOC    | Mt. Pleasant       | Elevator MWU Upgrade   | \$       |           | moved to the bottom of our needs.   | \$       | 95,257,530   |
|                  |              | 200    | inter roubuitt     |  | Ŷ        |           | 2" wide cracks at the joints, tuil of settlement cracks, some hole and  | Ť        | 00,201,000   |
|                  |              |        |                    |  |          |           | raised surfaces creating tripping hazards and broken and damaged  |          |              |
|                  |              |        |                    |  |          |           | concrete side walk curbs. 12B will be occupied for at least 1 year  |          |              |
|                  |              |        | Capitol            |  |          |           | by cell tower. Project will wait until IA Bldg demo is done and   |          |              |
| 178 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Replace parking lots 12A & B                                       | \$       |           | cell tower is removed. Reconsider in Spring 2015.   | \$       | 96,339,130   |
|                  |              |        | 0 11 1             |  |          |           | All of Elevator equipment is original equipment. The Wallace Building   |          |              |
| 170 (1) Cabadula |              | D 4 C  | Capitol            | Replace Wallace Buildings  | ¢        |           | Elevators had 32 service calls for not being in operation and 1   | <b>~</b> | 07 044 700   |
| 179 4) Schedule  | u C) > 1 yr  | DAS    | Complex            | Elevators  | \$       |           | entrapment.<br>All of Elevator equipment is original equipment. The Jessie Parker   | \$       | 97,644,730   |
|                  |              |        | Capitol            | Replace Jessie Parker Building                                     |          |           | building had 5 service calls for not being in operation and 4   |          |              |
| 180 4) Schedule  | d(C) > 1 vr  | DAS    | Complex            | Elevators 1.3.4 & 5  | \$       |           | entrapment calls.   | \$       | 98,693,986   |
|                  | u 0) > 1 yi  | 0/10   | Complex            |  | Ψ        | 1,040,200 |   | Ψ        | 50,055,500   |
|                  |              |        | Capitol            | Replace Grimes Building Elevators                                  |          |           | All of Elevator equipment is original equipment. The Grimes Building  |          |              |
| 181 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | 1, 2 & 3   | \$       |           | had 12 service calls for not being in operation and 1 entrapment call.  | \$       | 99,634,882   |
| /                | , ,          |        | Capitol            |  |          | ,         |   | †        | ,,           |
| 182 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Replace Historical Building Roof                                   | \$       | 1,498,319 | Roofs have reached their life expectancy and have been leaking.   | \$       | 101,133,201  |
|                  | , ,          |        | •                  |  |          |           | Remove the skylights and replace with something other than the  | Î        |              |
|                  |              |        | Capitol            | Replace Historical Building  |          |           | skylights that are always leaking. Costs from the Studies of the Lord   |          |              |
| 183 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Skylights  | \$       | 2,736,790 | Cultural Resources and the Ryan Companies US INC.   | \$       | 103,869,991  |
|                  |              |        | Capitol            | Replace Central Energy Plant                                       |          |           |   |          |              |
| 184 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Chiller #3   | \$       | 868,932   | Nearing the end of its life cycle   | \$       | 104,738,923  |
|                  |              | D 4 0  | Capitol            | Replace Central Energy Plant                                       | <b>^</b> | 000 000   | No serve the second of the life second  | •        | 405 007 055  |
| 185 4) Schedule  | a C) > 1 yr  | DAS    | Complex            | Chiller #1 Replace   | \$       | 868,932   | Nearing the end of its life cycle   | \$       | 105,607,855  |
|                  |              |        |                    | Replace Central Energy Plant<br>Cooling Tower #2 , Replace Fill on |          |           | Cooling tower #2 has exceeded its life expectancy and could become  |          |              |
|                  |              |        | Capitol            | Cooling Tower #2, Replace I in on<br>Cooling Tower #4, Enlarge     |          |           | unusable if anything major happens. Condenser water holding pit   |          |              |
| 186 4) Schedule  | d(C) > 1 vr  | DAS    | Complex            | Condenser Water Pit  | \$       |           | needs to be enlarged to run all 4 cooling towers at the same time.  | \$       | 106,353,880  |
|                  |              | 5/10   | Capitol            |  | Ŷ        |           | All elevator equipment is original equipment and having too many  | Ψ        | 100,000,000  |
| 187 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Replace IFA Building Elevator #2                                   | \$       |           | incidents and entrapment calls.   | \$       | 106,573,176  |
|                  |              | _      | Capitol            | Replace IWD Building Elevator #3                                   | Ŧ        |           | All elevator equipment is original equipment. The IWD Building had 5  | †        |              |
| 188 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | West Car   | \$       | 266,114   | service calls for not being in operation.   | \$       | 106,839,290  |
|                  |              |        | Capitol            | Replace Historical Building  |          |           | All elevator equipment is original equipment and having too many  | Ī        |              |
| 189 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Elevators  | \$       | 1,042,517 | incidents and entrapment calls.   | \$       | 107,881,807  |
|                  |              |        | Capitol            | IWD 150 Des Moines Street  |          |           |   |          |              |
| 190 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | Parking Lot Replacement  | \$       | 314,839   |   | \$       | 108,196,646  |
|                  |              |        | Capitol            | Facilities Management Center                                       |          |           |   |          |              |
| 191 4) Schedule  | d C) > 1 yr  | DAS    | Complex            | HVAC Renovations   | \$       |           | Replace main AHU, coils, dampers and controls to DDC.   | \$       | 108,617,079  |
| 100 A) O-b       |              | DAC    | Capitol            | Replace Central Energy Plant Boiler                                | ¢        |           | Boiler #1 is too small, once the outside temperature drops below 30   | <u> </u> | 400.000.070  |
| 192 4) Schedule  | a (c) > 1 yr | DAS    | Complex            | #1<br>Replace Central Energy Plant                                 | \$       | 316,000   | degrees this boiler can not keep up.<br>These are the two 200 HP primary pumps for the Capitol Complex's                                      | \$       | 108,933,079  |
| 103 1) Cohodula  |              | DAS    | Capitol<br>Complex | Replace Central Energy Plant<br>Secondary Chiller Pumps            | \$       | 250 225   | chilled water loop.   | ¢        | 100 102 444  |
| 193 4) Schedule  | u o / > i yi | DAG    | Capitol            | Historical Building Building                                       | φ        | 200,000   |   | Ф        | 109,183,414  |
| 194 4) Schedule  | d(C) > 1 vr  | DAS    | Complex            | Automation Controls Conversion                                     | \$       | 1 843 652 | Change over the pneumatic controls to DDC controls  | ¢        | 111,027,066  |
|                  |              | DAU    |                    |  | Ψ        | 1,070,002 |   | ψ        | 111,027,000  |

|      |              |             |              |              |  | I   | Funding     |  |     |              |
|------|--------------|-------------|--------------|--------------|--|-----|-------------|--|-----|--------------|
|      | Priority     | Immediacy   | Agency       | Facility     | Project Title                          | I   | Request     | Comments   | Ru  | Inning Total |
| 1    | -            |             |              | Capitol      | Monument and Art Work Repair and       |     | -           | The monument endowments cannot sustain the repair and                  | i   |              |
| 195  | 4) Scheduled | C) > 1 vr   | DAS          | Complex      | Restoration                            | \$  | 275.000     | restoration of all the different monuments.                            | \$  | 111,302,066  |
|      | ,            | -, ,        | _            | Capitol      |  |     | - ,         | Replace AHU, coils, fans, VAV, duct work and direct digital controls.  | iŤ  | ,,           |
| 196  | 4) Scheduled | C) > 1 vr   | DAS          | Complex      | Wallace HVAC Renovations               | \$  | 18,202,489  | All existing equipment is past its life expectancy.                    | \$  | 129,504,555  |
|      | .) concatica | c) / · · j. | 27.0         | Capitol      |  | Ψ   | .0,202, .00 |  | Í   | 120,001,000  |
| 197  | 4) Scheduled | C) > 1 vr   | DAS          | Complex      | Replace Vehicle Dispatch Roof          | \$  | 400 000     | Roof are nearing the end of their life expectancy.                     | \$  | 129,904,555  |
|      | .) concatica | c) / · · j. | 27.0         | Capitol      | Ola Babcock Miller Exterior            | Ψ   | ,           | Clean and seal exterior stone façade, tuck-point mortar joints, clean  | Í   | 120,001,000  |
| 198  | 4) Scheduled | C > 1 vr    | DAS          | Complex      | Restoration                            | \$  | 880 422     | and recaulk all building joints and around windows.                    | \$  | 130,784,977  |
| 150  |              | 0) > 1 yi   | DAO          | Capitol      | Replace Historical Building Chillers / | Ψ   | 000,422     | Both the chiller and the chiller/heat pump have exceeded their life    | ΙΨ  | 100,704,077  |
| 199  | 4) Scheduled | C > 1 vr    | DAS          | Complex      | Heat pump                              | \$  | 1 238 475   | expectancy and they have mechanical issues.                            | ¢   | 132,023,452  |
| 100  |              | 0) > 1 yi   | DAO          | Capitol      |  | Ψ   | 1,200,470   | Historical Boilers are 26 years old and are well beyond the life       | Ψ   | 132,023,432  |
| 200  | 4) Scheduled | C > 1 vr    | DAS          | Complex      | Replace Historical Building Boiler     | \$  | 424,074     | expectancy of 15 years for electric boilers.                           | ¢   | 132,447,526  |
| 200  | 4) Scheduled | C) > 1 yi   | DAG          | Complex      | Replace Historical Building Boller     | φ   | 424,074     | Provide maintenance and repair to the granite planter walls and        | φ   | 132,447,320  |
|      |              |             |              | Capitol      | Capitol Complex West Terrace           |     |             | stairs. Reset panels that have tilted out, clean out and recaulk all   | ł   |              |
| 201  | 4) Scheduled | C > 1 vr    | DAS          | Complex      | Repair and Maintenance                 | \$  | 275,000     |  | ¢   | 132,722,526  |
| 201  | 4) Scheduled | C) > 1 yi   | DAS          |              |  | Þ   | 275,000     | joints.  | Ф   | 132,722,320  |
| 202  | 4) Cabadulad | C) . 1      |              | Capitol      | Oran Pape Parking Lot Planter          | ¢   | 00.000      | Describe maintenance and remainte the neuron every date plantage       | •   | 400 000 500  |
| 202  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | Pavers Maintenance and Repair          | \$  | 80,000      | Provide maintenance and repair to the pavers around the planters.      | \$  | 132,802,526  |
|      |              |             |              |              | Capitol Complex Security Camera        |     |             | Provide for upgrading, replacing and new cameras; upgrade              | ł   |              |
| 000  |              |             | <b>D</b> 4 0 | Capitol      | and Surveillance Retention and         | •   |             | surveillance and retention system to a new IP system. Budget           |     |              |
| 203  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | Upgrades                               | \$  | 200,000     | estimate does not include project management fees.                     | \$  | 133,002,526  |
|      |              |             |              |              |  |     |             | Provides for removal and replacement of sidewalks through out the      | ł   |              |
|      |              | -           |              | Capitol      | Capitol Complex Sidewalk               |     |             | complex. New sidewalks to be 6 ft wide for more efficient and          | ۱.  |              |
| 204  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | Replacement Program                    | \$  | 1,156,990   | effective snow removal.  | \$  | 134,159,516  |
|      |              |             |              | Capitol      | Capitol Building North Plaza           |     |             | The concrete plazas between the stairs on the North side of the        | ł   |              |
| 205  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | concrete replacement                   | \$  | 438,697     | Capitol are badly spalled due to chemical treatment for ice.           | \$  | 134,598,213  |
|      |              |             |              |              |  |     |             | Provides for the upgrades to the most current versions of the          | ł   |              |
|      |              |             |              | Capitol      | Capitol Complex Building               |     |             | Siemens software for the Capitol Complex and Iowa Labs on an           | ł   |              |
| 206  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | Automation Upgrades                    | \$  | 138,875     | annual basis.  | \$  | 134,737,088  |
|      |              |             |              |              |  |     |             | The equipment in this building is the original equipment from when     | ł   |              |
|      |              |             |              | Capitol      |  |     |             | the building was built. There are 8 large AHUs in the mechanical       | ł   |              |
| 207  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | Hoover HVAC Systems Renovation         | \$  | 20,347,197  | penthouse with inline R/A fans in the duct work.                       | \$  | 155,084,285  |
|      |              |             |              |              | Iowa Labs Security System              |     |             | Provide for the upgrades to the to the security systems at the lowa    | ł   |              |
| 208  | 4) Scheduled | C) > 1 yr   | DAS          | Iowa Labs    | upgrades                               | \$  | 70,000      | Labs.  | \$  | 155,154,285  |
|      |              |             |              |              | Iowa Labs Cameras and                  |     |             |  | ł   |              |
|      |              |             |              |              | Surveillance Retention Equipment       |     |             | Provides for the upgrade to existing cameras, new cameras, with a      | ł   |              |
| 209  | 4) Scheduled | C) > 1 yr   | DAS          | Iowa Labs    | Upgrades                               | \$  | 100,000     | new IP based recording system for the DCI.                             | \$  | 155,254,285  |
|      |              |             |              |              | Iowa Labs Parking Lot                  |     |             | To maintain and replace the parking lots at the lowa Labs as they are  | ł   |              |
| 210  | 4) Scheduled | C) > 1 yr   | DAS          | Iowa Labs    | Improvements and Repair                | \$  | 760,040     | starting to develop large cracks and deteriorate due to poor drainage. | \$  | 156,014,325  |
|      | /            | , ,         |              |              |  | · · | ,           | Failure of the 1940's boilers refractory and controls repairs include  | i   | ,- ,         |
|      |              |             |              |              |  |     |             | extensive abatement. Project abandons boilers and installs new         | ł   |              |
|      |              |             |              |              |  |     |             | 300hp and 2-600hp in a new addition. Includes new DA, condensate,      | ł   |              |
| 211  | 4) Scheduled | C) > 1 vr   | DOC          | ASP          | Power House Upgrade                    | \$  | 6.800.000   | and support systems.   | \$  | 162,814,325  |
|      | .) concatica | c) / · · j. |              |              | Replace Building J freezer             | Ψ   | 0,000,000   | Walk-in freezers are damaged and in need of replacement from           | Í   | 102,011,020  |
| 212  | 4) Scheduled | C) > 1 vr   | DOC          | Ft Dodge CF  | compartment doors/openings             | \$  | 125 000     | continual pallet truck impact  | \$  | 162,939,325  |
| 2.2  | i) concatica | 0/2131      | 200          | i t Dougo oi |  | Ψ   | 120,000     |  | Í   | 102,000,020  |
| 213  | 4) Scheduled | C > 1 vr    | DOC          | Ft Dodge CF  | Replace Gym flooring                   | \$  | 32 000      | Rubber coated gym floor is damaged and worn                            | \$  | 162,971,325  |
| 215  |              | C) / I yi   | 200          |              |  | Ψ   | 52,000      | Lot 1 has 2" wide cracks at the joints, some settlement cracking,      | Ψ   | 102,011,020  |
|      |              |             |              |              |  |     |             | some low spots and broken and damaged concrete curb, about 10%.        | ł   |              |
|      |              |             |              |              |  |     |             | Lot 4 has 2" wide cracks at the joints, some settlement cracking,      | i   |              |
|      |              |             |              |              |  |     |             | some low spots and broken and damaged concrete curb, about 10%.        | i   |              |
|      |              |             |              | Conitol      | Poplage parking late 1 and 1           |     |             |  | i   |              |
| 24.4 | 1) Sobodulad | () > 1      | DAG          | Capitol      | Replace parking lots 1 and 4,          | ¢   | 1 015 544   | The over all condition of this parking lot is very hazardous to walk   | ¢   | 164 000 000  |
| 214  | 4) Scheduled | C) > 1 yr   | DAS          | Complex      | including new lighting                 | \$  | 1,915,514   | acioss.  | ¢ 1 | 164,886,839  |

|                  |           |        |                     | -   | F  | Funding   |  |     |              |
|------------------|-----------|--------|---------------------|---|----|-----------|--|-----|--------------|
| Priority         | Immediacy | Agency | Facility            | Project Title   | F  | Request   | Comments   | Rı  | unning Total |
|                  | _         |        |                     |   |    |           | Lot 2 has 1" wide cracks at the joints, some spider cracking and   | I   | _            |
|                  |           |        |                     |   |    |           | some settlement cracking along curb and gutter (5000 lin ft). Also   |     |              |
|                  |           |        |                     |   |    |           | has 10 concrete parking barriers which need to be replaced. Lot 13   |     |              |
|                  |           |        | Capitol             | Replace parking lots 2, 13 and drive                            |    |           | and the drive are full of 1" wide settlement cracks throughout the   |     |              |
| 215 4) Scheduled | C) > 1 yr | DAS    | Complex             | for 13, including new lighting                                  | \$ | 2,106,870 | entire lot and drive.  | \$  | 166,993,709  |
|                  | , ,       |        |                     |   |    |           | Lot 14 has 1" to 1-3/4" joint cracks (2,121 lin ft). Lot 15 has major  | t i | , ,          |
|                  |           |        | Capitol             | Replace parking lots 15 and 14,                                 |    |           | settlement cracks and wide joint cracks with surface crushing at the   |     |              |
| 216 4) Scheduled | C) > 1 yr | DAS    | Complex             | including new lighting  | \$ | 1,179,982 | inlets, joints, manholes and light pole basins.  | \$  | 168,173,691  |
|                  | , ,       |        | Capitol             | Replace parking lots 5 and 19,                                  |    |           | Lot 5 has 1" to 2" wide cracks at the joints, some settlement along the  | t i |              |
| 217 4) Scheduled | C) > 1 yr | DAS    | Complex             | including new lighting  | \$ | 653,546   | joints. Lot 19 has 1" wide settlement cracks throughout the lot.   |     | 168,827,237  |
|                  | , ,       |        |                     |   |    |           | The drive for lot 25 has some spalled joints and bad panels that need  | t i |              |
|                  |           |        |                     | Replace drive for parking lot 25 and                            |    |           | repaired or replaced (1,300 sf). Lot 11 has 3/4" to 1-1/4" wide cracks   |     |              |
|                  |           |        | Capitol             | parking lots 10, 11 and 12,                                     |    |           | at the joints (940 lin ft). Lot 12 has 3/4" to 1-1/2" wide cracks at the   |     |              |
| 218 4) Scheduled | C) > 1 vr | DAS    | Complex             | including new lighting  | \$ | 2,142,494 | joints (2,220 lin ft).   | \$  | 170,969,731  |
|                  | <i></i>   |        | Capitol             |   | Ŧ  | _,,       | <b>j</b>   | Ť   |              |
| 219 4) Scheduled | C) > 1 vr | DAS    | Complex             | Replace parking lots 9 and 9A                                   | \$ | 152,097   |  | \$  | 171,121,828  |
|                  | <i></i>   |        |                     | ······································                          | Ŧ  | ,         | Lot 25 needs to have joints cut out and resealed. Lot 28 needs joints  | Ť   | ,,           |
|                  |           |        |                     |   |    |           | cut out and resealed plus some cracking (1,284 lin ft). Lot 24 need  |     |              |
|                  |           |        | Capitol             | Replace parking lots 28, 24 (and                                |    |           | some cracks cut and sealed and the drive has two panels which need   |     |              |
| 220 4) Scheduled | C > 1 yr  | DAS    | Complex             | drive), and 25  | \$ | 368 905   | some repair or replacement.  |     | 171,490,733  |
|                  | 0/2191    | 27.0   | Complex             |   | Ψ  | 000,000   | Lot 26 needs joints cut out and resealed (6,236 lin ft). Lot 16 needs  | Ψ   | 171,400,700  |
|                  |           |        | Capitol             | Replace parking lots 3A, 6, 16, 21                              |    |           | some cracks filled coming of the corner of the islands (60 lin ft). The  |     |              |
| 221 4) Scheduled | C > 1 yr  | DAS    | Complex             | (and drive), 21A, and 26  | \$ | 4 058 609 | rest of these lots will need joints filled in a few years.   | \$  | 175,549,342  |
|                  | 0) > 1 yi | DAO    | 6535 Corporate      |   | Ψ  | 4,000,000 |  | Ψ   | 175,545,542  |
| 222 4) Scheduled | C > 1 vr  | IPTV   | Dr                  | Repair/replace roof   | \$ | 100.000   | The estimated timeframe for the replacement of the roof is FY 2017   | ¢   | 175,649,342  |
|                  | C) > 1 yi | 11 T V | Iowa Veterans       |   | Ψ  | 100,000   | Demolish existing service tunnel and erect new tunnel from Power   | Ψ   | 175,045,542  |
| 223 4) Scheduled | C > 1 vr  | DVA    | Home                | Tunnel Replacement, Heinz Hall                                  | \$ | 000 000   | House to Heinz Hall.   | ¢   | 176,549,342  |
| 223 4) Scheduled | C) > 1 yi | DVA    | Capitol             | Central Energy Plant Fuel Tank                                  | φ  | 900,000   |  | φ   | 170,549,542  |
| 224 4) Scheduled | C > 1 vr  | DAS    | Complex             | Replacement   | \$ | 402,180   |  | ¢   | 176,951,522  |
|                  | C) > 1 yi | DAG    | Capitol             | Replacement   | φ  | 402,100   |  | φ   | 170,951,522  |
| 225 4) Scheduled | C > 1 vr  | DAS    | Complex             | Paint Central Energy Plant                                      | \$ | 131,379   |  | ¢   | 177,082,901  |
| 223 4) Scheduled | C) > 1 yi | DAS    | Capitol             |   | φ  | 131,379   | This is the lead chiller for the Capitol Complex, installed in 1995, 23  | φ   | 177,002,901  |
| 226 4) Scheduled | C > 1 vr  | DAS    | Complex             | Replace Chiller #2  | \$ | 868 033   | year expected life.  | ¢   | 177,951,833  |
| 220 4) Scheduled | C) > 1 yi | DAS    | Capitol             | Restoration of Lucas Building                                   | φ  | 000,932   |  | φ   | 177,951,055  |
| 227 4) Scheduled | C > 1 vr  | DAS    | Complex             | Exterior  | \$ | 992,130   |  | ¢   | 178,943,963  |
| ZZI 4) Scheduled | C) > 1 yi | DAS    | Capitol             | Restoration of Grimes Building                                  | φ  | 992,150   |  | φ   | 170,943,903  |
| 228 4) Scheduled | C > 1 vr  | DAS    | Complex             | Exterior  | \$ | 600,000   |  | ¢   | 179,543,963  |
| 220 4) Scheduled | C) > 1 yi | DAS    | Capitol             | Litenoi   | φ  | 000,000   |  | φ   | 179,545,905  |
| 229 4) Scheduled | C > 1     | DAS    |                     | Tunnel Repair   | \$ | 4 750 000 | This includes repairs of utilities, piping and fire sprinklers.  | ¢   | 184,293,963  |
| 229 4) Scheduled | C) > 1 yi | DAS    | Complex             | Replace Front Exterior Doors in                                 | φ  | 4,750,000 |  | φ   | 104,295,905  |
| 230 4) Scheduled | C > 1 vr  | DOC    | Et Dodgo CE         |   | \$ | 28 000    | Post up by sorts   | ¢   | 104 001 000  |
| 230 4) Scheduled | C) > 1 yi | DOC    | Ft Dodge CF         | Living Units (6 sets)   | φ  | 28,000    | Beat up by carts.  | Ф   | 184,321,963  |
|                  | 0) . 1    | DOC    | North Central       | Lindata Linit C Fire Ference                                    | ¢  | 50.000    | Living Linit Linuxing Offenders (Inspeter  | ¢   | 404 074 000  |
| 231 4) Scheduled | C) > 1 yr | DOC    | CF                  | Update Unit C Fire Escape                                       | \$ | 50,000    | Living Unit Housing Offenders/Inmates  | Э   | 184,371,963  |
| 222 A) Cohodulad | () > 1    | пце    | Charakaa            | Lingrada fira alarm ayatam                                      | ¢  | 000 000   | Can still find refurbished parts   | ¢   | 105 074 000  |
| 232 4) Scheduled | () > 1 yr | DHS    | Cherokee            | Upgrade fire alarm system<br>Update Fire Escape on East Side of | \$ | 900,000   | Can still find refurbished parts.  | Ф   | 185,271,963  |
| 000 A) Cabadul   | 0.1.1.    | DOC    | North Central       |   | ¢  | 60.000    | The Lindete is required to replace the Fire Facence  | ŕ   | 405 004 000  |
| 233 4) Scheduled | () > 1 yr | DOC    | CF<br>North Central | Education Bldg.   | \$ | 60,000    | The Update is required to replace the Fire Escape.<br>This is a fire safety issue , has the panels need to be replaced and | Ф   | 185,331,963  |
| 004 A) Cabadul   | 0.1.1.    | DOC    |                     | Undete Fleetrigel to U.D. and D.S.D.                            | ¢  | 40.000    |  | ¢   | 105 074 000  |
| 234 4) Scheduled | C) > 1 yr | DOC    | CF                  | Update Electrical to LUB and R&D                                | \$ | 40,000    | updated.   | Ф   | 185,371,963  |
|                  |           |        |                     |   |    |           | have very old pneumatic controls, isolation valves that do not isolate   | 1   |              |
|                  |           |        |                     |   |    |           | when necessary for draining/cleaning and the tube bundles could  | 1   |              |
|                  |           |        |                     |   |    |           | have some work performed on them if not replaced. One tube bundle  | 1   |              |
|                  |           |        |                     |   |    |           | is being supported inside the tank by a 4x4 wooden block because   | 1   |              |
| 235 4) Scheduled | C) > 1 vr | DOC    | ASP                 | Replace hot water system  | \$ | 100.000   | the metal bracket rusted away some years back. Engineering done.   | \$  | 185,471,963  |
| .,               | -/:       | 1.2.2  | 1                   |   | Ŧ  |           |  |     | 3 of 21      |

|          |                             |                     |             |                | ,   | F  | unding    |  |  |
|----------|-----------------------------|---------------------|-------------|----------------|---|----|-----------|--|--|
|          | Priority                    | Immediacy           | Agency      | Facility       | Project Title   | R  | equest    | Comments   | Running Total                                |
|          |                             |                     |             |                |   |    |           | This building has perimeter heat and window air conditioning needs         | ľ  |
| 236      | 4) Scheduled                | C) > 1 yr           | DHS         | WRC            | Mechanical upgrade to e-home  | \$ | 150,000   | forced air heat and cooling. existing piping failing.                      | \$ 185,621,963                               |
|          |                             |                     |             |                | Replace and or repair prison metal                                  |    |           |  |  |
| 237      | 4) Scheduled                | C) > 1 yr           | DOC         | Clarinda DOC   | roof  | \$ | 750,000   | 17 year old roof leaks.  | \$ 186,371,963                               |
|          |                             |                     |             |                |   |    |           |  |  |
| 238      | 4) Scheduled                | C) > 1 yr           | DOC         | ASP            | Replace powerhouse water heaters                                    | \$ | 55,000    |  | \$ 186,426,963                               |
|          |                             |                     |             |                |   |    |           |  |  |
| 239      | <ol><li>Scheduled</li></ol> | C) > 1 yr           | DOC         | ASP            | Replace 2 DA tanks  | \$ | 50,000    |  | \$ 186,476,963                               |
|          |                             | -                   |             |                | Replace 100 & 5 lb header and                                       |    |           |  |  |
| 240      | 4) Scheduled                | C) > 1 yr           | DOC         | ASP            | valves  | \$ | 50,000    |  | \$ 186,526,963                               |
|          |                             | 0. 1                | <b>DO</b> O |                | Replace maintenance office and                                      | •  | 100.000   |  |  |
| 241      | 4) Scheduled                | C) > 1  yr          | DOC         | ASP            | tool control roofs  | \$ | 100,000   | These are the same building.   | \$ 186,626,963                               |
| 242      | 1) Schodulad                | () $()$             | DOC         |                | Dishwasher Drain Line   | ¢  | 100.000   | Currently plumbed to grace pit violates and                                | ¢ 400 700 000                                |
| 242      | 4) Scheduled                | C) > 1 yi           | DOC         | Ft Dodge CF    | Dishwasher Drain Line<br>Repair/replace boulevard inside            | \$ | 100,000   | Currently plumbed to grease pit, violates code.                            | \$ 186,726,963                               |
| 242      | 4) Scheduled                | C > 1 vr            | DOC         | Newton CF      |   | \$ | 336,000   |  | \$ 187,062,963                               |
| 243      | 4) Scheduled                | C) > 1 yi           | DOC         | Newton CF      | perimeter   | φ  | 330,000   |  | \$ 167,002,903                               |
| 244      | 4) Scheduled                | C > 1 vr            | DOC         | Newton CF      | CRC - Electrical Upgrade  | \$ | 1,500,000 |  | \$ 188,562,963                               |
| 277      |                             | 0/2191              | 000         | Newton of      | Replace misc. doors at NCF and                                      | Ψ  | 1,000,000 |  | φ 100,502,905                                |
| 245      | 4) Scheduled                | C) > 1 vr           | DOC         | Newton CF      | CRC   | \$ | 150,000   |  | \$ 188,712,963                               |
|          | .) Concurred                | c) / · · j:         |             |                | CRC - Non-Admin Roof  | ÷  |           |  | φ 100,112,000                                |
| 246      | 4) Scheduled                | C) > 1 vr           | DOC         | Newton CF      | Replacement   | \$ | 572,000   |  | \$ 189,284,963                               |
| -        | ,                           | -/ /                |             |                | NCF - Building H Roof Replacement                                   | Ť  | - ,       |  | +,,  |
| 247      | 4) Scheduled                | C) > 1 yr           | DOC         | Newton CF      | (support)   | \$ | 700,000   | Patching on the roof has happened and nearing the end of life cycle        | \$ 189,984,963                               |
|          | · ·                         |                     |             |                | Security cameras for  |    |           | Parts are increasingly difficult to find. No redundancy in existing        |  |
|          |                             |                     |             |                | interior/exterior viewing-campus                                    |    |           | system creating safety/security issue in the event of equipment or         |  |
| 248      | 4) Scheduled                | C) > 1 yr           | DHS         | CCUSO          | wide  | \$ | 950,000   | power failure. System supports both CCUSO and Cherokee MHI.                | \$ 190,934,963                               |
|          |                             |                     |             | Capitol        | Replace Capitol Exterior Building                                   |    |           | Replace the 1000 watt light fixtures that were originally installed in the |  |
| 249      | 4) Scheduled                | C) > 1 yr           | DAS         | Complex        | Lighting  | \$ | 850,000   | late 1980's.   | \$ 191,784,963                               |
|          |                             |                     |             |                | NCF - Building K Roof Replacement                                   |    |           |  |  |
| 250      | <ol><li>Scheduled</li></ol> | C) > 1 yr           | DOC         | Newton CF      | (admin)   | \$ | 150,000   | Patching on the roof has happened and nearing the end of life cycle        | \$ 191,934,963                               |
| <u> </u> |                             | <b>a</b> ) <i>i</i> |             | 6450 Corporate |   |    |           | Headquarters at 6450 Corporate Drive in Johnston. Warranty                 | <b>•</b> • • • • • • • • • • • • • • • • • • |
| 251      | 4) Scheduled                | C) > 1 yr           | IPTV        | Dr             | replace roof  |    |           | expires October, 2014. Roof will need to be replaced. 56,000 sq ft.        | \$ 191,934,963                               |
|          |                             |                     |             |                | Replace roof covering on Carpenter shop detached from main building |    |           |  |  |
| 252      | 4) Scheduled                | C > 1 vr            | DHS         | Clarinda MHI   | using metal roofing material  | \$ | 65 000    | Asbestos shingle covering, some leaks,                                     | \$ 191,999,963                               |
| 252      | 4) Scheduled                | C) > 1 yi           | 0113        |                | Replace roof covering on Paint                                      | φ  | 05,000    |  | \$ 191,999,903                               |
|          |                             |                     |             |                | shop detached from main building                                    |    |           |  |  |
| 253      | 4) Scheduled                | C) > 1 vr           | DHS         | Clarinda MHI   | using metal roofing material.                                       | \$ | 30.000    | Asbestos shingle covering original to the building, 1920's                 | \$ 192,029,963                               |
| 200      | .) Concurred                | c) / / . j.         | 20          |                | NCF - Building L Roof Replacement                                   | ÷  | 00,000    |  | φ 102,020,000                                |
| 254      | 4) Scheduled                | C) > 1 vr           | DOC         | Newton CF      | (power plant)   | \$ | 125.000   | Patching on the roof has happened and nearing the end of life cycle        | \$ 192,154,963                               |
|          | .,                          | -)···)·             |             |                | NCF - Building J Roof Replacement                                   | +  | ,         | μ  | +,   |
| 255      | 4) Scheduled                | C) > 1 yr           | DOC         | Newton CF      | (warehouse)   | \$ | 125,000   | Patching on the roof has happened and nearing the end of life cycle        | \$ 192,279,963                               |
|          | ,                           | , ,                 |             |                | NCF - Living Unit A Roof  |    | ·         |  |  |
| 256      | 4) Scheduled                | C) > 1 yr           | DOC         | Newton CF      | Replacement   | \$ | 150,000   | Patching on the roof has happened and nearing the end of life cycle        | \$ 192,429,963                               |
|          |                             |                     |             |                | NCF - Living Unit B Roof  |    |           |  |  |
| 257      | 4) Scheduled                | C) > 1 yr           | DOC         | Newton CF      | Replacement   | \$ | 350,000   | Patching on the roof has happened and nearing the end of life cycle        | \$ 192,779,963                               |
|          |                             |                     |             |                |   |    |           | The electrical service in the Admin Bldg is overloaded due to              |  |
| 258      | 5) Efficiency               | <1 yr               | DHS         | Glenwood       | Electrical upgrade in Admin Bldg                                    | \$ | 300,000   | increased demands on the building.   | \$ 193,079,963                               |
|          |                             |                     |             |                |   |    |           | The current condensate return system relies on numerous                    |  |
|          | <b>_</b>                    |                     |             |                | Evaluate condensate return system                                   |    |           | condensate pumps which are prone to failure and backup of                  |  |
| 259      | 5) Efficiency               | <1 yr               | DHS         | Glenwood       | for vacuum system replacement                                       | \$ | 50,000    | condensate which inhibits the efficiency of the heating system.            | \$ 193,129,963                               |

| 260       5) Efficiency       A) Now       DOC       Mt. Pleasant       West yard upgrade       \$ 150,000       retaining wall and tiling are also needed as the area takes on water.       \$         261       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Cooling Tower Walkway       \$ 12,000       Cited by Dan Duss to install working platforms on towers       \$         262       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Covered Entry to R&D vehicle       A covered entry is needed at our trip door for safely       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution       TV cabling is inadequate to support current use and continual       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$ 4,500       Renovate pharmacy/add pill line window       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficie  | Running Total         193,279,963         193,291,963         193,376,963         193,401,963         193,406,463         193,426,463 |
|---|---|
| 260       5) Efficiency       A) Now       DOC       Mt. Pleasant       West yard upgrade       \$ 150,000       retaining wall and tiling are also needed as the area takes on water.       \$         261       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Cooling Tower Walkway       \$ 12,000       Cited by Dan Duss to install working platforms on towers       \$         262       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Covered Entry to R&D vehicle       A covered entry is needed at our trip door for safely       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution       TV cabling is inadequate to support current use and continual       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$ 4,500       Renovate pharmacy/add pill line window       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficie  | <ul> <li>193,291,963</li> <li>193,376,963</li> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>                   |
| 260       5) Efficiency       A) Now       DOC       Mt. Pleasant       West yard upgrade       \$ 150,000       retaining wall and tiling are also needed as the area takes on water.       \$         261       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Cooling Tower Walkway       \$ 12,000       Cited by Dan Duss to install working platforms on towers       \$         262       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Covered Entry to R&D vehicle       A covered entry is needed at our trip door for safely       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution       TV cabling is inadequate to support current use and continual       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$ 4,500       Renovate pharmacy/add pill line window       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficie  | <ul> <li>193,291,963</li> <li>193,376,963</li> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>                   |
| 260       5) Efficiency       A) Now       DOC       Mt. Pleasant       West yard upgrade       \$ 150,000       retaining wall and tiling are also needed as the area takes on water.       \$         261       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Cooling Tower Walkway       \$ 12,000       Cited by Dan Duss to install working platforms on towers       \$         262       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Covered Entry to R&D vehicle       A covered entry is needed at our trip door for safely       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution       TV cabling is inadequate to support current use and continual       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution       TV cabling is inadequate to support current use and continual       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$ 4,500       Renovate pharmacy/add pill line window       \$         265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficiency       A)   | <ul> <li>193,291,963</li> <li>193,376,963</li> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>                   |
| 261       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Cooling Tower Walkway       \$ 12,000       Cited by Dan Duss to install working platforms on towers       \$         262       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Covered Entry to R&D vehicle<br>loading area       \$       Ac overed entry is needed at our trip door for safely<br>loading/offloading transfers during adverse weather conditions       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       System       \$       25,000       outages and repairs occur.       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution       TV cabling is inadequate to support current use and continual       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$       4,500       Renovate pharmacy/add pill line window       \$         265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$       20,000       set operational data from being displayed at the system touchscreen.       \$         265       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches  | <ul> <li>193,291,963</li> <li>193,376,963</li> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>                   |
| 262       5) Efficiency       A) Now       DOC       Ft Dodge CF       Add Covered Entry to R&D vehicle<br>loading area       \$       A covered entry is needed at our trip door for safely<br>loading/offloading transfers during adverse weather conditions       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       Replace Television Distribution<br>System       TV cabling is inadequate to support current use and continual<br>outages and repairs occur.       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$       4,500       Renovate pharmacy/add pill line window       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$       20,000       Replace defective NOL card in PLC. Faulty card prevents generator<br>set operational data from being displayed at the system touchscreen.       \$         265       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West<br>campus       Install gas lines and install hot water loop boilers Westwood, Larches<br>and Grandwood.       \$  | <ul> <li>193,376,963</li> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>  |
| 262       5) Efficiency       A) Now       DOC       Ft Dodge CF       loading area       \$ 85,000       loading/offloading transfers during adverse weather conditions       \$         263       5) Efficiency       A) Now       DOC       Ft Dodge CF       System       \$       25,000       outages and repairs occur.       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$       4,500       Renovate pharmacy/add pill line window       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$ 4,500       Renovate pharmacy/add pill line window       \$         265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       Replace defective NOL card in PLC. Faulty card prevents generator set operational data from being displayed at the system touchscreen.       \$         266       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches and Grandwood.       \$   | <ul> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>   |
| 263       5) Efficiency       A) Now       DOC       Ft Dodge CF       System       \$ 25,000       outages and repairs occur.       \$ 25,000       outages and repairs occur.       \$ 25,000       outages and repairs occur.       \$ 3,000   | <ul> <li>193,401,963</li> <li>193,406,463</li> <li>193,426,463</li> </ul>   |
| 263       5) Efficiency       A) Now       DOC       Ft Dodge CF       System       \$ 25,000       outages and repairs occur.       \$ 264       \$ 264       \$ 25,000       outages and repairs occur.       \$ 25,000       outages and repairs occur.       \$ 264       \$ 264       \$ 265,000       Period Pharmacy/add pill line window       \$ 266       \$ 266       \$ 20,000       Replace defective NOL card in PLC. Faulty card prevents generator       \$ 20,000       \$ 2   | <ul><li>193,406,463</li><li>193,426,463</li></ul>   |
| 264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Renovate Pharmacy       \$ 4,500       Renovate pharmacy/add pill line window       \$         264       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       Replace defective NOL card in PLC. Faulty card prevents generator set operational data from being displayed at the system touchscreen.       \$         266       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches and Grandwood.       \$   | <ul><li>193,406,463</li><li>193,426,463</li></ul>   |
| 265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       Replace defective NOL card in PLC. Faulty card prevents generator set operational data from being displayed at the system touchscreen.       \$ 20,000         266       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches and Grandwood.       \$ 160,000  | \$ 193,426,463  |
| 265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         266       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches       \$         266       5) Efficiency       A) Now       DHS       WRC       \$       160,000       and Grandwood.       \$  |   |
| 265       5) Efficiency       A) Now       DOC       Ft Dodge CF       Generator PLC repairs       \$ 20,000       set operational data from being displayed at the system touchscreen.       \$         266       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches       \$         266       5) Efficiency       A) Now       DHS       WRC       \$       160,000       and Grandwood.       \$  |   |
| 266       5) Efficiency       A) Now       DHS       WRC       Install Gas Lines East and West campus       Install gas lines and install hot water loop boilers Westwood, Larches  |   |
| 266 5) Efficiency A) Now DHS WRC campus \$ 160,000 and Grandwood. \$  | 100 500 100   |
|   | \$ 193,586,463  |
|   | ,,,   |
|   | \$ 193,836,463  |
| Iowa Veterans I Iowa Veterans | ,,,   |
|   | \$ 193,946,463  |
| No ac in kitchen. Staff and offender workers cooking food in 12-130   | 100,010,100   |
| s a la la la la la la la la la la la la l   | \$ 194,796,463  |
| Fire protection hydrants and These building do not have fire sprinkler systems and the closest fire   | 0,104,700,400   |
| Capitol sprinklers for the Central Energy hydrant to these building to not have me sprinkler systems and the closest me   |   |
|   | \$ 197,139,161  |
|   | § 197,639,161   |
| Install HVAC system in the Lodge Building has no AC, heating system is original 1940's. Needs   | p 197,039,101   |
|   | \$ 198,139,161  |
| Replace the Control Center 2 Gate   | p 190,139,101   |
|   | \$ 198,239,161  |
|   |   |
|   | <pre>\$ 198,414,161 \$ 200,414,161</pre>  |
|   |   |
| Air conditioning, ductwork dampers,   | \$ 202,807,194  |
| zone valves & convector upgrades  |   |
|   | 001 010 050   |
| 277       5) Efficiency       A) Now       DHS       Cherokee       to main building       \$ 1,511,664       Capital request       \$         277       5) Efficiency       A) Now       DHS       Cherokee       to main building       \$ 1,511,664       Capital request       \$   | \$ 204,318,858  |
|   |   |
|   | § 204,368,858   |
| 2/3 3) Efficiency A) Now DTS Chelokee Build enclosed stall towers-Friase 1 3 1,273,000 Capital request  | \$ 205,643,858  |
| 280 5) Efficiency A) Now DHS Cherokee Sidewalk replacement-campus wide \$ 588,500   | \$ 206,232,358  |
| 280       5) Efficiency       A) Now       DHS       Cherokee       Sidewalk replacement-campus wide       \$       588,500       \$         280       5) Efficiency       A) Now       DHS       Cherokee       Sidewalk replacement-campus wide       \$       588,500       \$         Main bldg north patient wing-\$748,500; main bldg south patient wing-       Main bldg north patient wing-\$748,500; main bldg south patient wing-       \$  | \$ 200,232,336  |
| Replace windows for all campus \$748,500; Main bldg east ADM wing-\$305,000; Main bldg west wing-   |   |
|   |   |
|   |   |
| 201 E) Efficiency A) New DUC Charakas MUDC  |   |
|   | § 207,722,358   |
|   | \$ 207,981,108  |
| Repair campus garages &   |   |
|   | § 208,049,308   |
|   | § 208,806,620   |
|   | \$ 208,966,620  |
| Building – Automation Controls –  |   |
|   | \$ 209,322,620  |
| Building – Automation Controls –  |   |
|   | 5 209,681,620   |
| 288       5) Efficiency       A) Now       DHS       Glenwood       Replace HVAC in 710 Lacey Hall.       \$ 512,309  | \$ 210,193,929  |

|     |               |           |             |              |                                     | F        | unding    | Joor ( 6440010   | _,    |              |
|-----|---------------|-----------|-------------|--------------|-------------------------------------|----------|-----------|--|-------|--------------|
|     | Priority      | Immediacy | Agency      | Facility     | Project Title                       | F        | Request   | Comments   | Rı    | unning Total |
|     |               |           |             |              |                                     |          |           | Doesn't meet the health code due to lack of sufficient dirty/clean       | 1     |              |
|     | 5) Efficiency | A) Now    | DOC         | ASP          | Remodel Laundry                     | \$       | 700,000   | laundry separation.  | \$    | 210,893,929  |
| 290 | 5) Efficiency | A) Now    | DHS         | Glenwood     | Window Replacement Building 106     | \$       | 435,000   |  |       | 211,328,929  |
| 291 | 5) Efficiency | A) Now    | DHS         | Glenwood     | Window Replacement Building 111     | \$       | 325,000   |  | \$    | 211,653,929  |
|     |               |           |             |              |                                     |          |           | Can reduce scope on this bldg - would like to do minimal window          |       |              |
|     |               |           |             |              |                                     |          |           | replacement on main floor and cover remaining windows - this bldg is     |       |              |
|     | 5) Efficiency |           | DHS         | Glenwood     | Window Replacement Building 119     | \$       | ,         | used for storage/upholstery shop   | - · · | 211,843,929  |
| 293 | 5) Efficiency | A) Now    | DHS         | Glenwood     | Window Replacement Building 121     | \$       | 80,000    |  | \$    | 211,923,929  |
|     |               |           |             |              |                                     |          |           | Facility is getting by with what they have (a ramp and small elevator),  |       |              |
| 294 | 5) Efficiency | A) Now    | DHS         | Glenwood     | Meyer Hall - Install New Elevator   | \$       | 596,500   | but a new elevator would be more convenient.                             | \$    | 212,520,429  |
|     |               |           |             |              |                                     |          |           | Cannot be used for drinking water without further treatment, but it is   |       |              |
|     |               |           |             |              |                                     |          |           | not currently used for drinking water and there is city water back-up if |       |              |
| 295 | 5) Efficiency | A) Now    | DOC         | ASP          | Add water treatment to well #4      | \$       | 1,000,000 | the other wells fail.  | \$    | 213,520,429  |
|     |               |           |             |              | Yard expansion with industrial      |          |           |  |       |              |
|     |               |           |             |              | arts/recreation building. Includes  |          |           |  |       |              |
| 296 | 5) Efficiency | A) Now    | DHS         | CCUSO        | 1600 linear feet of fencing         | \$       | 1,418,965 | Capital request. (Study-Phase I Project-Phase II)                        | \$    | 214,939,394  |
|     |               |           |             |              | Renovate South 1, S2 & S3 areas in  |          |           |  |       |              |
|     | 5) Efficiency |           | DHS         | CCUSO        | main building. (HVAC updates)       | \$       | 518,000   |  | - · · | 215,457,394  |
| 298 | 5) Efficiency | A) Now    | DHS         | CCUSO        | Outdoor Recreational facilities     | \$       | 175,000   | Capital request  | \$    | 215,632,394  |
|     |               |           |             |              | Powerhouse lighting, windows and    | •        | ~~ ~~~    |  |       |              |
| 299 | 5) Efficiency | A) Now    | DOC         | ASP          | ventilation                         | \$       | 60,000    |  | \$    | 215,692,394  |
|     |               |           |             |              | Connect Greenhouse to Hot Water     | •        | ~~ ~~~    |  |       |              |
|     | 5) Efficiency |           | DOC         | Ft Dodge CF  | Loop                                | \$       | 20,000    |  | - · · | 215,712,394  |
|     | 5) Efficiency |           | DOC         | Ft Dodge CF  | Salt-Sand Building                  | \$       |           | Should use capitol or operations funding.                                |       | 215,732,394  |
| 302 | 5) Efficiency | A) NOW    | DOC         | ASP          | Replace Security Lighting           | \$       | 50,000    |  | \$    | 215,782,394  |
| 000 |               | A) NI     | <b>D</b> 00 |              | Add Industry Building to Automation | <b>^</b> | 40.000    |  | •     |              |
| 303 | 5) Efficiency | A) Now    | DOC         | Ft Dodge CF  | System                              | \$       | 42,000    |  | \$    | 215,824,394  |
| 204 |               |           | DOC         |              |                                     | ¢        | 00.000    |  | ¢     | 045 004 004  |
| 304 | 5) Efficiency | A) NOW    | DOC         | ASP          | Replace windows & screens in LU-B   | \$       | 80,000    |  | \$    | 215,904,394  |
| 205 |               |           | DOC         |              | Replace windows & screens in LU-    | ¢        | 00.000    |  | ¢     | 045 004 004  |
| 305 | 5) Efficiency | A) Now    | DOC         | ASP          | Replace windows & screens in LU-    | \$       | 80,000    |  | Э     | 215,984,394  |
| 206 | E) Efficiency | A) Now    | DOC         | ASP          | D                                   | \$       | 80.000    |  | ¢     | 216 064 204  |
| 300 | 5) Efficiency | A) NOW    | DOC         | AGF          | Replace windows & screens in        | φ        | 80,000    |  | Ð     | 216,064,394  |
| 207 | 5) Efficiency | A) Now    | DOC         | ASP          | auditorium                          | \$       | 30,000    |  | ¢     | 216,094,394  |
| 307 | 5) Efficiency | A) NOW    | DOC         | AGF          | Replace windows & screens in        | φ        | 30,000    |  | - Φ   | 210,094,394  |
| 208 | 5) Efficiency |           | DOC         | ASP          | chapel                              | \$       | 30,000    |  | ¢     | 216,124,394  |
| 300 | 5) Eniciency  | A) NOW    | DOC         | AGF          | Replace windows & screens in        | φ        | 30,000    |  | φ     | 210,124,394  |
| 200 | 5) Efficiency |           | DOC         | ASP          | music room                          | \$       | 30,000    |  | ¢     | 216,154,394  |
| 309 | 5) Eniciency  | A) NOW    | DOC         | Capitol      | IWD 150 Des Moines Street PA        | φ        | 30,000    |  | φ     | 210,154,594  |
| 210 | 5) Efficiency | A) Now    | DAS         | Complex      | System                              | \$       | 50,000    |  | ¢     | 216,204,394  |
| 510 |               |           | 070         | Complex      | System                              | Ψ        | 50,000    | 2 Miura 300-hp boilers were purchased at the end of FY13 with            | φ     | 210,204,394  |
|     |               |           |             |              |                                     |          |           | operation funds eliminating the need to use Major Maintenance funds      |       |              |
|     |               |           |             |              |                                     |          |           | to secure the boilers themselves. Facility has also paid for and is      |       |              |
|     |               |           |             |              |                                     |          |           | anticipating the completion of the design for the installation of the    |       |              |
| 311 | 5) Efficiency | A) Now    | DHS         | Independence | Install New Boilers                 | \$       | 460 000   | units. Funds requested would make the boilers operational.               | \$    | 216,664,394  |
| 0.1 | c, Encicitoy  |           | 2.10        | Capitol      | Capitol Building Law Library Rare   | Ψ        | 400,000   | The most valuable and rare books of the law library are stored in this   | ť     | 210,004,004  |
| 312 | 5) Efficiency | A) Now    | DAS         | Complex      | Book Climate Control                | \$       | 25 250    | secure room that at times exceeds 90 degrees with high humidity.         | ¢     | 216,689,644  |
| 512 |               |           | 570         | Complex      |                                     | Ψ        | 20,200    | Isocare room mar ar ames enceeds 30 degrees with high humbling.          | ŢΦ    | 210,003,044  |

|     |               |           |        |             |  | F  | unding    |  |    |              |
|-----|---------------|-----------|--------|-------------|--|----|-----------|--|----|--------------|
|     | Priority      | Immediacy | Agency | Facility    | Project Title                          | R  | Request   | Comments   | R  | unning Total |
|     |               |           |        |             |  |    |           | safety and health. It is the main sewer effluent from our facility before<br>heading to city sewer system. It contains a manual bar screen that<br>needs to be cleaned by personnel. The bar screen is raked and the<br>contents are emptied into a bucket manually and sent to the landfill.<br>This material includes fecal material which can contain pathogens<br>harmful to the health of staff and inmates. Also include with this<br>trouble area is there is no atmosphere testing equipment to alarm<br>individuals of an unsafe environment. If the air is unsafe when<br>entering it could cause death of personnel. We are recommending<br>adding redundant automatic cleaning devices such as auger monster<br>type equipment to clean this system. Environmental controls should<br>be added to ensure the building atmosphere is safe. This should be   |    |              |
| 313 | 5) Efficiency |           | DOC    | ІМСС        | Sanitary Sewer Effluent Upgrade        | \$ | 1,970,482 |  | \$ | 218,660,126  |
| 010 |               |           |        |             |  | Ŷ  | 1,010,102 | Offenders are able to flood cells, which leaks down into offices, onto computers and other equipment. During construction of the CCU, an adequate way of shutting off the water to the showers on A & B pods was not installed. Since we are not able to isolate each shower individually, the inmates are able to flood the ranges. Since there are no floor drains for the contaminated water to go, "gray" and "black" water mixes together and leaks to the lower pods and/or  |    | 210,000,120  |
|     |               |           |        |             | Replace Plumbing Controls - John       |    |           | administrative offices, contaminating carpet, furniture, ceiling tiles,  |    |              |
| 314 | 5) Efficiency | A) Now    | DOC    | ISP         | Bennett                                | \$ | 55,000    | etc., which is a life/health/safety issue.   | \$ | 218,715,126  |
|     |               |           |        |             |  |    |           | operate at 70-100% load. These boiler were grossly undersized when<br>installed in 2006 and are designed for high pressure low volume<br>output. #1 boiler is 250 hp, #2 boiler is 150 hp and #3 boiler is 150<br>hp. These three vapor powered boilers replaced two Murray 600 hp<br>boilers in 2006. Buildings additions were added at that time however<br>the boiler capacity decreased by 650 hp. Because of this the facility<br>experiences reduced steam pressure in their systems resulting in hot<br>water fluctuations, traps working improperly and sometimes heating<br>issues. Additional boiler capacity needs to be added to ensure we<br>maintain a safe and secure environment. We are recommending four<br>250hp fire tube boilers with controls and Siemens communication be<br>supplied to give the facility redundancy and backup for safety and<br>security of our facility. Also in 2006 with the new power house<br>to feed the 3 boilers. DA tanks require internal inspections (requires<br>shut down of tank) every other year and without a redundant tank,<br>boiler feed water is required to bypass the DA tank during the<br>inspection. The DA tank is required to remove oxygen from the water<br>to maintain boiler tube integrity. The other issue is if this tank were to<br>fail we have no backup and the boiler would be forced to receive<br>oxygenated water which causes pitting, reduces tube life and could<br>lead to tube failure in the boiler. The 2006 upgrade also included the<br>addition of two 3600 gallon per minute Bell and Gossett water booster<br>pumps. Unless firefighting measures are required these pumps |    |              |
| 315 | 5) Efficiency | A) Now    | DOC    | IMCC        | Boiler Upgrades                        | \$ |           | operate at minimum speeds to supply water pressure to the facility   | \$ | 220,035,521  |
|     |               |           |        |             |  |    |           | Install a water line for irrigating gardens, washing down dog pee  |    |              |
| 216 | 5) Efficiency |           | DOC    | Ft Dodge CF | Add Untreated Water Line               | ¢  |           | pads, etc. Current only treated/conditioned water is available from the power plant.   |    | 220 042 024  |
| 310 | 5) Efficiency |           | DOC    |             | Add additional lighting to all pods in | \$ | 0,500     | power plant.   | Ð  | 220,042,021  |
| 317 | 5) Efficiency | A) Now    | DOC    | ISP         | John Bennett                           | \$ | 75,000    |  | \$ | 220,117,021  |

|     | Priority      | Immediacy | Agency | Facility      | Project Title                     | Funding<br>Request | Comments   | Running Total  |
|-----|---------------|-----------|--------|---------------|-----------------------------------|--------------------|--|----------------|
|     |               |           |        |               | -                                 | _                  |  | ]              |
|     |               |           |        |               | Retube hot water boilers at power |                    | Leaking tubes are being replaced as needed. Replacement of worn  |                |
| 318 | 5) Efficiency | A) Now    | DOC    | Ft Dodge CF   | plant                             | \$ 75,00           | 0 tubes (186) around the morrison tubes of all three boilers is needed.  | \$ 220,192,021 |
|     |               |           |        |               | Upgrade Camera Recording          |                    | Camera recording equipment is overloaded and can not store the   |                |
| 319 | 5) Efficiency | A) Now    | DOC    | Ft Dodge CF   | System                            | \$ 100,00          | 0 desired amount of data at the desired resolution.  | \$ 220,292,021 |
|     |               |           |        |               |                                   |                    | Our facility has its own hot water system which consists of three heating units and one storage tank. Since the installation of this |                |
|     |               |           |        |               |                                   |                    | system we have had to send each heating unit back to manufacturer  |                |
|     |               |           |        |               |                                   |                    | for refurbishing. The system continues to operate with water   |                |
|     |               |           |        |               |                                   |                    | temperature below necessary limits of 160 degrees. The system is<br>approximately 8 years old and needs to be updated to continue to |                |
|     |               |           |        |               |                                   |                    | supply water to washer for proper operation and to ensure clothes are  |                |
|     |               |           |        |               |                                   |                    | cleaned and disinfected properly by maintaining the temperatures.  |                |
|     |               |           |        |               |                                   |                    | Our Facility continues to rely on one hot water tank (1970 initial   |                |
|     |               |           |        |               |                                   |                    | building) to supply hot water to the older portion of our building. This   |                |
|     |               |           |        |               |                                   |                    | includes showers for inmates, dietary needs and general sink usage.  |                |
|     |               |           |        |               |                                   |                    | It consist of a 5000 gallon Tank which contains a steam heating coil   |                |
|     |               |           |        |               |                                   |                    | inside. Currently this coil is suspected to be ruptured causing heavier  |                |
|     |               |           |        |               |                                   |                    | loads to be place on our boilers, increases in condensate returning  |                |
|     |               |           |        |               |                                   |                    | and also increases chemical treatment chemical. All these items  |                |
|     |               |           |        |               |                                   |                    | increase costs to our facility. We recommend removing the old tank   |                |
|     |               |           |        |               |                                   |                    | and installing two new tanks (possibly dual fuel capability) and supply  |                |
| 320 | 5) Efficiency | A) Now    | DOC    | IMCC          | Hot Water Systems Upgrade         | \$ 501,72          | 9 Siemens communication to monitor this system.  | \$ 220,793,750 |
|     |               |           |        |               |                                   |                    | The older buildings at IMCC are currently 44 years old. As   | 1              |
|     |               |           |        |               |                                   |                    | modernization has occurred (Computers, cameras, inmates TV's,  |                |
|     |               |           |        |               |                                   |                    | radios, Fans Etc.) items have been added to the existing electrical  |                |
|     |               |           |        |               |                                   |                    | system and it is now full. Electrician are being asked to add  |                |
|     |               |           |        |               |                                   |                    | equipment but by codes, our system is no longer able to handles  |                |
|     |               |           |        |               |                                   |                    | additions. It is necessary to upgrade the electrical primary panels  |                |
|     |               |           |        |               |                                   |                    | (First panels inside the buildings) and add some additional panels,  |                |
|     |               |           |        |               |                                   |                    | wiring and junctions throughout our buildings (Older buildings).   |                |
|     |               |           |        |               |                                   |                    | Currently breakers trip repeatedly during normal daily activities such   |                |
|     |               |           |        |               |                                   |                    | as plugging in a vacuum or buffer. There would need to be an   |                |
|     |               |           |        |               |                                   |                    | engineering study performed, designed and arc flash program set up   |                |
| 321 | 5) Efficiency | A) Now    | DOC    | IMCC          | Electric Services Upgrade         | \$ 2,929,00        | 6 with this request.   | \$ 223,722,756 |
|     |               | A) Now    | DOC    | IMCC          | Old Records Remodel               | . ,                | 7 Remodel Old Records Area   | \$ 223,884,463 |
| 323 | 5) Efficiency | A) Now    | DOC    | IMCC          | Dead records Remodel              | \$ 557,49          | 1 Remodel Dead Records Area  | \$ 224,441,954 |
|     |               |           |        |               |                                   |                    |  |                |
|     | ->            |           |        | North Central |                                   | • • • • • • •      | To provide efficient access for security operations and egress , which   |                |
| 324 | 5) Efficiency | A) Now    | DOC    | CF            | Control Center Replacement        | \$ 1,000,00        | 0 retains all security doors, gates and egresses in and out of facility.   | \$ 225,441,954 |
|     |               |           |        |               |                                   |                    | Unit is original to 1979 construction, is undersized, with condensate  |                |
|     |               |           |        |               |                                   |                    | leaks. It has been re-skinned many times. DIA issued a comment   |                |
|     |               |           |        | Iowa Veterans |                                   |                    | during annual inspection, indicating this unit needs replaced to avoid   |                |
| 325 | 5) Efficiency | A) Now    | DVA    | Home          | Malloy Building Air Handler       | \$ 100,00          | 0 a citation.  | \$ 225,541,954 |
|     | ->            |           |        | Iowa Veterans |                                   | • • • • • •        |  |                |
| 326 | 5) Efficiency | A) Now    | DVA    | Home          | Chilled Water Distribution Valves | \$ 35,00           | 0 To improve system performance in Sheeler and Loftus  | \$ 225,576,954 |
|     |               |           |        | Iowa Veterans |                                   |                    | Hazard analysis of all electrical panels as required by Electrical   |                |
| 327 | 5) Efficiency | A) Now    | DVA    | Home          | Arc flash study                   | \$ 200,00          | 0 Inspector  | \$ 225,776,954 |
|     |               |           | DOC    | N / 05        | Update electrical at boiler and   |                    |  |                |
| 328 | 5) Efficiency | A) Now    | DOC    | Newton CF     | tunnel                            | \$ 60,00           |  | \$ 225,836,954 |
|     |               |           |        |               | Upgrade HVAC System in            |                    | The current ductwork needs to be modified to improve uniformity of   |                |
| 329 | 5) Efficiency | B) < 1 yr | DHS    | GRC           | Administration Bldg               | \$ 100,00          | 0 heating in the Administration Bldg.  | \$ 225,936,954 |

|     |                     |                            |        |                 |                                    |    | runding   |  |     |              |
|-----|---------------------|----------------------------|--------|-----------------|------------------------------------|----|-----------|--|-----|--------------|
|     | Priority            | Immediacy                  | Agency | Facility        | Project Title                      | I  | Request   | Comments   | Rι  | unning Total |
| Ī   |                     |                            |        |                 | Chilled water lines and HVAC       |    |           |  | T   |              |
|     |                     |                            |        |                 | equipment to patient areas of      |    |           |  |     |              |
| 220 | 5) Efficiency       | $D \rightarrow 1 \gamma r$ | DHS    | Clarinda MHI    | activities, and offices            | \$ | 2,601,000 |  | ¢   | 000 507 054  |
| 330 | 5) Efficiency       | b) < г уг                  | рпо    |                 |                                    | φ  | 2,001,000 |  | - Þ | 228,537,954  |
|     |                     |                            |        |                 | Generator Upgrade for Co-          |    |           |  |     |              |
|     |                     |                            |        |                 | generation (Combined Heat &        |    |           |  |     |              |
| 331 | 5) Efficiency       | B) <1 yr                   | DHS    | Independence    | Power)                             | \$ | 100,000   | Capital request.   | \$  | 228,637,954  |
|     | 5) Efficiency       |                            | DOC    | Newton CF       | Correct area drainage Bldg 10      | \$ | 35.000    |  | \$  | 228,672,954  |
|     | 5) Efficiency       |                            | DOC    | Mt. Pleasant    | 10 Cell Isolation Expansion        | \$ | )         | Capital. Need for additional lock-up space.                            |     | 228,972,954  |
| 000 |                     | 0) × 1 yi                  | 200    | Mit. Theasant   |                                    | Ψ  | 000,000   | Provides for design and renovation services to pave existing gravel    | Ψ   | 220,572,554  |
|     |                     |                            |        |                 |                                    |    |           | parking lots, including associated building demolition, add storm      |     |              |
|     |                     |                            |        |                 |                                    |    |           |  |     |              |
|     |                     |                            |        |                 |                                    |    |           | water detention as required by Iowa code, parking lot lighting and     |     |              |
|     |                     |                            |        |                 |                                    |    |           | area landscaping to enhance the appearance and comply with lowa        |     |              |
|     |                     |                            |        |                 |                                    |    |           | code. These two parking lots are existing gravel areas to the North of |     |              |
|     |                     |                            |        |                 |                                    |    |           | IWD and are on hill side and are unsafe to park in during the winter   |     |              |
|     |                     |                            |        | Capitol         |                                    |    |           | months as the vehicles will slide down the hill and is dangerous to    |     |              |
| 334 | 5) Efficiency       | C > 1 vr                   | DAS    | Complex         | Replace Parking Lots 17 and 22     | \$ |           | walk on. These lots have been closed off during icy conditions.        | \$  | 230,193,431  |
| 001 |                     | 0) / I Ji                  | 5/10   | Complex         |                                    | Ψ  | 1,220,111 | The existing emergency generators and transfer switches located at     | Ψ   | 200,100,401  |
|     |                     |                            |        | 0 11 1          |                                    |    |           |  |     |              |
|     |                     |                            |        | Capitol         | Capitol Complex Emergency          |    |           | the various buildings are a life / safety issues which need to be      |     |              |
| 335 | 5) Efficiency       | C) > 1 yr                  | DAS    | Complex         | Generator Study                    | \$ |           | addressed.   | \$  | 230,300,491  |
|     |                     |                            |        | Capitol         | Central Energy Plant Boiler        |    |           | Replace burners for Boiler #3 and add new DDC controls for all 3       |     |              |
| 336 | 5) Efficiency       | C) > 1 vr                  | DAS    | Complex         | Optimization                       | \$ | 412.200   | boilers optimization.  | \$  | 230,712,691  |
|     | -,,                 | -/ /                       | _      | Capitol         | Capitol Building Granite Retaining |    | ,         |  | Ť   | ,            |
| 337 | 5) Efficiency       | C > 1 vr                   | DAS    | Complex         | Wall Repair                        | \$ | 150 000   | To repair the North side granite retaining wall along Grand Ave        | ¢   | 230,862,691  |
| 557 | 5) Enciency         | C) > 1 yi                  | DAG    | Complex         | Capitol Complex Security Camera    | Ψ  | 150,000   |  | - Ψ | 230,002,091  |
|     |                     |                            |        |                 |                                    |    |           |  |     |              |
|     |                     |                            |        | Capitol         | Expansion for Parking Ramp and     |    |           | Add security cameras to the parking ramp and the parking lots North    |     |              |
| 338 | 5) Efficiency       | C) > 1 yr                  | DAS    | Complex         | North of Grand Ave                 | \$ | 308,385   | of Grand Ave.  | \$  | 231,171,076  |
|     |                     |                            |        | Capitol         | Capitol Complex Chilled Water 3-   |    |           | Valve replacement program to replace all 3-way chilled water valves    | Ī   |              |
| 339 | 5) Efficiency       | C) > 1 vr                  | DAS    | Complex         | way Valve Replacement              | \$ | 564,240   | with 2-way valves for system optimization.                             | \$  | 231,735,316  |
|     | c) <u>_</u> c.c.roj | <b>c</b> // · · j.         | 27.10  | e emplex        |                                    | Ψ  | 00.,2.0   | Over the years all types of mechanical/electrical equipment and        | Ť   | 201,100,010  |
|     |                     |                            |        |                 |                                    |    |           |  |     |              |
|     |                     |                            |        |                 |                                    |    |           | associated piping has been abandoned in place, taking up valuable      |     |              |
|     |                     |                            |        |                 |                                    |    |           | space which could be used for future projects. It also makes working   |     |              |
|     |                     |                            |        |                 |                                    |    |           | on the surrounding equipment difficult and costly. The abandon         |     |              |
|     |                     |                            |        |                 |                                    |    |           | equipment is also being used as a catch all for unneeded storage.      |     |              |
|     |                     |                            |        | Capitol         | Demolition of Old and Abandoned    |    |           | There is a salvage value to this equipment that could be utilized,     |     |              |
| 340 | 5) Efficiency       | C) > 1 vr                  | DAS    | Complex         | Mechanical and Electric Systems    | \$ | 282,120   | making it worth while to remove and dispose of.                        | \$  | 232,017,436  |
| 0.0 | c) <u>_</u> c.c.roj | <b>c</b> // · · j.         | 27.10  | Capitol         | Re-commissioning and Balancing of  | Ψ  |           | Efficiencies in equipment and extended equipment life can be gained    | Ť   | _0_,0,.00    |
| 244 | E) Efficiency       | (), $1$ , $m$              | DAS    |                 |                                    | ¢  |           |  | ¢   | 000 000 550  |
| 341 | 5) Efficiency       | C) > T yr                  | DAS    | Complex         | Systems and Equipment              | \$ | 202,120   | by balancing the needed equipment.                                     | •   | 232,299,556  |
|     |                     |                            |        |                 |                                    |    |           |  | 1   |              |
|     |                     |                            |        |                 | Iowa Labs Exhaust Duct             |    |           | The acid fumes keeps eating out the stainless steel ducts for the SHL  |     |              |
| 342 | 5) Efficiency       | C) > 1 yr                  | DAS    | Iowa Labs       | Replacement                        | \$ |           | fume hoods. Needs to be replaced with an acid resistant material.      | \$  | 232,399,556  |
| Ī   |                     |                            |        |                 | Iowa Labs Ag Dept Grinding Room    |    |           | Install dehumidifier in the grinding room, so the AHU does not need    | 1   |              |
| 343 | 5) Efficiency       | C > 1 vr                   | DAS    | Iowa Labs       | Dehumidification                   | \$ |           | to be run so low that it super cools adjacent areas.                   | \$  | 232,471,556  |
| 0.0 | c) <u>_</u> c.c.roj | <b>c</b> // · · j.         | 27.10  |                 | Iowa Labs Wall Extensions up to    | Ψ  |           | Extend walls up to the deck for pressurization requirements. Required  |     | _0_,,000     |
| 244 |                     | C) . 1                     | DAG    | lawa Laha       |                                    | ¢  |           |  |     | 000 004 550  |
| 344 | 5) Efficiency       | C) > 1 yr                  | DAS    | Iowa Labs       | the Deck                           | \$ |           | for testing requirements and cross contamination.                      | •   | 232,621,556  |
|     |                     |                            |        |                 |                                    |    |           | Install high efficiency cooling towers to reduce, energy consumption,  |     |              |
| 345 | 5) Efficiency       | C) > 1 yr                  | DOC    | Ft Dodge CF     | Replace 3 Cooling Towers           | \$ | 475,000   | water use and maintenance expenses.                                    | \$  | 233,096,556  |
| 346 | 5) Efficiency       | C) > 1 yr                  | ILEA   | ILEA            | Replace Boiler                     | \$ | 75,000    | Boiler was installed in 1969, but still works.                         | \$  | 233,171,556  |
| ľ   | . ,                 |                            |        |                 | <u> </u>                           |    | · · ·     | Rust around the steel frames and buckling sills from condensation,     | 1   |              |
| 347 | 5) Efficiency       | C > 1 yr                   | ILEA   | ILEA            | Replace windows                    | \$ |           | but no known infiltration.   | ¢   | 233,796,556  |
| 547 |                     | ⊂ <i>j ~</i> i yi          |        |                 |                                    | Ψ  | 020,000   |  | Ψ   | 200,700,000  |
|     |                     |                            |        |                 |                                    |    |           |  |     |              |
|     |                     |                            |        | State Training  |                                    |    |           |  | 1   |              |
| 348 | 5) Efficiency       | C) > 1 yr                  | DHS    | School - Eldora | Kitchen HVAC and hood ventilation  | \$ | 250,000   | Improved food safety/sanitation in food prep areas.                    | \$  | 234,046,556  |
| -   |                     |                            |        |                 |                                    |    |           |  |     |              |

|     |               |            |              |                 |   |          | Funding    |  |  |
|-----|---------------|------------|--------------|-----------------|---|----------|------------|--|--|
|     | Priority      | Immediacy  | Agency       | Facility        | Project Title   |          | Request    | Comments   | Running Total                                |
|     |               |            |              |                 |   |          | -          | Handicapped access for campus housing rental. Can find alternative   | _  |
|     |               |            |              |                 |   |          |            | locations when handicapped access is required. Cost may be double  |  |
| 349 | 5) Efficiency | C) > 1 yr  | DHS          | Cherokee        | Install elevator in Wirth Hall building                       | \$       | 715,000    | the request, based on CCUSO elevator cost.   | \$ 234,761,556                               |
|     |               | , ,        |              | North Central   | Ŭ   |          |            | No immediate danger, but are continuing to make minor repairs and  |  |
| 350 | 5) Efficiency | C) > 1 yr  | DOC          | CF              | Repair exterior Bldgs.  | \$       | 240,000    | the stucco is bad repair.  | \$ 235,001,556                               |
|     | 5) Efficiency |            | DHS          | Independence    | Stewart Hall Window Replacement                               | \$       | 352,500    |  | \$ 235,354,056                               |
|     |               | C) > 1 yr  | DHS          | Independence    | Infirmary Window Replacement                                  | \$       | 705,000    |  | \$ 236,059,056                               |
|     | 5) Efficiency |            | DHS          |                 | Witte Electrical Upgrade                                      | \$       | 200,000    |  | \$ 236,259,056                               |
| 354 | 5) Efficiency | C) > 1 yr  | DHS          | Independence    | Infirmary Electrical Upgrade                                  | \$       | 100,000    |  | \$ 236,359,056                               |
| 355 | 5) Efficiency | C) > 1 yr  | DHS          |                 | Campus-wide Asbestos Abatement                                | \$       | 300,000    |  | \$ 236,659,056                               |
|     |               |            |              | North Central   |   |          |            | Need to tie into Siemen Fire alarm System and cost of software and   |  |
| 356 | 5) Efficiency | C) > 1 yr  | DOC          | CF              | Greenhouse Automation   | \$       | 30,000     | wiring.  | \$ 236,689,056                               |
| 357 | 5) Efficiency | C) > 1 yr  | DOC          | Clarinda DOC    | Kitchen and storeroom   | \$       | 15,000,000 | Construct new kitchen and storeroom for the DOC. Storeroom has known structural cracking and deficiencies. Kitchen was last redone in 1995 and needs repaired or replaced. | \$ 251,689,056                               |
|     |               |            |              | 0               | Update Kitchen Cooler/Freezers                                |          |            | Kitchen coolers/freezers and food storage areas are in need of renovation and improvement in energy efficiency and are   |  |
| 358 | 5) Efficiency | C) > 1 yr  | DHS          | School - Eldora | and food storages areas                                       | \$       | 150,000    | approaching the end of their useful life.  | \$ 251,839,056                               |
|     |               |            |              |                 | Add wall in hallway between rec                               |          |            |  |  |
| 359 | 5) Efficiency | C) > 1 yr  | DOC          | Newton CF       | room and hall   | \$       | 100,000    |  | \$ 251,939,056                               |
|     |               |            |              |                 | Install security screens in dorms 1/2                         |          |            |  |  |
| 360 | 5) Efficiency | C) > 1 yr  | DOC          | Newton CF       | windows   | \$       | 175,000    |  | \$ 252,114,056                               |
|     |               |            |              |                 | Replace water line Bldg. #10 to                               |          |            |  |  |
| 361 | 5) Efficiency | C) > 1 yr  | DOC          | Newton CF       | shop, and warehouse   | \$       | 40,000     |  | \$ 252,154,056                               |
|     |               |            |              |                 | Replace electrical in Bldg. 14 (ILU)                          |          |            |  |  |
| 362 | 5) Efficiency | C) > 1 yr  | DOC          | Newton CF       | and 10 (training center)                                      | \$       | 15,000     |  | \$ 252,169,056                               |
|     | ->            |            |              |                 | CRC - Replace showers in Dorms 1                              | •        |            |  |  |
|     | 5) Efficiency |            | DOC          |                 | & 2   | \$       | 55,000     |  | \$ 252,224,056                               |
|     | 5) Efficiency |            | DOC          |                 | Replace dietary equipment                                     | \$       | 500,000    |  | \$ 252,724,056                               |
|     | 5) Efficiency |            | DOC          |                 | Chemical and paint storage facility                           | \$       | 55,000     |  | \$ 252,779,056                               |
|     |               | C) > 1 yr  | DOC          |                 | Replace servery equipment                                     | \$       | 250,000    |  | \$ 253,029,056                               |
|     | 5) Efficiency |            | DOC          |                 | Metal storage building  | \$       | 100,000    |  | \$ 253,129,056                               |
| 368 | 5) Efficiency | C) > 1 yr  | DOC          | Newton CF       | Vehicle building  | \$       | 125,000    |  | \$ 253,254,056                               |
| 000 |               |            | <b>DO</b> O  |                 | Add room to maintenance building                              | <b>~</b> | 50.000     |  | <b>•</b> • • • • • • • • • • • • • • • • • • |
| 369 | 5) Efficiency | C) > 1 yr  | DOC          |                 | and proper ventilation  | \$       | 50,000     | Debabilitete energiaine bistorie ale des auto the sectority for sectori  | \$ 253,304,056                               |
| 070 |               | 0) 1       | <b>D</b> 4 0 | Capitol         | Operational Desided and Operations                            | <b>~</b> | 45 000     | Rehabilitate remaining historic clocks onto the satellite time control   | ¢ 050.040.050                                |
| 370 | 5) Efficiency | C) > 1 yr  | DAS          | Complex         | Capitol Building Clock Conversion                             | \$       | 15,000     | system.  | \$ 253,319,056                               |
| 074 |               | 0). 1      | D00          |                 | Deplese laws day any instant                                  | ¢        | 200.000    | Rising population numbers have increased the laundry operation by  | ¢ 050.040.050                                |
| 3/1 | 5) Efficiency | C) > 1 yi  | DOC          | Ft Dodge CF     | Replace laundry equipment<br>Replace windows in main building | \$       | 300,000    | 30% taxing a system that is nearing the end of its life cycle.   | \$ 253,619,056                               |
| 272 | 5) Efficiency | C > 1 vr   | DHS          | Clarinda MHI    | administration area.  | \$       | 224 200    | Original 1885 windows still being used.  | ¢ 050 040 050                                |
|     | 5) Efficiency |            | DOC          |                 | Upgrade boilers and chillers                                  | ۰<br>\$  | 500,000    |  | \$253,943,356<br>\$254,443,356               |
|     | 5) Efficiency |            |              |                 | Building for salt and sand storage                            | ۰<br>\$  | 85,000     |  | \$ 254,528,356                               |
|     | 5) Efficiency |            |              |                 | Add A/C to East & West House                                  | \$       | 3,350,000  |  | \$ 257,878,356                               |
| 515 |               | ⊂) / i yi. | 500          |                 | Insulate steam and chilled water                              | Ψ        | 3,330,000  | The current insulation is in need of replacement to maintain the   | ψ 201,010,000                                |
| 376 | 5) Efficiency | Now        | DHS          | Glenwood        | lines in the utility tunnels                                  | \$       | 250 000    | structural integrity of the utility tunnels.   | \$ 258,128,356                               |
|     | 6) Demo       | A) Now     | DHS          |                 | Grove Hall Demolition   | э<br>\$  | 200,000    |  | \$ 258,328,356                               |
| 511 |               |            | 5110         |                 |   | Ψ        | 200,000    | abandoned, mold infested, safety, dangerous to the public and clients  | ψ 200,020,000                                |
| 378 | 6) Demo       | A) Now     | DOC          | Clarinda DOC    | Demolition of Hope Hall                                       | \$       | 400 000    | and staff.   | \$ 258,728,356                               |
|     |               | A) Now     | DHS          |                 | Demolition of 300,000 water tower                             | э<br>\$  |            | 1920's water tower needs removal. Safety   | \$ 258,808,356                               |
|     |               | A) Now     | DHS          |                 | Hill Top Demolition   | \$       | 100,000    |  | \$ 258,908,356                               |
| 500 | -,            |            |              |                 |   | Ť        | ,          | Vacant training academy used for storage. Large building that would  | 00,000,000                                   |
|     |               |            |              |                 |   |          |            | take too much money to become ADA compliant. Currently dealing   |  |
| 381 | 6) Demo       | C) > 1 yr  | DOC          | Mt. Pleasant    | Demolition of Training Academy                                | \$       | 225.000    | with mold issues as the building is closed up.   | \$ 259,133,356                               |
| 201 |               | - / · · J· | · · · · ·    |                 | g i cadoniy   | <u> </u> | 0,000      |  | ,,,,,  |

#### DRAFT Unfunded Major Maintenance Project Requests Funding

|     |          |           |        |                 |                                    | Funding  |  |                |
|-----|----------|-----------|--------|-----------------|------------------------------------|----------|--|----------------|
|     | Priority | Immediacy | Agency | Facility        | Project Title                      | Request  | Comments   | Running Total  |
|     |          |           |        |                 | Demolition - Poultry Feed, Canary, |          |  |                |
|     |          |           |        | State Training  | Coal Room, Concrete Garage, Root   |          |  |                |
| 382 | 6) Demo  | C) > 1 yr | DHS    | School - Eldora | Cellar                             | \$ 296,0 | 000 These buildings serves no function and are beyond repair | \$ 259,429,356 |
| 383 | 6) Demo  | C) > 1 yr | DHS    | Mt. Pleasant    | Demolition of 1102 E. Washington   | \$ 10,0  | 000 The house is vacant and in poor repair.                  | \$ 259,439,356 |
|     | 7) No    |           |        |                 |                                    |          |  |                |
| 384 | Requests |           | DVA    | IDVA            | No projects requested              | \$       | -  | \$ 259,439,356 |
|     | 7) No    |           |        |                 |                                    |          |  |                |
| 385 | Requests |           | ABD    | ABD             | No projects requested              | \$       | -  | \$ 259,439,356 |

Total \$ 259,439,356