	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
							The tunnel at ICIW is collapsing and unsafe. Numerous areas are			
							blocked off due to being unsafe to even walk on. Cannot be worked			
							on until current construction is complete, likely early FY2016. Some			
1	1) L/H/S	A) Now	DOC	ICIW	Demolish Tunnel		sections already demolished. Study underway to evaluate severity, cost and scope before funding.	R526	¢ 105 001	Funded - additional funding from M942
•	1) L/11/3	A) NOW	DOC	ICIVV	Plaster ceiling in Kitchen	\$ 500,000	Safety of staff, offenders, unsanitary, demo out plaster and install new	K320	φ 105,004	Funded - additional funding from 1942
2	2) Damage	A) Now	DOC	Clarinda	replacement	\$ 125,000	metal ceiling.	R526	\$ 125,000	Funded
_	2) Damage	ryrten	200	Capitol	Ola Babcock Miller Basement	120,000	Excavate and waterproof foundation at Ola Babcock Miller Building to	11020	ψ 120,000	- anaca
3	2) Damage	A) Now	DAS		Waterproofing	\$ 600,000	eliminate mold and interior wall damage.	R526	\$ 600,000	Funded
							Basement egress windows are not properly closed and sealed; need			
							to be removed, refilled, tiled, and area backfilled to prevent water			
					Loftus Basement & Foundation		penetration. DIA issued a comment during annual inspection,			Hold - should be funded by RIIF
4	2) Damage	A) Now	DVA	Home	Work	\$ 75,000	indicating this work needs completed to avoid a citation.			remodel project in FY17.
_	o) D		200	Q	Replace roof covering on the Engine	Φ 05.000	Composite shingle failure with leaks into the building interior causing	D.=00		
5	2) Damage	A) Now	DOC	Clarinda	room Main building	\$ 85,000	damage. Facility requests metal replacement.	R526	\$ 85,000	Funded
							To avoid exponential damage to facility, exterior windows will need to be removed and resealed properly to avoid water damage. These			
				Capitol	Remove and Reseal Windows at		recommendations are part of the window study conducted by Elite			
6	2) Damage	A) Now		· ·	Oran Pape Building	\$ 207 438	Glass and Metal company.	R526	\$ 207,438	Funded
	2) Damago	71,11011	D/ (C	Complex	Crair r apo Ballaring	207,100	Frames are rusting through. Leaking occurs. Single glass pane	11020	Ψ 201,400	T dilaca
7	2) Damage	A) Now	DOC	Mt. Pleasant	Window Replacement - East & Gym	\$ 750,000	windows with cracks. Contains lead paint.	R526	\$ 750,000	Funded
	,			Matthew Edel		·				
				Blacksmith						
8	2) Damage	A) Now	DCA	Shop House	Building envelope repairs	\$ 200,000	Study done in 2012. Glass now falling out of windows.	R526	\$ 200,000	Funded
							Maintenance painting of windows at the Capitol Building that were last			
_	-> -				Painting Capitol Building North and		done early to mid 1990's. Some wood sills are completely exposed			l
9	2) Damage	A) Now	DAS	Complex	South Face Windows	\$ 1,138,350				Hold - pending dome study evaluation.
							Previous MM project installed a temporary fix to get the facility through			
							the winter months and evaluated options to correct the issues. New funding is needed to correct the issues. As of 3/13 the temporary fix			
					WHTC Roof Replacement and		was holding and it was not currently leaking. 9/14 started leaking			Hold - DCA requested we postpone
10	2) Damage	A) Now	DCA	WHTC	interior repair	\$ 450,000	, , ,			funding until FY17.
	<u> </u>	1 1/11011		Iowa Veterans		, , , , , , , , , , , , , , , , , , ,				Hold - should be funded by RIIF
11	2) Damage	A) Now	DVA	Home	Sheeler Building Tuck Pointing	\$ 75,000	Tuck pointing needed to protect against moisture damage			remodel project in FY17.
12	2) Damage	A) Now	DHS	Glenwood	Tuckpointing in Lacey Complex	\$ 370,000	Bricks falling off the façade.	R526	\$ 370,000	
							Leaking. Facility thinks rain water is getting behind the EPDM liner			
							where it is attached to the posts on the railing of the widows walk.			
40	2) Dazz	A) Nove	DCA	Montoul	Main Hayes Doof Daylessays	<b>6</b> 00 000	They used roof caulk a few years ago to reseal them, will plan to do	DEOC	<b></b>	Francisco de d
13	2) Damage	A) Now	DCA	Montauk	Main House Roof Replacement	\$ 60,000	that again this fall and hope that it helps.	R526	\$ 60,000	runded
					Bathroom repair/redesign South 9		Poor design is resulting in decay and rot of walls and floor from showers. Also, population trends at CCUSO require more ADA			
14	2) Damage	A) Now	DHS	ccuso	and South 6		facilities for patients.	R526	\$ 400,000	Funded
	_, _amago		20			700,000	Repoint or seal all mortar joints in the turrets, chimneys, parapets and	7.020	ψ .00,000	Funded - created 2 projects to expedite
							water tables. Inspect and flashing and sealants and make repairs as			repair for emergency need at vehicular
15	2) Damage	A) Now	DOC	ASP	Tuckpointing priorities 1	\$ 400,000	· · · · · · · · · · · · · · · · · · ·	R526	\$ 410,000	• •
							Existing doors securing office area are original wooden doors.			
					Secure Doors for South 6 and South		Security concern that patients could compromise and enter secure			
16	2) Damage	A) Now		CCUSO	9	\$ 30,000		R526	\$ 30,000	Funded
	a)			Capitol	Oran Pape exterior drainage		Design is estimated at \$10,000. When it rains hard (3-5 times a year)	<b>D</b> =00		<u> </u>
17	2) Damage	A) Now	DAS	Complex	improvement	\$ 75,000		R526	\$ 75,000	Funded
10	2) Domeses	A) Nove	DHC	Charakas	Deplete fleering on North Court	¢ 00.000	Flooring is cracked in several areas and is creating a trip/fall and	DEOC	¢ 00.000	Funded
Ig	2) Damage	A) Now	DHS	Cherokee	Replace flooring on North 9 ward	φ 80,000	sanitation issue.	R526	\$ 80,000	runded

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
19	2) Damage	A) Now	DOC	ICIW	Replace Pharmacy Windows		Building interior was remodeled recently, but several of the windows leak severely in driving rains. 12 windows in total.			Hold - pending additional review.
20	2) Damage	A) Now	DAS	Capitol Complex	Capitol West Drive Repair	\$ 300,000	Repair broken pavers on Capitol West Drive.	R526	\$ 300,000	Funded
21	2) Damage	A) Now	DHS	Glenwood	Tuckpointing in Building 120 Phase I	\$ 660,000		R526	\$ 660,000	Funded
							No current citation. However, both systems are not in compliance with requirements of Chapter 69. Continued use of the systems under			
							current wastewater loads is not recommended because of the			
							uncertainty of their condition and treatment effectiveness. Fayette			
							County could require the upgrade of the systems if a notice of violation is issued. If the wastewater contribution to the existing			
							system is increased it may cause the systems to fail and cause a			
22	2) Damage	A) Now	DCA	Montauk	Montauk Septic Replacement	\$ 100,000	surface discharge or a backup into the structure.  Does not meet city compliance. Significant fines may be effective in	R526	\$ 100,000	Funded
							year 2014. Will require engineering. High sewer bills due to storm			
23	2) Damage	A) Now	DOC	Mt. Pleasant	Storm Water Separation	\$ 350,000	water going thru sewer meter.	R526	\$ 350,000	Funded
							Evaluate the number of expansion joints, anchors and pipe guides required to update and replace the current expansion joints on the 6"			
							and 10" lines in the utility tunnels. The current expansion joints are no			
							longer supported and the proper packing is no longer available. There			
							needs to be additional expansion joints added to eliminate the deflection of the current piping. These steam leaks affect the integrity			
					Add and Replace Steam Expansion		of the tunnel, increase energy cost in lost steam, and creates a safety			
24	2) Damage	A) Now	DHS	Glenwood	Joints in Tunnel	\$ 200,000	hazard for the staff working in the tunnel.	R526	\$ 200,000	
25	2) Damage	A) Now	DHS	Glenwood	Renovate HVAC & Building Envelope for Cottage #36	\$ 260,000	Currently vacated, budget includes mold remediation.			Hold - facility determined the cottage may be leased out and renovated.
25	z) Damage	A) NOW	DITIO	Gieriwood	Envelope for Cottage #50	Ψ 200,000	Currently vacated, budget includes mold remediation.			inay be leased out and removated.
					L		Design is estimated at \$9,000. During heavy rains water enters the			
26	2) Damage	A) Now	DAS	Capitol Complex	Historical Building exterior drainage improvement	\$ 100,000	building causing damage. During the winter the lack of drainage causes water pooling on the side walk leading to a build up of ice.			Hold - pending additional review.
20	z) Damage	A) NOW	DAO	Complex	Improvement	Ψ 100,000	eadses water pooling on the side waik leading to a build up of ice.			Hold - Postponed to FY17; facility can
27	2) Damage	A) Now	DOC	Mt. Pleasant	Replacing Cooling units/AC for gym	\$ 250,000				keep running one more year.
							The tunnels located on the west side of cellhouse row is in dire need			
							of repair. Repairs have been made to the topside, however, the			
							underside is crumbling. As the tunnel could collapse, this is a life/safety issue. The water, electrical, sewer & steam lines all run			
							through these tunnels and if they collapse, it will cause damage to all			
							of these items. Shoring and/or bracing these areas would not be			Hold - reduced urgency. Traffic is now
28	2) Damage	A) Now	DOC	ISP	Tunnel Project	\$ 250,000	adequate to prevent a collapse. Although we try to limit the traffic on this tunnel, it is the main transportation route to the cellhouses.			limited, but still needs to be addressed because all utilities run through it.
_5	_, barrage	, , , , , , , ,		.5.	1 3	200,000				See
0.0	0) D	A) NI	DCC	IONA		Φ 07.000	Extensive concrete deterioration around storm intake causing it to			
29	2) Damage	A) Now	DOC	ICIW	Sally Port Concrete Repair	\$ 25,000	cave in. High traffic area for trucks entering and exiting the institution.			Hold - pending additional review.  Hold - the braking system was
										replaced; remaining elevator is still
30	2) Damage	A) Now	DOC	Mt. Pleasant	Elevator B	\$ 220,000	The braking system is obsolete and at life's end.			obsolete.
31	2) Damage	A) Now	DOC	Mt. Pleasant	North Core capstone study	\$ 25,000	Capstones are showing signs of movement and need study for appropriate repair.	R526	\$ 25,000	Funded
31	z) Damage	/ () T ( O ( )		ivit. i leasant	Troffir Gold Capatolie Study		Rust around the steel frames and buckling sills from condensation,	11020	Ψ 25,000	T GRACO
							but no known infiltration. 3/2015, beginning to have water infiltration			
32	2) Damage	A) Now	ILEA	ILEA	Replace windows	\$ 625,000	affecting sills and drywall. Some exterior seals are hanging from the	R526	\$ 760,000	Funded
SZ	z) Damaye	A) NOW	ILLA	TILEY	Interlace williams	Ψ 025,000	name.	1520	φ / 60,000	i unueu

	Priority	Immediacy	Agency	Facility	Project Title	Funding Reque	est	Comments	Funding Source	Funding Allocated	Status
					Replace Water Softeners at						
33	2) Damage	B) <1 yr	DOC	ASP	Powerhouse	\$ 1		Facility can't get parts when they break.			
					Roof Replacement – North Addition			Patched multiple times. Membrane is pulling away at corners. Leaks			
34	2) Damage	B) <1 yr	DOC	IMCC	Lower Level	\$ 7	•	currently.			
								Water softeners are approx. ten years old and becoming very			
								problematic because the inside of the cast iron regeneration controls			
								is rotting away. They experience malfunctions due to diaphragm			
								rupture from rust cutting them during re-generation. Also rust travels			
								thru the controls and hangs up the control shutting off the water flow			
								period. This issue is even more serious if this occurs during the night			
								when the power house is not staffed. Ultimately this cuts off the flow of domestic hot water campus wide and boiler make-up water which			
								eventually shuts the boiler down on low water alarm. Then someone			
								has to be called in to repair or by-pass them until repairs can be			
35	2) Damage	B) <1 vr	DHS	Cherokee	Replace Water Softeners	\$ 1	20,000	· · · · · · · · · · · · · · · · · · ·			
00	z) zamago	2) 1. j.	5110	American	Trapiaco Trator Contenero		20,000				
36	2) Damage	B) <1 yr	DCA		Additional building envelope repairs	\$ 1	00,000				
		, ,			Roof Replacement – North Addition		· · · · · · · · · · · · · · · · · · ·				
37	2) Damage	B) <1 yr	DOC	IMCC	Upper Level	\$ 7	85,000	Patched multiple times. Membrane is pulling away at corners.			
					,			Based on recommendations from forced main sewer line study. Have			
								been putting bandaids on the problem but if it breaks down			
38	2) Damage	B) <1 yr	DOC	Newton CF	Repair pump station	\$ 5	05,800	completely, it will be a big issue. Project # 8713.00			
								Door tracking system is extremely worn. Has been retro fitted. Car is			
								past life expectancy. Does not have phase one fire recall.			
39	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Elevator C	\$ 2	220,000	Schumacher has said it is now critical.			
								Evidence of water infiltration, concrete deterioration in areas where			
					Densir Main Duilding to Voldens			rebar is exposed. Not critical yet (7/2014), but could deteriorate			
40	2) Damage	D) <1 vr	DHS	Cherokee	Repair Main Building to Voldeng Tunnel	¢ 5		quickly and be much more expensive to replace than repair. Voldeng tunnel in slightly worse shape.			
40	z) Damage	ы) < т уг	טווט	Cherokee	Turirier	φ 5	70,000	Evidence of water infiltration, concrete deterioration in areas where			
					Repair Main Building to Ginzberg			rebar is exposed. Not critical yet (7/2014), but could deteriorate			
41	2) Damage	B) <1 vr	DHS	Cherokee	Tunnel	\$ 5		quickly and be much more expensive to replace than repair.			
					CRC - Training Center Roof	· ·	,				
42	2) Damage	B) <1 yr	DOC	Newton CF	Replacement	\$	87,000	Patch a couple of times a year, 10 years past expected life.			
								Concrete has spalled resulting in unsafe conditions, exposing rebar.			
				6450 Corporate	Repair dock and replace precast			There is an uneven surface resulting in tripping hazards. Existing			
43	2) Damage	B) <1 yr	IPTV	Dr	steps	\$	40,000	precast steps don't align well with dock.			
								Tunnel tops are rapidly deteriorating. All utilities are located in the			
								tunnels. Tunnel top failure could result in disruption of utilities. This			
	a) <b>a</b>	<b>5</b> )	200			•		would be an ongoing project as not all tunnels would need to be			
44	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Tunnel Tops	\$		replaced at the same time.			
45	2) Domogo	D) -1 vr	DOC	Mt. Pleasant	Ventilation for East & West Housing	¢ o		Zero ventilation of air for the living units. Institution is not air conditioned so there are periodic mold issues.			
40	2) Damage	D) < 1 УІ		lowa Veterans	Ventilation for East & West Housing	Φ 2		The concrete tunnel tops are breaking down allowing water infiltration.			
46	2) Damage	B) <1 vr			Tunnel top Replacement	\$ 2		Needs additional evaluation to finalize budget.			
40	z) Bamage	D) <1 y1	DVA	TIOTIC	Tarmer top replacement		.00,000	The roof has been patched and it is a constant patch following a rain.			
								The roofing material is shrinking and pulling away from the parapet			
47	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Replacement of Building 20 roof	\$ 3	300,000				
					Ţ			Pipes require extensive repair and patching. This is a high client use			
48	2) Damage	B) <1 yr	DHS	Glenwood	Replace plumbing in Meyer Bldg	\$ 3	300,000	building as it houses all of the GRC's vocational services.			
								Need to evaluate to determine current condition of underground water			
								service lines and identify reason for lack of adequate water			
40	0) D	D) 4	DUG	Olara I	E al ata Maria Maria	•		delivery/pressure between water tower and booster station to			
49	2) Damage	B) <1 yr	DHS	Glenwood	Evaluate Water Mains and Shut-offs	<b>\$</b>	50,000	residential houses.			

_	Priority	Immediacy	Agency	Facility	Project Title	Funding Requ	est	Comments	Funding Source	Funding Allocated	Status
50	2) Damage	B) <1 yr	DHS	Glenwood	Replace roof on mule barn	\$	75,000	The roof is leaking and damaging the stored contents. The current shingles are asbestos and would need to be abated to replace with shingles. We are proposing to add a metal roof on top of the current shingles which would alleviate the need to abate.			
51	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Replace MSU Northcore & Southcore roof	\$ 4	450,000	Rubber is deteriorating and has to be patched constantly. In addition, the rubber is pulling away from the corners. As a result, leaks are occurring and water has gone into the elevator shaft.	R526		Funded after recent site visit determined that membrane was no longer attached and could be removed by a strong wind.
52	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Replace Two Towers	\$	700,000	Our current towers, intended to be temporary, must be replaced. Current structure is post frame construction. They are structurally compromised and have become unsafe. We evacuate in storms due to the lack of acceptable sheltering. Should a fire occur, the situation becomes more serious as the wood is so very dry. The pipes freeze every year, which requires officers to haul water for flushing toilets. We supply hand wipes and bottled water for drinking. With these new towers are also asking to include stationary camera in strategic areas with split screen monitoring in these two towers.			
52	2) Damage	B) <1 vr	IPTV	6450 Corporate Dr	repair roof	\$	65,000	To prevent ice damming on a rubber membrane roof; four openings			
33	z) Damaye	(b) < 1 yi	IF I V	Ы	Reynolds Masonry Repair Phase	Ψ	03,000	To prevent ice damining on a rubber membrane root, rour openings			Propose funding - reports of loose
<mark>54</mark>	2) Damage	B) <1 yr	DHS	Independence	3B		200,000	4C was ald with an appropriate distribution of audition according to			stones and current leaks.
55	2) Damage	B) <1 vr	DOC	Ft Dodge CF	Replace Unit A Roof	\$		16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (12,205 sq.ft.)			
	2) Damage		DOC	Ft Dodge CF	Replace Cedar Unit Roof			16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (29,296 sq.ft.)			
	2) Damage		DOC	Ft Dodge CF	Replace Boone Unit Roof		300,000	16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (29,296 sq. ft.)			
58	2) Damage	B) <1 yr	DOC	IMCC	Roof Replacement – North Link	\$	125,000				
59	2) Damage	B) <1 yr	DOC	Ft Dodge CF	Replace Floyd Unit Roof	\$ 3		16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (30,563 sq.ft.)			
		B) <1 yr	DOC	Ft Dodge CF	Replace Grove Unit Roof	\$ 3		16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (29.296 sq.ft.)			
-	2) Damage		DOC		Replace Emmet Unit Roof			14 yrs. old (26,480 sq.ft.)			
F	, ,	B) <1 yr B) <1 yr	DOC	Ft Dodge CF Clarinda	Replace Dolliver Unit Roof Tuck pointing main building	·		14 yrs. old (26,480 sq.ft.) Can be done in stages as before. 1/4 completed 2009, 3/4 remains			
	2) Damage		DOC	North Central	Repair of Tunnel			There is quite a bit of damage over the years, but repair of side walls will reinforce the utility lines for the operations. There is also asbestos throughout tunnel area. 3/2015 Several areas damaged, large patches of concrete have fallen in from the ceiling, lighting and conduit are hanging without support due to the soft and brittle concrete being unable to hold anchors. This tunnel is the lifeline through the camp carrying all data cables, water, and steam. Immediate repair is necessary to prevent severe damage to one or all of these critical systems.			
0-4	_, Damaye	<i>D<sub>1</sub></i> < 1 y1	500		ποραίι οι ταιπισι	Ψ (	500,000	Combination flat roof and pitched roof has exceed useful life.			
65	2) Damage	B) <1 yr	DHS	Glenwood	Replace powerhouse roof			Currently leaking into interior of bldg which will create structural damage.	R526		Funded after recent site visit found roof had begun leaking severely.

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
							Replace existing roofing on the admin building. 3/2015 East side is			
	-> -						part membrane, part shingles and leaks badly on the shingle side			
66	2) Damage	B) <1 yr	DOC	IMCC	Admin Bldg East Roof Replacement	\$ 76,202	during torrential rains. West side re-done 2009 and is okay.			
67	O) Damas	O) . 4	D00	Mt Discount	Flouritan D	Φ 200,000	Car is past life expectancy. Tracks are worn. Does not have phase			
67	2) Damage	C) > 1 yr	DOC	Mt. Pleasant	Elevator D	\$ 220,000	one fire recall.  IVH has repaired two recent sewer line breaks. The lines are aged			
							and allow either ground water infiltration or collapse. This increases			
							the sewage flowing into the treatment plant from this facility due to			
				Iowa Veterans			ground water, or allows sewage to flow on the ground until an			
68	2) Damage	C) > 1 vr	DVA		Sanitary Sewer Line Replacement	\$ 310,000	emergency repair can be arranged.			
00	z) Damage	0) > 1 y1	DVA	TIOTIC	Caritary Cewer Eine Replacement	Ψ 310,000	Reseal all mortar joints and cracks on the walkways on top of			
							stonewalls.\$50,000.			
							Repair stone masonry and install new coping to the top of stonewall			
69	2) Damage	C) > 1 vr	DOC	ASP	Tuckpointing priorities 2 & 3	\$ 100.000	on the southwest corner of the south wall. \$40,000.			
	,	- / ,			31	*	Tunnel system provides major utilities (steam, water, fiber, telephone,			
				State Training	Tunnel repairs and replacement -		fire alarms). Tunnel failure would cause catastrophic damage to these			
70	2) Damage	C) > 1  yr	DHS		sections A to D (HR Green study)	\$ 1,120,800	,			
	,				,		Tunnel system provides major utilities (steam, water, fiber, telephone,			
				State Training	Tunnel repairs and replacement -		fire alarms). Tunnel failure would cause catastrophic damage to these			
71	2) Damage	C) > 1 yr	DHS	School - Eldora	sections E to J (HR Green study)	\$ 957,200	systems.			
	,				~		Tunnel system provides major utilities (steam, water, fiber, telephone,			
				State Training	Tunnel repairs and replacement -		fire alarms). Tunnel failure would cause catastrophic damage to these			
72	2) Damage	C) > 1 yr	DHS	School - Eldora	sections K to N (HR Green study)	\$ 1,152,500	systems.			
73	2) Damage	C) > 1 yr	DHS	Cherokee	Tuck pointing Phase 2.2	\$ 360,000	Finish north side of main building.			
							Bricks are falling off the façade. 9/10/14 - 29C20 submitted for roof			Propose funding because recent site
							leak due to storm; needs complete replacement. Bricks are falling			visit found bricks not addressed
							onto current roof, so should address current tuckpointing at same			through roof project are now falling off
74	2) Damage	C) > 1 yr	DHS	Glenwood	Tuck pointing in Buildings 102	\$ 280,000	time.			façade.
	_, _				Tuck pointing in Building 120 Phase	•				
		C) > 1 yr	DHS	Glenwood		\$ 330,000				
	,	C) > 1 yr	DHS	Glenwood	Tuck pointing in Buildings 110	\$ 85,000				
77	2) Damage	C) > 1 yr	DHS	WRC	Tunnel cap at Supply Building	<u> </u>	Below existing truck service road			
70	o) <b>D</b>	0) 4	DUIO	State Training			Seal top of tunnel system to prevent water infiltration and further			
			DHS		Tunnel Top Sealing		deterioration			
	,	<u> </u>	DHS	Cherokee	Tuck pointing Phase 2.3		Finish south side of main building.			
80	2) Damage	C) > 1 yr	DHS	WRC	Tuck Point various buildings	\$ 80,000	Westwood and larches and other areas			
							4. Repoint the defective mortar joints on the Administration Building. \$90,000.			
							5. Repoint all mortar joints on the top half of stonewalls, tuckpoint only			
							the defective mortar joints on the bottom half of the stonewalls.			
							\$900,000			
							6. Repoint all mortar joints 100% on the west wall on the school / store			
81	2) Damage	C) > 1 yr	DOC	ASP	Tuckpointing priorities 4, 5 &6		room / living unit E. \$90,000.			
01	z) Damage	0) > 1 yi	D00	AOI	Tuckpointing phonties 4, 5 do	Ψ 1,000,000	7.Secure the bulging stone on west wall of the old kitchen-dinning hall			
							and repoint all mortar joints 100% on the entire building. \$220,000			
							8. Repoint defective mortar joints, thirty-two feet on the west wall, sixty			
							feet on the east wall and all mortar joints above the windows on the			
							south wall of the Clothing, R&D and Custom Wood Building. \$ 60,000			
							9. Repoint all mortar joints on the east wall of the Living Unit A, Living			
							Unit C and Living Unit E and replace some eroded stone Repoint only			
82	2) Damage	C) > 1 vr	DOC	ASP	Tuckpointing priorities 7, 8 &9		the defective mortar joints on the west inside walls. \$520,000			
82	∠) ∪amage	(C) > 1 yr	DOC	ASP	i uckpointing priorities 7, 8 &9	\$ 800,000	the defective mortar joints on the west inside walls. \$520,000			

									Funding	Funding	
	Priority	Immediacy	Agency	Facility	Project Title	Funding R	Request	Comments	Source	Allocated	Status
								10. Repoint defective mortar on the south wall of Living Unit B and D.			
								\$375,000			
								11. Repoint the defective mortar joints as needed on the Sign Shop,			
	_, _							Commissary, Gymnasium, Maintenance Shop and Deputy's			
83	2) Damage				Tuckpoint priorities 10 & 11	\$		Office.\$450,000			
84	2) Damage	C) > 1 yr	DOC	Newton CF	Tuckpoint Dorms 1&2 (CRC)	\$	60,000				
								Who noted that turned was definient and a society throat of collegeing			
								Was noted that tunnel was deficient and a serious threat of collapsing on mechanical systems in the tunnel. No pedestrian use inside the			
					Tunnel repair/replace main bldg to			tunnel but heavy ped use on top as a walkway. Utility only inside.			
85	2) Damage	C > 1  yr	DOC		SW Wing	<b>C</b>		However, in 2014 the facility said tunnel was not in bad shape.			
00	z) Damage	0) > 1 yi			Repair Historical Building Exterior	Ψ	1,109,000	i nowever, in 2014 the facility said turiner was not in bad shape.			
86	2) Damage	C) > 1 vr		•	Walls	\$	1 874 000	Repair the exterior granite stone façade.			
00	z, zamago	(a)	<i>D7</i> (0	Complex	Trans	Ψ	1,01 1,000	Roofing contractor advised IPTV to re-caulk the joints because cracks			
								in the caulk may be the cause of water leaks. Upon visual inspection			
				6450 Corporate	Re-caulk joints between concrete			the caulking looks like it needs to be replaced. Caulking was last			
87	2) Damage	C) > 1 yr			panels for the entire building	\$	40,000	done prior to 1999 (we think 1996)			
	,	,	<del>Terrace</del>		East Porch Newel Post and Spindle		·				Facility removed because they funded
88	<del>2) Damage</del>	<del>C) &gt; 1 yr</del>	Hill	Terrace Hill	Repair	\$	42,000	Rotting out supports; new foundation for posts (heaving)			the work themselves.
				State Training							
89	2) Damage	C) > 1 yr	DHS	School - Eldora	Kitchen Tuck pointing	\$	75,000	Building exteriors is in critical need of tuck pointing repairs			
								Leak has been repaired, but the material is breaking down and is not			
					Replace Administration Building			bonded in place. Drainage issues. New estimate Aug 2012. Estimate			
90	2) Damage	C) > 1 yr	DHS	Glenwood	Roof	\$	175,000	does not include A & E, PM or CM costs.			
	o) 5		D110		_ , , , , , , , , , , , , , , , , , , ,		40.000				Facility removed because they did the
91	<del>2) Damage</del>	<del>C) &gt; 1 yr</del>	DHS	Glenwood	Tuck pointing in Building 116	-\$-	40,000	New data and have a start of the day of the start of the large start of the start o			work in-house.
00	2) Domosso	C) . 1	DLIC	Clamusad	Tuels pointing in Duilding 110	œ.	100 000	Need to address water infiltration in one section but rest of bldg can			
92	2) Damage	C) > 1 yr	DHS	Glenwood	Tuck pointing in Building 119	\$	180,000				
								MPCF requested this project be added back to the list. Frame are rusting through and leaking occurs. Single glass panes are cracked			
93	2) Damage	C > 1  yr	DOC	Mt. Pleasant	Window Replacement - West	\$	700 000	and paint contains lead.			
93	z) Damage	C) > 1 yi	DOC	IVIL. FIEdSant	Willdow Replacement - West	Ψ	700,000	16 yrs. old – rubber membrane is dried out and pulling away from the			
								leading edge of the roof creating leaks into the space below - ongoing			
94	2) Damage	C) > 1 vr	DOC	Et Dodge CE	Replace Power Plant Roof	\$	110 000	repairs as leaks develop. (10,392 sq.ft.)			
٠.	z) zamago	σ, ε · y.	1200	r t Dougo o.	replace Feller Flam Floor	Ψ		16 yrs. old – rubber membrane is dried out and pulling away from the			
								leading edge of the roof creating leaks into the space below - ongoing			
95	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Warehouse Roof	\$		repairs as leaks develop. (8,756 sq. ft.)			
	, ,	<u> </u>		Ĭ			,	16 yrs. old – rubber membrane is dried out and pulling away from the			
								leading edge of the roof creating leaks into the space below - ongoing			
96	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Administration Roof	\$		repairs as leaks develop. (7,700 sq.ft.)			
								14 yrs. old - skylight flashing continues to leak into building - ongoing			
97	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Education Roof	\$	200,000	repairs as leaks develop. (19,399 sq.ft.)			

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
	2) Damaga		DOC	North Central	Fine Alexan I In one do	T.00.000	Addressing system upgrade by location and clean up fault issues. Siemens install electrical estimate and parts for updated / replacement of fire alarm system. The fire alarm panel located in our administration building operates the fire detection system for 6 buildings. During inspections we have found multiple troubles in the system that we are unable to repair due to outdated equipment with unavailable parts. We have found that in several locations removing a smoke or heat head will not sound a trouble, pull stations will not operate horn/strobes, and heads that are tested with smoke may or may not sound the alarm. The systems have multiple ground fault issues that caused us to remove the ground fault detection. Nuisance trouble alarms have desensitized staff causing lax response times and investigation to drills. Zoning is a huge issue as some building are attached yet have separate entrances causing alarm notifications from our annunciator to send staff to the wrong locations. Nonfunctioning heads are undetectable without troubles being detected at the head end. An actual fire could go undetected. Inspections have			Propose funding because recent site visit determined that system is non-addressable and not all buildings are
98	2) Damage	C) > 1 yr	DOC	CF	Fire Alarm Upgrade	\$ 700,000	documented that this system is not passing current tests.  The grading is too low at the fire exit on Maytag auditorium and water			staffed 24x7.
				6450 Corporate			is backing up into the auditorium. Need to fix the retaining wall and			
99	2) Damage	C) > 1 yr	IPTV	Dr	Repair auditorium exterior fire exit	\$ 75,000	change the grade of either the door or the ground.			
100	2) Damage	C) > 1 yr		Mt. Pleasant	Northcore Air Conditioning Unit	\$ 150,000	System is partially functioning. Prone to refrigerant leaking. Equipment is 20+ years old. A temporary fix was made in July 2014 so the new equipment/repairs should last for a couple more years.	R526		Funded after unit failed and was beyond repair.
404	O) D	0) 4		Capitol	Repair Existing Pedestrian Tunnel	Φ 0.507.400	To water proof the existing tunnel and to bring it up to all Building and			
101	2) Damage	C) > 1 yr	DAS	Complex	between Lucas and the Capitol	\$ 6,527,483	Fire Codes.  Project funded, designed, and bid in 2010, but placed on "hold" since			Funded because it will be reimbursed
102	2) Damage	C) > 1 yr	DOC	ASP	Laundry Roof Replacement	\$ 250,000	bid was over budget . Laundry roof is now shot and leaking.	R526	\$ 250,000	
103	2) Damage	C) > 1 vr	DOC	North Central CF	Roof Project Replacement of Treatment Bldg, and Control Center	\$ 45,000	Both roofs have been damaged from storms and winter weather conditions, there are missing shingles and there has been leaks periodically throughout the last four years. The gutters are in need of replacement and fascia boards are damaged. Per CM in June 2014 the roofs could last another 5 years.			Propose funding because recent site visit determined there are now missing shingles and leaks.
	2) Damage			Ft Dodge CF	Replace delaminated glass in Master Control Center		High security glass in the control center is delaminating. This glass and the bars on the windows is all that separates control center staff from the main yard. Manufacturer feels that the integrity isn't compromised yet, but may be in a few years.			ormigico ana icako.
105	2) Damage	C) > 1 yr	DOC	North Central CF	Repair building exteriors	\$ 240,000	5 of our buildings have received severe damage to the stucco over the years. Some areas are cracked and should be repaired as soon as possible to prevent further damage, other areas have large blisters and have separated from the structure many feet in diameter where the stucco is nearly ready to fall off. Prolonging these repairs will only result in further structural damage.			Propose funding for EIFS exteriors because a recent site visit determined areas are now leaking.
106	3) ADA	A) Now		Centennial Building, Iowa City	Elevator Replacement	\$ 300,000	This elevator has had several engineering studies and was prioritized under ADA funding. The elevator was recently cited by Workforce Development as being non-compliant and it skips one stop.  Needed for elderly patients and med clinic. Currently non-ambulatory			
107	3) \D\	A) Now	DHS	CCUSO	ADA compliant restrooms for S1 and S2 wards	¢ 250,000	patients are taken through the food service area to use an ADA			
107	3) ADA	A) Now	סחט	CCUSU	Voldeng Building Elevator and	φ ∠50,000	compliant restroom on another ward.			
108	3) ADA	A) Now	DHS	Cherokee	Lobby Area Remodel	\$ 750,000	Improvements to accommodate ADA			

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
		1			<u>,</u>		Cannot achieve Correctional Education Accreditation until this is			
109	3) ADA	A) Now	DOC	ASP	Access to School and Library	\$ 98,000	addressed, but can provide services through other means.			
	,	,					Lifts currently in place (main building and Ginzberg) fail regularly. At			
							least three times in the last year we've had handicapped people stuck			
110	3) ADA	A) Now	DHS	Cherokee	Redesign handicap entrances	\$ 100,000	on the lifts. Would prefer a non-mechanical solution.			
							Interior ramp needs to be redesigned to comply with 2010 ADA			
							Standards for Accessible Design. Adjustments are required for slope,			
							distance, and level to assure resident safety. Preliminary estimate in			
							range of \$500,000. Ramp is very steep and the facility has installed			
							bumpers at the bottom facing wall and assigned staff to watch the			
	-\ <b></b> .			Iowa Veterans			ramp. Governor recommended for FY17 Capitals. Reconsider if not			
111	3) ADA	A) Now		Home	Loftus Resident Ramp	\$ 500,000	funded.			
440	2) ADA	D) 4		North Central	Education Dida Dama ADA	¢	Access to the Education hide for disable research (110			
112	3) ADA	B) <1 yr	DOC	CF	Education Bldg. Ramp ADA	\$ 6,000	Access to the Education bldg for disable persons / HS			
					Remodel/Renovate restroom &		Restrooms do not comply with ADA regulations. There is poor exhaust resulting in mold issues. There are also safety concerns with			
112	3) ADA	C) > 1 yr	DOC		shower on living units of #20 bldg	\$ 1.645.360	the slick flooring.			
113	3) ADA	C) > 1 yi		North Central	shower on living units of #20 blug	φ 1,045,300	life sick flooring.			
114	3) ADA	C) > 1 yr			Replace Non-Standard Walks ADA	\$ 60,000	Widening of current main sidewalk on inside perimeter			
	3) / (3) (	0) × 1 y.		0.	replace from Grandara France 71271	Φ σο,σσο	We need to repaint the inside of the GRC campus water tower to			
115	4) Scheduled	A) Now	DHS	Glenwood	Paint inside of water tower	90,000	ensure safe drinking water for clients and staff.			
-	,				1///		<b>3</b>			
							These systems have outlived their life expectancy and electrical power			
							system needs to be redesigned. Smaller compressors on 480volt			
					Replace compressor racks and		system only last 18 - 24 months before they burnout. Evaporator coils			
					evaporators in dietary and		and electric reheat coils are corroding and beginning to fail. Repairs to			
116	4) Scheduled	A) Now	DOC	Ft Dodge CF	warehouse freezers/coolers.	\$ 150,000	corroded coils are becoming more frequent and difficult.			
117	4) Scheduled	A) Now	DOC	Mt. Pleasant	Parking lots NE and SE	\$ 95,000	The lots are in very bad shape and the area is so large.			
							Proper spill containment needed for 70,000 gallon diesel tank.			
118	4) Scheduled	A) Now	DOC	Mt. Pleasant	Spill Containment for diesel tank	\$ 75,000	Current have a soil and grass berm. Fire Marshal warning.			
							The fence is becoming wavy and we need cement under the fencing.			
119	4) Scheduled	A) Now	DOC	Mt. Pleasant	Perimeter Fence	\$ 1,000,000	This is a high need for security.			
				Openital (	Dealess Loos Building Floretons		All of Floreston and increase is existed a suitance of The Luces Duilding			
120	4) Scheduled	A) Now			Replace Lucas Building Elevators 1,2,3,4 & 5	¢ 4 927 940	All of Elevator equipment is original equipment. The Lucas Building			
120	4) Scrieduled	A) NOW	DAS	Complex	1,2,3,4 & 5	\$ 1,62 <i>1</i> ,640	had 56 service calls for not being in operation with 4 entrapment calls.  The penthouse roof is past its life expectancy, the membrane is			
							shrinking and the loose ballast has been eroded and is being blown off			
				Capitol			the roof. Underside of roof deck coated with a spray-on fire proofing			
121	4) Scheduled	A) Now			Replace Grimes Penthouse Roof	\$ 128,000	that contains asbestos.			
'-'	., concadica	, 1, 11011	5, 10	Complex	Topiaco Cimico i Cinilodoc (Coli	120,000	Equipment is at the limit of its usable lifetime, has never worked			
122	4) Scheduled	A) Now	DPS	Post 12	New HVAC & Controls	\$ 250.000	properly. Annual maintenance cost is increasing rapidly.			
	,	ĺ					The roofing membrane on all of these section has shrunk and has			
							pulled away from the parapet walls, and starting to pull the parapet			
				Capitol	Jessie Parker Building, Sections E,		walls in ward. Penthouses need tuck pointing and sealed, along with			
123	4) Scheduled	A) Now	DAS	Complex	F, G, H Roof Replacement	\$ 565,000	the exterior perimeter walls below the roof coping.			
							We have four roof top units at 6535. They are over 15 years old. We			
				6535 Corporate			need to start replacing them. This is a request to replace one of the			
124	4) Scheduled	A) Now	IPTV	Dr	Replace roof top unit at 6535	\$ 60,000				
							The Lucas Building's roofs are 14 years old. These roofs are a Fully			
							Adhered TPO Reinforced Membrane System. The Main section of			
							this roof has had a lot of wind damage over the years, so they have			
405	4) 0 4 1 1	A) No		Capitol	Deplese Luces Building Depl	040.000	installed 24" X 24" concrete pavers over the entire roof on 6 foot			
125	4) Scheduled	A) NOW	DAS	Complex	Replace Lucas Building Roof	\$ 648,960	centers as ballast. This roof system has had a few leaks.			

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
							Replace AHU, connect cooling coils to the Central Energy Plant			
				Capitol			chilled water loop, duct work, VAV and direct digital controls. All			
126 ₫	1) Scheduled	A) Now	DAS	Complex	Jessie Parker HVAC Renovations	\$ 8,331,892	existing equipment is past its life expectancy.			
							Replace AHU, coils, fans, VAV, duct work, and direct digital controls.			
							All existing equipment is past its life expectancy. The equipment in			
							this building is the original dual duct AHU, with chilled water and hot			
							water coils, dampers and louvers that were installed when the building			
				Capitol			was built. The asbestos needs abated just to work on or replace this			
127 🛭	1) Scheduled	A) Now	DAS	Complex	IWD HVAC Renovations	\$ 8,027,590	equipment.			
				Capitol						
128 ⊿	1) Scheduled	A) Now	DAS	Complex	Replace Condensate tanks	\$ 368,665	Condensate tanks in the tunnel at Wallace and the Capitol			
							Replace cooler flooring as it has buckled and relocate condensing			
							units to the exterior of the building for easier maintenance. The metal			
129 ⊿	1) Scheduled			Iowa Labs	Cooler Modification	\$ 60,000	floor is icing up and makes it slick to walk across.			
130 ⊿	1) Scheduled	A) Now	DOC		Fire Panel Upgrade	\$ 150,000	Replace obsolete system			
					Replace Unit 9 Control Centers'					
131 ⊿	1) Scheduled	A) Now	DOC	ICIW	Heat Pumps	\$ 14,000	Replace heat pumps in both control centers			
	<u> </u>						Air handling system needs to be balanced and the unit control center			
						///	needs a separate heat pump so if chemicals are discharged it does			
					Renovate Segregation Unit HVAC		not enter the control center. System condensates and dumps water			
132 ⊿	1) Scheduled	A) Now	DOC	ICIW	system	\$ 12,000	on the floor.			
							Need tube replacement and convert to 10 gauge boiler tubes.			
							Annually, we continue to replace tubes inside boiler #1 and #2, at an			
							estimated cost of at least \$15,000. Downtime is an increasing issue			
							leaving much of the campus without heat until the second boiler can			
							be brought on line (as long as it is not leaking too much). In addition to			
							this it would be more operationally cost effective to replace burner			
				North Central			heads with smaller more controllable heads that will allow for a			
133 ⊿	1) Scheduled	A) Now	DOC	CF	Renovate 2 Boilers	\$ 58,000	smaller low fire for warmer weather.			
				Post 13 Mount						
134 4	1) Scheduled	A) Now	DPS	Pleasant	Repave parking lot	\$ 90,000	Rock/tar lot last resurfaced in 1999			
							This includes new cooling coils, VAV boxes with hot water reheat			
							coils, dampers, drain pan liners in the both AHU, damper operators			
				(			and DDC Controls. Equipment is original to building (1969),			
							temperatures are difficult to control. The condition of the leaking coils			
				Capitol			could lead to a health problem for the building occupants. Needs to be			
135 🗸	1) Scheduled	A) Now			Grimes Building HVAC Updates	\$ 7,385,897	a capital request.		<u> </u>	
							This includes new cooling coils and removal of the existing steam			
							reheat coils that were installed behind the existing cooling coils in both			
				Capitol	Lucas Building Cooling Coil		AHU 1 & 2. 2 coils are broken and 2 have questionable flow. Difficult			
	1) Scheduled				Replacement		to maintain cooling in summer heat.			
137 🛚	1) Scheduled	A) Now	DHS	WRC	Larches chillers replacement	\$ 250,000	2 ea - 80 ton & 65 ton			
Γ					Security updates, installation of walk-					
					through sally port gate and widening		Add pedestrian sally port. Need a sliding gate between E/W yards.			
138 ⊿	1) Scheduled	A) Now	DHS	CCUSO	of E/W yard gate	\$ 200,000	Not wide enough for maintenance equipment to service area.			
			Terrace							
139 ⊿	1) Scheduled	A) Now	Hill	Terrace Hill	Elevator repair	\$ 35,000	New controller			
				Union Sunday						
				School/Clermo						
140 4	1) Scheduled	A) Now	DCA	nt	Roof and Tuck Pointing	\$ 31,500				
				Clermont	j	·				
141 4	1) Scheduled	A) Now			Clermont Museum Repairs	\$ 32,000				
					Repair or replace streets, curbs,	·				
		A) Now			sidewalks on the Complex	\$ 276,800			I I	

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
143 4)	Scheduled	A) Now	DAS	Capitol Complex	Replace Controls At The Historical Building With Direct Digital Controls	\$ 1,727,680	System is failing			
444 (1)	O a la a de d a d	A \ N. 1	DAG	Capitol	Finish full restoration of Soldiers &	Ф 000,000				
144 4)	Scheduled	A) NOW	DAS	Complex	Sailors Monument	\$ 260,000	The water is very hard and continues to damage equipment. Requires			
145 (4)	Scheduled	A) Now	DOC	North Central CF	Replace Water Softeners	\$ 100,000	12 bags/ day. There are leaks in tanks and tanks are steel, the contractor advised there are no parts to repair tanks and recommend fiber glass tanks be installed. The concern is if water softener tanks fail, we will need emergency funds to make repairs to damaged tanks. This is a critical need to replace current tanks and equipment. The current equipment has exceeded its life cycle.			
	Scheduled		DHS	WRC	Grandwood chiller replacement		1 ea - 120 ton			
,	Scheduled	,	DOC	ASP	Replace Cell Locking System for Living Unit B and D-3		Will pursue a capital request.			
148 4)	Scheduled	A) Now	DAS	Capitol Complex	Replace Central Energy Plant deaerator tank	\$ 452,298				
	Scheduled	· '	DHS	Independence	Reynolds Masonry Repair Phase 4	\$ 1,010,000				
	Scheduled	· ·	DHS	Independence	Infirmary Masonry Repair	\$ 405,000				
	Scheduled	· ·	DHS	Independence	Reynolds Masonry Repair Phase 5	\$ 300,000	Cost estimate lowered based on reassessment.			
152 4)	Scheduled	A) Now	DOC	Ft Dodge CF	Replace Automation Panels		Obsolete, can't upgrade software. Have some spare parts in inventory.			
153 <u>4)</u>	Scheduled	A) Now	DOC	Ft Dodge CF	Repair Laundry Hot Water Recovery System Entry		Hot water recovery system needed to keep up with hot water demand, current pit very difficult to clean.			
154 <u>4)</u>	Scheduled	A) Now	DAS	Capitol Complex	Replace parking lot 3, including new lighting Install backflow prevention or dry sprinkler system in residential	\$ 1,400,880	Lot 3 has buckled in several place, creating large pot holes. There are lots of sunken in spots from heavy loading and wide joint and settlement cracks. The over all condition of this parking lot is very hazardous to drive or walk across.			
155 4)	Scheduled	A) Now	DHS	Glenwood	houses	\$ 260,000	no citations, no contamination of drinking water			
156 4)	Scheduled	A) Now	DHS	Cherokee	Replace Roof - Motor Pool	\$ 150,000	Project was funded 8/2013, but engineering review determined it did not need to be replaced yet.			
157 <u>4)</u>	Scheduled	A) Now	Terrace Hill	Terrace Hill	Replace wood shake roof on Carriage House	\$ 200,000	Inspection of roof to determine how much wood rot that is apparent if not 100%. No water issues inside.			
158 4)	Scheduled	A) Now	Terrace Hill	Terrace Hill	Timbers for Pool house	\$ 60,000	Timbers to be cured for one year and placed the following year			
159 4)	Scheduled	A) Now	DOC	IMCC	Electrical Upgrade Study	\$ 100.000	Electrical upgrade for the old part of the facility. Because of ever changing needs in Corrections, existing cells and other areas do not have enough power capabilities which are becoming necessary. Wiring is becoming aged as well. Our electrician is telling us we simply do not have any more available power to simply add an outlet.			
	Scheduled		DHS	Cherokee	Replace Condensate Return from Four Corners to Powerhouse		Current condensate lines are deteriorated and leak badly. Most of the design done under 8691.00			Propose funding because a recent site visit determined steam leaks are deteriorating pipe chase and associated walkway on top as well as co-located electrical lines.

outer store is starting to ge many gains in II. Water is the nable to get into the gaps and interesting and interesting the immediate. These caps also allow animals/broad-bodens, to build note to note of the super more. Will be immediate, the immediate extracting statement and interesting animal statement of the super more. Will be immediate extracting statement and in the Manufa Register created for animal statement of the super more. Will be immediate extracting statement and in the Manufa Register. We then the Manufa Register created for animal statement of the state door statement and the statement of the state door frames. Russoft transes are being registed as super more. Will be that is corrosive to the steel door frames. Russoft transes are being registed as super more will be in a super part of the steel door frames. Russoft transes are being registed as super more will be in a super part of the steel door frames. Russoft transes are being registed as super more will be in a super part of the steel door frames. Russoft transes are being registed as superment of 2th coord frames are being registed as superment of 2th coord frames are being registed as superment of 2th coord frames are being registed as superment of 2th coord frames are being registed as superment of 2th coord frames are being register. The forcer evertage in the state to register and propriet frames are being register. The forcer evertage and contact and the state of the state	_	Priority	Immediacy	Agency	Facility	Project Title	Funding Req	uest	Comments	Funding Source	Funding Allocated	Status
Scheduled   A) Now   DOC   ISP   Tuckpoint of CH17   \$ 10,0000   to keep it selected with grower installed using an incompatible grout material that is conceive to the seed of fames. Revised frames are continued using an incompatible grout material that is conceive to the seed door frames. An incompatible grout material that is conceive to the seed door frames. An incompatible grout material that is conceive to the seed door frames are continued using an incompatible grout material that is conceive to the seed door frames. An incompatible grout material that is conceive to the seed door frames are continued state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state that will require the replacement of 275 door frames for some state of the some state of the state of the some state of the state of th									get into the gaps and freeze/expand, crushing the limestone. These caps also allow animals/birds/rodents, to build nests in some of the			
Essing steef frame doors were installed using an incompatible grout message and common and a common project of the required frame and common project of the required frame and common project frame the common project of the required frame and common project of the required frame and common project frame from the common project frame from the common project frame from the common project frame from project frame frame frame from the document of the following frame frame frame frame frame frame f									· ·			
A   Scheduled   A   Now   DOC   Ft Dodge CF   Substituted   A   Now   DOC   St Dodge CF   Substituted   Substi	161	4) Scheduled	A) Now	DOC	ISP	Tuckpoint of CH17	\$	100,000				
Replace rusted out door frame in being replaced as required. Eventually at the frames will be in a critical state that will require the replacement of 275 door frames for such as a critical state that will require the replacement of 275 door frames for such as a critical state that will require the replacement of 275 door frames for such as a critical state that will require the replacement of 275 door frames for such as a critical state that will require the replacement of 275 door frames for such as a critical state that will require the replacement of 275 door frames for such as a critical state that will require the replacement of 275 door frames for such as a critical state of the will require the replacement of 275 door frames for such as a critical state of the will require the replacement of 275 door frames for such as a critical state of the will require the replacement of 275 door frames for such as a critical state of the will require the replacement of 275 door frames for such as a critical state of the will require the replacement in the last two years and 125 service calls for people being enhancing with the such meeting and cocing to cell houses. efficise, didnay and other activity areas at our facility. If removal and replacement is projected it will be necessary to remove some of the units through the rocks of our facility as there is no way of accessing the areas accept with bot staffs and walk frough doorses, Roofing projects are already on the major walk frough doorses, Roofing projects. These units would also need to be fail into our Subsequent of the units through the rocks are already on the major walk frough doorses, Roofing projects. These units would also need to be fail into our subsequent to subsequent the subsequent of the units through the rocks are already on the major walk frough doorses, are already on the major walk frough doorses, Roofing enhancement project will be necessary to remove the four tenths walk frough doorses, are already on the major walk frough doorses, are alr												
A   Scheduled   A   Now   DC   F   Dodge CF												
162   4  Scheduled   A  Now   DCC   F   Dodge CF									9 1			
4) Scheduled A) Now DC Mr. Pleasant Repair parting lot \$ 65,000 The lot is in very poor resuit.  A) Scheduled A) Now DAS Complex Replace Hoover Building Elevators \$ 2,001430 [The lot is in very poor resuit. A) All of Elevator equipment. The Hoover elevators had 38 service calls for not being in operation in the last two years and Capital Complex Replace Hoover Building Elevators \$ 2,001430 [The lot is in very poor resuit. A) All of Elevators equipment is original equipment. The Hoover elevators had 38 service calls for not being in operation in the last two years and Capital Complex of the Complex o	400	4) 0 -1 - 1 1 - 1	A	D00	ELD ALAM OF	•	•		· · · · · · · · · · · · · · · · · · ·			
All of Elevator suppress its original equipment. The Hoover elevators had 38 service calls for people being entrapped.  Complex  Replace Hoover Building Elevators  \$ 2,031,430 (12 service calls for people being entrapped.  Complex  Replace Hoover Building Elevators  \$ 2,031,430 (12 service calls for people being entrapped.  Complex  Replace Hoover Building Elevators  \$ 2,031,430 (12 service calls for people being and not peration since approximately 1970. The old part of our facility has 15 existing air handling units which need replacement before lading over experts to. They do provide heating and coding to cell house, offices, deletary and other actively areas at our facility. If removal and replacement is projected it will be necessary to more some of the units through the root of our facility or wait, through covery. Rooting projects are already on the major maintenance list and it may be an opportune time to stain replacing some of these unit with a root project. These units would also need to be fell into our Stemens building automation system. This estimate does not include engineering fees. It is based off \$150,000/air  A) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 3,000.00 and Individual engineering fees. It is based off \$150,000/air  (a) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 3,000.00 and Individual engineering fees. It is based off \$150,000/air  (b) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 3,000.00 and Individual engineering fees. It is based off \$150,000/air  (c) A) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 3,000.00 and Individual engineering fees. It is based off \$150,000/air  (d) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 3,000.00 and Individual engineering fees. It is based off \$150,000/air  (e) A) Scheduled A) Now DVA Home Cast from Pipe Replacement \$ 3,000.00 and unique engineering fees. It is based off \$150,000/air  (e) A) Scheduled A) Now DVA Home Cast from Pipe Replacement \$ 3,000.00 and unique engineering fees. It is based t							\$		·			
A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.196,817 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now DC IMCC Air Handler Replacement S 3.00,000 Anader.  A) Scheduled A) Now	163	4) Scheduled	A) Now	DOC	Mt. Pleasant	Repair parking lot	\$					
4) Scheduled A) Now DAS Complex Replace Hoover Building Elevators \$ 2,031,430   12 service calls for people being entrapped.  Our facility has 16 oxisting air handling units which need replacement before failure occurs. These units are placed in locations that make it very difficult to provide repairs to. They do provide heating and cooling to cell houses, offices, didataly and other activity areas at our facility, if removal and replacement is projected it will be necessary to remove some of the units through the races accept with foot traffic and walk through doorways. Roofing projects are areasy on the major maintenance list and it may be an opportune time to start replacing some of these units with a roof project. These units a would also need to be field into our Siemens building automation system. This selfmate does not include engineering fees. It is based off S165,000/air handler.  4) Scheduled A) Now DOC IMCC Air Handler Replacement \$ 3,196,817 handler.  4) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 300,000 and Lordon a									, , , , , , , , , , , , , , , , , , , ,			
Our facility has been in operation since approximately 1970. The old part of ural facility has 15 existing air handing units with cheed replacement before failure occurs. These units are placed in locations that make it very difficult to provide peaps to. They do provide heating and cooling to cell houses, offices, dictary and other activity areas at our facility. If emoved and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected it will be necessary to remove and replacement is projected in the necessary to remove and replacement is projected in the necessary to remove and replacement in the removed to remove the necessary to remove and replacement is necessary to remove and replacement on the submitted and remove a placement of the necessary to remove and replacement of the necessary to remove and replacement and remove and replacement and remove a placement and remove and replacement and remove and replacement and remove a placement and remove a placement and remove and remove a placement and remove and remove and remove and replacement and remove and remove and remove a placement and remove a placement and remove a placement and remove and remove and replacement and remove and remove and remove and remove and r	404	4) 0 -1 - 1 1 - 1	A	D 4 0	·	Dealers Herring D. H.Frey Elevations		004 400				
part of our facility has 15 existing air handling units which need replacement before failure occurs. These units are placed in locations that make it very difficult to provide repairs to. They do provide healting and cooling to cell houses, offices, dietary and other activity areas at our facility, if removal and replacement is projected it will be necessary to remove some of the units through her ords of our facility as there is no way of accessing the areas accept with foot traffic and walk through downways. Roofing projects are already on the major maintenance list and it may be an opportune time to start replacing some of these unit with a roof project. These units would also need to be tell into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,0000 air and ones to be tell into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,0000 air and ones to be tell into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,0000 air and ones to be tell into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,0000 air and ones to be tell into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,0000 air and ones. The project list is a second of the project list in the project list is a second of the project list in the project list.  185 4) Scheduled A) Now DOC Flodge CF Replacement \$ 300,000 and Loffus. Areas are brittle, with frequent breakages  4) Scheduled A) Now DOC Mit. Pleasant North Core Generator \$ 40,000 backups for the main security system.  186 4) Scheduled A) Now DOC Mit. Pleasant North Core Generator \$ 40,000 backups for the main security system.  187 4) Scheduled A) Now DOC Mit. Pleasant North Core Generator \$ 40,000 backups for the main security system.  189 4) Scheduled A) Now DOC Mit. Pleasant North Core Generator	164	4) Scheduled	A) NOW	DAS	Complex	Replace Hoover Building Elevators	\$ 2	2,031,430				
roplacement before failure occurs. These units are placed in locations that make it very difficult to provide repairs on. These points are placed in locations that make it very difficult to provide repairs to. They do provide heating and cooling to cell houses, offices, dietary and other activity areas at our facility. If removal and replacement is projected it will be necessary to remove some of the units through the roots of our facility as there is no way of accessing the areas accept with four traffic and wall through doorways. Roofing projects are already on the major maintenance list and if may be an opportune lime to start replacing some of these unit with a roof project. These units would also need to be teld into our Slemens building automation system. This estimate does not include engineering fees. It is based off \$150,000/air handler.  4) Scheduled A) Now DVA Iowa Veterans  4) Scheduled A) Now DVA Iowa Veterans  Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, and Loffus. Areas are brittle, with flequent breakages  8 As Scheduled A) Now DCC Ft Dodge CF urits  9 A Scheduled A) Now DCC Microscoping with the proposed for the propos							~					
that make it very difficult to provide repairs to. They do provide healing and cooling to cell houses, offices, dietary and other activity areas at our facility. It removal and replacement is projected it will be necessary to remove some of the units through the roofs of our facility as there is no way of accessing the areas accept with foot traffic and walk through droorways. Roofing projects are already on the major maintenance list and it may be an opportune time to start replacing some of these unit with a roof project. These units would also need to be tied into our Siemens building automation system. This settimate does not include engineering fees. It is based off \$150,000/air does not include engineering fees, it is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is a backup to a backup generator. This generator is becoming antiquated and now regains and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backup for the main security system.  GRC previously submitted a request to evaluate the water mains (see 446 on earlier list). After speaking to a mechanical eng												
and cooling to cell houses, offices, dietary and other activity areas at our facility. If removed and replacement is projected it will be necessary to remove some of the units through the roofs of our facility as there is no way of accessing the areas accept with foot traffic and walk through doorways. Roofing projects are already on the major maintenance list and it may be an opportune time to start replacing some of these unit with a roof project. These units would also need to be teld into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,000/air  4) Scheduled A) Now DVA Home Cast fron Pipe Replacement \$ 300,000 And fail at an unacceptable rate.  4) Scheduled A) Now DOC Ft Dodge CF units with sensor reporting units are aged and beginning to give failse alarms  5 30,000 And fail at an unacceptable rate.  6 4) Scheduled A) Now DOC Met Pleasant North Core Generator \$ 40,000 And fail at an unacceptable rate.  6 6 7 Scheduled A) Now DOC Mt. Pleasant North Core Generator \$ 40,000 And fail at an unacceptable rate.  7 8 Facility removed from project list.  7 8 GRC previously submitted a request to evaluate the water mains (see 446 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive execusion. They recommended we consider replacement since they advised there is no good method to evaluate the water mains without extensive execusion. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.							/ <		·			
our facility. If removal and replacement is projected it will be necessary to remove some of the units through the rodos for our facility as there is no way of accessary to remove some of the units through the rodos accept with foot traffic and walk through doorways. Roding projects are already on the major maintenance list and it may be an opportune time to start replacing some of these unit with a rod project. These units would also need to be tiled into our Stermens building automation system. This estimate does not include engineering fees. It is based off \$150,000 and all and and Loffus. Areas are brittle, with frequent breakages    4 Scheduled   A   Now   DVA   Home   Cast Iron Pipe Replacement   \$30,000 and Loffus. Areas are brittle, with frequent breakages   \$4 Scheduled   A   Now   DVC   Ft Dodge CF   Units   \$50,000 and fall at an unacceptable rate.   \$150,000 and fall at an unacceptable rate.   \$1												
necessary to remove some of the units through the roofs of our facility as there is no way of accessing the areas accept with four traffic and walk through doorways. Roofing projects are already on the major malinenance list and it may be an opportune time to start replacing some of these units would also need to be tied into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,000/air and some off \$												
as there is no way of accessing the areas accept with foot traffic and walk through doorways. Roofing projects are already on the major maintenance list and it may be an opportune time to start replacing some of these unit with a roof project. These units would also need to be tied into our Siemens building automation system. This settimate does not include engineering fees. It is based off \$150,000/air handler.  4) Scheduled A) Now DVA Idva Veterans Home Cast Iron Pipe Replacement \$ 3,196,817 handler.  4) Scheduled A) Now DVA Idva Veterans Replace Start on Pipe Replacement \$ 30,000 and fail at an unacceptable rate.  8 A) Scheduled A) Now DVA Idva Veterans Replace Start on Pipe Replacement \$ 30,000 and fail at an unacceptable rate.  9 A) Scheduled A) Now DVA Idva Veterans Replace Start on Pipe Replacement \$ 20,000 and fail at an unacceptable rate.  9 A) Scheduled A) Now DVA Idva Veterans Replace Start on Pipe Replacement \$ 20,000 and fail at an unacceptable rate.  169 A) Scheduled A) Now DVA Idva Veterans Replace Siding on Bidg 14 (ILU) \$ 25,000 and fail at an unacceptable rate.  169 A) Scheduled A) Now DVA Idva Veterans Replace Siding on Bidg 14 (ILU) \$ 25,000 and fail at an unacceptable rate.  169 A) Scheduled A) Now DVA Idva Veterans Replacement Siding on Bidg 14 (ILU) \$ 25,000 and fail at an unacceptable rate.  169 A) Scheduled A) Now DVA Idva Veterans Veterans Replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  169 A) Scheduled A) Now DVA Idva Veterans Veterans Replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  160 A) Scheduled A) Now DVA Idva Veterans Veterans Replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  160 A) Scheduled A) Now Idva Veterans Veterans Replacements are costly. The generator is increasingly unreliable. If it should go down we l									· · · · · · · · · · · · · · · · · · ·			
walk through doorways. Roofing projects are already on the major maintenance list and it may be an opportune time to stair replacing some of these unit with a roof project. These units would also need to be field into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,000 air handler.  4) Scheduled A) Now DOC MicCo Air Handler Replacement \$ 3,196,817 handler.  Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in based of the Sheeler, Based and Dackup date are again and patients of Malloy, Dack, Sheeler, Replace horizontal drain lines in based of the Sheeler, Based and Dackup date are again date based on the based of the Sheeler, Based and Dackup date are again and pat												
maintenance list and it may be an opportune time to start replacing some of these unit with a roof project. These units would also need to be field into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering fees. It is based off \$150,000/air does not include engineering to generator include engineering engin												
Scheduled   A) Now   DOC   IMCC   Air Handler Replacement   \$ 3,196,817   handler.												
be tied into our Siemens building automation system. This estimate does not include engineering fees. It is based off \$150,000/air handler.    Scheduled   A) Now   DVA   Home   Cast Iron Pipe Replacement   S 30,000 and Loftus. Areas are brittle, with frequent breakages									· · · · · · · · · · · · · · · · · · ·			
does not include engineering fees. It is based off \$150,000/air handler.  4) Scheduled A) Now DVA Home Cast Iron Pipe Replacement \$ 3,196,817 Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, Home Cast Iron Pipe Replacement \$ 300,000 and Loftus. Areas are brittle, with frequent breakages  4) Scheduled A) Now DOC Ft Dodge CF units \$ 150,000 and Loftus. Areas are brittle, with frequent breakages  5 Sensor reporting units are aged and beginning to give false alarms and fail at an unacceptable rate.  6 4) Scheduled A) Now DOC Newton CF Replace siding on Bidg 14 (ILU) \$ 25,000 and Loftus. Areas are brittle, with frequent breakages  6 Sensor reporting units are aged and beginning to give false alarms and fail at an unacceptable rate.  7 This is a backup to a backup generator. This generator is becoming antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  6 GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.									·			
4  Scheduled   A  Now   DOC   IMCC   Air Handler Replacement   \$ 3,196,817 handler.   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Alloy of Alloy of Malloy Sensor reporting units are aged and beginning to give false alarms   Replace horizontal drain lines in basements of Malloy, Dack, Sheeler,   Alloy of Malloy Sensor reporting units are aged and beginning to give false alarms   Alloy of Malloy Sensor reporting units are aged and beginning to give false alarms   Alloy of Malloy Sensor reporting units are aged and beginning to give false alarms   Alloy Sensor reporting un									· · · · · · · · · · · · · · · · · · ·			
Replace horizontal drain lines in basements of Malloy, Dack, Sheeler, and Loftus. Areas are brittle, with frequent breakages  Replace taut wire sensor reporting untils  Replace taut wire sensor reporting untils  Sensor reporting units are aged and beginning to give false alarms  Sensor reporting units are aged and beginning to give false alarms  A) Now DOC Newton CF Replace siding on Bidg 14 (ILU) \$  25,000  This is a backup to a backup generator. This generator is becoming antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.	165	4) Scheduled	A) Now	DOC	IMCC	Air Handler Replacement	\$ 3	3 196 817				
4   Scheduled   A   Now   DVA   Home   Cast Iron Pipe Replacement   \$ 300,000   and Loftus. Areas are brittle, with frequent breakages   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   A   Scheduled   A   Now   DOC   Replace siding on Bidg 14 (ILU)   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning to give false alarms   Sensor reporting units are aged and beginning t		i) concained	7.9.1.0.1			7 III T Iditale Treplace The I	, v					
167 4) Scheduled A) Now DOC Ft Dodge CF Units \$ 150,000 Sensor reporting units are aged and beginning to give false alarms and fail at an unacceptable rate.  168 4) Scheduled A) Now DOC Newton CF Replace siding on Bidg 14 (ILU) \$ 25,000 This is a backup to a backup generator. This generator is becoming antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  169 4) Scheduled A) Now DOC Mt. Pleasant North Core Generator \$ 40,000 Sensor reporting units are aged and beginning to give false alarms and fail at an unacceptable rate.  Facility removed from project list.  Facility removed from project list.  This is a backup to a backup generator. This generator is becoming antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.	166	4) Scheduled	A) Now	DVA		Cast Iron Pipe Replacement	\$					
167 4) Scheduled A) Now DOC Ft Dodge CF units \$ 150,000 and fail at an unacceptable rate.  168 4) Scheduled A) Now DOC Newton CF Replace siding on Bidg 14 (ILU) \$ 25,000 This is a backup to a backup generator. This generator is becoming antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  169 4) Scheduled A) Now DOC Mt. Pleasant North Core Generator \$ 40,000 The main security system.  169 GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.		.,	.,				<b>*</b>	•	, 1			
4) Scheduled A) Now DOC Mt. Pleasant North Core Generator \$ 40,000 Backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.	167	4) Scheduled	A) Now	DOC	Ft Dodge CF		\$					
This is a backup to a backup generator. This generator is becoming antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.							¢					Coolity removed from project list
antiquated and now repairs and replacements are costly. The generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.	+00	4) Scrieduleu	<del>A) NOW</del>	<del>500</del>	INEWION OF	Replace Siding on Blug 14 (ILO)	-\$	<del>- 20,000</del>	This is a hapkup to a hookup generator. This generator is becoming			racility removed from project list.
generator is increasingly unreliable. If it should go down we lose the backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.												
4) Scheduled A) Now DOC Mt. Pleasant North Core Generator \$ 40,000 backups for the main security system.  GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.												
GRC previously submitted a request to evaluate the water mains (see #46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.	160	4) Schodulad	A) Now	DOC	Mt Placeant	North Core Generator	¢	40.000				
#46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.	108	T) Scrieduled	A) INOW	טטט	IVIL. FIEdSallL	INOTHI COLE GENERALUI	Ψ	40,000	backups for the main security system.			
#46 on earlier list). After speaking to a mechanical engineer they advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.									GRC previously submitted a request to evaluate the water mains (see			
advised there is no good method to evaluate the water mains without extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.												
extensive excavation. They recommended we consider replacement since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.									, , ,			
since the water mains are more than 100 years old and we are experiencing rust and contamination in the domestic water supply.												
experiencing rust and contamination in the domestic water supply.									·			
	170	4) Scheduled	B) < 1 vr	DHS	Glenwood	Replace water mains	<b>S</b> 1	.000 000	, , ,			

	Driority	Immediacy	Agonov	Facility	Project Title	Funding Reque	\c.t	Comments	Funding Source	Funding Allocated	Status
Г	Priority	Immediacy	Agency	racility	Project Title	runding Reque	251		Source	Allocated	Status
								Unit A, B, C and Condenser Unit D. Unit D-3 of the 6 condensing			
								coils on the roof top unit have severe deterioration of the fins and			
								lines, without this unit operating we have no AC to our 320 man unit.			
								Unit A, B, C both condenser and evaporator coils on all or most of			
								these units are deteriorated, constant thawing of these units are			
								required due to plugged and damaged coils reducing proper air flow			
								through the unit, this in turn causes excessive wear and tear on the			
								compressors not to mention the excessive wear on the unit by			
								constant tear down to thaw. Furthermore the placement of these units			
								is a hazard to the offenders and staff that must perform weekly and			
								sometimes more often maintenance as the units are placed above a			
								stair well and requires scaffold to be built on the primary stair well to			
				North Central	Air Handler Replacement and			allow offenders to thaw and clean the units. All of these units are			
171	4) Scheduled	B) < 1 yr	DOC	CF	Condenser Coils	\$ 13	30,000	problematic and are not expected to operate much longer.			
								Panels are obsolete and malfunctioning often. These energy			
								management panels controls all heating and cooling operations on the			
					Energy Management Field Panel			facility. Malfunction recently caused numerous boiler shutdowns			
172	4) Scheduled	B) < 1 yr	DHS	School - Eldora	Replacements	\$ 1	51,271	during dead of winter.			
								The two 1,000 gallon tanks have passed life cycle end and are			
					Replace Hot Water Tanks and			showing signs of leakage and wear. They supply all the hot water for			
173	4) Scheduled	B) < 1 yr	DOC	Mt. Pleasant	Controls	\$	60,000	the 20 building			
ľ											
174	4) Scheduled	B) < 1 yr	DOC	Newton CF	Update CCTV system	\$ 2	50,000				
ľ	,	, ,					,	Currently have to replace a \$7,000 pump about every 5 years. Will			
175	4) Scheduled	B) <1 vr	DOC	ASP	Luster Heights – New Water Well	\$ 50	05.000	pursue a capital request.			
_	,	, ,					,	Condensate Storage tanks have holes in them allowing steam to			
								escape in the upper end. The lower end may rust through some day			
					Replace steam condensate storage	2		as well. If these tanks become unusable, boilers will not operate.			
176	4) Scheduled	B) <1 vr	DOC	ASP	system	\$ 2		Engineering done.			
	.,						,				
177	4) Scheduled	B) <1 vr	DOC	Ft Dodge CF	Replace Water Conditioning System	\$	70 000	Undersized, regenerate 3 - 4 times/day			
	.,			cage c.	Replace large 350 lb built in clothes	Ψ	. 0,000	Laundry process approx. 5000lbs of laundry per day on average of			
178	4) Scheduled	B) <1 vr	DOC	Clarinda	dryers in laundry	\$ 25	50.000	offender clothing.			
170	i) Concadica	<i>D</i> ) 11 y.	200	Ciarinaa	aryere in laditary	<del>)</del>	00,000	Current phone system is end of life (replacement parts are not			Removed when determined was
<del>179</del>	4) Scheduled	B) <1 vr	<del>DOC</del>	<del>Clarinda</del>	Replacement of IP Phone System	\$ 5	00 000	manufactured anymore).			ineligible for MM funding.
., 0	1) 0011000100	<i>D</i> ) 11 y.	200	Oldinida	NCF - Living Unit C Roof	Ψ	00,000	manadotaroa ariyinoroji			intelligible for this randing.
180	4) Scheduled	B) <1 vr	DOC	Newton CF	Replacement	\$ 3	50 000	Patching on the roof has happened and nearing the end of life cycle			
.00	1) 0011000100	<i>2)</i> (1) y.	200	Tromton or	NCF - Living Unit D Roof	<del>-</del>	00,000	and meaning are and real mac mappened and meaning are one or me system			
181	4) Scheduled	B) <1 vr	DOC	Newton CF	Replacement	\$ 3	50.000	Patching on the roof has happened and nearing the end of life cycle			
	., 55.1544154	-/ -: 5'				<del>-</del>	20,000	Ceiling tiles are currently stained with water and wear and tear; the			
								grid system has to be replaced because the current ceiling tile are no			
								longer available because of their size (20x60). At the same time we			
				6450 Corporate				need to replace the flourescent lights in the grid due to fit and so we			
182	4) Scheduled	C) > 1 yr		•	Replace ceiling tiles and grid system	\$ 2	75 000	can replace the lights with higher efficiency lighting.			
102	+) Ochcadica	0) > 1 yi	11 1 V	Di	Treplace celling thes and gha system	Ψ	70,000	Car is past life expectancy. Controller is in need of repair. Does not			
								have phase one fire recall. The facility is being vacated and has been			
102	4) Scheduled	C) > 1 vr	DOC	Mt. Pleasant	Elevator MWU Upgrade	\$ 2	20 000	moved to the bottom of our needs.			
103	T) Scrieduled	0) / 1 yi	500	IVIL. I IDASAIIL	District Wive Opyrace	Ψ Ζ.	۷,000	2" wide cracks at the joints, full of settlement cracks, some hole and			
								raised surfaces creating tripping hazards and broken and damaged			
								concrete side walk curbs. 12B will be occupied for at least 1 year by			
				Capitol				cell tower. Project will wait until IA Bldg demo is done and cell tower is			
19/	4) Scheduled	C) > 1 yr		•	Replace parking lots 12A & B	\$ 1,08		removed. Reconsider in Spring 2015.			
104	+, Coriectalea	0, - 1 yi	טאט	Complex	Tropiaco parking loto 12A & D	Ψ 1,00	51,000	All of Elevator equipment is original equipment. The Wallace Building			
				Capitol	Replace Wallace Buildings			Elevators had 32 service calls for not being in operation and 1			
105	4) Sobodulad	C) > 1 1/2		•		¢ 4.0	05 600	,			
192	4) Scheduled	(J) > 1 yr	DAS	Complex	Elevators	[φ 1,3	000,cu	entrapment.			

Priority	/ Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
						All of Elevator equipment is original equipment. The Jessie Parker			
			Capitol	Replace Jessie Parker Building		building had 5 service calls for not being in operation and 4			
4) Schedul	led C) > 1 yr	DAS	Complex	Elevators 1,3,4 & 5	\$ 1,049,256	entrapment calls.			
		D 4 0	Capitol	Replace Grimes Building Elevators	Φ 040.000	All of Elevator equipment is original equipment. The Grimes Building			
4) Schedul	led C) > 1 yr	DAS	Complex	1, 2 & 3	\$ 940,896	had 12 service calls for not being in operation and 1 entrapment call.			
1 (A) Cabadul	lod C) - 1 vr	DAS	Capitol	Donland Historical Building Doof	¢ 1.409.310	Doofs have reached their life expectancy and have been looking			
4) Scriedui	led C) > 1 yr	DAS	Complex	Replace Historical Building Roof	1,496,319	Roofs have reached their life expectancy and have been leaking.  Remove the skylights and replace with something other than the			
			Capitol			skylights that are always leaking. Costs from the Studies of the Lord			
) (4) Schadul	led C) > 1 yr		Complex	Replace Historical Building Skylights		Cultural Resources and the Ryan Companies US INC.			
4) Scriedui	led C <sub>f</sub> > 1 yr	DAG	Capitol	Replace Central Energy Plant Chiller	φ 2,730,790	Cultural Nesources and the Nyari Companies 03 inc.			
) (4) Schedul	led C) > 1 yr	DAS	Complex	#3	\$ 868 932	Nearing the end of its life cycle			
+) Geriedai		DAG	Capitol	Replace Central Energy Plant Chiller	Ψ 000,002	Incaming the one of its inc cycle			
4) Schedul	led C) > 1 yr	DAS	Complex	#1 Replace	\$ 868,932	Nearing the end of its life cycle			
1) Conodai	104 0/ > 1 yi	127.0	Complex	Replace Central Energy Plant	Ψ 000,002	Treating the one of ite ine eyele			
				Cooling Tower #2 , Replace Fill on		Cooling tower #2 has exceeded its life expectancy and could become			
			Capitol	Cooling Tower #4, Enlarge		unusable if anything major happens. Condenser water holding pit			
4) Schedul	led C) > 1 yr		Complex	Condenser Water Pit	\$ 746,025	needs to be enlarged to run all 4 cooling towers at the same time.			
,	, ,	_	Capitol		1111	All elevator equipment is original equipment and having too many			
4) Schedul	led C) > 1 yr	DAS	Complex	Replace IFA Building Elevator #2	\$ 219,296	incidents and entrapment calls.			
,	, ,		Capitol	Replace IWD Building Elevator #3		All elevator equipment is original equipment. The IWD Building had 5			
4) Schedul	led C) > 1 yr	DAS	Complex	West Car	\$ 266,114	service calls for not being in operation.			
	ĺ		Capitol	Replace Historical Building		All elevator equipment is original equipment and having too many			
4) Schedul	led C) > 1 yr	DAS	Complex	Elevators	\$ 1,042,517	incidents and entrapment calls.			
			Capitol	IWD 150 Des Moines Street Parking					
4) Schedul	led C) > 1 yr	DAS	Complex	Lot Replacement	\$ 314,839				
			Capitol	Facilities Management Center					
4) Schedul	led C) > 1 yr	DAS	Complex	HVAC Renovations	\$ 420,433	Replace main AHU, coils, dampers and controls to DDC.			
			Capitol	Replace Central Energy Plant Boiler		Boiler #1 is too small, once the outside temperature drops below 30			
4) Schedul	led C) > 1 yr	DAS	Complex	#1	\$ 316,000	degrees this boiler can not keep up.			
			Capitol	Replace Central Energy Plant		These are the two 200 HP primary pumps for the Capitol Complex's			
4) Schedul	led C) > 1 yr	DAS	Complex	Secondary Chiller Pumps	\$ 250,335	chilled water loop.			
			Capitol	Historical Building Building					
4) Schedul	led C) > 1 yr	DAS	Complex	Automation Controls Conversion	\$ 1,843,652	Change over the pneumatic controls to DDC controls			
			Capitol	Monument and Art Work Repair and	_	The monument endowments cannot sustain the repair and restoration			
4) Schedul	led C) > 1 yr	DAS	Complex	Restoration	\$ 275,000	of all the different monuments.			
			Capitol		•	Replace AHU, coils, fans, VAV, duct work and direct digital controls.			
4) Schedul	led C) > 1 yr	DAS	Complex	Wallace HVAC Renovations	\$ 18,202,489	All existing equipment is past its life expectancy.			
	15-1 0) 4	D 4 C	Capitol	Devile as Valida Biografia B	Ф 400.000	Doct are position the and of the States are set.			
4) Schedul	led C) > 1 yr	DAS	Complex	Replace Vehicle Dispatch Roof	\$ 400,000	Roof are nearing the end of their life expectancy.			
1 A) Calcado	lod (C) : 4 :	DAG	Capitol	Ola Babcock Miller Exterior	ф <u>000</u> 400	Clean and seal exterior stone façade, tuck-point mortar joints, clean			
4) Schedul	led C) > 1 yr	DAS	Complex	Restoration	\$ 880,422	and recaulk all building joints and around windows.			
(A) Sahadul	lod (C) > 1 1 17	DAS	Capitol	Replace Historical Building Chillers /	¢ 4.000 475	Both the chiller and the chiller/heat pump have exceeded their life			
4) Schedul	led C) > 1 yr	DAO	Complex	Heat pump	Φ 1,238,475	expectancy and they have mechanical issues.  Historical Boilers are 26 years old and are well beyond the life			
(A) Sabadul	lod (C) > 1 vr	DAG	Capitol	Poplace Historical Building Poiler	¢ 424.074	· · · · · · · · · · · · · · · · · · ·			
4) Scriedul	led C) > 1 yr	DAS	Complex	Replace Historical Building Boiler	φ 424,074	expectancy of 15 years for electric boilers.			
			Capitol	Capitol Complex West Terrace		Provide maintenance and repair to the granite planter walls and stairs.			
(4) Schedul	led C) > 1 yr		Complex	Repair and Maintenance	\$ 275,000	Reset panels that have tilted out, clean out and recaulk all joints.			
T) Sorieudi	100 0, × 1 y1	2,10	Capitol	Oran Pape Parking Lot Planter	Ψ 213,000	process pariolo triat riavo trico out, oloari out and recadit all joints.			
4) Schedul	led C) > 1 yr	DAS	Complex	Pavers Maintenance and Repair	\$ 80,000	Provide maintenance and repair to the pavers around the planters.			
, <del>-, ocnedul</del>		DAG	Joinpiex	Capitol Complex Security Camera	Ψ 00,000	Provide for upgrading, replacing and new cameras; upgrade			
1			Capitol	and Surveillance Retention and		surveillance and retention system to a new IP system. Budget			
	1	1	Jupitul	Taria Carvoniano Recontion and		positionarios and retention system to a new it system. Duayet		i I	

Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
						Provides for removal and replacement of sidewalks through out the			
			Capitol	Capitol Complex Sidewalk		complex. New sidewalks to be 6 ft wide for more efficient and effective			
210 4) Schedule	d C) > 1 yr	DAS	Complex	Replacement Program	\$ 1,156,990	snow removal.			
			Capitol	Capitol Building North Plaza		The concrete plazas between the stairs on the North side of the			
211 4) Schedule	d C) > 1 yr	DAS	Complex	concrete replacement	\$ 438,697	Capitol are badly spalled due to chemical treatment for ice.			
			Capitol	Capitol Complex Building		Provides for the upgrades to the most current versions of the Siemens			
212 4) Schedule	d C) > 1 yr	DAS	Complex	Automation Upgrades	\$ 138,875	software for the Capitol Complex and Iowa Labs on an annual basis.			
						The equipment in this building is the original equipment from when the			
			Capitol			building was built. There are 8 large AHUs in the mechanical			
213 4) Schedule	d C) > 1 yr	DAS	Complex	Hoover HVAC Systems Renovation	\$ 20,347,197	penthouse with inline R/A fans in the duct work.			
				Iowa Labs Security System		Provide for the upgrades to the to the security systems at the lowa			
214 4) Schedule	d C) > 1 yr	DAS	Iowa Labs	upgrades	\$ 70,000	Labs.			
				Iowa Labs Cameras and					
				Surveillance Retention Equipment		Provides for the upgrade to existing cameras, new cameras, with a			
215 4) Schedule	d C) > 1 yr	DAS	Iowa Labs	Upgrades	\$ 100,000	new IP based recording system for the DCI.			
,					,	,			
				Iowa Labs Parking Lot		To maintain and replace the parking lots at the lowa Labs as they are			
216 4) Schedule	d C) > 1 vr	DAS	Iowa Labs	Improvements and Repair	\$ 760.040	starting to develop large cracks and deteriorate due to poor drainage.			
, , , ,						Failure of the 1940's boilers refractory and controls repairs include			
						extensive abatement. Project abandons boilers and installs new			Funded design for Boiler #2
						300hp and 2-600hp in a new addition. Includes new DA, condensate,			replacement when it failed inspection
217 4) Schedule	d(C) > 1  vr	DOC	ASP	Power House Upgrade	\$ 6,800,000		R526	\$ 150,000	and couldn't be repaired.
217 1) Conocaio	u 0, > 1 y.	200	7101	Replace Building J freezer	Ψ 0,000,000	Walk-in freezers are damaged and in need of replacement from	11020	Ψ 100,000	and occident bo repaired.
218 4) Schedule	d(C) > 1  yr	DOC	Ft Dodge CF	compartment doors/openings	\$ 125,000	continual pallet truck impact			
219 4) Schedule		DOC	Ft Dodge CF	Replace Gym flooring		Rubber coated gym floor is damaged and worn			
219 4) Scriedule	u (C) > 1 yi	DOC	T t Douge Ci	Replace Gylli flooring	Ψ 32,000	Lot 1 has 2" wide cracks at the joints, some settlement cracking,			
						some low spots and broken and damaged concrete curb, about 10%.			
						Lot 4 has 2" wide cracks at the joints, some settlement cracking,			
			Canital	Deplese policing late 4 and 4		some low spots and broken and damaged concrete curb, about 10%.			
000 4) 0 -1 - 1 1-	1 0) 4 "	D 4 0	Capitol	Replace parking lots 1 and 4,	<b>.</b>	The over all condition of this parking lot is very hazardous to walk			
220 4) Schedule	a (C) > 1 yr	DAS	Complex	including new lighting	\$ 1,915,514				
						Lot 2 has 1" wide cracks at the joints, some spider cracking and some			
						settlement cracking along curb and gutter (5000 lin ft). Also has 10			
						concrete parking barriers which need to be replaced. Lot 13 and the			
			Capitol	Replace parking lots 2, 13 and drive		drive are full of 1" wide settlement cracks throughout the entire lot and			
221 4) Schedule	d C) > 1 yr	DAS	Complex	for 13, including new lighting	\$ 2,106,870				
						Lot 14 has 1" to 1-3/4" joint cracks (2,121 lin ft). Lot 15 has major			
			Capitol	Replace parking lots 15 and 14,		settlement cracks and wide joint cracks with surface crushing at the			
222 4) Schedule	d C) > 1 yr	DAS	Complex	including new lighting	\$ 1,179,982	inlets, joints, manholes and light pole basins.			
			Capitol	Replace parking lots 5 and 19,		Lot 5 has 1" to 2" wide cracks at the joints, some settlement along the			
223 4) Schedule	d C) > 1 yr	DAS	Complex	including new lighting	\$ 653,546	joints. Lot 19 has 1" wide settlement cracks throughout the lot.			
						The drive for lot 25 has some spalled joints and bad panels that need			
				Replace drive for parking lot 25 and		repaired or replaced (1,300 sf). Lot 11 has 3/4" to 1-1/4" wide cracks			
			Capitol	parking lots 10, 11 and 12,		at the joints (940 lin ft). Lot 12 has 3/4" to 1-1/2" wide cracks at the			
224 4) Schedule	d C) > 1 yr	DAS	Complex	including new lighting	\$ 2,142,494	joints (2,220 lin ft).			
			Capitol						
225 4) Schedule	d C) > 1 vr	DAS	Complex	Replace parking lots 9 and 9A	\$ 152,097				
, = 3115 31 2116	, ,		1 -	, , , , , , , , , , , , , , , , , , , ,		Lot 25 needs to have joints cut out and resealed. Lot 28 needs joints			
						cut out and resealed plus some cracking (1,284 lin ft). Lot 24 need			
			Capitol	Replace parking lots 28, 24 (and		some cracks cut and sealed and the drive has two panels which need			
226 4) Schedule	d(C) > 1  vr	DAS	Complex	drive), and 25	\$ 368,905	some repair or replacement.			
ZZO (+) Scriedule	u   0 / 2 1 yl	סעם	Combiex	Turres, and 20	ψ 300,905	שטחוט וטףמוו טו ופףומטפווופוונ.		<u> </u>	<u> </u>

	Priority	Immediacy	Agency	Facility	Project Title	Funding Requ	est	Comments	Funding Source	Funding Allocated	Status
								Lot 26 needs joints cut out and resealed (6,236 lin ft). Lot 16 needs			
007	4) 0 -1 1 11	0) 4			Replace parking lots 3A, 6, 16, 21	Φ 4.0		some cracks filled coming of the corner of the islands (60 lin ft). The			
227	4) Scheduled	C) > 1 yr	DAS	Complex 6535 Corporate	(and drive), 21A, and 26	\$ 4,0	158,609	rest of these lots will need joints filled in a few years.			
228	4) Scheduled	C) > 1  yr	IPTV		Repair/replace roof	\$ 1	00 000	The estimated timeframe for the replacement of the roof is FY 2017			
220	+) Ocheduled	0) > 1 yi		Iowa Veterans	Терап/теріасе тооі	Ψ	00,000	Demolish existing service tunnel and erect new tunnel from Power			
229	4) Scheduled	C) > 1 yr	DVA	Home	Tunnel Replacement, Heinz Hall	\$ 9	000,000	House to Heinz Hall.			
				Capitol	Central Energy Plant Fuel Tank		•				
230	4) Scheduled	C) > 1 yr	DAS	· · · · · · · · · · · · · · · · · · ·	Replacement	\$ 4	102,180				
				Capitol							
231	4) Scheduled	C) > 1 yr	DAS		Paint Central Energy Plant	\$ 1	31,379	Ti.:			
222	4) Cabadulad	C) > 1 \ m	DAS	Capitol	Replace Chiller #2	Ф с	060 000	This is the lead chiller for the Capitol Complex, installed in 1995, 23			
232	4) Scheduled	C) > 1 yi	DAS		Restoration of Lucas Building	Ф	000,932	year expected life.			
233	4) Scheduled	C) > 1 vr	DAS	Complex	Exterior	\$ 9	92,130				
200	1) Corrodated	0) × 1 y1	D/ (C	Capitol	Restoration of Grimes Building	Ψ	702,100				
234	4) Scheduled	C) > 1 yr	DAS	Complex	Exterior	\$ 6	000,000				
				Capitol			•				
235	4) Scheduled	C) > 1 yr	DAS	Complex	Tunnel Repair	\$ 4,7	750,000	This includes repairs of utilities, piping and fire sprinklers.			
					Replace Front Exterior Doors in						
236	4) Scheduled	C) > 1 yr	DOC	Ft Dodge CF	Living Units (6 sets)	\$	28,000	Beat up by carts.			
007	4) Cabadulad	0) 4	DOC	North Central	Hadata Hait O Fire Faces	0	F0 000	Listing Heit Herring of Office days the senten			
237	4) Scheduled	C) > 1 yr	DOC	CF	Update Unit C Fire Escape	\$	50,000	Living Unit Housing Offenders/Inmates  Can still find refurbished parts but were informed that parts will no			
238	4) Scheduled	C) > 1  yr	DHS	Cherokee	Upgrade fire alarm system	<b>\$</b>	200 000	longer be available in three years (3/2015).			
200	+) Ochcadica	0) > 1 yi	Dilo		Update Fire Escape on East Side of	9	00,000	longer be available in timee years (5/2015).			
239	4) Scheduled	C) > 1 yr	DOC		Education Bldg.	\$	60,000	The Update is required to replace the Fire Escape.			
	,							Some wiring in our health services/ living unit B/ and R&D are still			
								operating on the old two wire circuits (ungrounded). Many of these			
								circuits are overloaded due to years of cobbling and splicing. Issues			
								are addressed as problems arise, and old wiring in replaced during			
				North Control				renovations. However much of this is still a safety hazard as these			
240	4) Scheduled	C) > 1  yr		North Central CF	Update Electrical to LUB and R&D	\$		circuits do not have a safety ground installed and could cause an electrocution or fire.			
240	+) Ocheduled	0) > 1 yi	DOC	Ci	Opuate Electrical to EOD and N&D	Ψ	40,000	The hot water tanks are very uncontrollable with temperature. They			
								have very old pneumatic controls, isolation valves that do not isolate			
					~//			when necessary for draining/cleaning and the tube bundles could have			
								some work performed on them if not replaced. One tube bundle is			
								being supported inside the tank by a 4x4 wooden block because the			
241	4) Scheduled	C) > 1 yr	DOC	ASP	Replace hot water system	\$ 1	00,000	metal bracket rusted away some years back. Engineering done.			
								This building has perimeter heat and window air conditioning needs			
242	4) Scheduled	C) > 1 yr	DHS	WRC	Mechanical upgrade to e-home	\$ 1	50,000	forced air heat and cooling. existing piping failing.			
											Funded when recent site visit
											Funded when recent site visit determined the roof is currently leaking
					Replace and or repair prison metal						into the building in several areas even
243	4) Scheduled	C) > 1 vr	DOC	Clarinda	roof	\$ 7	750.000	17 year old roof leaks.	R526		after they have repaired several times.
	4) Scheduled		DOC		Replace powerhouse water heaters	\$	55,000			Ţ . J J, J J J	
	4) Scheduled		DOC		Replace 2 DA tanks	\$	50,000				
0	, 23.1244104	-/· J'	1-00		Replace 100 & 5 lb header and	7	20,000				
246	4) Scheduled	C) > 1 yr	DOC	ASP	valves	\$	50,000				
		,			Replace maintenance office and tool						
247	4) Scheduled	C) > 1 yr	DOC	ASP	control roofs	\$ 1	00,000	These are the same building.			

Р	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
					Repair/replace boulevard inside					
248 4) S	cheduled	C) > 1 yr	DOC	Newton CF	perimeter	\$ 336,000				
249 4) S	cheduled	C) > 1 yr	DOC	Newton CF	CRC - Electrical Upgrade	\$ 1,500,000				
					Replace misc. doors at NCF and					
250 4) S	cheduled	C) > 1 yr	DOC	Newton CF	CRC	\$ 150,000				
					CRC - Non-Admin Roof					
251 4) S	cheduled	C) > 1 yr	DOC	Newton CF	Replacement	\$ 572,000				
050 (1) 0		O) 1	D00	N	NCF - Building H Roof Replacement	<b>7</b> 00 000				
252 <u>4) S</u>	cheduled	C) > 1 yr	DOC	Newton CF	(support)	\$ 700,000	Patching on the roof has happened and nearing the end of life cycle			
							Parts are increasingly difficult to find. No redundancy in existing			
					Coourity compress for interior/outerior		system creating safety/security issue in the event of equipment or power failure. System supports both CCUSO and Cherokee MHI.			
					Security cameras for interior/exterior viewing-campus wide. Video		Existing VMS not supported. Video data will be permanently lost if			
					management system and CCTV		system fails. Server scheduled to be replaced. No guarantee existing			
253 (1) \$	cheduled	C > 1  yr	DHS	ccuso	upgrades.	\$ 950,000	equipment compatible w/ new server OS.			
200 [4] 0	oneduled	<i>Oj ∕</i> 1 yī		Capitol	Replace Capitol Exterior Building	Ψ 950,000	Replace the 1000 watt light fixtures that were originally installed in the			
254 11 9	cheduled	C) > 1 vr		Complex	Lighting	\$ 850,000	late 1980's.			
204 4) 3	oi icaalea	<i>○j  ~</i> 1 yı	DAG	Complex	NCF - Building K Roof Replacement	Ψ 030,000	1000 3.			
255 4) S	cheduled	C) > 1 vr	DOC	Newton CF	(admin)	\$ 150,000	Patching on the roof has happened and nearing the end of life cycle			
200 +) 0	oncadica	0) > 1 yı	100	6450 Corporate	,	Ψ 100,000	Headquarters at 6450 Corporate Drive in Johnston. Warranty expires			
256 4) S	cheduled	C) > 1 vr	IPTV	Dr	replace roof	\$ 600.000	October, 2014. Roof will need to be replaced. 56,000 sq ft.			
200 1,0	onodalod	<i>3) &gt; 1 y</i> .			Topidoo Tool	Ψ σσσ,σσσ	Cottober, 201 II. 11001 IIII. 11000 to be replaced. Co,000 oq 11.			Funded when site visit determined roof
					Replace roof covering on Carpenter					is leaking badly with rotted sheathing.
					shop detached from main building					Still occupied by carpenters and
257 4) S	cheduled	C) > 1 vr	DOC	Clarinda	using metal roofing material	\$ 65.000	Asbestos shingle covering, some leaks,	R526		offender labor.
, ,		-, ,			Replace roof covering on Paint shop		<b>3</b> , 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		<b>\$</b>	
					detached from main building using					
258 4) S	cheduled	C) > 1 yr	DOC	Clarinda	metal roofing material.	\$ 30,000	Asbestos shingle covering original to the building, 1920's			
,		, ,			NCF - Building L Roof Replacement	,	<u> </u>			
259 4) S	cheduled	C) > 1 yr	DOC	Newton CF	(power plant)	\$ 125,000	Patching on the roof has happened and nearing the end of life cycle			
		•			NCF - Building J Roof Replacement					
260 4) S	cheduled	C) > 1 yr	DOC	Newton CF	(warehouse)	\$ 125,000	Patching on the roof has happened and nearing the end of life cycle			
		•			NCF - Living Unit A Roof					
261 4) S	cheduled	C) > 1 yr	DOC	Newton CF	Replacement	\$ 150,000	Patching on the roof has happened and nearing the end of life cycle			
					NCF - Living Unit B Roof					
262 4) S	cheduled	C) > 1 yr	DOC	Newton CF	Replacement	\$ 350,000	Patching on the roof has happened and nearing the end of life cycle			
							The system is obsolete. It is rusted over and leaking leaving it very-			Removed; facility replaced when it
<del>263</del> 4) S	cheduled	C) > 1 yr	<del>DOC</del>	Mt. Pleasant	Steam booster heater, Laundry	\$ 25,000	inefficient. This needs replaced.			failed.
							The electrical service in the Admin Bldg is overloaded due to			
264 5) E	fficiency	<1 yr	DHS	Glenwood	Electrical upgrade in Admin Bldg	\$ 300,000	increased demands on the building.			
							The current condensate return system relies on numerous condensate			
005 5, 5		4	DUG		Evaluate condensate return system	<b>—</b>	pumps which are prone to failure and backup of condensate which			
265 <u>5)</u> E	fficiency	<1 yr	DHS	Glenwood	for vacuum system replacement	\$ 50,000	inhibits the efficiency of the heating system.			
							Building code requires that grease traps be used in commercial			
							kitchens discharging grease into sewer system. Cherokee has never			
260 5/ 5	fficions	۸ \ N. اه. ۱۰۰۰	DHC	Charalia	Install groups from in Distance Days	ф 4E0.000	had one installed. We occasionally get complaints from the City of			
∠00 (5) E	fficiency	A) NOW	DHS	Cherokee	Install grease trap in Dietary Dept.	\$ 150,000	Cherokee about grease we are producing.  Square D electrical power monitoring interface between the building			
							automation system and electrical panels has failed. Monitoring and			
					Repair Square D gateway interface		troubleshooting electrical usage and problems throughout the facility			
267 5) 5	fficiency	Δ) Νοω	DOC	Ft Dodge CF	to BAS system	\$ 5,000	is non-functioning.			
201 3) [	поспо	A) INOW	1000	T Douge CF	to DAO system	Ψ 5,000	This includes the need for new tennis and basketball courts and			
							weight yard repair as this yard is short of much needed activities. A			
268 5) =	fficiency	A) Now	DOC	Mt. Pleasant	West yard upgrade	\$ 150,000	retaining wall and tiling are also needed as the area takes on water.			
200 3) E	inclency	A) NOW	IDOC	IIVII. FIEdSalli	Ivvest yaru upgraue	ψ 150,000	petaning wan and thing are also needed as the area takes off Water.			

_	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
269	5) Efficiency	A) Now	DOC	Ft Dodge CF	Add Cooling Tower Walkway	\$ 12,00	Cited by Dan Duss to install working platforms on towers			
					Add Covered Entry to R&D vehicle		A covered entry is needed at our trip door for safely loading/offloading			
270	5) Efficiency	A) Now	DOC	Ft Dodge CF	loading area	\$ 85,00	transfers during adverse weather conditions			
074	=\ =(c: :	A > N	D.O.O.	E. D. J. OF	Replace Television Distribution	Φ 05.00	TV cabling is inadequate to support current use and continual outages			Removed when determined ineligible
	5) Efficiency		DOC	Ft Dodge CF	System  Description Discrete August 1997	,	and repairs occur.			for MM funding.
2/2	5) Efficiency	A) NOW	DOC	Ft Dodge CF	Renovate Pharmacy	\$ 4,50	Renovate pharmacy/add pill line window			
							Replace defective NOL card in PLC. Faulty card prevents generator			
273	5) Efficiency	A) Now	DOC	Ft Dodge CF	Generator PLC repairs	\$ 20,000	set operational data from being displayed at the system touchscreen.			
	o, Emelency	7.17.1.0.11		i i Boago o.	Install Gas Lines East and West	20,00	b oct operational data from borning diopidy od at the eyetem todoriooneering			
274	5) Efficiency	A) Now	DHS	WRC	campus	\$ 160,000	Install gas lines and install hot water loop boilers Grandwood.			
Ī	, ,	,			Renovate a campus building for	· ,				
275	5) Efficiency	A) Now	DHS	CCUSO	expanding programs (Study Only)	\$ 250,000	Capital request			
				Iowa Veterans			E-85 usage had been mandated by the Governor's office. There is no			
276	5) Efficiency	A) Now	DVA	Home	Install E-85 fueling station	\$ 110,000	public E-85 dispensing station nearby.			
							No ac in kitchen. Staff and offender workers cooking food in 120-130-			Removed; facility will address with
<del>277</del>	5) Efficiency	A) Now	DOC	Clarinda	Install Air Conditioning in Kitchen	\$ 850,00	degree room temperatures. Unsanitary and unsafe.			AHU from Glenwood.
					Fire protection hydrants and		These building do not have fire sprinkler systems and the closest fire			
.=.	->			Capitol	sprinklers for the Central Energy		hydrant to these building is on North side of Court Ave which is over			
	5) Efficiency		DAS	Complex	Plant		8 600 feet.			
279	5) Efficiency	A) NOW	DOC	ISP	Farm 1 Living Unit Renovation	\$ 500,000	Also recommended in Governor's FY2014 budget			
280	5) Efficiency	A) Now	DOC	Clarinda	Install HVAC system in the Lodge building	\$ 500,000	Building has no AC, heating system is original 1940's. Needs replaced. System is designed already and ready for rebidding.			
200	3) Liliciency	A) NOW	DOC	Ciamila	Replace the Control Center 2 Gate	φ 300,000	replaced. System is designed already and ready for rebidding.			
281	5) Efficiency	A) Now	DOC	ASP	Locking System	\$ 100.000	Have to make parts in-house when it fails.			
201	e) Emoleriey	71) 11011	B00	7.61	Locking Cyclem	Ψ 100,00	Thave to make parte in neade when the falle.			Removed when facility found another
<del>282</del>	5) Efficiency	A) Now	DOC	Ft Dodge CF	Add heat to Main Vehicle Gate	\$ 175,00	Freezes shut if they don't exercise it hourly in cold weather.			solution.
	,					9				
283	5) Efficiency	A) Now	DOC	ASP	Install fire exit stairs at Living Unit B	\$ 2,000,000	Fire Marshal notation, but no citation. Will pursue a capital request.			
284	5) Efficiency	A) Now	DHS	Cherokee	New interior electrical wiring.	\$ 2,393,03	Main bldg; Ginzberg Bldg; Wirth Hall; Voldeng Bldg.			
					Air conditioning, ductwork dampers,					
	_,				zone valves & convector upgrades					
285	5) Efficiency	A) Now	DHS	Cherokee	to main building	\$ 1,511,66	Capital request			
000	Γ\ <b>Γ</b> #:-:	A) N	DOC	IMAGG	Building – Automation Controls –	ф <u>го</u> оо				
286	5) Efficiency	A) NOW	DOC	IMCC	Phase II	\$ 50,00	)			Dropose funding a study for this project
										Propose funding a study for this project at 1A, likely funded from 70T6,
										because a recent site visit determined
										there is no direct escape for the west
										end of the 3rd and 4th floors of Admin
287	5) Efficiency	A) Now	DHS	Cherokee	Build enclosed stair towers-Phase I	\$ 1,275,000	Capital request			Building.
	<del>, , , , , , , , , , , , , , , , , , , </del>					· · · · · · · · · · · · · · · · · · ·				j
288	5) Efficiency	A) Now	DHS	Cherokee	Sidewalk replacement-campus wide	\$ 588,500				
Ī							Main bldg north patient wing-\$748,500; main bldg south patient wing-			
				1	Replace windows for all campus		\$748,500; Main bldg east ADM wing-\$305,000; Main bldg west wing-			
					buildings-Phase I. NoteDonahoe		\$245,000; Powerhouse-\$123,000; Ginzberg bldg-\$408,000; Voldeng			
000	c)	A \ A \	DUIG		omitted from this project as per	Φ	bldg-\$162,000; Wirth Hall bdg-\$175,000 plus all design & supervision			
	5) Efficiency		DHS	Cherokee	MHDS	\$ 1,490,000				
290	5) Efficiency	A) NOW	DHS	Cherokee	Clean attics & insulate ceilings	\$ 258,75	J			
201	5) Efficiency	Δ) Nον.	DHS	Cherokee	Repair campus garages & doors/including duplex garages	\$ 68,20				
	5) Efficiency		DHS	Cherokee	Motor Pool Renovation Project		2 Capital request			
	5) Efficiency		DOC	ISP	Warehouse Upgrade	\$ 160,000				
_00 [	c, =oioiioy	1. 1, 1. 1011	1200	1.0.		Ţ 100,000	<u>′1</u>		1	1

	Priority	Immediacy	Agency	Facility	Project Title	Funding Reque	est	Comments	Funding Source	Funding Allocated	Status
	<u>-</u>	1		<u> </u>	Building – Automation Controls –						
294	5) Efficiency	A) Now	DOC	IMCC	Phase III	\$ 3	356,000	Pneumatic systems do not offer efficiency of todays technology.			
					Building – Automation Controls –						
	5) Efficiency			IMCC	Phase IV			Pneumatic systems do not offer efficiency of todays technology.			
296	5) Efficiency	A) NOW	DHS	Glenwood	Replace HVAC in 710 Lacey Hall.	\$ 5	512,309	Doesn't meet the health code due to lack of sufficient dirty/clean			
297	5) Efficiency	A) Now	DOC	ASP	Remodel Laundry	\$ 7		laundry separation.			
-	5) Efficiency	· '		Glenwood	Window Replacement Building 106		135,000	idunary ooparation.			
_	5) Efficiency			Glenwood	Window Replacement Building 111		325,000				
	<i>z</i> , <u></u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		0.0	The state of the s	<del>-</del>		Can reduce scope on this bldg - would like to do minimal window			
								replacement on main floor and cover remaining windows - this bldg is			
300	5) Efficiency	A) Now	DHS	Glenwood	Window Replacement Building 119	\$ 1	190,000	used for storage/upholstery shop			
301	5) Efficiency	A) Now	DHS	Glenwood	Window Replacement Building 121	\$	80,000				
								Facility is getting by with what they have (a ramp and small elevator),			
302	5) Efficiency	A) Now	DHS	Glenwood	Meyer Hall - Install New Elevator	\$ 5	596,500	but a new elevator would be more convenient.			
								Cannot be used for drinking water without further treatment, but it is			
202	5) Efficiency	A) Now	DOC	ASP	Add water treatment to well #4	\$ 1,0		not currently used for drinking water and there is city water back-up if the other wells fail.			
303	5) Efficiency	A) NOW	DOC	ASP	Yard expansion with industrial	Φ 1,0	000,000	the other wells fall.			
					arts/recreation building. Includes						
304	5) Efficiency	A) Now	DHS	CCUSO	1600 linear feet of fencing	\$ 1,4	118,965	Capital request. (Study-Phase I Project-Phase II)			
Ī	,	,			Renovate South 1, S2 & S3 areas in						
	5) Efficiency			CCUSO	main building. (HVAC updates)		18,000				
306	5) Efficiency	A) Now	DHS	CCUSO	Outdoor Recreational facilities	\$ 1	75,000	Capital request			
	->		200		Powerhouse lighting, windows and						
307	5) Efficiency	A) Now	DOC	ASP	ventilation	\$	60,000				
200	5) Efficiency	A) Now	DOC	Ft Dodge CF	Connect Greenhouse to Hot Water Loop	¢	20,000				
300	3) Linciency	A) NOW	DOC	i i Douge Ci	Ευσρ	Ψ.	20,000				Removed per facility request - no
309	5) Efficiency	A) Now	DOC	Ft Dodge CF	Salt-Sand Building	\$	20.000	Should use capitol or operations funding.			longer desired.
310	5) Efficiency	A) Now	DOC	ASP	Replace Security Lighting	\$	50,000	1 1			<u> </u>
	-				Add Industry Building to Automation						
311	5) Efficiency	A) Now	DOC	Ft Dodge CF	System	\$	42,000				
0.40	->		200			•					
312	5) Efficiency	A) Now	DOC	ASP	Replace windows & screens in LU-B	\$	80,000				
212	5) Efficiency	A) Now	DOC	ASP	Replace windows & screens in LU-C	¢	80,000				
313	3) Liliciericy	A) NOW	DOC	AOF	Replace Windows & screens in Eo-C	Ψ	80,000				
314	5) Efficiency	A) Now	DOC	ASP	Replace windows & screens in LU-D	\$	80,000				
	,	,			Replace windows & screens in	·	,				
315	5) Efficiency	A) Now	DOC	ASP	auditorium	\$	30,000				
					Replace windows & screens in						
316	5) Efficiency	A) Now	DOC	ASP	chapel	\$	30,000				
247	E) Efficience:	A) Novi	DOC	ACD	Replace windows & screens in	ф	20.000				
317	5) Efficiency	A) NOW		ASP Capitol	music room IWD 150 Des Moines Street PA	\$	30,000				
318	5) Efficiency	A) Now		Complex	System	\$	50,000				
010	o, Emolorioy	7.914044	5,10	Complex	- Cystonii	<b>Y</b>		2 Miura 300-hp boilers were purchased at the end of FY13 with			
								operation funds eliminating the need to use Major Maintenance funds			
								to secure the boilers themselves. Facility has also paid for and is			
								anticipating the completion of the design for the installation of the			
319	5) Efficiency	A) Now			Install New Boilers	\$ 4	160,000	units. Funds requested would make the boilers operational.			
200	T\	A) Novi		Capitol	Capitol Building Law Library Rare	¢.	05.050	The most valuable and rare books of the law library are stored in this			
320	5) Efficiency	A) NOW	DAS	Complex	Book Climate Control	<b>D</b>	25,250	secure room that at times exceeds 90 degrees with high humidity.			

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
							Our current sewer building does not meet current regulations for safety and health. It is the main sewer effluent from our facility before heading to city sewer system. It contains a manual bar screen that needs to be cleaned by personnel. The bar screen is raked and the contents are emptied into a bucket manually and sent to the landfill. This material includes fecal material which can contain pathogens harmful to the health of staff and inmates. Also include with this trouble area is there is no atmosphere testing equipment to alarm individuals of an unsafe environment. If the air is unsafe when entering it could cause death of personnel. We are recommending adding redundant automatic cleaning devices such as auger monster type equipment to clean this system. Environmental controls should			
201	->		DOC			<b>.</b>	be added to ensure the building atmosphere is safe. This should be			
	5) Efficiency  5) Efficiency			IMCC	Sanitary Sewer Effluent Upgrade  Replace Plumbing Controls - John Bennett		communicated through Siemens building automation systems.  Offenders are able to flood cells, which leaks down into offices, onto computers and other equipment. During construction of the CCU, an adequate way of shutting off the water to the showers on A & B pods was not installed. Since we are not able to isolate each shower individually, the inmates are able to flood the ranges. Since there are no floor drains for the contaminated water to go, "gray" and "black" water mixes together and leaks to the lower pods and/or administrative offices, contaminating carpet, furniture, ceiling tiles, etc., which is a life/health/safety issue.			
							Currently IMCC has 3 Vapor power boilers which are asked to operate at 70-100% load. These boiler were grossly undersized when installed in 2006 and are designed for high pressure low volume output. #1 boiler is 250 hp, #2 boiler is 150 hp and #3 boiler is 150 hp. These three vapor powered boilers replaced two Murray 600 hp boilers in 2006. Buildings additions were added at that time however the boiler capacity decreased by 650 hp. Because of this the facility experiences reduced steam pressure in their systems resulting in hot water fluctuations, traps working improperly and sometimes heating issues. Additional boiler capacity needs to be added to ensure we maintain a safe and secure environment. We are recommending four 250hp fire tube boilers with controls and Siemens communication be supplied to give the facility redundancy and backup for safety and security of our facility. Also in 2006 with the new power house addition, the project only placed one DA tank in the new power house to feed the 3 boilers. DA tanks require internal inspections (requires shut down of tank) every other year and without a redundant tank, boiler feed water is required to bypass the DA tank during the inspection. The DA tank is required to remove oxygen from the water to maintain boiler tube integrity. The other issue is if this tank were to fail we have no backup and the boiler would be forced to receive oxygenated water which causes pitting, reduces tube life and could lead to tube failure in the boiler. The 2006 upgrade also included the addition of two 3600 gallon per minute Bell and Gossett water booster pumps. Unless firefighting measures are required these pumps operate at minimum speeds to			
323	5) Efficiency	A) Now	DOC	IMCC	Boiler Upgrades	\$ 1,320,395	supply water pressure to the facility from a nearby water tower.			
							Install a water line for irrigating gardens, washing down dog pee pads, etc. Current only treated/conditioned water is available from the power			
324	5) Efficiency	A) Now	DOC	Ft Dodge CF	Add Untreated Water Line	\$ 6,500	plant.			

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
					Add additional lighting to all pods in					
325 <u>5</u>	) Efficiency	A) Now	DOC	ISP	John Bennett	\$ 75	000			
					Retube hot water boilers at power		Leaking tubes are being replaced as needed. Replacemen			
326 <u>5</u>	) Efficiency	A) Now	DOC	Ft Dodge CF	plant	\$ 75	tubes (186) around the morrison tubes of all three boilers			
			200				Camera recording equipment is overloaded and can not st	ore the		
327 <u>5</u>	) Efficiency	A) Now	DOC	Ft Dodge CF	Upgrade Camera Recording System	\$ 100	desired amount of data at the desired resolution.			
							Our facility has its own hot water system which consists of			
							heating units and one storage tank. Since the installation of			
							system we have had to send each heating unit back to ma			
							for refurbishing. The system continues to operate with water			
							temperature below necessary limits of 160 degrees. The s			
							approximately 8 years old and needs to be updated to con-			
							supply water to washer for proper operation and to ensure			
							cleaned and disinfected properly by maintaining the tempe			
							Facility continues to rely on one hot water tank (1970 initia			
							supply hot water to the older portion of our building. This in			
						/ <	showers for inmates, dietary needs and general sink usage			
					6		of a 5000 gallon Tank which contains a steam heating coil			
							Currently this coil is suspected to be ruptured causing hear			
							be place on our boilers, increases in condensate returning			
							increases chemical treatment chemical. All these items inc			
							to our facility. We recommend removing the old tank and in			
220 5	\ <b>F</b> #:=:===:	A) Now	DOC	IMCC	Llot Motor Cyatama Llagrada	ф <b>г</b> О4	new tanks (possibly dual fuel capability) and supply Sieme	ns		
320 3	) Efficiency	A) NOW	DOC	IMCC	Hot Water Systems Upgrade	<b>\$</b> 501	<ul><li>'29 communication to monitor this system.</li><li>The older buildings at IMCC are currently 44 years old. As</li></ul>			
							modernization has occurred (Computers, cameras, inmate			
							radios, Fans Etc.) items have been added to the existing e			
							system and it is now full. Electrician are being asked to ad-			
							equipment but by codes, our system is no longer able to ha			
							additions. It is necessary to upgrade the electrical primary			
							(First panels inside the buildings) and add some additional			
							wiring and junctions throughout our buildings (Older building			
							Currently breakers trip repeatedly during normal daily activ			
							as plugging in a vacuum or buffer. There would need to be			
							engineering study performed, designed and arc flash progr			
329 5	) Efficiency	A) Now	DOC	IMCC	Electric Services Upgrade	\$ 2,929	106 with this request.	am oot up		
	) Efficiency			IMCC	Old Records Remodel		707 Remodel Old Records Area			
	) Efficiency	,		IMCC	Dead records Remodel	•	91 Remodel Dead Records Area			
	,	. ,				7	To provide efficient access for offender work crews we pro	pose a new		
							building located on the South side of the current Control ce	enter/front		
							gate. The current method requires us to process all offend			
							crews though our vehicle sally port and does not allow suff			
							shelter for offenders crews during inclement weather. In ac			
							this our current Control Center is becoming increasingly sn			
							inadequate to house the necessary electronic equipment a			
							necessary for an ever evolving data age. Furthermore, the			
							vehicle sally port is very aged and needs to be increased in			
							longer trucks, as well as new concrete or asphalt as the ro			
				North Central			is too small and severely damaged, also new slider gates v			
222 5	) Efficiency	A) Now		CF	Control Center Replacement	\$ 1.000	allow easier access for wide load vehicles.			

_	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
							Unit is original to 1979 construction, is undersized, with condensate			
				lavva Matanana			leaks. It has been re-skinned many times. DIA issued a comment			
222 1	E) Efficiency	A) Now	DVA	Iowa Veterans	Molloy Building Air Handler		during annual inspection, indicating this unit needs replaced to avoid a			
333	5) Efficiency	A) NOW	DVA	Home Iowa Veterans	Malloy Building Air Handler	\$ 100,000	citation.			
334	5) Efficiency	A) Now	DVA	Home	Chilled Water Distribution Valves	\$ 35,000	To improve system performance in Sheeler and Loftus			
334	) Linciency	A) NOW	DVA	Iowa Veterans	Crimed Water Distribution Valves	Ψ 33,000	Hazard analysis of all electrical panels as required by Electrical			
335	5) Efficiency	A) Now	DVA	Home	Arc flash study	\$ 200,000	Inspector			
	o Lineieney	7 t) 1 to ti	<i>D</i>	1101110	7 He Haell Study					
336	5) Efficiency	A) Now	<del>DOC</del>	Newton CF	Update electrical at boiler and tunnel	\$ 60,000				Facility removed from project list.
					Upgrade HVAC System in	,	The current ductwork needs to be modified to improve uniformity of			, ,
337 5	5) Efficiency	B) < 1 yr	DHS	Glenwood	Administration Bldg	\$ 100,000	heating in the Administration Bldg.			
							The building at 6450 has a sprinkler system but not a fire alarm			
				6450 Corporate	Install a fire alarm system at 6535		system. We would like advice on whether there should be a fire alarm			
338	5) Efficiency	B) <1 yr	IPTV	Dr	Corporate Drive	\$ 100,000	system of some type.			
					Chilled water lines and HVAC					
					equipment to patient areas of					
339	5) Efficiency	B) <1 yr	DOC	Clarinda	activities, and offices	\$ 2,601,000				
					Generator Upgrade for Co-	//				
	->	<b>5</b> )	D. 10	l	generation (Combined Heat &					
	5) Efficiency		DHS	Independence	Power)		Capital request.			
341	5) Efficiency	B) <1 yr		Newton CF	Correct area drainage Bldg 10	\$ 35,000				
242	E) Efficiency	C) > 1 vr	IPTV	Dr Corporate	Install a janitorial closet with a mop sink	\$ 5,000	ignitare are not alconing appropriately			
342	5) Efficiency	C) > 1 yl	IFIV	DI	SIIIK	\$ 5,000	janitors are not cleaning appropriately  The electrical system in the Admin Bldg is overleaded due to			Removed when determined this was a
343	5) Efficiency	C) > 1  yr	DHS	<del>Glenwood</del>	Electrical upgrade in Admin Bldg	150.000	increased computer and kitchen demands.			duplicate request to #264.
	5) Efficiency			Mt. Pleasant	10 Cell Isolation Expansion	,	Capital. Need for additional lock-up space.			
	, =			Capitol			Provides for design and renovation services to pave existing gravel parking lots, including associated building demolition, add storm water detention as required by Iowa code, parking lot lighting and area landscaping to enhance the appearance and comply with Iowa code. These two parking lots are existing gravel areas to the North of IWD and are on hill side and are unsafe to park in during the winter months as the vehicles will slide down the hill and is dangerous to walk on.			
345	5) Efficiency	C) > 1 yr		Complex	Replace Parking Lots 17 and 22	\$ 1,220,477	These lots have been closed off during icy conditions.			
							The existing emergency generators and transfer switches located at			
				Capitol	Capitol Complex Emergency		the various buildings are a life / safety issues which need to be			
346	5) Efficiency	C) > 1 yr		Complex	Generator Study	\$ 107,060	addressed.			
				Capitol	Central Energy Plant Boiler		Replace burners for Boiler #3 and add new DDC controls for all 3			
347	5) Efficiency	C) > 1 yr		Complex	Optimization	\$ 412,200	boilers optimization.			
	-> =	0) 4		Capitol	Capitol Building Granite Retaining	4=0				
348	5) Efficiency	C) > 1 yr	DAS	Complex	Wall Repair	\$ 150,000	To repair the North side granite retaining wall along Grand Ave			
				O a militari	Capitol Complex Security Camera		Address of the sector of the s			
240	-\ <b>-</b> (#:-:	C) . 4		Capitol	Expansion for Parking Ramp and		Add security cameras to the parking ramp and the parking lots North			
349	5) Efficiency	(C) > 1 yr		Complex	North of Grand Ave	<b>δ</b> 308,385	of Grand Ave.			
250	5) Efficiency	C) > 1 v/r		Capitol	Capitol Complex Chilled Water 3-	¢ 564.040	Valve replacement program to replace all 3-way chilled water valves with 2-way valves for system optimization.			
330	5) Efficiency	( <i>O) &gt;</i> 1 yl	DAO	Complex	way Valve Replacement	\$ 564,240	with z-way valves for system optimization.			

	Priority	Immediacy	Agency	Facility	Project Title	Funding Request	Comments	Funding Source	Funding Allocated	Status
Г				<u> </u>	1	3 1 3	Over the years all types of mechanical/electrical equipment and			
							associated piping has been abandoned in place, taking up valuable			
							space which could be used for future projects. It also makes working			
							on the surrounding equipment difficult and costly. The abandon			
							equipment is also being used as a catch all for unneeded storage.			
				Capitol	Demolition of Old and Abandoned		There is a salvage value to this equipment that could be utilized,			
351 5	) Efficiency	C) > 1 yr	DAS	Complex	Mechanical and Electric Systems	\$ 282,120	making it worth while to remove and dispose of.			
				Capitol	Re-commissioning and Balancing of		Efficiencies in equipment and extended equipment life can be gained			
352 5	) Efficiency	C) > 1 yr	DAS	Complex	Systems and Equipment	\$ 282,120	by balancing the needed equipment.			
										Funded when recent re-inspection
										showed duct was leaking sulfuric acid
050	\ <b>-</b>	0) 4			Iowa Labs Exhaust Duct	400,000	The acid fumes keeps eating out the stainless steel ducts for the SHL	D=00		onto ceiling panels and multiple areas
353 5	) Efficiency	C) > 1 yr	DAS	Iowa Labs	Replacement	\$ 100,000	fume hoods. Needs to be replaced with an acid resistant material.	R526	\$ 100,000	were deteriorated.
254	) <b>[</b> #:=:====	O) . 4		lavva Laba	Iowa Labs Ag Dept Grinding Room	ф <b>7</b> 0,000	Install dehumidifier in the grinding room, so the AHU does not need to			
354 5	) Efficiency	C) > 1 yr	DAS	Iowa Labs	Dehumidification Iowa Labs Wall Extensions up to the	\$ 72,000	be run so low that it super cools adjacent areas.			
255 5	) Efficiency	C) > 1 vr	DAS	lowa Labs	Deck	\$ 150,000	Extend walls up to the deck for pressurization requirements. Required for testing requirements and cross contamination.			
333 3	) Efficiency	C) > 1 yl	DAS	10wa Labs	Deck	j 150,000	Install high efficiency cooling towers to reduce, energy consumption,			
356 5	) Efficiency	C) > 1  yr	DOC	Ft Dodge CF	Replace 3 Cooling Towers	\$ 475,000	water use and maintenance expenses.			
	) Efficiency		ILEA	ILEA	Replace Boiler		Boiler was installed in 1969, but still works.			
007	Lineichey	0) > 1 y1	ILL/\	State Training	Tropidos Bollet	γο,οσο	Bollot was installed in 1905; but still works.			
358 5	) Efficiency	C) > 1 vr	DHS	•	Kitchen HVAC and hood ventilation	\$ 250.000	Improved food safety/sanitation in food prep areas.			
	,,	- / ,			116		Handicapped access for campus housing rental. Can find alternative			
							locations when handicapped access is required. Cost may be double			
359 5	) Efficiency	C) > 1 yr	DHS	Cherokee	Install elevator in Wirth Hall building	\$ 715,000	the request, based on CCUSO elevator cost.			
	) Efficiency		DHS		Stewart Hall Window Replacement	\$ 352,500				
	) Efficiency		DHS		Infirmary Window Replacement	\$ 705,000				
	) Efficiency		DHS		Witte Electrical Upgrade	\$ 200,000				
363 5	) Efficiency	C) > 1 yr	DHS	Independence	Infirmary Electrical Upgrade	\$ 100,000				
		_, .								
364 <u>5</u>	) Efficiency	C) > 1 yr	DHS	Independence	Campus-wide Asbestos Abatement	\$ 300,000				
005 5	) <b>–</b> (('-'	0) 4	D00	North Central		<u> </u>	Need to tie into Siemen Fire alarm System and cost of software and			
305 5	) Efficiency	C) > 1 yr	DOC	CF	Greenhouse Automation	\$ 30,000	wiring.			
							Construct new kitchen and storeroom for the DOC. Storeroom has			
266 5	) Efficiency	C) > 1  yr	DOC	Clarinda	Kitchen and storeroom	\$ 15.000.000	known structural cracking and deficiencies. Kitchen was last redone in 1995 and needs repaired or replaced.			
300   3	) Efficiency	C) > 1 yl	DOC	Ciarifiua	Richert and Storeroom	тэ,000,000	Kitchen coolers/freezers and food storage areas are in need of			
				State Training	Update Kitchen Cooler/Freezers		renovation and improvement in energy efficiency and are approaching			
367 5	) Efficiency	C) > 1 vr	DHS		and food storages areas	\$ 150,000	the end of their useful life.			
55. <u> </u>	, =oioiioy	-	120	Solicoi Eldora	Add wall in hallway between rec	100,000	and on their decide mor			
368 5	) Efficiency	C) > 1 vr	DOC	Newton CF	room and hall	\$ 100,000				
- <u> </u>	,	, ,		-	Install security screens in dorms 1/2					
369 5	) Efficiency	C) > 1 yr	DOC	Newton CF	windows	\$ 175,000				
					Replace water line Bldg. #10 to	·				
370 5	) Efficiency	C) > 1 yr	DOC	Newton CF	shop, and warehouse	\$ 40,000				
					Replace electrical in Bldg. 14 (ILU)					
371 5	) Efficiency	C) > 1 yr	DOC	Newton CF	and 10 (training center)	\$ 15,000				
					CRC - Replace showers in Dorms 1					
	) Efficiency			Newton CF	& 2	\$ 55,000				
	) Efficiency		DOC	Newton CF	Replace dietary equipment	\$ 500,000				
	) Efficiency		DOC	Newton CF	Chemical and paint storage facility	\$ 55,000				
	) Efficiency			Newton CF	Replace servery equipment	\$ 250,000				
	) Efficiency		DOC	Newton CF	Metal storage building	\$ 100,000				
3// 5	) Efficiency	(C) > 1 yr	DOC	Newton CF	Vehicle building	\$ 125,000				

									Funding	Funding	
	Priority	Immediacy	Agency	Facility	Project Title	Funding Requ	uest	Comments	Source	Allocated	Status
					Add room to maintenance building						
378	5) Efficiency	C) > 1 yr	DOC	Newton CF	and proper ventilation	\$	50,000				
				Capitol				Rehabilitate remaining historic clocks onto the satellite time control			
379	5) Efficiency	C) > 1 yr	DAS	Complex	Capitol Building Clock Conversion	\$		system.			
								Rising population numbers have increased the laundry operation by			
380	5) Efficiency	C) > 1 yr	DOC	Ft Dodge CF	Replace laundry equipment	\$	300,000	30% taxing a system that is nearing the end of its life cycle.			
					Replace windows in main building						
	5) Efficiency	, ,		Clarinda	administration area.	\$	324,300	Original 1885 windows still being used.			
382	5) Efficiency	C) > 1 yr		Newton CF	Upgrade boilers and chillers	\$	500,000				
	5) Efficiency				Building for salt and sand storage	\$	85,000				
384	5) Efficiency	C) > 1 yr.	DOC	Mt. Pleasant	Add A/C to East & West House	\$ 3	,350,000				
					Insulate steam and chilled water			The current insulation is in need of replacement to maintain the			
385	5) Efficiency			Glenwood	lines in the utility tunnels	\$	250,000	structural integrity of the utility tunnels.			
386	6) Demo	A) Now	DHS	Independence	Grove Hall Demolition	\$	200,000				
								abandoned, mold infested, safety, dangerous to the public and clients			
	,	A) Now		Clarinda	Demolition of Hope Hall	\$	400,000	and staff.			
		A) Now		Clarinda	Demolition of 300,000 water tower	\$		1920's water tower needs removal. Safety			
389	6) Demo	A) Now	DHS	Independence	Hill Top Demolition	\$	100,000				
						1//		Vacant training academy used for storage. Large building that would			
					,			take too much money to become ADA compliant. Currently dealing			
390	6) Demo	C) > 1 yr	DOC	Mt. Pleasant		\$	225,000	with mold issues as the building is closed up.			
					Demolition - Poultry Feed, Canary,						
					Coal Room, Concrete Garage, Root						
	·	C) > 1 yr		School - Eldora		\$		These buildings serves no function and are beyond repair			
		C) > 1 yr	DOC	Mt. Pleasant	Demolition of 1102 E. Washington	\$	10,000	The house is vacant and in poor repair.			
	7) No										
	Requests		DVA	IDVA	No projects requested	\$	-				
	7) No										
394	Requests		ABD	ABD	No projects requested	\$	-				

Total \$

261,526,856

Total Funding Allocated: \$

8,253,322