

210.7 Bottomless measure.

Bottomless dry measures shall not be used unless they conform in shape to the United States standard dry measures.

[SS15, § 3009-j; C24, 27, 31, 35, 39, § **3233**; C46, 50, 54, 58, 62, 66, 71, 73, 75, 77, 79, 81, § 210.7]