

567—39.4(455B) Abandoned well owner responsibilities.

39.4(1) *Plugging requirements.* The well owner is responsible for ensuring an abandoned well is plugged pursuant to this chapter.

39.4(2) *Record.* It is the responsibility of the owner to complete, certify, and submit to the department, or the local county health department when seeking private well grant funds, the well plugging form documenting that an abandoned well has been plugged in accordance with the requirements in this chapter, within 30 calendar days of the completed plugging. The well plugging form shall include confirmation of the well plugging by the designated agent for the county or a certified well contractor. The form is available on the department's website at www.iowadnr.gov.

[ARC 9197C, IAB 5/14/25, effective 6/18/25]