

567—49.16(455B) Pitless adapters and pitless units.

49.16(1) Pitless adapters and pitless units conforming to WSC Pitless Adapter Standard—1997 (PAS-97) are considered compliant with these rules.

49.16(2) No well casing shall be cut off or cut into below ground surface except to install a pitless well adapter below the frost level.

49.16(3) A pitless subsurface pipe connection to a well casing pipe shall be made with a weld-on, clamp-on, or bolt-on pitless adapter or weld-on or threaded pitless unit. Aboveground discharge pitless adapters with a drain-back into the well are prohibited on systems under continuous pressure.

49.16(4) If the pitless adapter is gasketed, the opening in the casing shall be sawed to the diameter recommended by the manufacturer with a hole saw and not cut with a torch. The pitless adapter used shall have the correct curvature to fit the diameter of the casing.

[ARC 9196C, IAB 5/14/25, effective 6/18/25]