

**481—404.9(103) Report of inspection.** After the completion of an inspection, the inspector will issue an inspection report indicating the results of the inspection and provide any necessary notice to the utility providing electrical service pursuant to Iowa Code section 103.28. The results of the inspection may be any of the following:

**404.9(1) Approval.** If the inspector finds that the installation is in compliance with applicable requirements, the inspector will issue a report indicating that the installation is approved.

**404.9(2) Order of correction.** If the inspector finds that the installation is not in compliance with applicable requirements but does not present an imminent threat to the health or safety of any person, the inspector will issue an order of correction, prescribing a time frame during which corrective action shall be taken by the licensee responsible for the installation to bring the installation fully into compliance.

**404.9(3) Order of disconnection.** If the inspector finds that the installation is not in compliance with applicable requirements and presents an imminent threat to the health or safety of any person, the inspector will issue an order of disconnection, requiring that the installation be disconnected until corrective action has brought the installation into full compliance with applicable requirements. The installation shall not be reconnected until the corrected installation has been approved by an inspector as in compliance with all applicable requirements. The inspector issuing an order of disconnection will notify the utility providing electrical service to the location of the order and will notify the utility when the order of disconnection is no longer effective.

[ARC 9033C, IAB 3/19/25, effective 7/1/25; Editorial change: IAC Supplement 7/9/25]