
2013 Major and Routine Maintenance Annual Report


The Department of Administrative Services' Vertical Infrastructure Program works collaboratively with member agencies to identify building maintenance projects and establish priorities on an enterprise-wide basis. The 12 state agencies and divisions participating in the Vertical Infrastructure Program of the Department of Administrative Services (DAS) collectively have approximately 900 buildings at more than 70 sites across the state, representing nearly 12 million square feet. This report will outline the major maintenance needs of state facilities and summarize progress made during 2013.

In 2013, more than \$233 million in major maintenance projects were identified at the participating state facilities. \$13.31 million in FY2014 funds and an additional \$2.7 million in FY2013 funds were appropriated to address these projects in 2013, a significant increase from the funding in previous three fiscal years, but less than the Department's request of \$31 million and far short of the identified need. The \$16 million will fund approximately forty projects across the state, but many more projects, such as leaking roofs, crumbling building façades and deteriorating tunnel caps will continue to worsen and will threaten the state's multi-billion dollar investment in its buildings.

The Legislature has already appropriated \$14 million for Major Maintenance in FY2015, and the Department's request for \$16.6 million in additional Major Maintenance funding is the Department's top priority for FY2015. If fully funded, this request would address all existing projects that pose a threat to life/health or safety and nearly all existing projects where exponential damage is occurring, assuming no new emergency projects arose. The Governor's recommendation of an additional \$7 million for FY2015 would address all existing projects that pose a threat to life/health or safety and nearly 60% of the existing projects where exponential damage is occurring.



In 2013, agencies were once again encouraged to submit all projects they knew were in need of major maintenance funding. The Capitol Complex in particular undertook a thorough review of deferred maintenance and identified more than \$125 million of additional major maintenance needs, mainly in the priority 4 scheduled maintenance category, which were added to the list. DAS has encouraged other facilities to undertake a similar review to ensure all scheduled maintenance and operational efficiency projects have been identified and included on the list and expects the total to grow to \$750 million or more when all deferred maintenance is included.





Many State facilities need roof replacements, window replacements and tuckpointing to stop water infiltration and preserve the structural integrity of the facilities. If roofs are not replaced at the end of their useful life, leaks can develop and lead to the need to replace ceilings, finishes and equipment inside buildings in addition to the roof. Antiquated HVAC equipment and failing controls continue to waste money. If boilers are not replaced at the end of their useful life, they can deteriorate and fail unexpectedly, creating the need for costly temporary heating and emergency procurement. Tunnel caps are eroded and in danger of failing, creating potential hazards for pedestrian and vehicle traffic above and threatening the distribution of utilities to buildings. Steam lines are corroded, posing danger to personnel as well as wasting energy and money. Outdated electrical distribution systems are no longer capable of providing adequate power for modern operations. Sidewalks and curbs are crumbling, posing tripping hazards to employees, residents and visitors. Abandoned buildings in need of demolition are continuing to deteriorate and may begin to pose a threat to employees and visitors.

DAS reviewed more than 350 project requests for the \$16 million in new major maintenance funds appropriated in 2013. Projects are reviewed on a quarterly basis and ranked using criteria such as whether there was an immediate threat to life, health or safety, whether damage was currently occurring, the severity and extent of damage, how soon construction could begin and the Department and institution's project ranking. All projects submitted and meeting the definition for major maintenance have been prioritized and funds have been allocated, however more than *\$233 million in identified projects are still unfunded.* The current list of unfunded major maintenance projects is attached to this report.

Although the deferred maintenance backlog is daunting, the recent increase in Major Maintenance funding has addressed critical needs at institutions across the state:

Department of Administrative Services

- At the Capitol Complex in Des Moines:
 - Completed repairs to the North stairs at the Iowa Workforce Development building. The stairs had allowed moisture to leak onto electrical distribution equipment.
 - Substantially completed demolition of the Iowa Building. Final site work is expected to be completed in spring of 2014.
 - Began design to upgrade security doors at the Hoover, Grimes and Lucas buildings to ensure the building occupants could exit safely in the event of a fire alarm.
 - Substantially completed design for repairs to the Hoover Exterior Walkway, where water damage was deteriorating the structural support. Construction is expected to be completed in 2014.



 Began evaluating the replacement of the Hoover Building aging switchgear and generators.

Iowa Building Demolition

- Completed the design for roof replacements at the Iowa Workforce Development, Jessie Parker and Wallace buildings. Construction is expected to be completed in 2014.
- Substantially completed design for the conversion of the Capitol Complex security system. Construction is expected to be completed in 2014.
- At the Iowa Laboratories Facility:
 - Completed sound dampening at the firing range. Staff had experienced hearing loss due to the noise level at the range.
 - Began design for the remediation of drainage and repair of a parking lot where the subgrade has been washed out, causing bridging with the potential for collapse.
 - Designed the relocation of the boiler exhaust flue, which currently condenses and has leaked onto lab areas.

Department of Corrections

- At the Anamosa State Penitentiary:
 - Completed demolition of the Old Auto Body Shop, which had been shedding exterior bricks into a pedestrian walkway.
 - Increased boiler blowdown piping capacity to serve seasonal emergency flows.

- Replaced the refractory lining of the Boiler #2 stack. The refractory lining inside the boiler #2 stack had degraded to the point that the refractory had fallen off and the wire mesh behind the refractory was exposed.
- Began upgrading the wastewater handling system to avoid further fines from the City of Anamosa (the facility incurred a \$110,000 fine in 2013).
- Began a project to install an ADA accessible route from Infirmary to Visiting. Currently, staff must carry inmates in wheelchairs up the stairs, which poses a safety hazard.
- Began a project to replace the cistern cap, which also serves as a sidewalk, where moisture has damaged the concrete and exposed rebar.
- At the Fort Dodge Correctional Facility:
 - Replaced a sidewalk that posed a trip hazard.
 - Installed a wastewater sampling station and metering to be in compliance with new utility regulations and avoid significant fines.
- At the Iowa Correctional Institution for Women:
 - Completed phase 2 of the facility electrical distribution upgrade.
 - Completed repairs to roof leaks at existing buildings 6B and 9.
 - Construction of new boilers in existing buildings 6 and 9 is nearly complete.
 - Work began to upgrade doors at an existing building to ensure they locked securely and would release in a fire alarm.
- At the Iowa State Penitentiary, completed the transfer of water supply from a dedicated well to city water.
- At the Mount Pleasant Correctional facility:
 - Completed the Power House roof replacement.
 - Completed design for the East and West building roof replacement. Construction is expected to be completed in 2014.
- At the Newton Correctional Facility:
 - Replaced hot water heaters and piping. Sediment had filled the piping and two of the four water heaters were out of services.
 - Began an evaluation of the forced main sewer line. The line continually plugs with air, which requires temporary water use restrictions at the facility.
 - Began design for the replacement for the Living Unit E roof.
 - Began design for the replacement of the CRC administration roof and rooftop air conditioning unit.



Newton Water Heater Piping

• At the North Central Correctional Facility, completed design for the replacement for six leaking roofs. Construction is expected to be completed in 2014.

Department of Cultural Affairs

- At the Matthew Edel Blacksmith Shop House, repaired the roof.
- At the Western Historic Trails Center, completed emergency repairs to the roof parapet and prepared cost analysis for future replacement options.

Department of Human Services

- At the Cherokee Mental Health Institute:
 - Replaced instantaneous water heaters that were obsolete and continually failing.
 - Completed design to replace existing steam piping that was not rated for the high pressure steam needed for the clothes dryers. The dryers were obsolete and it was difficult to source replacement parts, so gas dryers will replace the existing dryers and a gas line will replace the steam line. Construction is expected to start in 2014.
 - Construction is underway to replace flooring in patient areas that posed infection control issues and trip hazards.
 - Completed design for tuckpointing the main building. Construction is expected to start spring 2014.
 - Completed design for replacing roofs at the Ginzberg and Voldeng buildings. Construction is expected to start spring 2014.
- At the Clarinda Mental Health Institute:
 - Construction to replace windows with safety glass is underway. The window glass shattered into long, sharp shards and could have been used to harm patients or staff.
 - Completed waterproofing and tunnel cap replacement for tunnel sections from the Lodge to the Main building and from the Main building to Southview. The tunnel caps were becoming structurally deficient and allowed significant water infiltration.
 - Began work to replace the fire detection alarm system. A recent inspection found many deficiencies in the existing system.
- At the Glenwood Resource Center:
 - Completed tuckpointing building 115 to stop water infiltration, which had resulted in bricks falling out of the façade and exposed rebar in the basement ceiling, as well as the temporary relocation of the building occupants.
 - Replaced the air handling unit and controls in the hydrotherapy pool building, where high humidity and chlorine levels were degrading the ceiling and brick walls.
 - Repaired a section of tunnel cap and walls because the cap was cracking and rebar was exposed.
 - Awarded contract to repair the Building 102 stairwell tower where settling has caused stair tower to separate from building, creating structural issues as well as damage due to the exposure to exterior conditions.
 - Bid out emergency remediation of sinkhole caused by the 0 collapse of an abandoned utility tunnel.



Glenwood Stair Tower

At the Independence Mental Health Institute, began work on replacement of the campus wide fire alarm system. The current system was antiquated and firewatch was required campus-wide whenever the system malfunctioned, resulting in substantial overtime costs.

- At the State Training School in Eldora:
 - Completed the addition of fire escapes for living units, along with adjacent site work (sidewalks, ADA accessibility, and site grading).
 - Fire alarm panel replacements are underway in the four living units.
- At the Woodward Resource Center:
 - Replaced an eroded tunnel cap that also served as the main stairs into Westwood.
 - Completed repairs to the exterior walls and roof of the water plant. Exterior walls were coated and new roof and structure were installed along with new gutters and downspouts.
 - Design work has also begun to replace two chillers, address fire hydrant water pressure issues and upgrade an inadequate domestic water heating control system for the cottages.
 - Installed a new water line loop for the west half of the Resource Center to address fire hydrant water pressure issues. Design is underway for a new water line loop for the east half to address similar concerns.
 - Replaced the Westwood building chiller. The chiller had required frequent repairs and ultimately failed completely, requiring emergency replacement.
 - Upgrade of the domestic water heating control system for the cottages is nearly complete.

Department of Public Safety

- Replaced a non-functioning fire alarm system at Post 4.
- Nearly completed remediation of drainage issues at Post 1 that had created an ice patch near the building during winter months.
- Completed design to replace the main driveway at Post 2. Construction is expected to be complete in mid-2014.
- Completed design to replace the malfunctioning furnace and air conditioning system at the Fleet and Supply building. Construction is expected to be complete in 2014.
- Began design to remediate drainage issues at Post 12 that have created interior mold issues.

Iowa Law Enforcement Academy

- Repaired an unsafe elevator.
- Replaced doors that were no longer locking securely.

Iowa Public Television

- Added air vents to ensure the chiller works correctly in the winter.
- Completed design for repairs to a sidewalk to eliminate trip hazards. Construction is expected to be complete in 2014.

Iowa Veterans Home


• Completed replacement of the ADA ramp at the Whitehill Auditorium.

Terrace Hill

• Replaced a malfunctioning security gate arm.

Routine maintenance funding is essential for the regular care and upkeep of buildings and equipment. Delaying or deferring routine maintenance work substantially increases the expense and the need for major maintenance. For example, if routine tuckpointing is not done, moisture infiltration widens the scope of tuckpointing needed and many times leads to replacement of drywall and potential mold issues.

Iowa code requires agencies to include the proposed costs for annual routine and preventive maintenance in their five-year capital budget requests. The costs are required to be based on an industry standard of one percent of the estimated replacement cost of the department's facilities. In the past, DAS has estimated this to be \$20 million annually. No funds have been appropriated for routine maintenance since FY2010, compared to appropriations ranging from \$1.6 million to \$5 million in the past. Due to the lack of funding, agencies have had to reallocate operational funds or, more likely, delay regular maintenance work, which has contributed to the rise in major maintenance project requests. The chart below illustrates routine maintenance funding levels (in millions of dollars) compared to the requested \$20 million:



	Priority	Immedia cy	Agency	Facility	Project Title	F	- Funding Request	Comments	Running Total
1	1) L/H/S	A) Now	DOC	ICIW	Demolish Tunnel/Replace Water Line to Unit 6	\$		The tunnel at ICIW is collapsing and unsafe. Numerous areas are blocked off due to being unsafe to even walk on. Water line to unit 6 is in this tunnel and also needs to be replaced. Cannot be worked on until current construction is complete, likely early 2015.	2,000,000
								Roof is in poor shape. Many seams are coming apart. There is very little relief on the roof itself (only two roof drains and two overflows). They have had the acoustical ceiling on the top floor removed since it was always wet with leaks. This combines two prior separate requests for the Meyer School and Auditorium/Gym, since they are all one	
2	2) Damage	A) Now	DHS	Glenwood	Meyer Hall Roof Replacement	\$		connected building and roofs are the same age.	2,320,000
3	2) Damage	A) Now	DHS	Glenwood	Plumbing Upgrade in 710 Lacey Hall.	\$	979 653	Split into phases. Pipes require a lot of patching and repair, this is a high use building.	3,299,653
Ũ	2) Duniago	/ / / / / / / / / / / / / / / / / / / /	BHO	Clichwood		Ψ	070,000	Roof failing, façade shedding bricks; houses entry to main tunnel	0,200,000
4	2) Damage	A) Now	DHS	WRC	Demolish hot well house	\$	165,000	system. Project is to demolish the structure and pour a cap.	3,464,653
								Replace the concrete top caps on the tunnel that runs for 40 - 50 ft in front of Living Unit B & D that has deteriorated to the point that the rebar in the concrete is showing. With most of the rebar showing	
5	2) Damage	A) Now	DOC	ASP	Replace tunnel cap	\$	100,000	there is not much support left in the caps.	3,564,653
6	2) Damage	A) Now	DHS	Clarinda MHI	Replace roof covering on the Engine room Main building using metal roofing material.	\$	85,000	Composite shingle failure with leaks into the building interior causing damage.	3,649,653
								Repoint or seal all mortar joints in the turrets, chimneys, parapets and water tables. Insect and flashing and sealants and make repairs as	
7	2) Damage	A) Now	DOC	ASP	Tuckpointing priorities 1	\$	400,000		4,049,653
-			-	Iowa Veterans		•		The concrete tunnel tops are breaking down allowing water infiltration.	
8	2) Damage	,	DVA	Home	Tunnel top Replacement	\$		Needs additional evaluation to finalize budget.	4,299,653
9	2) Damage	A) Now	DCA	Montauk	Guttering system and re-pointing	\$	66,500	Gutters are spilling over and causing water damage. Frames are rusting through. Leaking occurs. Single glass pane	4,366,153
10	2) Damage	A) Now	DOC	Mt. Pleasant	Window Replacement - East & Gym	\$	750,000	windows with cracks. Contains lead paint.	5,116,153
11	2) Damage	A) Now	DOC	Mt. Pleasant	Tunnel Tops	\$		Tunnel tops are rapidly deteriorating. All utilities are located in the tunnels. Tunnel top failure could result in disruption of utilities. This would be an ongoing project as not all tunnels would need to be replaced at the same time.	5,166,153
								No current citation. However, both systems are not in compliance with requirements of Chapter 69. Continued use of the systems under current wastewater loads is not recommended because of the uncertainty of their condition and treatment effectiveness. Fayette County could require the upgrade of the systems if a notice of violation is issued. If the wastewater contribution to the existing system is increased it may cause the systems to fail and cause a surface	-,,
12	2) Damage	A) Now	DCA	Montauk	Montauk Septic Replacement	\$	100,000	discharge or a backup into the structure.	5,266,153
13	2) Damage	A) Now	DOC	Mt. Pleasant	Storm Water Separation	\$		Does not meet city compliance. Significant fines effective in year 2014. Will require engineering. High sewer bills due to storm water going thru sewer meter.	5,616,153
14	2) Damage	A) Now	DHS	Glenwood	Add and Replace Steam Expansion Joints in Tunnel	\$		Evaluate the number of expansion joints , anchors and pipe guides required to update and replace the current expansion joints on the 6" and 10" lines in the utility tunnels. The current expansion joints are no longer supported and the proper packing is no longer available. There needs to be additional expansion joints added to eliminate the deflection of the current piping . These steam leaks affect the integrity of the tunnel, increase energy cost in lost steam, and creates a safety hazard for the staff working in the tunnel.	5,816,153

	_	Immedia					unding		Running
	Priority	cy	Agency	Facility	Project Title		lequest	Comments	Total
15	2) Damage	A) Now	DHS	Glenwood	Tuckpointing in Lacey Complex	\$	370,000	Bricks falling off the façade. The hospital falls under the regulations of CMS. The gym is the only	6,186,153
16	2) Damage	A) Now	DHS	Mt. Pleasant	Replacing Cooling units/AC for MHI gym	\$	250,000	large area in which clients/patients can gather. Recreation is critical to treatment and the gym is an key in recreation. This also is used for sharing state changes/information with the community regarding the facility in Mt. Pleasant.	6,436,153
17	2) Damage	A) Now	DHS	Glenwood	Tuckpointing in Building 120 Phase I	\$	660,000		7,096,153
18	2) Damage	A) Now	DOC	ICIW	Replace Pharmacy Windows	\$		Building interior was remodeled recently, but several of the windows leak severely in driving rains. 12 windows in total.	7,116,153
								System is partially functioning. Prone to refrigerant leaking. Equipment is 20+ years old. May not last this cooling season. There is an increase urgency on this AC unit. We have had increasing issues with its operation. Replacement is ever more critical. Twice this summer it stopped working. All new radio equipment will be on 5th floor with AC. Should	
19	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Northcore Air Conditioning Unit	\$	150,000	the AC fail it could have serious impact on the functionality	7,266,153
								Water softeners are approx. ten years old and becoming very problematic because the inside of the cast iron regeneration controls is rotting away. They experience malfunctions due to diaphragm rupture from rust cutting them during re-generation. Also rust travels thru the controls and hangs up the control shutting off the water flow period. This issue is even more serious if this occurs during the night when the power house is not staffed. Ultimately this cuts off the flow of domestic hot water campus wide and boiler make-up water which eventually shuts the boiler down on low water alarm. Then someone	
20	2) Damage	B) <1 yr	DHS	Cherokee	Replace Water Softeners	\$	120,000	has to be called in to repair or by-pass them until repairs can be made.	7,386,153
21	2) Damage	B) <1 yr	DCA	American Gothic/Eldon	Additional building envelope repairs	\$	100,000		7,486,153
22	2) Damage	B) <1 yr	DCA	Matthew Edel Blacksmith Shop House	Building envelope repairs	\$	200,000		7,686,153
23	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Ventilation for East & West Housing	\$		Zero ventilation of air for the living units. Institution is not air conditioned so there are periodic mold issues.	7,936,153
23 24	2) Damage	B) <1 yr	DHS	Clarinda MHI	Tuck pointing main building	φ \$		Can be done in stages as before. 1/4 completed 2009, 3/4 remains	10,605,603
25	2) Damage	B) <1 yr	DOC	IMCC	Tuckpointing R/S Housing Unit - North & South Walls	\$		To fix worst areas. Majority of damage is around windows.	10,630,603
					Tuckpointing R/S Housing Unit -	1			
26	2) Damage	B) <1 yr	DOC	IMCC	West Wall	\$	25,000	To fix worst areas. Majority of damage is around windows.	10,655,603
27	2) Damage	B) <1 yr	DOC	Ft Dodge CF	Replace H Building Roof	\$	650,000	(64,709sq.ft.)	11,305,603
28	2) Damage	B) <1 yr	DOC	Ft Dodge CF	Replace Unit A Roof	\$	128,000	16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (12,205 sq.ft.)	11,433,603
29	2) Damage	B) <1 yr	DOC	IMCC	Roof Replacement – North Addition	\$	785 000	Patched multiple times. Membrane is pulling away at corners.	12,218,603
29	2) Damaye	D) < 1 yi	000			φ	785,000	Door tracking system is extremely worn. Has been retro fitted. Car is	12,210,005
30	2) Damage	B) <1 yr	DOC	Mt. Pleasant	Elevator C	\$		past life expectancy. Does not have phase one fire recall. Schumacher has said it is now critical.	12,438,603
C 1			DOC		Plaster ceiling in Kitchen	^	105 005	Safety of staff, offenders, unsanitary, demo out plaster and install new	10 500 000
31	2) Damage	B) <1 yr	DOC	Clarinda DOC	replacement	\$		metal ceiling.	12,563,603
32	2) Damage	B) <1 yr	DOC	Ft Dodge CF	Replace Cedar Unit Roof	\$		16 yrs. old – rubber membrane is dried out and pulling away from the leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (29,296 sq.ft.)	12,863,603

		Immedia			omanaoa major		Funding		Running
	Priority	су	Agency	Facility	Project Title	F	Request	Comments	Total
								16 yrs. old – rubber membrane is dried out and pulling away from the	
33	2) Damage	B) <1 yr	DOC	Ft Dodge CF	Replace Boone Unit Roof	\$	300 000	leading edge of the roof creating leaks into the space below - ongoing repairs as leaks develop. (29,296 sq. ft.)	13,163,603
34	2) Damage		DOC	IMCC	Roof Replacement – North Link	Ψ \$	125,000		13,288,603
04	2) Damage	D) < 1 y	000			Ψ	120,000	16 yrs. old – rubber membrane is dried out and pulling away from the	10,200,000
								leading edge of the roof creating leaks into the space below - ongoing	
35	2) Damage	B) <1 yr	DOC	Ft Dodge CF	Replace Floyd Unit Roof	\$	310,000	repairs as leaks develop. (30,563 sq.ft.)	13,598,603
36	2) Damage	B) <1 yr	DOC	Newton CF	CRC - Training Center Roof Replacement	\$	87,000		13,685,603
30	2) Damage	D) < T yi	DOC	Newton Ci	neplacement	φ	07,000	Previous MM project installed a temporary fix to get the facility through	13,005,005
								the winter months and evaluated options to correct the issues. New	
					WHTC Roof Replacement and			funding is needed to correct the issues. As of 3/13 the temporary fix	
37	2) Damage	B) <1 yr	DCA	WHTC	interior repair Roof Replacement – North Addition	\$	450,000	was holding and it was not currently leaking. Patched multiple times. Membrane is pulling away at corners. Leaks	14,135,603
38	2) Damage	B) <1 yr	DOC	IMCC	Lower Level	\$	785,000	currently.	14,920,603
	_) _aage	2) () j.	Terrace			Ŷ		Existing storm windows are falling apart allowing water	,,
39	2) Damage	B) <1 yr	Hill	Terrace Hill	Storm windows	\$	350,000	infiltration/rotting of sills and windows	15,270,603
40			DUIO		Waterproof top of Voldeng &	•	547 500	Both are pedestrian walkways inside and Voldeng tunnel is also a fire	15 700 400
40	2) Damage	B) <1 yr	DHS	Cherokee 6450 Corporate	Ginzberg tunnels	\$	517,500	escape.	15,788,103
41	2) Damage	B) <1 yr	IPTV	Dr	repair roof	\$	65,000	To prevent ice damming on a rubber membrane roof; four openings	15,853,103
		, ,						1995 system in use a not supported by the manufacturer. 17 year old	
					Security system, door control and			computer system and operation system that needs updated for	
42	2) Damage	B) <1 yr	DOC	Clarinda DOC	monitoring electronic system replacement	\$	600 000	support. When system fails, the public, staff and offenders are at greater risk.	16,453,103
76	2) Damage	D) < 1 y	000		Reynolds Masonry Repair Phase	Ψ	000,000		10,400,100
43	2) Damage	B) <1 yr	DHS	Independence	зв	\$	200,000		16,653,103
44	2) Damage	C) > 1 yr	DHS	Cherokee	Tuck pointing Phase 2.2	\$	360,000	Finish north side of main building.	17,013,103
								2. Reseal all mortar joints and cracks on the walkways on top of	
								stonewalls.\$50,000. 3. Repair stone masonry and install new coping to the top of stonewall	
45	2) Damage	C) > 1 yr	DOC	ASP	Tuckpointing priorities 2 & 3	\$	100,000	on the southwest corner of the south wall. \$40,000.	17,113,103
								Car is past life expectancy. Tracks are worn. Does not have phase	
46	2) Damage	C) > 1 yr	DOC	Mt. Pleasant	Elevator D	\$	220,000	one fire recall.	17,333,103
				State Training	Tunnel repairs and replacement -			Tunnel system provides major utilities (steam, water, fiber, telephone, fire alarms). Tunnel failure would cause catastrophic damage to these	
47	2) Damage	C) > 1 yr	DHS		sections A to D (HR Green study)	\$	1,120,800	systems.	18,453,903
	, 0	, ,					, ,	IVH has repaired two recent sewer line breaks. The lines are aged	
								and allow either ground water infiltration or collapse. This increases	
				Iowa Veterans				the sewage flowing into the treatment plant from this facility due to ground water, or allows sewage to flow on the ground until an	
48	2) Damage	C) > 1 yr	DVA		Sanitary Sewer Line Replacement	\$		emergency repair can be arranged.	18,763,903
	_, _ ege	<i>cj·</i> · <i>j·</i>			Tuck pointing in Building 120 Phase	+	,		,
49	2) Damage	C) > 1 yr		Glenwood		\$	330,000		19,093,903
50	2) Damage	C) > 1 yr		Glenwood	Tuck pointing in Buildings 102	\$	-	Bricks are falling off the façade.	19,373,903
51	2) Damage	C) > 1 yr		Glenwood	Tuck pointing in Buildings 110	\$	85,000		19,458,903
52	2) Damage	C) > 1 yr	DHS	WRC	Tunnel cap at Supply Building	\$	150,000	Below existing truck service road	19,608,903
				North Central				There is quite a bit of damage over the years, but repair of side walls	
53	2) Damage	C) > 1 yr	DOC		Repair of Tunnel	\$	600.000	will reinforce the utility lines for the operations. There is also absectos in on through out tunnel area.	20,208,903
			1	1		٣	000,000		

		Immedia				F	unding		Running
	Priority	су	Agency	Facility	Project Title		Request	Comments	Total
			DHS	State Training					
- 4				School - Eldora		•	05 000	Seal top of tunnel system to prevent water infiltration and further	~~ ~~ ~~~
54	2) Damage	C) > 1 yr			Tunnel Top Sealing	\$		deterioration	20,233,903
55	2) Damage	C) > 1 yr		Cherokee	Tuck pointing Phase 2.3	\$		Finish south side of main building.	20,593,903
56	2) Damage	C) > 1 yr	DHS	WRC	Tuck Point various buildings	\$	80,000	Westwood and larches and other areas	20,673,903
					Tuckpoint Old Bunkhouse Bldg.				
57	2) Damage	C) > 1 yr	DOC	Newton CF	(CRC)	\$	60,000		20,733,903
58	2) Damage	C) > 1 yr	DOC	ASP	Tuckpointing priorities 4, 5 &6	\$	1,080,000	 Repoint the defective mortar joints on the Administration Building. \$90,000. Repoint all mortar joints on the top half of stonewalls, tuckpoint only the defective mortar joint on the bottom half of the stonewalls. \$900,000 Repoint all mortar joints 100% on the west wall on the school / store room / living unit E. \$90,000. 	21,813,903
50		(), 1	DOC	Neuton CE	Replace roofs on Bldg 10 (Training	¢	15 000		01 000 000
59	2) Damage	C) > 1 yr	DOC	Newton CF	Center)	\$	15,000		21,828,903
								7.Secure the bulging stone on west wall of the old kitchen-dinning hall and repoint all mortar joints 100% on the entire building. \$220,000 8.Repoint defective mortar joints, thirty-two feet on the west wall, sixty feet on the east wall and all mortar joints above the windows on the south wall of the Clothing, R&D and Custom Wood Building. \$ 60,000 9. Repoint all mortar joints on the east wall of the Living Unit A, Living Unit C and Living Unit E and replace some eroded stone Repoint only	
60	2) Damage	C) > 1 yr	DOC	ASP	Tuckpointing priorities 7, 8 &9	\$	800,000	the defective mortar joints on the west inside walls. \$520,000	22,628,903
61	2) Damage	C) > 1 yr	DOC	ASP	Tuckpoint priorities 10 & 11	\$	825,000	 Repoint defective mortar on the south wall of Living Unit B and D. \$375,000 Repoint the defective mortar joints as needed on the Sign Shop, Commissary, Gymnasium, Maintenance Shop and Deputy's Office.\$450,000 	23,453,903
								Roofing contractor advised IPTV to re-caulk the joints because cracks	
62	2) Damage	C) > 1 yr	IPTV	6450 Corporate Dr	Re-caulk joints between concrete panels for the entire building	\$	40,000	in the caulk may be the cause of water leaks. Upon visual inspection the caulking looks like it needs to be replaced. Caulking was last done prior to 1999 (we think 1996)	23,493,903
		, i	Terrace		East Porch Newel Post and Spindle				
63	2) Damage	C) > 1 yr	Hill	Terrace Hill	Repair	\$	42,000	Rotting out supports; new foundation for posts (heaving)	23,535,903
C 4		01.	рце	State Training	Kitaban Tuak painting	¢	75 000	Duilding outeriers is in eritical pood of tuck pointing repairs	00 610 000
64	2) Damage	C) > 1 yr	DH2	School - Eldora	Kitchen Tuck pointing	\$	/5,000	Building exteriors is in critical need of tuck pointing repairs Leak has been repaired, but the material is breaking down and is not	23,610,903
					Replace Administration Building			bonded in place. Drainage issues. New estimate Aug 2012. Estimate	
65	2) Damage	C) > 1 yr	-	Glenwood	Roof	\$,	does not include A & E, PM or CM costs.	23,785,903
66	2) Damage	C) > 1 yr	DHS	Glenwood	Tuck pointing in Building 116	\$	40,000		23,825,903
67	2) Damage	C) > 1 yr	DHS	State Training School - Eldora	Tunnel repairs and replacement - sections E to J (HR Green study)	\$	957,200	Tunnel system provides major utilities (steam, water, fiber, telephone, fire alarms). Tunnel failure would cause catastrophic damage to these systems.	24,783,103
~~~			DUC		Tuels painting in Duilding 110	¢	100.000	Need to address water infiltration in one section but rest of bldg can be	04 000 400
68	2) Damage	C) > 1 yr	DHS	Glenwood	Tuck pointing in Building 119	\$	180,000	Tunnel system provides major utilities (steam, water, fiber, telephone,	24,963,103
<u> </u>		0.1.	рце	State Training	Tunnel repairs and replacement -	¢	1 150 500	fire alarms). Tunnel failure would cause catastrophic damage to these	06 115 600
69	2) Damage	C) > 1 yr	DHO	SCHOOL - EIGORA	sections K to N (HR Green study)	\$	1,152,500	systems.	26,115,603

	Priority	Immedia cy	Agency	Facility	Project Title		unding Request	Comments	Running Total
								16 yrs. old – rubber membrane is dried out and pulling away from the	
70	2) Damage	0.1.1.	DOC	Ft Dodge CF	Replace Grove Unit Roof	¢	200.000	leading edge of the roof creating leaks into the space below - ongoing	00 415 000
70	2) Damage	C) > 1 yr		FI Douge CF		\$	300,000	repairs as leaks develop. (29.296 sq.ft.) 16 yrs. old – rubber membrane is dried out and pulling away from the	26,415,603
								leading edge of the roof creating leaks into the space below - ongoing	
71	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Power Plant Roof	\$	110.000	repairs as leaks develop. (10,392 sq.ft.)	26,525,603
	_)g.	<b>c</b> ): . <b>j</b> :		i i i i i i i i i i i i i i i i i i i		Ŧ	,	16 yrs. old – rubber membrane is dried out and pulling away from the	,,
								leading edge of the roof creating leaks into the space below - ongoing	
72	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Warehouse Roof	\$	90,000	repairs as leaks develop. (8,756 sq. ft.)	26,615,603
								Frames are rusting through. Leaking occurs. Single glass pane	
73	2) Damage	C) > 1 yr	DOC	Mt. Pleasant	Window Replacement - West	\$	700,000	windows with cracks. Contains lead paint.	27,315,603
								16 yrs. old – rubber membrane is dried out and pulling away from the	
			500			<b>^</b>	~~~~~	leading edge of the roof creating leaks into the space below - ongoing	
74	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Administration Roof	\$	80,000	repairs as leaks develop. (7,700 sq.ft.)	27,395,603
75			000		Deplace Education Dept	۴	000 000	14 yrs. old - skylight flashing continues to leak into building - ongoing	07 505 600
75	, 0	C) > 1 yr		Ft Dodge CF	Replace Education Roof	\$		repairs as leaks develop. (19,399 sq.ft.)	27,595,603
76	, 0	C) > 1 yr		Ft Dodge CF	Replace Emmet Unit Roof	\$		14 yrs. old (26,480 sq.ft.)	27,865,603
77	2) Damage	C) > 1 yr	DOC	Ft Dodge CF	Replace Dolliver Unit Roof	\$	270,000	14 yrs. old (26,480 sq.ft.)	28,135,603
				Capitol	Repair Existing Pedestrian Tunnel			To water proof the existing tunnel and to bring it up to all Building and	
78	2) Damage	C) > 1 yr	DAS	Complex	between Lucas and the Capitol	\$	6,527,483	Fire Codes.	34,663,086
70				Capitol	Repair Historical Building Exterior	•	1 074 000		00 507 000
79	2) Damage	C) > 1 yr	DAS	Complex Centennial	Walls	\$	1,874,000	Repair the exterior granite stone façade. This elevator has had several engineering studies and was prioritized	36,537,086
				Building, Iowa				under ADA funding. The elevator was recently cited by Workforce	
80	3) ADA	A) Now	DCA	City	Elevator Replacement	\$	300.000	Development as being non-compliant and it skips one stop.	36,837,086
00	0) //	/ () / (011	DON	Oity		Ψ	000,000	Needed for elderly patients and med clinic. Currently non-ambulatory	00,007,000
					ADA compliant restrooms for S1 and			patients are taken through the food service area to use an ADA	
81	3) ADA	A) Now	DHS	CCUSO	S2 wards	\$	250,000	compliant restroom on another ward.	37,087,086
					Voldeng Building Elevator and				
82	3) ADA	A) Now	DHS	Cherokee	Lobby Area Remodel	\$	750,000	Improvements to accommodate ADA	37,837,086
								Cannot achieve Correctional Education Accreditation until this is	
83	3) ADA	A) Now	DOC	ASP	Access to School and Library	\$	98,000	addressed, but can provide services through other means.	37,935,086
		-		North Central					
84	3) ADA	B) <1 yr	DOC	CF	Education Bldg. Ramp ADA	\$	6,000	Access to the Education bldg for disable persons / HS	37,941,086
05			000	North Central CF	Deplace New Chandend Wolks, ADA	۴	<u> </u>	Widing of suggest point cidewally on incide povinces.	00 001 000
85	3) ADA	C) > 1 yr	DOC	GF	Replace Non-Standard Walks ADA	\$	60,000	Widing of current main sidewalk on inside perimeter	38,001,086
					Remodel/Renovate restroom & shower facilities on 4 living units of			Bathrooms do not comply with ADA regulations. Poor exhaust resulting in mold issues. Safety concerns with different type of floor	
86	3) ADA	C) > 1 yr	рне	Mt. Pleasant	#20 bldg	\$	1,645,360	surfaces causing slick floors.	39,646,446
00	3) ADA	0) > 1 yi		Capitol	Replace Lucas Building Elevators	Ψ	1,043,300	All of Elevator equipment is original equipment. The Lucas Building	33,040,440
87	4) Scheduled	A) Now	DAS	Complex	1,2,3,4 & 5	\$	1,827,840	had 56 service calls for not being in operation with 4 entrapment calls.	41,474,286
								All of Elevator equipment is original equipment. The Hoover elevators	
				Capitol				had 38 service calls for not being in operation in the last two years and	
88	4) Scheduled	A) Now	DAS	Complex	Replace Hoover Building Elevators	\$	2,031,430	12 service calls for people being entrapped.	43,505,716
								The electrical switchgear in Hoover is over 35 years old and needs to	
								be replaced before it becomes an emergency. The East end of this	
								switchgear is already shut down due to the coils in the transformer	
				Capitol	Replace Hoover Building Primary			delaminating, so the emergency tie breaker was closed so the West end of the switchgear could energize the East Breakers in the	
89	4) Scheduled	A) Now	DAS	Capitol Complex	Electrical Switchgear	\$	1 953 318	switchgear.	45,459,034
00			5/10	Complex	Lioothoai Owitongeai	Ψ	1,000,010	omtongour.	

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
				Capitol				The penthouse roof is past its life expectancy, the membrane is shrinking and the loose ballast has been eroded and is being blown off the roof. Underside of roof deck coated with a spray-on fire proofing	
90	4) Scheduled	A) Now	DAS	Complex	Replace Grimes Penthouse Roof	\$	128,000	that contains asbestos.	45,587,034
91	4) Scheduled	A) Now	DPS	Post 12	New HVAC & Controls	\$	250,000	Equipment is at the limit of its usable lifetime, has never worked properly. Annual maintenance cost is increasing rapidly.	45,837,034
				Capitol	Jessie Parker Building, Sections E,			The roofing membrane on all of these section has shrunk and has pulled away from the parapet walls, and starting to pull the parapet walls in ward. Penthouses need tuck pointing and sealed, along with	
92	4) Scheduled	A) Now	DAS	Complex	F, G, H Roof Replacement	\$	565,000	the exterior perimeter walls below the roof coping. We have four roof top units at 6535. They are over 15 years old. We	46,402,034
93	4) Scheduled	A) Now	IPTV	6535 Corporate Dr	Replace roof top unit at 6535	\$	60,000	need to start replacing them. This is a request to replace one of the four.	46,462,034
94	4) Scheduled		DAS	Capitol Complex	Replace Lucas Building Roof	\$		The Lucas Building's roofs are 14 years old. These roofs are a Fully Adhered TPO Reinforced Membrane System. The Main section of this roof has had a lot of wind damage over the years, so they have installed 24" X 24" concrete pavers over the entire roof on 6 foot centers as ballast. This roof system has had a few leaks.	47,110,994
				Conital				Replace AHU, connect cooling coils to the Central Energy Plant chilled	
95	4) Scheduled	A) Now	DAS	Capitol Complex	Jessie Parker HVAC Renovations	\$	8,331,892	water loop, duct work, VAV and direct digital controls. All existing equipment is past its life expectancy. Replace AHU, coils, fans, VAV, duct work, and direct digital controls.	55,442,886
96	4) Scheduled	A) Now	DAS	Capitol Complex	IWD HVAC Renovations	\$	8,027,590	All existing equipment is past its life expectancy. The equipment in this building is the the original dual duct AHU, with chilled water and hot water coils,dampers and louvers that were installed when the building was built. The asbestos needs abated just to work on or replace this equipment.	63,470,476
07				Capitol	Deplace Condeparts topla	¢	000.005	Condemaste tenks in the turned at Wallace and the Conited	CO 000 1 11
97 98	<ul><li>4) Scheduled</li><li>4) Scheduled</li></ul>	,	DAS DAS	Complex Iowa Labs	Replace Condensate tanks Cooler Modification	\$ \$		Condensate tanks in the tunnel at Wallace and the Capitol Replace cooler flooring as it has buckled and relocate condensing units to the exterior of the building for easier maintenance. The metal floor is icing up and makes it slick to walk across.	63,839,141 63,899,141
99	4) Scheduled	A) Now	DCA	Montauk, Clermont,	Barn Roof replacement	\$	68,000	This roof was identified in 2008 facilty study as in poor condition. It is a wood shingled roof that has had some patch repairs in the past year but the roof continues to deteriorate.	63,967,141
100	4) Scheduled	A) Now	DOC	Ft Dodge CF	Fire Panel Upgrade	\$	150,000	Replace obsolete system	64,117,141
101	4) Scheduled	A) Now	DOC	ICIW	Replace Unit 9 Control Centers' Heat Pumps		14,000	Replace heat pumps in both control center	64,131,141
102	4) Scheduled	A) Now	DOC	ICIW	Renovate Segregation Unit HVAC system		12,000	Air handling system needs to be balanced and the unit control center needs a separate heat pump so if chemicals are discharged it does not enter the control center. System condensates and dumps water on the floor.	64,143,141
	4) Scheduled		DOC	IMCC	New Boiler	\$		IMCC currently has 3 Vapor Power Boilers which are undersized during winter months. If 1 of the existing 3 boilers are inoperable then the facility cannot meet the system requirements. If system requirements cannot be met, it will affect systems such as hot water, heat, and dietary operations. Results could be health, life and safety of offenders, staff and public. Add 500 hp fire tube boiler programmed with Siemens controls apogee system - building addition may be necessary to house new boiler.	64,893,141
	4) Scheduled	,	DOC	Mt. Pleasant	Parking lots NE and SE	\$		The lots are in very bad shape and the area is so large.	64,988,141

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
		_			-		•	Need tube replacement and convert to 10 gauge boiler tubes.	
				North Central				Annually, we continue to replace tubes inside boiler #1 and #2, at an	
105	4) Scheduled	A) Now	DOC	CF	Renovate 2 Boilers	\$	58,000	estimated cost of at least \$15,000.	65,046,141
100			рце	Mt Discount	Denoir parking lat	¢	65 000	The lot is in very poor repair. Could be done in conjunction with future road repair.	CE 111 141
	4) Scheduled		DHS	Mt. Pleasant	Repair parking lot	\$ \$		Rock/tar lot last resurfaced in 1999	65,111,141
107	4) Scheduled	A) NOW	DPS	Pleasant	Repave parking lot	2	90,000	This includes new cooling coils, VAV boxes with hot water reheat coils,	65,201,141
				Capitol				dampers, drain pan liners in the both AHU, damper operators and DDC Controls. Equipment is original to building (1969), temperatures are difficult to control. The condition of the leaking coils could lead to a health problem for the building occupants. Needs to be a capital	
108	4) Scheduled	A) Now	DAS	Complex	Grimes Building HVAC Updates	\$	7,385,897	request.	72,587,038
109	4) Scheduled	A) Now	DAS	Capitol Complex	Lucas Building Cooling Coil Replacement	\$	568,328	This includes new cooling coils and removal of the existing steam reheat coils that were installed behind the existing cooling coils in both AHU 1 & 2. 2 coils are broken and 2 have questionable flow. Difficult to maintain cooling in summer heat.	73,155,366
						Ť		All equipment is original to the building (1978) and is critical to backup the state data center. There's been trouble with one of the transfer	
110	1) Sabadulad		DAS	Capitol	Replace Hoover emergency generators and emergency	¢	1 210 600	switches in the emergency switchgear in the past and water has leaked into the room over time, creating a corrosive environment (that	74 465 066
	4) Scheduled		DAS DHS	Complex WRC	switchgear	\$ \$		has recently been repaired).	74,465,966
111	4) Scheduled	A) NOW	DHS	WRC	Larches chillers replacement Security updates and installation of	\$	250,000	2 ea - 80 ton & 65 ton	74,715,966
112	4) Scheduled	A) Now	DHS	ccuso	walk-through sally port gate	\$	195,500		74,911,466
	.) concadica		2.10	Iowa Veterans	Hant in ough oany port gato	Ť	,	Replace sidewalks and concrete areas that are deteriorating and/or	,•, .••
113	4) Scheduled	A) Now	DVA	Home	Sidewalk and Concrete Repairs	\$	200,000	difficult for residents to navigate with wheel chairs.	75,111,466
			Terrace						
114	4) Scheduled	A) Now	Hill	Terrace Hill	Elevator repair	\$	35,000	New controller	75,146,466
				Union Sunday School/Clermo					
115	4) Scheduled	A) Now	DCA	nt	Roof and Tuck Pointing	\$	31,500		75,177,966
		/	DON	Clermont		Ψ	01,000		,,
116	4) Scheduled	A) Now	DCA	Museum	Clermont Museum Repairs	\$	32,000		75,209,966
				Capitol	Repair or replace streets, curbs,				
117	4) Scheduled	A) Now	DAS	Complex	sidewalks on the Complex	\$	276,800		75,486,766
118	4) Scheduled	A) Now	DAS	Capitol Complex	Replace Controls At The Historical Building With Direct Digital Controls	\$	1,727,680	System is failing	77,214,446
110		A) NI	DAC	Capitol	Finish full restoration of Soldiers &	•	000.000		77 474 440
119	4) Scheduled	A) NOW	DAS	Complex North Control	Sailors Monument	\$	260,000	The water is very hard and continues to demage equipment. Requires	77,474,446
120	4) Scheduled	A) Now	DOC	North Central CF	Replace Water Softeners	\$	100 000	The water is very hard and continues to damage equipment. Requires 12 bags/ day.	77,574,446
	4) Scheduled		DHS	WRC	Grandwood chiller replacement	φ \$		1 ea - 120 ton	77,704,446
	., conodaiou				Replace Cell Locking System for	Ψ	100,000		
122	4) Scheduled	A) Now	DOC	ASP	Living Unit B and D-3	\$	3,000,000	Will pursue a capital request. Proper spill containment needed for 70,000 gallon diesel tank. Current	80,704,446
123	4) Scheduled	A) Now	DOC	Mt. Pleasant	Spill Containment for diesel tank	\$	75,000	have a soil and grass berm. Fire Marshal warning.	80,779,446
				Capitol	Replace Central Energy Plant				
	4) Scheduled		DAS	Complex	deaerator tank	\$	452,298		81,231,744
	4) Scheduled		DHS	Independence	Reynolds Masonry Repair Phase 4	\$	1,010,000		82,241,744
	4) Scheduled		DHS	Independence	Infirmary Masonry Repair	\$	405,000		82,646,744
127	4) Scheduled	A) Now	DHS	Independence	Reynolds Masonry Repair Phase 5	\$	300,000	Cost estimate lowered based on reassessment.	82,946,744

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
128	4) Scheduled	A) Now	DOC	Newton CF	Replace siding on Bldg 14 (ILU)	\$	25,000		82,971,744
129	4) Scheduled	A) Now	DOC	Ft Dodge CF	Replace Automation Panels	\$	280,000	Obsolete, can't upgrade software. Have some spare parts in inventory.	83,251,744
		, , , , , , , , , , , , , , , , , , ,			Repair Laundry Hot Water Recovery			Hot water recovery system needed to keep up with hot water demand,	
130	4) Scheduled	A) Now	DOC	Ft Dodge CF	System Entry	\$	10,000	current pit very difficult to clean.	83,261,744
								Fire control system antiquated and no longer supported. Currently	
								functioning and they have some parts, but parts are becoming	
								unavailable. This has been moved up due the recent events of failure.	
								Parts can no longer be procured easily. Windows is the latest the	
131	4) Scheduled	A) Now	DOC	Mt. Pleasant	Life Safety Systems Upgrade	\$	2,000,000	system can adapt to. These parts are rapidly becoming unavailable.	85,261,744
								Lot 3 has buckled in several place, creating large pot holes. There are	
								lots of sunken in spots from heavy loading and wide joint and	
				Capitol	Replace parking lot 3, including new			settlement cracks. The over all condition of this parking lot is very	
132	4) Scheduled	A) Now	DAS	Complex	lighting	\$	1,400,880	hazardous to drive or walk across.	86,662,624
		-						The fence is becoming wavy and we need cement under the fencing.	
	4) Scheduled		DOC	Mt. Pleasant	Perimeter Fence	\$		This is a high need for security.	87,662,624
134	4) Scheduled	B) < 1 yr	DOC	Newton CF	Update CCTV system	\$	250,000		87,912,624
				North Central	Air Handler Replacement and				
135	4) Scheduled	B) < 1 yr	DOC	CF	Condenser Coils	\$	130,000	Unit A, B , C and Condenser Unit D.	88,042,624
				North Central					
136	4) Scheduled	B) < 1 yr	DOC	CF	Fire Alarm Upgrade	\$	195,000	Addressing system upgrade by location and clean up fault issues.	88,237,624
								Currently have to replace a \$7,000 pump about every 5 years. Will	
137	4) Scheduled	B) <1 yr	DOC	ASP	Luster Heights – New Water Well	\$	505,000	pursue a capital request.	88,742,624
								Condensate Storage tanks have holes in them allowing steam to	
								escape in the upper end. The lower end may rust through some day as	
100					Replace steam condensate storage	<b>^</b>	~~~~~~	well. If these tanks become unusable, boilers will not operate.	~~~~~~
	4) Scheduled		DOC	ASP	system	\$		Engineering done.	88,942,624
139	4) Scheduled	B) <1 yr	DOC	Ft Dodge CF	Replace Water Conditioning System	\$	70,000	Undersized, regenerate 3 - 4 times/day	89,012,624
		-			Replace large 350 lb built in clothes			Laundry process approx. 5000lbs of laundry per day on average of	
140	4) Scheduled	B) <1 yr	DOC	Clarinda DOC	dryers in laundry	\$	250,000	offender clothing.	89,262,624
			<b>DOO</b>		NCF - Living Unit C Roof	<b>^</b>	050 000		
141	4) Scheduled	B) <1 yr	DOC	Newton CF	Replacement	\$	350,000	Patching on the roof has happened and nearing the end of life cycle	89,612,624
1 1 0			000		NCF - Living Unit D Roof	¢	050 000	Detailing on the most have been and and measure the soul of life such	~~~~~
142	4) Scheduled	B) < 1 yr	DOC	Newton CF	Replacement	\$	350,000	Patching on the roof has happened and nearing the end of life cycle	89,962,624
								2" wide cracks at the joints, full of settlement cracks, some hole and	
								raised surfaces creating tripping hazards and broken and damaged	
								concrete side walk curbs. 12B will be occupied for at least 1 year	
1.10			D 4 0	Capitol	Deplete a registration late 404.0 D	<b></b>	1 001 000	by cell tower. Project will wait until IA Bldg demo is done and cell	01 044 004
143	4) Scheduled	C) > 1 yr	DAS	Complex	Replace parking lots 12A & B	\$	1,081,600	tower is removed. Reconsider in Spring 2014.	91,044,224
					Repair/replace boulevard inside		150 000		
144	4) Scheduled	C) > 1 yr	DOC	Newton CF	perimeter	\$	150,000		91,194,224
								All of Elevator equipment is original equipment. The Wallace Building	
4.45			D 4 0	Capitol	Replace Wallace Buildings	•	1 005 000	Elevators had 32 service calls for not being in operation and 1	~~ ~~ ~~ ~
145	4) Scheduled	∪) > 1 yr	DAS	Complex	Elevators	\$	1,305,600	entrapment.	92,499,824
				Carrital	Deplese Jassie Devley Duilding			All of Elevator equipment is original equipment. The Jessie Parker	
140		0.1.	DAG	Capitol	Replace Jessie Parker Building	¢	1 040 050	building had 5 service calls for not being in operation and 4	02 540 000
146	4) Scheduled	∪) > 1 yr	DAS	Complex	Elevators 1,3,4 & 5	\$	1,049,256	entrapment calls.	93,549,080
			D.4.0	Capitol	Replace Grimes Building Elevators	<b>~</b>	040.000	All of Elevator equipment is original equipment. The Grimes Building	04 400 070
147	4) Scheduled	∪) > 1 yr	DAS	Complex	1, 2 & 3	\$	940,896	had 12 service calls for not being in operation and 1 entrapment call.	94,489,976
140		0.1.	DAG	Capitol	Deplese Historical Duilding Dest	¢	1 400 010	Deefe have reached their life expectancy and have been leading	05 000 005
148	4) Scheduled	∪) > I yr	DA2	Complex	Replace Historical Building Roof	\$	1,498,319	Roofs have reached their life expectancy and have been leaking.	95,988,295

Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
		<u> </u>	<b>,</b>				Remove the skylights and replace with something other than the	I
			Capitol				skylights that are always leaking. Costs from the Studies of the Lord	
149 4) Scheduled	C) > 1 yr	DAS	Complex	Replace Historical Building Skylights	\$	2,736,790	Cultural Resources and the Ryan Compies US INC.	98,725,085
			Capitol	Replace Central Energy Plant Chiller				
150 4) Scheduled	C) > 1 yr	DAS	Complex	#3	\$	868,932	Nearing the end of its life cycle	99,594,017
			Capitol	Replace Central Energy Plant Chiller				
151 4) Scheduled	C) > 1 yr	DAS	Complex	#1 Replace	\$	868,932	Nearing the end of its life cycle	100,462,949
150 (1) Sabadulad	0) - 1 - 1		Capitol Complex	Replace Central Energy Plant Cooling Tower #2, Replace Fill on Cooling Tower #4, Enlarge Condenser Water Pit	¢	746 005	Cooling tower #2 has exceeded its life expectancy and could become unusable if anything major happens. Condenser water holding pit needs to be enlarged to run all 4 cooling towers at the same time.	101 009 074
152 4) Scheduled	C) > 1 yr	DAS			\$	746,025		101,208,974
152 (1) Schodulod	() > 1	DAG	Capitol Complex	Replace IFA Building Elevator #2	\$	210 206	All elevator equipment is original equipment and having too many incidents and entrapment calls.	101,428,270
153 4) Scheduled	C) > 1 yr	DAS	Capitol	Replace IWD Building Elevator #3	φ	219,290	All elevator equipment is original equipment. The IWD Building had 5	101,420,270
154 (1) Schodulod	C > 1 vr		Complex	West Car	\$	266 114		101 604 294
154 4) Scheduled	∪ > i yî	DAG	Capitol	Replace Historical Building	φ	200,114	service calls for not being in operation. All elevator equipment is original equipment and having too many	101,694,384
155 4) Scheduled	C > 1 vr	DAS	Complex	Elevators	\$	1 042 517	incidents and entrapment calls.	102,736,901
	0) / I yi	DAG	Capitol	IWD 150 Des Moines Street Parking	Ψ	1,042,517		102,730,301
156 4) Scheduled	C > 1 vr	DAS	Complex	Lot Replacement	\$	314,839		103,051,740
	0) / I yi	DAO	Capitol	Facilities Management Center	Ψ	014,000		100,001,740
157 4) Scheduled	C > 1 vr	DAS	Complex	HVAC Renovations	\$	420 433	Replace main AHU, coils, dampers and controls to DDC.	103,472,173
	0) > 1 yi	DAO	Capitol	Replace Central Energy Plant Boiler	Ψ	420,400	Boiler #1 is too small, once the outside temperature drops below 30	100,472,170
158 4) Scheduled	C > 1 vr	DAS	Complex	#1	\$	316 000	degrees this boiler can not keep up.	103,788,173
	0/2191	DAO	Capitol	Replace Central Energy Plant	Ψ	010,000	These are the two 200 HP primary pumps for the Capitol Complex's	100,700,170
159 4) Scheduled	C > 1 vr	DAS	Complex	Secondary Chiller Pumps	\$	250 335	chilled water loop.	104,038,508
			Capitol				The existing underground fuel oil tanks are way oversized and full of fuel oil that never gets used. Also the old fuel oil day tank inside the building is in poor condition and can only be turned on when the generators are running, as they will over fill and leak out all over the	
160 4) Scheduled	C) > 1 vr		Complex	Replace Hoover Building Fuel Tank	\$	143.913	mechanical room floor.	104,182,421
	<b>c</b> ) / · · <b>j</b> .	27.10	Capitol	Historical Building Building	Ŷ	1.0,010		
161 4) Scheduled	C) > 1 vr	DAS	Complex	Automation Controls Conversion	\$	1.843.652	Change over the pneumatic controls to DDC controls	106,026,073
	<i>c</i> // · · <b>j</b> ·		Capitol	Monument and Art Work Repair and	Ŧ	.,	The monument endowments cannot sustain the repair and restoration	
162 4) Scheduled	C) > 1 yr	DAS	Complex	Restoration	\$	275,000	of all the different monuments.	106,301,073
,			Capitol				Replace AHU, coils, fans, VAV, duct work and direct digital controls.	
163 4) Scheduled	C) > 1 yr	DAS	Complex	Wallace HVAC Renovations	\$	18,202,489	All existing equipment is past its life expectancy.	124,503,562
			Capitol					1
164 4) Scheduled	C) > 1 yr	DAS	Complex	Replace Vehicle Dispatch Roof	\$	400,000	Roof are nearing the end of their life expectancy.	124,903,562
			Capitol	Ola Babcock Miller Exterior			Clean and seal exterior stone façade, tuck-point mortar joints, clean	I
165 4) Scheduled	C) > 1 yr	DAS	Complex	Restoration	\$	880,422	and recaulk all building joints and around windows.	125,783,984
			Capitol	Replace Historical Building Chillers /			Both the chiller and the chiller/heat pump have exceeded their life	I
166 4) Scheduled	C) > 1 yr	DAS	Complex	Heat pump	\$	1,238,475	expectancy and they have mechanical issues.	127,022,459
			Capitol				Historical Boilers are 26 years old and are well beyond the life	
167 4) Scheduled	C) > 1 yr	DAS	Complex	Replace Historical Building Boiler	\$	424,074	expectancy of 15 years for electric boilers.	127,446,533
			Capitol	Capitol Complex West Terrace			Provide maintenance and repair to the granite planter walls and stairs.	
168 4) Scheduled	C) > 1 yr	DAS	Complex	Repair and Maintenance	\$	275,000	Reset panels that have tilted out, clean out and recaulk all joints.	127,721,533
			Capitol	Oran Pape Parking Lot Planter				
169 4) Scheduled	C) > 1 yr	DAS	Complex	Pavers Maintenance and Repair	\$	80,000	Provide maintenance and repair to the pavers around the planters.	127,801,533
170 (1) Cabadula -	0). 1		Capitol	Capitol Complex Security Camera and Surveillance Retention and	6	170.000	Provide for upgrading, replacing and new cameras; upgrade	107 074 000
170 4) Scheduled	_∪) > i yr	DAO	Complex	Upgrades	\$	172,090	surveillance and retention system to a new IP system.	127,974,228

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
	FIOITLY	Cy	Agency	raciiity		1	nequesi	Provides for removal and replacement of sidewalks through out the	TOtal
				Capitol	Capitol Complex Sidewalk			complex. New sidewalks to be 6 ft wide for more efficient and effective	
171	4) Scheduled	C) > 1 vr	DAS	Complex	Replacement Program	\$	1,156,990	snow removal.	129,131,218
	.) 0011000100	€/ F . J.	27.0	Capitol	Capitol Building North Plaza	Ť	.,,	The concrete plazas between the stairs on the North side of the	,,
172	4) Scheduled	C) > 1 yr	DAS	Complex	concrete replacement	\$	438,697	Capitol are badly spalled due to chemical treatment for ice.	129,569,915
	,	, ,		Capitol	Capitol Complex Building		·	Provides for the upgrades to the most current versions of the Siemens	
173	4) Scheduled	C) > 1 yr	DAS	Complex	Automation Upgrades	\$	138,875	software for the Capitol Complex and Iowa Labs on an annual basis.	129,708,790
	,	, <b>,</b>						The equipment in this building is the original equipment from when the	
				Capitol				building was built. There are 8 large AHUs in the mechanical	
174	4) Scheduled	C) > 1 yr	DAS	Complex	Hoover HVAC Systems Renovation	\$	20,347,197	penthouse with inline R/A fans in the duct work.	150,055,987
					Iowa Labs Security System			Provide for the upgrades to the to the security systems at the lowa	
175	4) Scheduled	C) > 1 yr	DAS	lowa Labs	upgrades	\$	70,000	Labs.	150,125,987
					Iowa Labs Cameras and				
					Surveillance Retention Equipment			Provides for the upgrade to existing cameras, new cameras, with a	
176	4) Scheduled	C) > 1 yr	DAS	lowa Labs	Upgrades	\$	100,000	new IP based recording system for the DCI.	150,225,987
					Iowa Labs Parking Lot	Ι.		To maintain and replace the parking lots at the lowa Labs as they are	
177	4) Scheduled	C) > 1 yr	DAS	lowa Labs	Improvements and Repair	\$	760,040	starting to develop large cracks and deteriorate due to poor drainage.	150,986,027
								Failure of the 1940's boilers refractory and controls repairs include	
								extensive abatement. Project abandons boilers and installs new 300hp	
						•		and 2-600hp in a new addition. Includes new DA, condensate, and	
1/8	4) Scheduled	C) > 1 yr	DOC	ASP	Power House Upgrade	\$	6,800,000	support systems.	157,786,027
						•		Project funded, designed, and bid, but placed on "hold" since bid was	
1/9	4) Scheduled	C) > 1 yr	DOC	ASP	Laundry Roof Replacement	\$	250,000	over budget .	158,036,027
100		0). 1	000		Replace Building L freezer	<u>م</u>	105 000	Walk-in freezers are damaged and in need of replacment from	150 161 007
	4) Scheduled			Ft Dodge CF	compartment doors/openings	\$		continual pallet truck impact	158,161,027
181	4) Scheduled	C) > 1 yr	DOC	Ft Dodge CF	Replace Gym flooring	\$	32,000	Rubber coated gym floor is damaged and worn	158,193,027
								Car is past life expectancy. Controller is in need of repair. Does not	
100	4) Scheduled	() > 1	DOC	Mt. Pleasant	Elevator MWU Upgrade	\$	220.000	have phase one fire recall. The facility is being vacated and has been moved to the bottom of our needs.	158,413,027
102	4) Scheduled	C) > 1 yi	000	IVIL. Fleasall		φ	220,000	Lot 1 has 2" wide cracks at the joints, some settlement cracking, some	150,415,027
								low spots and broken and damaged concrete curb, about 10%. Lot 4	
								has 2" wide cracks at the joints, some settlement cracking, some low	
				Capitol	Replace parking lots 1 and 4,			spots and broken and damaged concrete curb, about 10%. The over	
183	4) Scheduled	C) > 1 yr	DAS	Complex	including new lighting	\$	1 915 514	all condition of this parking lot is very hazadous to walk across.	160,328,541
100	1) 0011000100	0/2 i ji	5/10	Complex		Ψ	1,010,011	Lot 2 has 1" wide cracks at the joints, some spider cracking and some	,02,020,011
								settlement cracking along curb and gutter (5000 lin ft). Also has 10	
								concrete parking barriers which need to be replaced. Lot 13 and the	
				Capitol	Replace parking lots 2, 13 and drive			drive are full of 1" wide settlement cracks throughout the entire lot and	
184	4) Scheduled	C) > 1 yr	DAS	Complex	for 13, including new lighting	\$	2,106,870	drive.	162,435,411
	,	· · ·		·				Lot 14 has 1" to 1-3/4" joint cracks (2,121 lin ft). Lot 15 has major	
				Capitol	Replace parking lots 15 and 14,			settlement cracks and wide joint cracks with surface crushing at the	
185	4) Scheduled	C) > 1 yr	DAS	Complex	including new lighting	\$	1,179,982	inlets, joints, manholes and light pole basins.	163,615,393
				Capitol	Replace parking lots 5 and 19,			Lot 5 has 1" to 2" wide cracks at the joints, some settlement along the	
186	4) Scheduled	C) > 1 yr	DAS	Complex	including new lighting	\$	653,546	joints. Lot 19 has 1" wide settlement cracks throughout the lot.	164,268,939
								The drive for lot 25 has some spalled joints and bad panels that need	
					Replace drive for parking lot 25 and			repaired or replaced (1,300 sf). Lot 11 has 3/4" to 1-1/4" wide cracks	
				Capitol	parking lots 10, 11 and 12, including			at the joints (940 lin ft). Lot 12 has 3/4" to 1-1/2" wide cracks at the	
187	4) Scheduled	C) > 1 yr	DAS	Complex	new lighting	\$	2,142,494	joints (2,220 lin ft).	166,411,433
				Capitol		<b>^</b>			
188	4) Scheduled	C) > 1 yr	DAS	Complex	Replace parking lots 9 and 9A	\$	152,097		166,563,530

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
		_					-	Lot 25 needs to have joints cut out and resealed. Lot 28 needs joints cut out and resealed plus some cracking (1,284 lin ft). Lot 24 need	
				Capitol	Replace parking lots 28, 24 (and			some cracks cut and sealed and the drive has two panels which need	
189	4) Scheduled	C) > 1 yr	DAS	Complex	drive), and 25	\$	368,905	some repair or replacement.	166,932,435
								Lot 26 needs joints cut out and resealed (6,236 lin ft). Lot 16 needs	
				Capitol	Replace parking lots 3A, 6, 16, 21	<b>^</b>		some cracks filled coming of the corner of the islands (60 lin ft). The	
190	4) Scheduled	C) > 1 yr	DAS	Complex	(and drive), 21A, and 26	\$	4,058,609	rest of these lots will need joints filled in a few years.	170,991,045
				6535 Corporate		•	100.000		
191	4) Scheduled	C) > 1 yr	IPTV	Dr	Repair/replace roof	\$	100,000	The estimated timeframe for the replacement of the roof is FY 2017	171,091,045
100				Iowa Veterans	Turned Device even extended in the line	<u>م</u>	000 000	Demolish existing service tunnel and erect new tunnel from Power	171 001 045
192	4) Scheduled	C) > 1 yr	DVA	Home	Tunnel Replacement, Heinz Hall	\$	900,000	House to Heinz Hall.	171,991,045
100			D 4 0	Capitol	Central Energy Plant Fuel Tank	<u>م</u>	400 400		170 000 005
193	4) Scheduled	C) > 1 yr	DAS	Complex	Replacement	\$	402,180		172,393,225
101			D 4 0	Capitol	Deint Oentrel Engenne Dient	<u>م</u>	101 070		
194	4) Scheduled	C) > 1 yr	DAS	Complex	Paint Central Energy Plant	\$	131,379	This is the least shills for the Oscital Oscialar installed in 1005, 00	172,524,603
105			D 4 0	Capitol	Danlaas Ohillan #0	<u>م</u>	000 000	This is the lead chiller for the Capitol Complex, installed in 1995, 23	170 000 505
195	4) Scheduled	C) > 1 yr	DAS	Complex	Replace Chiller #2	\$	868,932	year expected life.	173,393,535
100				Capitol	Restoration of Lucas Building	<b>~</b>	000 400		174 005 005
196	4) Scheduled	C) > 1 yr	DAS	Complex	Exterior	\$	992,130		174,385,665
107			D 4 0	Capitol	Restoration of Grimes Building	<u>م</u>	000 000		174 005 005
197	4) Scheduled	C) > 1 yr	DAS	Complex	Exterior	\$	600,000		174,985,665
100				Capitol	Turnel Denein	<b>~</b>	4 750 000	This is shaden as sing of utilities, wishes and first southlaters	170 705 005
	4) Scheduled			Complex	Tunnel Repair	\$		This includes repairs of utilities, piping and fire sprinklers.	179,735,665
199	4) Scheduled	C) > 1 yr	DOC	Newton CF	CRC - Electrical Upgrade	\$	1,500,000		181,235,665
					Replace Front Exterior Doors in	•			
200	4) Scheduled	C) > 1 yr	DOC	Ft Dodge CF	Living Units (6 sets)	\$	28,000	Beat up by carts.	181,263,665
				North Central		•			
	4) Scheduled			CF	Update Unit C Fire Escape	\$		Living Unit Housing Offenders/Inmates	181,313,665
202	4) Scheduled	C) > 1 yr	DHS	Cherokee	Upgrade fire alarm system	\$	900,000	Can still find refurbished parts.	182,213,665
				North Central	Update Fire Escape on East Side of				
203	4) Scheduled	C) > 1 yr	DOC	CF	Education Bldg.	\$	60,000	The Update is required to replace the Fire Escape.	182,273,665
		<b>.</b>		North Central				This is a fire safety issue , has the panels need to be replaced and	
204	4) Scheduled	C) > 1 yr	DOC	CF	Update Electrical to LUB and R&D	\$	40,000	updated.	182,313,665
					Replace tank hot water heaters with			Very old tank heaters supply potable hot water to patient and staff	
205	4) Scheduled	C) > 1 yr	DHS	Clarinda MHI	instantaneous heaters main building	\$	180,000	areas. Needs replaced soon, suggest instantaneous heaters	182,493,665
					Replace roof covering on Carpenter				
					shop detached from main building				
206	4) Scheduled	C) > 1 yr	DHS	Clarinda MHI	using metal roofing material	\$	65,000	Asbestos shingle covering, some leaks,	182,558,665
					Replace roof covering on Paint shop				
					detached from main building using				
207	4) Scheduled	C) > 1 yr	DHS	Clarinda MHI	metal roofing material.	\$	30,000	Asbestos shingle covering original to the building, 1920's	182,588,665
					Replace misc. doors at NCF and				
208	4) Scheduled	C) > 1 yr	DOC	Newton CF	CRC	\$	150,000		182,738,665
								The hot water tanks are very uncontrollable with temperature. They	
								have very old pneumatic controls, isolation valves that do not isolate	
								when necessary for draining/cleaning and the tube bundles could have	
								some work performed on them if not replaced. One tube bundle is	
								being supported inside the tank by a 4x4 wooden block because the	
209	4) Scheduled	C) > 1 yr	DOC	ASP	Replace hot water system	\$	100,000	metal bracket rusted away some years back. Engineering done.	182,838,665
					CRC - Non-Admin Roof				
210	4) Scheduled	C) > 1 yr	DOC	Newton CF	Replacement	\$	572,000		183,410,665
								This building has perimeter heat and window air conditioning needs	
	4) Scheduled	() > 1 yr	DHS	WRC	Mechanical upgrade to e-home	\$	150,000	forced air heat and cooling. existing piping failing.	183,560,665

	Priority	Immedia cy	Agency	Facility	Project Title	F	unding equest	Comments	Running Total
					Replace and or repair prison metal				Ĩ
212	4) Scheduled	C) > 1 yr	DOC	Clarinda DOC	roof	\$	750,000	17 year old roof leaks.	184,310,665
213	4) Scheduled	C) > 1 yr	DOC	ASP	Replace powerhouse water heaters	\$	55,000		184,365,665
214	4) Scheduled	C) > 1 yr	DOC	ASP	Replace 2 DA tanks	\$	50,000		184,415,665
					Replace 100 & 5 lb header and				Ī
215	4) Scheduled	C) > 1 yr	DOC	ASP	valves	\$	50,000		184,465,665
					NCF - Building H Roof Replacement				
216	4) Scheduled	C) > 1 yr	DOC	Newton CF	(support)	\$	700,000	Patching on the roof has happened and nearing the end of life cycle	185,165,665
					Replace maintenance office and tool				
	4) Scheduled			ASP	control roofs	\$		These are the same building.	185,265,665
218	4) Scheduled	C) > 1 yr	DOC	Ft Dodge CF	Dishwasher Drain Line	\$	100,000	Currently plumbed to grease pit, violates code.	185,365,665
					NCF - Building K Roof Replacement				
219	4) Scheduled	C) > 1 yr	DOC	Newton CF	(admin)	\$	150,000	Patching on the roof has happened and nearing the end of life cycle	185,515,665
					NCF - Building L Roof Replacement				
220	4) Scheduled	C) > 1 yr	DOC	Newton CF	(power plant)	\$	125,000	Patching on the roof has happened and nearing the end of life cycle	185,640,665
					NCF - Building J Roof Replacement				
221	4) Scheduled	C) > 1 yr	DOC	Newton CF	(warehouse)	\$	125,000	Patching on the roof has happened and nearing the end of life cycle	185,765,665
					NCF - Living Unit A Roof				
222	4) Scheduled	C) > 1 yr	DOC	Newton CF	Replacement	\$	150,000	Patching on the roof has happened and nearing the end of life cycle	185,915,665
					NCF - Living Unit B Roof				
223	4) Scheduled	C) > 1 yr	DOC	Newton CF	Replacement	\$		Patching on the roof has happened and nearing the end of life cycle	186,265,665
								Install a water line for irrigating gardens, washing down dog pee pads,	
								etc. Currenty only treated/conditioned water is available from the	
	5) Efficiency	,		Ft Dodge CF	Add Untreated Water Line	\$		power plant.	186,272,165
225	5) Efficiency	A) Now	DOC	Ft Dodge CF	Add Cooling Tower Walkway	\$		Cited by Dan Duss to install working platforms on towers	186,284,165
					Add Covered Entry to R&D vehicle			A covered entry is needed at our trip door for safely loading/offloading	
226	5) Efficiency	A) Now	DOC	Ft Dodge CF	loading area	\$	85,000	transfers during adverse weather conditions	186,369,165
					Replace Television Distribution			TV cabling is inadequate to support current use and continual outages	
227	5) Efficiency	A) Now	DOC	Ft Dodge CF	System	\$		and repairs occur.	186,394,165
228	5) Efficiency	A) Now	DOC	Ft Dodge CF	Renovate Pharmacy	\$	4,500	Renovate pharmacy/add pill line window	186,398,665
								Replace defective NOL card in PLC. Faulty card prevents generator	Ĩ
229	5) Efficiency	A) Now	DOC	Ft Dodge CF	Generator PLC repairs	\$		set operational data from being displayed at the system touchscreen.	186,418,665
		,						This includes the need for new tennis and basketball courts and	
								weight yard repair as this yard is short of much needed activities. A	
230	5) Efficiency	A) Now	DOC	Mt. Pleasant	West yard upgrade	\$		retaining wall and tiling are also needed as the area takes on water.	186,568,665
					Security cameras for interior/exterior			Parts for existing system are increasingly difficult to find, only	
231	5) Efficiency	A) Now	DHS	CCUSO	viewing-campus wide	\$		refurbished parts available.	187,068,665
		/			Install Gas Lines East and West	·		Install gas lines and install hotwater look boilers Westwod, Larches	
232	5) Efficiency	A) Now	DHS	WRC	campus	\$		and grandwood.	187,228,665
		,			Renovate a campus building for				
233	5) Efficiency	A) Now	DHS	CCUSO	expanding programs (Study Only)	\$	250,000	Capital request	187,478,665
		/		Iowa Veterans				E-85 usage had been mandated by the Governor's office. There is no	
234	5) Efficiency	A) Now	DVA	Home	Install E-85 fueling station	\$		public E-85 dispensing station nearby.	187,588,665
		,			<u> </u>			No ac in kitchen. Staff and offender workers cooking food in 12-130	
235	5) Efficiency	A) Now	DOC	Clarinda DOC	Install Air Conditioning in Kitchen	\$		degree room temperatures. Unsanitary and unsafe.	188,438,665
	, <b>.</b>	, -			Fire protection hydrants and		- ,	These building do not have fire sprinkler systems and the closest fire	, _,
				Capitol	sprinklers for the Central Energy			hydrant to these building is on North side of Court Ave which is over	
236	5) Efficiency	A) Now	DAS	Complex	Plant	\$	2,342,698		190,781,363
			DOC	ISP	Farm 1 Living Unit Renovation	\$		Also recommended in Governor's FY2014 budget	191,281,363
		.,			Install HVAC system in the Lodge	<b>T</b>		Building has no AC, heating system is original 1940's. Needs replaced.	,,,
238	5) Efficiency	A) Now	DOC	Clarinda DOC	building	\$		System is designed already and ready for rebidding.	191,781,363
	, <b>,</b>	, -	•		, J		-,	, , , , , , , , , , , , , , , , , , , ,	• • • • • • •

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
	c) = (( )		500	105	Replace the Control Center 2 Gate	•	100.000		
		A) Now	DOC	ASP	Locking System	\$		Have to make parts in-house when it fails.	191,881,363
	5) Efficiency	,	DOC	Ft Dodge CF	Add heat to Main Vehicle Gate Update electrical at boiler and tunnel	\$		Freezes shut if they don't exercise it hourly in cold weather.	192,056,363
	5) Efficiency	,	DOC	Newton CF ASP			60,000	Fire Marchal notation, but no citation, Will purpus a conital request	192,116,363
	5) Efficiency	,	DOC DHS	Cherokee	Install fire exit stairs at Living Unit B	\$ \$		Fire Marshal notation, but no citation. Will pursue a capital request.	194,116,363
243	5) Efficiency	A) Now	DHS	Cherokee	New interior electrical wiring. Air conditioning, ductwork dampers,	\$	2,393,033	Main bldg; Ginzberg Bldg; Wirth Hall; Voldeng Bldg.	196,509,396
244	5) Efficiency	A) Now	DHS	Cherokee	zone valves & convector upgrades to main building Building – Automation Controls –	\$	1,511,664	Capital request	198,021,060
245	5) Efficiency	A) Now	DOC	IMCC	Phase II	\$	50,000		198,071,060
246	5) Efficiency	A) Now	DHS	Cherokee	Build enclosed stair towers-Phase I	\$	1,275,000	Capital request	199,346,060
247	5) Efficiency	A) Now	DHS	Cherokee	Sidewalk replacement-campus wide	\$	588,500		199,934,560
0.40			5.10		Replace windows for all campus buildings-Phase I. NoteDonahoe omitted from this project as per	<b>*</b>	4 400 000	Main bldg north patient wing-\$748,500; maint bldg south patient wing- \$748,500; Main bldg east ADM wing-\$305,000; Main bldg west wing- \$245,000; Powerhouse-\$123,000; Ginzberg bldg-\$408,000; Voldeng bldg-\$162,000; Wirth Hall bdg-\$175,000 plus all design & supervision	
	5) Efficiency		DHS	Cherokee	MHDS	\$	, ,	fees.	201,424,560
	5) Efficiency		DHS	Cherokee	Replace stair treads	\$	21,615		201,446,175
250	5) Efficiency	A) Now	DHS	Cherokee	Clean attics & insulate ceilings	\$	258,750		201,704,925
251	5) Efficiency	A) Now	DHS	Cherokee	Repair campus garages & doors/including duplex garages	\$	68,200		201,773,125
252	5) Efficiency	A) Now	DHS	Cherokee	Motor Pool Renovation Project	\$	757,312	Capital request	202,530,437
253	5) Efficiency	A) Now	DOC	ISP	Warehouse Life Safety Systems	\$	160,000		202,690,437
254	5) Efficiency	A) Now	DHS	Cherokee	Laundry Renovation	\$	192,500	Capital request	202,882,937
255	5) Efficiency	A) Now	DHS	Cherokee	Security cameras for interior/exterior viewing-campus wide	\$	357,500		203,240,437
256	5) Efficiency	A) Now	DOC	IMCC	Building – Automation Controls – Phase III	\$	356,000	Pneumatic systems do not offer efficiency of todays technology.	203,596,437
257	5) Efficiency	A) Now	DOC	IMCC	Building – Automation Controls – Phase IV	\$	359,000	Pneumatic systems do not offer efficiency of todays technology.	203,955,437
258	5) Efficiency	A) Now	DHS	Glenwood	Replace HVAC in 710 Lacey Hall.	\$	512,309		204,467,746
								Doesn't meet the health code due to lack of sufficient dirty/clean	I
	5) Efficiency		DOC	ASP	Remodel Laundry	\$	700,000	laundry separation.	205,167,746
260	5) Efficiency	A) Now	DHS	Glenwood	Window Replacement Building 106	\$	435,000		205,602,746
261	5) Efficiency	A) Now	DHS	Glenwood	Window Replacement Building 111	\$	325,000		205,927,746
262	5) Efficiency	A) Now	DHS	Glenwood	Window Replacement Building 119	\$	190.000	Can reduce scope on this bldg - would like to do minimal window replacement on main floor and cover remaining windows - this bldg is used for storage/upholstery shop	206,117,746
	5) Efficiency		DHS	Glenwood	Window Replacement Building 121	\$	80.000		206,197,746
200	5) Enciency			Clenwood		Ψ	00,000	Facility is getting by with what they have (a ramp and small elevator),	200,137,740
264	5) Efficiency	A) Now	DHS	Glenwood	Meyer Hall - Install New Elevator	\$	596,500	but a new elevator would be more convenient.	206,794,246
	5) Efficiency		DOC	ASP	Add water treatment to well #4	\$		Cannot be used for drinking water without further treatment, but it is not currently used for drinking water and there is city water back-up if the other wells fail.	207,794,246
					Yard expansion with industrial arts/recreation building. Includes				
266	5) Efficiency		DHS	ccuso	1600 linear feet of fencing	\$	1 418 065	Capital request. (Study-Phase I Project-Phase II)	209,213,211
200					Renovate South 1, S2 & S3 areas in	φ	1,+10,505		203,213,211
267	5) Efficiency	A) Now	DHS	ccuso	main building. (HVAC updates)	\$	518,000		209,731,211
	5) Efficiency		DHS	CCUSO	Outdoor Recreational facilities	\$		Capital request	209,906,211

		Immedia	_				Funding		Running
	Priority	су	Agency	Facility	Project Title		Request	Comments	Total
	->				Powerhouse lighting, windows and	•			
269	5) Efficiency	A) Now	DOC	ASP	ventilation	\$	60,000		209,966,211
070		A) N	D00		Connect Greenhouse to Hot Water	<b>ب</b>	00.000		000 000 011
		,		Ft Dodge CF		\$	20,000		209,986,211
		/		Ft Dodge CF	Salt-Sand Building	\$		Should use capitol or operations funding.	210,006,211
272	5) Efficiency	A) Now	DOC	ASP	Replace Security Lighting	\$	50,000		210,056,211
070					Add Industry Building to Automation	¢	40.000		010 000 011
	5) Efficiency			Ft Dodge CF	System	\$	42,000		210,098,211
		/	DOC	ASP	Replace windows & screens in LU-B	\$	80,000		210,178,211
		/	DOC	ASP	Replace windows & screens in LU-C	\$	80,000		210,258,211
276	5) Efficiency	A) Now	DOC	ASP	Replace windows & screens in LU-D	\$	80,000		210,338,211
					Replace windows & screens in				
277	5) Efficiency	A) Now	DOC	ASP	auditorium	\$	30,000		210,368,211
	->	• • • •			Replace windows & screens in	•			
278	5) Efficiency	A) Now	DOC	ASP	chapel	\$	30,000		210,398,211
	->	• • • •			Replace windows & screens in	•			
279	5) Efficiency	A) Now	DOC	ASP	music room	\$	30,000		210,428,211
		A \	540	Capitol	IWD 150 Des Moines Street PA	•	50.000		010 170 011
280	5) Efficiency	A) NOW	DAS	Complex	System	\$	50,000		210,478,211
								Water infiltration into sanitary sewer system is an on-going problem -	
				Ctoto Training				using the lining system allows minimal disruption to the facility and is	
001				State Training	Coniton Cower Lining 750 ft	¢	00.000	less costly due the location of sewer lines which are under	010 510 011
281	5) Efficiency	B) < 1 yr	DHS	School - Eldora	Sanitary Sewer Lining - 750 ft.	\$	32,000	roads/electrical lines and near functional buildings	210,510,211
					Chilled water lines and HVAC				
000			DUC	Clarinda MIII	equipment to patient areas of	¢	0 001 000		010 111 011
282	5) Efficiency	B) < 1 yr	DH2	Clarinda MHI	activities, and offices Generator Upgrade for Co-	\$	2,601,000		213,111,211
					generation (Combined Heat &				
202	5) Efficiency	P $< 1 vr$	DHS	Independence	Power)	\$	100 000	Capital request.	213,211,211
				•	,	\$		Capital request.	- · · · ·
284	5) Efficiency	B) <1 yr	DOC	Newton CF	Correct area drainage Bldg 10	\$	35,000	Dravidas far design and renevation services to pave evicting gravel	213,246,211
								Provides for design and renovation services to pave existing gravel parking lots, including associated building demolition, add storm water	
								detention as required by Iowa code, parking lot lighting and area	
								landscaping to enhance the appearance and comply with lowa code.	
								These two parking lots are existing gravel areas to the North of IWD	
								and are on hill side and are unsafe to park in during the winter months	
				Capitol				as the vehicles will slide down the hill and is dangerous to walk on.	
285	5) Efficiency	C > 1 vr	DAS	Complex	Replace Parking Lots 17 and 22	\$	1,220,477	These lots have been closed off during icy conditions.	214,466,688
200		0/ × 1 Ji	27.0	Complex		Ψ	1,220,177	The existing emergency generators and transfer switches located at	,,,
				Capitol	Capitol Complex Emergency			the various buildings are a life / safety issues which need to be	
286	5) Efficiency	C) > 1 vr	DAS	Complex	Generator Study	\$	107.060	addressed.	214,573,748
	e,,	<i>c)</i> · · <i>j</i> ·		Capitol	Central Energy Plant Boiler	Ŧ	,	Replace burners for Boiler #3 and add new DDC controls for all 3	,
287	5) Efficiency	C) > 1 vr	DAS	Complex	Optimization	\$	412,200	boilers optimization.	214,985,948
	e,	<i>c)</i> ,		Capitol	Capitol Building Granite Retaining	Ŧ	,		
288	5) Efficiency	C) > 1 yr	DAS	Complex	Wall Repair	\$	150,000	To repair the North side granite retaining wall along Grand Ave	215,135,948
	, <u>,</u>	, ,			Capitol Complex Security Camera		, -		
				Capitol	Expansion for Parking Ramp and			Add security cameras to the parking ramp and the parking lots North	
289	5) Efficiency	C) > 1 yr		Complex	North of Grand Ave	\$	308,385	of Grand Ave.	215,444,333
				Capitol	Capitol Complex Chilled Water 3-			Valve replacement program to replace all 3-way chilled water valves	Ī
200	5) Efficiency	C) > 1 vr	DAS	Complex	way Valve Replacement	\$	564,240	with 2-way valves for system optimization.	216,008,573

	Priority	Immedia cy	Agency	Facility	Project Title		Funding Request	Comments	Running Total
								Over the years all types of mechanical/electrical equipment and	
								associated piping has been abandoned in place, taking up valuable	
								space which could be used for future projects. It also makes working	
								on the surrounding equipment difficult and costly. The abandon	
								equipment is also being used as a catch all for unneeded storage.	
				Capitol	Demolition of Old and Abandoned	•		There is a salvage value to this equipment that could be utilized,	
291	5) Efficiency	C) > 1 yr	DAS	Complex	Mechanical and Electric Systems	\$	282,120	making it worth while to remove and dispose of.	216,290,693
				Capitol	Re-commissioning and Balancing of	•		Efficiencies in equipment and extended equipment life can be gained	
292	5) Efficiency	C) > 1 yr	DAS	Complex	Systems and Equipment	\$	282,120	by balancing the needed equipment.	216,572,813
			5.4.0		Iowa Labs Exhaust Duct	•		The acid fumes keeps eating out the stainless steel ducts for the SHL	
293	5) Efficiency	C) > 1 yr	DAS	lowa Labs	Replacement	\$	100,000	fume hoods. Needs to be replaced with an acid resistant material.	216,672,813
			5.40		Iowa Labs Ag Dept Grinding Room	•	70.000	Install dehumidifier in the grinding room, so the AHU does not need to	
294	5) Efficiency	C) > 1 yr	DAS	lowa Labs	Dehumidification	\$	72,000	be run so low that it super cools adjacent areas.	216,744,813
			5.40		Iowa Labs Wall Extensions up to the	•		Extend walls up to the deck for pressurization requirements. Required	
295	5) Efficiency	C) > 1 yr	DAS	lowa Labs	Deck	\$	150,000	for testing requirements and cross contamination.	216,894,813
			500			•	175 000	Install high efficiency cooling towers to reduce, energy consumption,	
	5) Efficiency				Replace Cooling Tower	\$		water use and maintenance expenses.	217,369,813
297	5) Efficiency	C) > 1 yr	ILEA	ILEA	Replace Boiler	\$	75,000	Boiler was installed in 1969, but still works.	217,444,813
								Rust around the steel frames and buckling sills from condensation, but	
298	5) Efficiency	C) > 1 yr	ILEA	ILEA	Replace windows	\$	625,000	no known infiltration.	218,069,813
								The City of Johnston has plans to increase foot traffic behind IPTV's	
								headquarters building. There are large satellite dishes behind the	
				6450 Corporate				building for the safety of people as well as protection of the satellite	
299	5) Efficiency	C) > 1 yr			Install fence for security reasons	\$	30,000	dishes, there should be a fence. Also need for chiller enclosures	218,099,813
			DHS	State Training					
300	5) Efficiency	C) > 1 yr		School - Eldora	Kitchen HVAC and hood ventilation	\$	250,000	Improved food safety/sanitation in food prep areas.	218,349,813
					Add wall in hallway between rec				
301	5) Efficiency	C) > 1 yr	DOC	Newton CF	room and hall	\$	100,000		218,449,813
								Handicapped access for campus housing rental. Can find alternative	
								locations when handicapped access is required. Cost may be double	
302	5) Efficiency	C) > 1 yr	DHS	Cherokee	Install elevator in Wirth Hall building	\$	715,000	the request, based on CCUSO elevator cost.	219,164,813
					Install security screens in dorms 1/2				
303	5) Efficiency	C) > 1 yr	DOC	Newton CF	windows	\$	175,000		219,339,813
					Replace windows in main building	•			
304	5) Efficiency	C) > 1 yr	DHS	Clarinda MHI	administration area.	\$	324,300	Original 1885 windows still being used.	219,664,113
				North Central		•		No immediate danger, but are cintinuing to make minor repairs and the	
	5) Efficiency	· ·			Repair exterior Bldgs.	\$	,	stucco is bad repair.	219,904,113
	5) Efficiency			Independence	Stewart Hall Window Replacement	\$	352,500		220,256,613
	5) Efficiency	, ,			Infirmary Window Replacement	\$	705,000		220,961,613
308	5) Efficiency	C) > 1 yr	DHS	Independence	Witte Electrical Upgrade	\$	200,000		221,161,613
309	5) Efficiency	C) > 1 yr	DHS	Independence	Infirmary Electrical Upgrade	\$	100,000		221,261,613
	5) Efficiency				Campus-wide Asbestos Abatement	\$	300,000		221,561,613
		<u>, , , , , , , , , , , , , , , , , , , </u>		North Central		Ŧ		Need to tie into Siemen Fire alarm System and cost of software and	
311	5) Efficiency	C) > 1 vr	DOC	CF	Greenhouse Automation	\$	30,000	-	221,591,613
	, <b>,</b>			1	Replace water line Bldg. #10 to		, 0	Ŭ T	,
312	5) Efficiency	C) > 1 vr	DOC	Newton CF	shop, and warehouse	\$	40,000		221,631,613
	, <b>,</b>						-,0	Construct new kitchen and storeroom for the DOC. Storeroom has	
								known structural cracking and defieciences. Kitchen was last redone	
313	5) Efficiency	C) > 1 vr	DOC	Clarinda DOC	Kitchen and storeroom	\$	4,000,000	in 1995 and needs repaired or replaced.	225,631,613
	,,						, ,	Kitchen coolers/freezers and food storage areas are in need of	-,,
		1	1	la					
				State Training	Update Kitchen Cooler/Freezers			renovation and improvement in energy efficiency and are approaching	

	Immedia				I	Funding		Runniı
Priority	Су	Agency	Facility	Project Title		Request	Comments	Tota
	C) > 1 yr	• •	Mt. Pleasant	10 Cell Isolation Expansion	\$	-	Capital. Need for additional lock-up space.	226,081,
5) Enciency	() > 1 yi	DOC	IVIL. Fleasant	Replace electrical in Bldg. 14 (ILU)	φ	300,000		220,001
5) Efficiency	C > 1 vr	DOC	Newton CF	and 10 (training center)	\$	15.000		226.096
	0) / I yi	200		CRC - Replace showers in Dorms 1	Ψ	10,000		220,000
5) Efficiency	C) > 1 vr	DOC	Newton CF	& 2	\$	55,000		226,151
5) Efficiency			Newton CF	Replace dietary equipment	\$	500,000		226,651
5) Efficiency			Newton CF	Chemical and paint storage facility	\$	55.000		226,70
	C) > 1 yr		Newton CF	Replace servery equipment	\$	250,000		226,95
	C) > 1 yr		Newton CF	Metal storage building	\$	100,000		227,05
· · · ·	C) > 1 yr		Newton CF	Vehicle building	φ \$	125,000		227,03
5) Efficiency	C) > 1 yr	DOC	Newton CF	Add room to maintenance building	φ	125,000		227,10
5) Efficiency	() > 1 vr	DOC	Newton CF	and proper ventilation	\$	50.000		227,23
	C) > 1 yr		Newton CF	Upgrade boilers and chillers	φ \$	500,000		227,73
· · · ·	, ,							-
	C) > 1 yr		Newton CF	Building for salt and sand storage Add A/C to East & West House	\$	85,000		227,81
5) Efficiency	C) > 1 yr.	DOC	Mt. Pleasant Capitol	Add A/C to East & west House	\$	3,350,000		231,16
6) Demo	A) Now	DAS	Capitol	Mercy Annex Demolition	\$	401,000		231,56
· ·	- /					,		-
6) Demo	A) Now	DHS	Clarinda MHI	Demolition of 300,000 water tower	\$		1920's water tower needs removal. Safety	231,64
6) Demo	A) Now	DHS	Independence	Hill Top Demolition	\$	100,000		231,74
6) Demo	A) Now	DHS	Independence	Grove Hall Demolition	\$	200,000		231,94
					•		abandoned, mold infested, safety, dangerous to the public and clients	
6) Demo	A) Now	DOC	Clarinda DOC	Demolition of Hope Hall	\$	400,000		232,34
							This building is scheduled to be torn down under Phase 3 of the	
							master plan in (2031-2040). The masonary walls are deteriorating, the	
							parapet walls are falling over onto the roof amd the old roof is deteriorating and leaking, creating an unstable structure. The	
							deteriorating condition of this building, along with the moisture entering	
							the building system, is the catalyst for creating mold and other health	
			Capitol				related conditions. This building's structure is not being maintained	
6) Demo	C) > 1 yr	DAS	Complex	Demolition of Old Carriage House	\$	258,719	and is rapidly become a safety hazard.	232,60
	0) / I yi	DAO	Complex	Demonition of Old Gamage House	Ψ	200,710	Vacant house. May try to sell the house on GovDeals with purchaser	202,00
6) Demo	C) > 1 yr	DHS	Mt. Pleasant	Demolition of 1102 E. Washington	\$	10.000	responsible for moving.	232,61
0) 200	<i>c/ F</i> . <b>j</b> .	2.10	inter roublant	Demolition - Poultry Feed, Canary,	Ŷ	. 0,000		,
			State Training	Coal Room, Concrete Garage, Root				
6) Demo	C) > 1 yr	DHS	School - Eldora		\$	296,000	These buildings serves no function and are beyond repair	232,91
,						,	Vacant training academy used for storage. Large building that would	Í
							take too much money to become ADA compliant. Currently dealing	
6) Demo	C) > 1 yr	DOC	Mt. Pleasant	Demolition of Training Academy	\$	225,000	with mold issues as the building is closed up.	233,13
6) Demo	C) > 1 yr	DOC	Newton CF	Remove south farm house	\$	10,000		233,14
7) No		1	_			-,		1 .
Requests		DVA	IDVA	No projects requested	\$	-		233,14
7) No	İ							1
7) INO								