## **321.396** Exception.

Section 321.395 shall not apply when an accident extinguishes said light and renders a vehicle incapable of use, and when the person in control of the vehicle erects, at the earliest opportunity after the accident, such proper light at or near the vehicle as will give warning of the presence of said vehicle.

 $\begin{array}{l} [\text{C24}, 27, 31, 35, \$5055; \text{C39}, \$\textbf{5034.05}; \text{C46}, 50, 54, 58, 62, 66, 71, 73, 75, 77, 79, 81, \$321.396] \\ \text{Referred to in } \$321.1, \$456A.12 \end{array}$