

481—390.6(89) Fees.

390.6(1) *Special inspector commission fee.* A \$55 fee shall be paid annually to the director to obtain a special inspector commission pursuant to Iowa Code section 89.7.

390.6(2) *Certificate fee.* A \$40 fee shall be paid for each one-year certificate, an \$80 fee shall be paid for each two-year certificate, and a \$160 fee shall be paid for each four-year certificate.

390.6(3) *Fees for inspection.* An inspection fee for each object inspected by a department inspector shall be paid by the appropriate party as follows:

a. A \$55 fee for each water heater supply boiler.

b. A \$95 fee for each boiler, other than a water heater supply boiler, having a working pressure up to and including 450 pounds per square inch or generating between 20,000 and 100,000 pounds of steam per hour.

c. A \$215 fee for each boiler, other than a water heater supply boiler, having a working pressure in excess of 450 pounds per square inch and generating in excess of 100,000 pounds of steam per hour.

d. A \$55 fee for each pressure vessel, such as steam stills, tanks, jacket kettles, sterilizers and all other reservoirs having a working pressure of 15 pounds or more per square inch.

e. An additional fee will be charged if, upon the request of an owner or user, the director agrees to any non-routine schedule for an inspection outside of normal business hours, a special inspection, or a site visit. The additional fee will be calculated at a rate of \$200 per hour, including travel time, with a minimum charge of \$400.

f. If a boiler or pressure vessel has to be reinspected, there shall be another inspection fee as specified above.

390.6(4) *Fees for attempted inspections.* A \$35 fee is charged for each attempt by a department inspector to conduct an inspection that is not completed through no fault of the department.

[ARC 8887C, IAB 2/19/25, effective 3/26/25; Editorial change: IAC Supplement 7/9/25]