

**875—76.1(89A) Owner's responsibility.** The procuring of new installation, major alteration permits, operating permits, and the payment of all fees shall be the responsibility of the owner. No installation or alteration shall begin until approved and the permit has been issued. Failure to obtain the appropriate permit prior to installation or alteration may, at the discretion of the labor commissioner, result in the automatic assessment of a reinspection fee under 875—subrule 75.1(1) and a referral to the attorney general for prosecution of criminal penalties described in Iowa Code section 89A.17.