

House File 461

H-1203

1 Amend House File 461 as follows:

2 1. Page 1, before line 1 by inserting:

3 <Section 1. Section 89.2, Code 2023, is amended by adding  
4 the following new subsection:

5 NEW SUBSECTION. 5A. *"National board inspection code"*  
6 means the manual for boiler and pressure vessel inspectors  
7 published by the national board of boiler and pressure vessel  
8 inspectors.>

9 2. Page 1, by striking lines 1 through 13.

10 3. By striking page 1, line 16, through page 2, line 1, and  
11 inserting:

12 <NEW SUBSECTION. 5A. *a.* The owner of an object that meets  
13 all of the criteria in subsection 4, paragraph *"a"*, may request  
14 from the director an internal inspection time period of longer  
15 than two years, but not to exceed seven years, if the object  
16 is an integral part of a continuous operation of a process  
17 that is covered by and compliant with the occupational safety  
18 and health administration process safety management standard  
19 contained in 29 C.F.R. §1910.119 and has a planned outage  
20 schedule that is longer than two years.

21 *b.* The director may grant the longer inspection interval  
22 if the owner is able to demonstrate to the director that the  
23 object is in compliance with the process safety management  
24 standard contained in 29 C.F.R. §1910.119 and that the object  
25 is included as process safety management process equipment in  
26 the owner's process safety management program. In evaluating  
27 the request, the director shall also consider whether the  
28 object meets the requirements contained in the national board  
29 inspection code, the object is fit for service based on the  
30 year of fabrication and the estimated service life of the  
31 object as determined by part 2 of the national board inspection  
32 code, and the owner has implemented practices for managing  
33 consumable items and ancillary equipment of the object. Upon  
34 request by the director, the owner shall provide the director  
35 with the findings of any previous inspections of the object

1 under this chapter.

2 *c.* If the director intends to deny the request, the director  
3 shall contact the owner prior to the denial and provide an  
4 opportunity for the owner to address the reasons for the  
5 intended denial. If the board has not adopted rules pursuant  
6 to section 89.14, subsection 11, the lack of adoption shall not  
7 be grounds for the director not to consider a request for a  
8 longer inspection interval pursuant to this subsection.

9 *d.* The owner of the object that is granted the longer  
10 inspection interval shall comply with the requirements  
11 contained in subsection 5, paragraph "b".>

12 4. Page 2, after line 1 by inserting:

13 <Sec. \_\_\_\_\_. Section 89.14, Code 2023, is amended by adding  
14 the following new subsection:

15 NEW SUBSECTION. 11. The board shall adopt rules to allow  
16 an extended internal inspection interval of up to seven years  
17 for objects that are subject to inspection pursuant to section  
18 89.5A.>

19 5. By renumbering as necessary.

---

BERGAN of Winneshiek

---

JOHNSON of Buchanan