

Senate File 321

S-3152

1 Amend Senate File 321 as follows:

2 1. Page 1, before line 1 by inserting:

3 <Section 1. Section 89.2, Code 2023, is amended by adding
4 the following new subsection:

5 NEW SUBSECTION. 5A. *"National board inspection code"*
6 means the manual for boiler and pressure vessel inspectors
7 published by the national board of boiler and pressure vessel
8 inspectors.>

9 2. Page 1, by striking lines 1 through 13.

10 3. By striking page 1, line 16, through page 2, line 1, and
11 inserting:

12 <NEW SUBSECTION. 5A. a. The owner of an object that meets
13 all of the criteria in subsection 4, paragraph "a", may request
14 from the director an internal inspection time period of longer
15 than two years, but not to exceed seven years, if the object
16 is an integral part of a continuous operation of a process
17 that is covered by and compliant with the occupational safety
18 and health administration process safety management standard
19 contained in 29 C.F.R. §1910.119 and has a planned outage
20 schedule that is longer than two years.

21 b. The director may grant the longer inspection interval
22 if the owner is able to demonstrate to the director that the
23 object is in compliance with the process safety management
24 standard contained in 29 C.F.R. §1910.119 and that the object
25 is included as process safety management process equipment in
26 the owner's process safety management program. In evaluating
27 the request, the director shall also consider whether the
28 object meets the requirements contained in the national board
29 inspection code, the object is fit for service based on the
30 year of fabrication and the estimated service life of the
31 object as determined by part 2 of the national board inspection
32 code, and the owner has implemented practices for managing
33 consumable items and ancillary equipment of the object. Upon
34 request by the director, the owner shall provide the director
35 with the findings of any previous inspections of the object

SF 321.1789 (1) 90

(amending this SF 321 to CONFORM to HF 461)

1 under this chapter.

2 *c.* If the director intends to deny the request, the director
3 shall contact the owner prior to the denial and provide an
4 opportunity for the owner to address the reasons for the
5 intended denial. If the board has not adopted rules pursuant
6 to section 89.14, subsection 11, the lack of adoption shall not
7 be grounds for the director not to consider a request for a
8 longer inspection interval pursuant to this subsection.

9 *d.* The owner of the object that is granted the longer
10 inspection interval shall comply with the requirements
11 contained in subsection 5, paragraph "b".>

12 4. Page 2, after line 1 by inserting:

13 <Sec. ____ . Section 89.14, Code 2023, is amended by adding
14 the following new subsection:

15 NEW SUBSECTION. 11. The board shall adopt rules to allow
16 an extended internal inspection interval of up to seven years
17 for objects that are subject to inspection pursuant to section
18 89.5A.>

19 5. By renumbering as necessary.

ADRIAN DICKEY