IAC Ch 63, p.1

567—63.5 (455B) Self-monitoring and reporting for animal feeding operations.

63.5(1) The following self-monitoring requirements may be imposed on an animal-feeding operation in any operation permit issued for such an operation.

- a. Measurement of liquid level in a waste storage facility on a periodic basis.
- b. Measurement of daily precipitation, as appropriate.
- c. Sampling and analysis of groundwater as necessary to determine effects of wastewater application.
 - d. Other measurements necessary to evaluate the adequacy of a waste disposal system.
- **63.5(2)** Reports of the self-monitoring results shall be submitted to the appropriate regional field office of the department quarterly. The quarterly reports shall cover the periods January through March, April through June, July through September, and October through December. The quarterly report for each period shall be submitted by the tenth day of the month following the quarter being reported.

[ARC 7625B, IAB 3/11/09, effective 4/15/09]