
BUDGET UNIT BRIEF – FY 2022

Fiscal Services Division

July 1, 2021



Ground Floor, State Capitol Building

Des Moines, Iowa 50319

515.281.3566

State Capitol Smaller Domes — RIIF

Purpose and History

This appropriation is to the Iowa General Assembly to repair the four corner domes of the Iowa State Capitol Building. In 2019, an inspection found a number of issues including eroding bricks, holes, and warping in the steel structure; mortar joint deterioration; and other issues. These issues are primarily due to water infiltration and condensation. This project is intended to repair damage due to this deterioration, waterproof the domes, improve floor capacity, and improve access.

Funding

This appropriation is funded by the Rebuild Iowa Infrastructure Fund (RIIF).

Budget Unit Number

510003A0017

Doc ID 1231260

More Information

Iowa General Assembly: www.legis.iowa.gov
LSA Staff Contact: Adam Broich (515.281.8223) adam.broich@legis.iowa.gov